A DORMAN EXCLUSIVE CATEGORY



FLUID RESERVOIRS COVERAGE GUIDE



NEW PRODUCTS • NEW SOLUTIONS • NEW OPPORTUNITIES





COMPLETE RESERVOIR IDENTIFICATION GUIDE



COMMON FAILURE PATTERN EXPLANATIONS



TECH TIPS



EXCLUSIVE DORMAN COVERAGE

COOLANT RESERVOIRS



603-350 VW Beetle 2010-98

Pressurized

LOCATION

 Typically located along fender, in front of strut

COMMON REASON FOR FAILURE

- Crack in reservoir leading to loss of fluid and eventual engine overheating
- Cap failure (not releasing pressure or not properly attached)
- Collision damage

TECH TIPS

- Ensure fluid cools before opening cap
- Ensure level sensor is operating properly (if applicable)

Non-pressurized

FAILURES

coolant fluid

Damaged during

Collision damage

Ensure radiator is

only to cold level

operating properly

Ensure reservoir is filled

TECH TIPS

Located next to, or

attached to radiator; or radiator fan shroud

Use of fluids other than

replacement of other items

(radiator, radiator fan, etc.)

(AKA Overflow Bottle)

LOCATION



603-392 Chrysler Sebring, Dodge Stratus, 2005-01 Mitsubishi Eclipse 2005-98

POWER STEERING RESERVOIRS



603-934 2007-01 Chrysler Caravan, Grand Caravan, Town & Country, Voyager

Typically Located behind engine, next to or attached to Power Steering Pump



COMMON REASON FOR FAILURE

- Damaged during power steering pump removal
- · Where applicable, o-rings deteriorate creating bad seal
- Where applicable, screen clogs with debris prohibiting free flow of fluid
- Collision damage

TECH TIPS

- Ensure proper seal to power steering pump
- · Ensure power steering pump is operating correctly

WINDSHIELD WASHER RESERVOIRS



603-159 Ford Explorer 2010-02, Lincoln Aviator 2005-03, Mercury Mountaineer 2010-02



LOCATION

• Typically located behind one of the headlights




- Use of fluids other than wiper fluid
- Road debris puncturing bottle
- Cap may be cracked, missing or improvised as a result of regular DIY fluid maintenance
- Collision damage

TECH TIPS

- Always use Windshield Wiper Fluid. Water expands when frozen and may crack reservoir.
- · Some installations may require wheel and wheel well liner removal




FLUID RESERVOIR COVERAGE GUIDE





FLUID RESERVOIRS SUPERIOR COVERAGE

WINDSHIELD WASHER RESERVOIRS POWER STEERING RESERVOIRS PRESSURIZED COOLANT RESERVOIRS NON-PRESSURIZED COOLANT RESERVOIRS



224 SKUS COVERING OVER 212 MILLION VEHICLES

| NEW PRESSURIZED COOLANT RESERVOIRS | | | |
|------------------------------------|---|---------|----------|
| Make | Model | Year | Dorman # |
| Chrysler | Avenger, 200 | 2013 | 603-379 |
| Chrysler | 300, Charger, Magnum | 2010-06 | 603-056 |
| Ford | Fusion, Milan | 2011-10 | 603-333 |
| Ford | Edge, MKX | 2010-08 | 603-353 |
| Ford | F Series Trucks, Expedition | 2010-03 | 603-028 |
| Ford | Mustang | 2010-05 | 603-051 |
| Ford | Grand Marquis, Crown Victoria, Town Car | 2011-98 | 603-050 |
| Ford | Explorer | 2005-02 | 603-070 |
| GM | Cruze | 2013 | 603-383 |
| GM | Intrigue | 2002-00 | 603-143 |
| GM | Malibu, Pontiac G6 | 2006-04 | 603-066 |
| GM | Malibu, Pontiac G6 | 2012-06 | 603-067 |
| GM | Saturn Vue | 2007-02 | 603-238 |
| GM | LaCrosse, Regal, Cadillac SRX | 2012-10 | 603-228 |
| GM | Concours, Deville, Eldorado, Seville | 2002-94 | 603-133 |
| VW | Jett, GTI, EOS, A3, TT, TT Quattro, Passat, R32, Rabbit, Tiguan | 2012-05 | 603-253 |



