A DORMAN EXCLUSIVE CATEGORY



FLUID RESERVOIRS COVERAGE GUIDE



NEW PRODUCTS • NEW SOLUTIONS • NEW OPPORTUNITIES

LOOK INSIDE FOR:











COOLANT RESERVOIRS

603-350 VW Beetle 2010-98

Pressurized

LOCATION

 Typically located along fender, in front of strut



COMMON REASON FOR FAILURE

- Crack in reservoir leading to loss of fluid and eventual engine overheating
- Cap failure (not releasing pressure or not properly attached)
- Collision damage



TECH TIPS

- Ensure fluid cools before opening cap
- Ensure level sensor is operating properly (if applicable)

Non-pressurized

(AKA Overflow Bottle)



LOCATION

 Located next to, or attached to radiator; or radiator fan shroud



FAILURES

- Use of fluids other than coolant fluid
- Damaged during replacement of other items (radiator, radiator fan, etc.)
- Collision damage



TECH TIPS

- Ensure radiator is operating properly
- Ensure reservoir is filled only to cold level



603-392

Chrysler Sebring, Dodge Stratus, 2005-01 Mitsubishi Eclipse 2005-98

POWER STEERING RESERVOIRS



603-934 2007-01 Chrysler Caravan, Grand Caravan, Town & Country, Voyager



LOCATION

• Typically Located behind engine, next to or attached to Power Steering Pump



COMMON REASON FOR FAILURE

- Damaged during power steering pump removal
- Where applicable, o-rings deteriorate creating bad seal
- Where applicable, screen clogs with debris prohibiting free flow of fluid
- · Collision damage



TECH TIPS

- Ensure proper seal to power steering pump
- · Ensure power steering pump is operating correctly

WINDSHIELD WASHER RESERVOIRS



603-159Ford Explorer 2010-02, Lincoln Aviator 2005-03, Mercury Mountaineer 2010-02



LOCATION

• Typically located behind one of the headlights




COMMON REASON FOR FAILURE

- · Use of fluids other than wiper fluid
- · Road debris puncturing bottle
- Cap may be cracked, missing or improvised as a result of regular DIY fluid maintenance
- Collision damage



TECH TIPS

- Always use Windshield Wiper Fluid. Water expands when frozen and may crack reservoir.
- · Some installations may require wheel and wheel well liner removal



FLUID RESERVOIRS SUPERIOR COVERAGE

WINDSHIELD WASHER RESERVOIRS

POWER STEERING RESERVOIRS

PRESSURIZED COOLANT RESERVOIRS

NON-PRESSURIZED COOLANT RESERVOIRS




73
MILLION
VEHICLES COVERED

MILLION VEHICLES COVERED



MILLION VEHICLES COVERED



VEHICLES COVERED

224 SKUS COVERING OVER 212 MILLION VEHICLES

NEW PRESSURIZED COOLANT RESERVOIRS			
Make	Model	Year	Dorman #
Chrysler	Avenger, 200	2013	603-379
Chrysler	300, Charger, Magnum	2010-06	603-056
Ford	Fusion, Milan	2011-10	603-333
Ford	Edge, MKX	2010-08	603-353
Ford	F Series Trucks, Expedition	2010-03	603-028
Ford	Mustang	2010-05	603-051
Ford	Grand Marquis, Crown Victoria, Town Car	2011-98	603-050
Ford	Explorer	2005-02	603-070
GM	Cruze	2013	603-383
GM	Intrigue	2002-00	603-143
GM	Malibu, Pontiac G6	2006-04	603-066
GM	Malibu, Pontiac G6	2012-06	603-067
GM	Saturn Vue	2007-02	603-238
GM	LaCrosse, Regal, Cadillac SRX	2012-10	603-228
GM	Concours, Deville, Eldorado, Seville	2002-94	603-133
VW	Jett, GTI, EOS, A3, TT, TT Quattro, Passat, R32, Rabbit, Tiguan	2012-05	603-253

The cooling system includes the radiator, cooling fan, water pump, thermostat, coolant, and the necessary hoses, clamps, and fittings.



