



IMPORTANT NOTICE

(PLEASE READ BEFORE INSTALLATION)

Upon replacement of this distributor cap or installation of a new ignition coil, CAUTION must be observed to assure that the ignition coil is properly grounded through the center terminal of the distributor terminal block.

**FAILURE TO OBSERVE THIS PRECAUTION
CAN LEAD TO SYSTEM FAILURE!**

FORM 109-0158
34614-29

7-82