



**096-1608**

**2001-03 Toyota Sienna 6 cyl, 3.0L Rear**

**Engine Control Module May Need Replacement to Prevent MIL**

Toyota Service Bulletin EG047-05 dated October 19, 2005 states that certain Toyota Sienna applications may need the ECM to be replaced in order to prevent DTC P0420.

The replacement ECM logic has been modified to improve this condition and the repair may fall under factory warranty.

If applicable, the ECM should be replaced prior to catalytic converter replacement.