



**096-1662**

**2003-08 Toyota Corolla**

**Engine Control Module May Need Reflashed to Prevent MIL**

Toyota Service Bulletin EG028-04 dated July 19, 2004 states that certain Toyota Corolla applications may need to have the ECM reflashed in order to prevent DTC P0420.

Tip applies to 2003-2004 Corolla vehicles with the 1ZZ-FE engine produced BEFORE the Production Change Effective VINS shown below:

<b>Model</b>	<b>Plant</b>	<b>Production Change Effective VIN</b>
Corolla	Shokki	JTDBR3#E#52048919
	NUMMI	1NXBR3#E#4Z339353
	TMMC	2T1BR3#E#4C312392

If applicable, the ECM should be reflashed prior to catalytic converter replacement.