



096-3021

1998-2005 VW Passat, 4 cyl. 1.8L

Engine Control Module May Require Update to Prevent P0420

Volkswagen Technical Bulletin Group 01 number 07 37 dated April 18, 2007 states that certain Volkswagen Passat applications may need the ECM to be updated in order to prevent DTC P0420.

The bulletin goes on to state that the catalyst should NOT be replaced prior to performing the update function as explained in this bulletin.

This bulletin applies to the following units:

Model(s)	Year	Engine Code	Trans Code	VIN Range From	VIN Range To
Passat, Passat Wagon	2002-2005	1.8L (AWM)	All	All	All