



**099-1429**

**2001-04 Nissan Pathfinder**

**Engine Control Module May Require Reprogramming**

Nissan Bulletin NTB02-087a suggests that certain 2001 Nissan Pathfinders displaying MIL and storing a P0420 and/or a P0430 DTC may need to have the ECM reprogrammed to correct the MIL condition.

The bulletin goes on to state that if applicable, this action should be performed prior to catalytic converter replacement.