



099-1657

2002-06 Toyota Camry 2.4L Front

Engine Control Module May Need Re-flashed to Prevent MIL

Toyota Service Bulletin EG024-04 revised April 3, 2007 states that certain Toyota Camry applications may need to have the ECM re-flashed in order to prevent DTC P0420.

Tip applies to 2002-2004 Corolla vehicles with the 2AZ-FE engine (non PZEV) and automatic transmission produced BEFORE the Production Change Effective VINS shown below:

Model	Plant	Production Change Effective VIN
Camry (2AZ-FE)	TMMK Line 1	4T1BE3#K#4U323000
	TMMK Line 2	4T1BE3#K#4U869000
	Tsutsumi	JTDBE3#K#40283686

If applicable, the ECM should be re-flashed prior to catalytic converter replacement.