



**099-1729**

*Bulletin Applies To:*

**2002-03 Mazda MPV**



**PCM Update is Available**

Mazda Service Bulletin 01-035/04 states that certain MPV applications are prone to engine pinging during acceleration and/or light throttle cruising.

If these symptoms exist, a repair procedure consisting of reprogramming the PCM to the latest calibration is available.

Because incorrect PCM calibration can often lead to misdiagnosis of catalytic converter failure, it is recommended that this repair be performed on any vehicle exhibiting these systems prior to catalytic converter replacement.