


# MERCEDES INTAKE MANIFOLD ADJUSTER REPAIR KIT

LINE EXTENSION

## ORIGINAL ASSEMBLY



### OE PROBLEM:

- Original unit includes plastic components which become brittle and often fail
- OE replacement requires the purchase of an entire assembly



IMPORT

615-905

Mercedes-Benz 2013-05

Pop Code: D | VIO: 891,782



- Dorman's repair addresses the failed original part, without the need to purchase an entire assembly
- Dorman's part has been upgraded to aluminum for added durability and longer service life

### FAILURE MODE:



Failure results in illumination of the check engine light