

BLEND DOOR REPAIRS


AFTERMARKET EXCLUSIVE CATEGORY

17 SKUs Cover Over 24 Million Vehicles




902-307
Grand Cherokee
2004-88
Installed through
Glove Box Area

Reduce Repair Cost:
Replace Just the Failed Blend Door
Instead of the Entire Plenum



DORMAN
Engineered

Aluminum Reinforcement
Prevents Breakage



902-207
Blackwood, Expedition,
F Series, Navigator
2004-97



902-203
E Series Vans
2009-97



902-221
Explorer, Mazda Pick-up,
Mountaineer, Navajo, Ranger
2011-91

COMPLETE KIT

Includes installation instructions
and metal tape to close box
after installation



902-320
Grand Cherokee
2004-99
Installed Through
Dashboard Area

Original Failure Mode:

- Blend Door hinge snaps
- Failure results in improper air flow

DORMAN
SOLUTIONS™

DORMAN
NEW SINCE 1918