

NEW TO THE AFTERMARKET KNOCK SENSOR HARNESS

Assists in relaying electrical signals to the Engine Management System

Covers
9.5 MILLION
REPAIR OPPORTUNITIES



917-033
Various GM Models
2008-99

Failure Mode

- Rubber dries and cracks
- Wires become brittle and corrode

2012028
74080

DORMAN
NEW SINCE 1918

NEW PRODUCTS • NEW SOLUTIONS • NEW OPPORTUNITIES

**BE THE FIRST
TO KNOW!**
ABOUT FORMERLY "DEALER ONLY" PARTS

Dorman provides the best in replacement ignition parts equipment.