

1



Suspension strut support mount

Art.-Nr. 10573 01, 12194 01, 12195 04, 12292 01, 25978 01, 27001 01, 27309 01, 33417 01, ... ...





The ball bearing installed in the suspension strut support mount may appear to be moving roughly when it is turned. This is due to the cracking of the outer ring during production and impairs neither function nor service life of the ball bearing.