



Mounting Instruction



Screw thread missing in strut bearing

The thread for screwing the strut bearing into the strut top mounting is missing in the new part. To fasten the bearing, special thread cutting screws are needed (use OE part), which cut the thread during the initial installation. This creates screw retention.