

Ford '04-14, F-150, 5.5', 6', & 8' BEDS: For 30035 Kit

Read pages of the 30035 instructions before starting installation. Failure to do so could result in significant vehicle damage!


IMPORTANT NOTES FOR THIS INSTALLATION:

Hole in Frame

Lockwasher

Nut

- 1. Do not drill through both walls of frame. Drill only through wall of frame to which bracket is mounted.
- 2. Find parallel rows of bed sill spot welds in bed of truck. No drilling should be done in the \sim 4" between parallel rows of spot welds where the bed sill sits.



Drilled Hole Driver Side Brackets

Hole in Frame Jounce Block


Ford '04-14, F-150, 5.5', 6', & 8' BEDS: For 30095 kit

⚠ CAUTION! **⚠**

Read pages 2-3 of the 30095 instructions before starting installation. Failure to do so could result in significant vehicle damage!

IMPORTANT NOTES FOR THIS INSTALLATION:

- 1. Do not drill through both walls of frame. Drill only through wall of frame to which bracket is mounted.
- 2. Find parallel rows of bed sill spot welds in bed of truck. No drilling should be done in the ~4" between parallel rows of spot welds where the bed sill sits.



Check for obstructions before drilling. Failure to do so could result in damaged fuel or brake lines, structural members, etc. CEQUENT TOWING PRODUCTS does its best to communicate tow vehicle manufacturer changes; however, it is ultimately the responsibility of the installer to prevent damage due to installation.