



# SMITTYBILT TECHNICAL UPDATE

DATE 7-14-16

APPLICATION 2007+ JK

PART NO. 2793

## TECHNICAL ISSUE

Depending on positioning of table, side brackets may slightly come into contact with tailgate if mounted on the inside of the tailgate.

## CORRECTIVE ACTION

Short term fix: use M12 or ½" flat washer( qty 4) as spacer between tailgate and table.

Long term fix: revising part for future manufacturing.

## EXPECTED CORRECTION TIME

Corrected. See Corrective Action (above)  
 14 Days  30 Days  60 Days  90 Days

## REQUIRES PART NOTE IN ISIS

YES  NO

NOTES:



Depending on mounting location, side brackets may slightly contact tailgate when mounted on the inside of the tailgate.(fig 1) Use flat washer between tailgate and table to allow for clearance. Use one washer for each of the 4 mounting bolts. Fig 2

