

GL5341-1B

CAUTION: Fuel System may be pressurized even with ignition off. Refer to service manual before working on fuel system.