

These pictures show examples of damage caused by a lack of grease in the cross and bearing kit.



**TRUNION & YOKE EAR** 



**TRUNION & YOKE EAR** 



TRUNION



TRUNION