
INSTALLATION INSTRUCTIONS





APPLICATION:

2019 Chevy Silverado/GMC Sierra 1500 Crew Cab & Double Cab (Excl. 2019 Silverado LD / Sierra 1500 Limited)

PART NUMBER:

 $21\text{-}24130, 21\text{-}24135, 21\text{-}54130, 21\text{-}54135, 21\text{-}24120, 21\text{-}24125, 21\text{-}54120, 21\text{-}54125}$

				CONTE	NT		
ITEM	QUAN'	TITY	DESCRIPTION				TOOLS NEEDED
1,2	2		STEP BAR ASSEMBLY (1 DRIVER, 1 PASSENGER)				10MM SOCKET
3	3		DRIVER MOUNTING BRACKET				10MM WRENCH
4	3		PASSENGER MOUNTING BRACKET				13MM SOCKET
5	6		PLASTIC BRACKET COVER				13MM WRENCH
6	12	2	M8 HEX HEAD CAP SCREW				16MM SOCKET
7	12		M8 SPLIT LOCK WASHER				16MM WRENCH
8	12		M8 FLAT WASHER				RATCHET
9	12		M10 BUTTON HEAD SCREW				TORQUE WRENCH
10	12	2	M10 TOOTHED LOCK WASHER				
11	12	2	M10 FLAT WASHER				
12	12	2	M6 HEX HEAD CAP SCREW				
13	24	1	M6 FLAT WASHER				
14	12	2	M6 NYLOCK NUT				
15	15 1		HEX KEY TOOL				
ANTI-SEIZE LUBRICANT MUST BE USED ON ALL STAINLESS STEEL FASTENERS TO PREVENT THREAD DAMAGE AND GALLING							
ITEM 2	Front A	<u> </u>	• • •	•			Passenger
	<u> </u>			-			
Front Driver							
Crew Cab shown; Double Cab will be shorter with 3 sets of holes Pro Traxx 4 Sho							own; Pro Traxx 5 Similar
ITEM 3 (Pro Traxx 4) ITEM 4			Pro Traxx 4)	ITEM 4 (Pro Traxx 5)	ITEM 4 (Pro Traxx 5)	ITEM 5	
		5					WESTIN .




PROCEDURE

- 1. Remove contents from box, verify if all parts listed are present and free from damage. Carefully read and understand all instructions before attempting installation.
 - Failure to identify damage before installation could lead to a rejection of any claim.
- 2. Starting on the driver side, remove the rubber plugs located on the rocker panel at each mounting location. See **Figure 1**.
- 3. **For models with threaded holes:** At each bracket mounting location on the rocker panel there should be a welded factory nut.




- 4. Loosely preinstall the Bracket Covers (5) to the Mounting Brackets using the included M6 Hardware. See Figure 2.
- 5. Partially install the M8 Hardware in the bottom of the rocker panel and then slide the Mounting Brackets (3 & 4) into place and install the remaining M8 Hardware. See **Figures 3 & 4.** *Note:* The rear Mounting Location for Crew Cab has two options (See **Figure 4**). Double Cab only has one rear mounting location option.





2

- 6. Fasten step bars respectively to either side using the included M10 hardware (9-11). See **Figure 5**.
- 7. Align and adjust the step bars as needed and fully tighten all hardware. Torque all M6 fasteners to 5-7 ft-lbs, all M8 fasteners to 15-18 ft-lbs, and all M10 fasteners to 30-35 ft-lbs.











WARNING



Failure to follow these instructions could lead to death, personal injury, and / or property damage.

Failure to follow these instructions could lead to death, personal injury, and / or property damage.

FASTENERS:

All Westin supplied fasteners must be utilized and installed in accordance with the installation instructions and apply torque to the specifications as defined. DOUBLE CHECK ALL FASTENERS BEFORE INITIAL USE, AND PERIODICALLY IN THE FUTURE TO ENSURE PROPER FUNCTION AND SAFETY.

DRILLING:

Most Westin products do not require drilling for installation. If drilling is defined as required, use caution when drilling a vehicle. FAILURE TO REVIEW AN AREA TO BE DRILLED MAY RESULT IN PERSONAL INJURY AND/OR INJURY TO OTHERS AS WELL AS VEHICLE DAMAGE.

EYE PROTECTION:

ALWAYS WEAR SAFETY GLASSES OR GOGGLES DURING THE INSTALLATION PROCESS TO AVOID PERSONAL INJURY.

MAXIMUM TOWING/CARRYING CAPACITY: (if applicable)

The Westin Receiver Hitches will have a visible tow rating label affixed directly on the product. User should never exceed the vehicle manufacturers maximum tow and weight rating regardless of the capacity of the hitch. FAILURE TO FOLLOW THESE GUIDELINES WILL VOID THE WESTIN WARRANTY AND MAY RESULT IN PERSONAL INJURY AND/OR INJURY TO OTHERS AS WELL AS VEHICLE DAMAGE.

FOR CALIFORNIA RESIDENTS ONLY-PROP 65 WARNING:

Some products may contain chemicals such as DEHP, which can cause cancer, birth defects or other reproductive harm.

