

On some engines, including most GM applications, it may be necessary to install the retaining clips in the upper, full circumference slot to ensure the injectors seat properly in both the fuel rails and intake manifolds/heads.



**INST150INJ**