




**Model # 78620**

**SUBARU BALL  
JOINT PULLER**



**FOR DIFFICULT TO REMOVE,  
SEIZED, RUSTED AND/OR CORRODED  
BOLT-IN SUBARU BALL JOINTS**



Model	Applications
78620	Subaru Baja 2003+, Forester 1998+, Impreza 1993+, Legacy 1990+, Outback 2000+ and more

**DESIGNED FOR EASY USE WITH VEHICLE  
ON JACK STANDS USING A DEEP 24MM  
SOCKET AND IMPACT OR HAND WRENCH  
OR USE INCLUDED 5/8-18 THREAD  
ADAPTER WITH ANY COMMON SLIDE  
HAMMER**







# Astro

MODEL NO. **78620**

# SUBARU BALL JOINT PULLER

- ✓ **FOR DIFFICULT TO REMOVE, SEIZED, RUSTED AND/OR CORRODED BOLT-IN SUBARU BALL JOINTS**
- ✓ **DESIGNED FOR EASY USE WITH VEHICLE ON JACK STANDS USING A DEEP 24MM SOCKET AND IMPACT OR HAND WRENCH**
- ✓ **5/8-18 THREAD ADAPTER CAN BE USED WITH ANY COMMON SLIDE HAMMER**
- ✓ **SLIDING PIN NON-ROTATING DESIGN REMOVES BALL JOINTS IN A SINGLE PULLING MOTION WITHOUT SPINNING THE BALL JOINT STUD**

## APPLICATIONS

*Subaru Baja 2003+, Forester 1998+, Impreza 1993+, Legacy 1990+, Outback 2000+ and more*

