

## **PYROMETER USING STEPPER AND LED LIGHTING** HARNESS WIRE IDENTIFICATION AND POSITION



(viewed from the wire IN side of the plug)


## **WIRING DIAGRAM**

- 1. Red to Probe
- 2. Yellow to Probe
- 3. X=Empty
- 4. White Dash Lights, or may be empty for non LED gauges
- 5. X=Empty
- 6. Red-12 volt switched power

(viewed from the wire IN side of the plug)

- 7. X=Empty
- 8. Black-Gauge ground
- 9. X=Empty
- 10. X=Empty

10



(viewed from the wire IN side of the plug)