


Analog Meter *Static Removal*

The manufacturer takes precautions to eliminate static from all Analog Meters before shipment. If you experience erratic needle behavior follow one of these steps.



- 1.** Mix a solution of 1 part liquid dish soap with 4 parts water and wipe on the meter cover.
- 2.** Spray an antistatic solution on meter cover