


Analog Meter Static Removal STATIC

The manufacturer takes precautions to eliminate static from all Analog Meters before shipment. If you experience erratic needle behavior follow one of these steps.



Mix a solution of 1 part liquid dish soap with 4 parts water and wipe on the meter cover.



2. Spray an antistatic solution on meter cover