

2650-753X-10


Mounting

It is important to mount the converter away from any direct engine heat sources. Make sure the wires reach the kill switch and a 12 volt source.

Wiring

- RED- To a switched 12 volt source.
- BLACK- Connect to the negative battery terminal.
- VIOLET- Connect to the trigger input wire of the tachometer.
- BROWN / BLACK- Common ground or COIL Negative.
- BROWN / ORANGE - MSD Pro Mag
- BROWN / YELLOW - Mallory or Vertex External Coil and Capacitor.

*We recommend that helically wound type suppression plug wires be used instead of solid core wires. Check with magneto manufacturer on application.



Tip: For Super Mag applications it is recommended that ground straps be connected from the magneto clamp to both cylinder heads.