BD FUEL INJECT	ION CORE ACCEPTANCE POLICY		
Full Credit Criteria	Deduction	No Credit	
 Like for Like, application years & models must match. No external damage All components present and assembled. 	 Governor Housing Damaged Front or Back (25% Deduction) Main Body Damaged (50% Deduction) AFC Housing Damaged (25% Deduction) Cracked or Damaged due to freight (50-100%) 	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Damaged Camshaft on 911/913 pumps. Part disassembled 	
 Like for like No Fire Damage All components present and assembled. No external damage 	 Missing Parts (50% Deduction) AFC Housing Damaged (25% Deduction) Main Body Damaged (50% Deduction) Cold Advanced Housing Damaged (50% Deduction) 	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Seized Head (Does not turn) Part disassembled 	
 Like for Like No Housing Damage All components present and assembled. 	 Missing/Damaged Metering Unit (50% Deduction) 	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Seized (Does not turn) Part disassembled 	
 No Housing Damage All components present and assembled. 	• Missing Metering Unit (50% Deduction)	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Seized (Does not turn) Part disassembled 	
 All components present and assembled. Like for like models Must be rebuildable 	 Missing or Damaged Electronics (50% Deduction) Seized Head (Does not turn) (50% Deduction) 	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Damaged Housing Part disassembled 	
 All components present and assembled. Must be rebuildable	 Missing or Damaged Electronics (50% Deduction) Seized Head (Does not turn) (50% Deduction) 	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Damaged Housing Part disassembled 	
 All components present and assembled. Like for like models Body and threads are in good quality Solenoid Broken plastic tabs allowed. 	 Solenoid melted or destroyed beyond repair (25% Deduction) 	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Damaged Body Part disassembled 	
 Like for like Body and threads are in good quality 		 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Damaged Body Part disassembled 	
	 Full Credit Criteria Like for Like, application years & models must match. No external damage All components present and assembled. Like for like No Fire Damage All components present and assembled. No external damage Like for Like No Housing Damage All components present and assembled. No Housing Damage All components present and assembled. No Housing Damage All components present and assembled. Like for Like No Housing Damage All components present and assembled. Like for like models Must be rebuildable All components present and assembled. Like for like models Must be rebuildable All components present and assembled. Like for like models Must be rebuildable All components present and assembled. Like for like models Must be rebuildable All components present and assembled. Like for like models Body and threads are in good quality Solenoid Broken plastic tabs allowed. Like for like Body and threads are in 	 Like for Like, application years & models must match. No external damage All components present and assembled. Like for Like All components present and assembled. Like for Like No Fire Damage All components present and assembled. Like for Like No external damage AFC Housing Damaged (25% Deduction) Cold Advanced Housing Damaged (50% Deduction) Missing/Damaged Metering Unit (50% Deduction) Missing or Damaged Electronics (50% Deduction) Seized Head (Does not turn) (50% Deduction) Seize	

	BD TURBOCHARGER	CORE ACCEPTANCE POLICY	
Turbo Model/ Application	Full Credit Criteria	Deduction	No Credit
Cummins ISX VGT Air or Electronic Actuated	 Light or minimal damaged to Compressor & Turbine Wheel. Light or minimal damage to compressor and turbine housing. All components present and assembled. Like for like models 	 Missing Parts or Actuators (50% Deduction) Damaged Electronics (50% Deduction) Missing Clamps (25% Deduction) Heavily damage wheels and/or shaft (50% Deduction) Turbine Wheel Separation (50% Deduction) Cracked or Damaged due to freight (50- 100%) Damaged Electronics (50% Deduction) 	 Fire Damage Knock Off Models (Not Genuine) Excessive Rust or water damage
Caterpillar (Ball Bearing) Models	 Light or minimal damaged to Compressor & Turbine Wheel. Light or minimal damage to compressor and turbine housing. All components present and assembled. Like for like models, must have CAT logo 	 Missing Parts or Actuators (50% Deduction) Missing Clamps (25% Deduction) Heavily damage wheels and/or shaft (50% Deduction) Turbine Wheel Separation (50% Deduction) Cracked or Damaged due to freight (50- 100%) Damaged Electronics (50% Deduction) 	 Fire Damage Knock Off Models (Not Genuine) Excessive Rust or water damage
Caterpillar (Standard Turbocharger) 704604-9007, 704604-9011)	 Light or minimal damaged to Compressor & Turbine Wheel. Light or minimal damage to compressor and turbine housing. All components present and assembled. Like for like, must have CAT or Garrett logo. 4 Support Webs 	 Missing Parts or Actuators (50% Deduction) Missing Clamps (25% Deduction) Heavily damage wheels and/or shaft (50% Deduction) Turbine Wheel Separation (50% Deduction) Cracked or Damaged due to freight (50- 100%) Damaged Electronics (50% Deduction) 	 Fire Damage Knock Off Models (Not Genuine) Excessive Rust or water damage Turbo with 3 support Webs
Detroit Diesel VGT	 Light or minimal damaged to Compressor & Turbine Wheel. Light or minimal damage to compressor and turbine housing. All components present and assembled. Like for like models 	 Missing Parts or Actuators (50% Deduction) Missing Clamps (25% Deduction) Heavily damage wheels and/or shaft (50% Deduction) Turbine Wheel Separation (50% Deduction) Cracked or Damaged due to freight (50- 100%) Damaged Electronics (50% Deduction) 	 Fire Damage Knock Off Models (Not Genuine) Excessive Rust or water

I-00434 Ford 6.4 Powerstroke	 Light or minimal damaged to Compressor & Turbine Wheel. Light or minimal damage to compressor and turbine housing. All components present and assembled. Like for like models 	 Missing Parts or Actuators (50% Deduction) Missing Clamps (25% Deduction) Damaged VGT cage due to turbine wheel explosion (50%) Cracked or Damaged due to freight (50- 100%) Damaged Electronics (50% Deduction) 	 Fire Damage Knock Off Models (Not Genuine) Excessive Rust or water
Dodge Cummins 6.7 HE351VG/HE300VG	 Light or minimal damaged to Compressor & Turbine Wheel. Light or minimal damage to compressor and turbine housing. All components present and assembled. Like for like models 	 Missing Parts or Actuators (50% Deduction) Missing Clamps (25% Deduction) Cracked or Damaged due to freight (50- 100%) Damaged Electronics (50% Deduction) 	 Fire Damage Knock Off Models (Not Genuine) Excessive Rust or water
Standard Turbochargers (All Models, Non VGT)	 On Vehicle damaged to Compressor & Turbine Wheel. On Vehicle damage to compressor and turbine housing. All components present and assembled. Like for like models 	 Missing Parts or Actuators (50% Deduction) Damaged Electronics (50% Deduction) Missing Clamps (25% Deduction) Cracked or Damaged due to freight (50- 100%) Damaged Electronics (50% Deduction) 	 Fire Damage Knock Off Models (Not Genuine) Excessive Rust or water

I-00434			
	BD TRANSMISSION		
	ACCE	ACCEPTANCE POLICY	
Model	Full Credit Criteria	Deduction	No Credit
Transmissions	 No external damage No case cracks Drive shafts intact Dowel pin holes not damaged Threads not damaged No missing pieces Like for Like Must be assembled 	 Cracked or heavily corroded extension/OD housings (50% Deduction) Broken shafts (Requires disassembly for accurate costing) Missing electronics (25% Deduction) 	 Catastrophic damaged Damaged input shaft area, destroyed pump, case and convertor area Cracked Case Fire Excessive corrosion
Torque Convertors	 No Rust No damage to Hub, Impeller and turbine Like for like 	 Hub and Impeller damaged. (50% Deduction) Modified/Aftermarket convertors in which the stator or turbine have been modified. (<u>Only on purchased cores. 50% Deduction</u>) 	 Excessive corrosion Seized Catastrophic failure
Valve Bodies	Like for likeNo missing parts	Missing electronics (25% Deduction)	Excessive corrosion

GENERAL CORE ACCEPTANCE POLICY

Freight and removal damage are not covered. Ensure you packaged the core sufficiently!

Core must be rebuildable!