

bosal

096-1631

2001-06 Lexus LS430



Check for Exhaust Leaks Prior to Converter Replacement

Certain Lexus LS430 vehicles may be prone to small exhaust leaks in the piping below the downstream O2 Sensors which could trigger DTC P0420 or P0430.

The absence of any exhaust leaks should be confirmed prior to catalytic converter replacement.