



BULLDOG HD™

HEAVY DUTY SHOCK ABSORBERS

**PROFESSIONAL
GRADE**



2021 CATALOG

BULLDOG HD 2021 Catalog

Contents	Page
Warranty	3
Vehicle Fitment Applications - BullDog HD	6
Competitive Part Interchanges	120
Applications by Part Number	124
Cab Shock Applications	138

IMPORTANT INFORMATION

The goal of this catalog is to provide our customers with as complete a listing of their parts requirements as possible. We took great care to ensure that all listings, applications, and interchanges were compiled as accurately as possible; however, we cannot assume any responsibility for possible errors in listings, applications or interchanges. I

This catalog supercedes all previous catalogs and listings.



2 YEAR OR 200,000 MILE LIMITED WARRANTY

BULLDOG HD™ is pleased to warrant to the original vehicle owner that each new **BULLDOG HD™** shock shall be free from defects in workmanship and materials, when used under normal operating conditions. 2 year or 200,000 miles is defined as for as long as the original purchaser owns the vehicle on which the **BULLDOG HD™** products were installed.

This warranty is limited to the exchange/replacement of the **BULLDOG HD™** product that is being claimed as defective. This warranty makes no further expressed or implied obligation under this warranty. This warranty is expressed for the exchange or replacement cost of the defect product or a refund of the original purchase price of the product. This warranty does not apply to conditions caused by normal wear and tear or to products that have been altered, modified, improperly installed, used in applications other than their original intent, and damaged due to vehicle modification or accident.

All cost associated with the installation, removal and replacement of the defective product is not included in this warranty and shall not be considered for re-imbusement.

Procedure for Making a Warranty Claim

As the exclusive authorized distributor for **BULLDOG HD™** in North America, all warranty claims will be processed by DMA Sales, LLC on the behalf of **BULLDOG HD™**. All warranty claim decisions made by DMA Sales, LLC are final.

In order to process a warranty claim, the defective part must be returned to the parts distributor with whom the part was originally purchased. The defective part must be accompanied by the following documents:

1. Original dated purchase invoice showing to whom the part was sold and when it was installed.
2. Replacement part dated invoice showing that the defective part was replaced with a new **BULLDOG HD™** part.

Once the part has been inspected by the original distributor and determined to comply with the stipulations of this warranty, all defective parts should be held by the distributor and the associated paper work must be returned to DMA Sales, LLC for final processing. Upon receiving the warranty documents, DMA Sales, LLC shall issue the parts distributor a credit on their account for the amount of credit due, if all is in compliance to the warranty policy. Once warranty is credited, the distributor shall be responsible for destroying the product. If DMA requests warranty products to be returned, the distributor must return the parts to DMA in order to receive credits.

BULLDOG HD™ Shocks

Fast Facts



✓ BEST TECHNOLOGY ✓ BEST PERFORMANCE ✓ ULTRA PREMIUM HEAVY DUTY SHOCKS

BULLDOG HD™ RAISES THE BAR ON PREMIUM SHOCK STRENGTH AND LONGEVITY!

Through innovative performance features and utilizing advanced raw materials, we established the Superior "Best in Class" **BULLDOG HD™ Shock Program**.

US HD Market Sold 4 Million Units ≈ \$300 Million Dollars a Year!

The **BULLDOG HD™** Difference

- ✓ Engineered to Combat Top Shock Failure Modes
 - Excessive Misting
 - Weak Welds
 - Poor Bushing Quality
- ✓ Industry Leading Warranty
- ✓ Performance Tested to Exceed Market Standards
- ✓ Fleet Tested, Fleet Approved
- ✓ Extended Performance Life
- ✓ First Class Customer Service, Marketing & Technical Support




The Power of **Ultra Premium** Quality

- ✓ Safety! – Reduced Driver Fatigue
- ✓ Reduced Unscheduled Maintenance
- ✓ Increased Revenue Due to Less Downtime
- ✓ Extended Life of Other Components like Tires and Airbags

13%
of Large Truck Accidents
Due to Driver Fatigue
-FMCSA Crash Test

20%
Increase in Unscheduled
Maintenance Costs since 2018
-TMC FleetData



- TRAILERS
- TRUCKS CLASS 8
- CONTAINER CHASSIS
- TRUCKS CLASS 7
- TRUCKS CLASS 6

END USER POINT OF PURCHASE



CAB SHOCKS | STEERING DAMPENERS | SHOCK ABSORBERS



ISO 9001:2015



REDEFINING THE PREMIUM HEAVY DUTY SHOCK!



BULLDOG HD™ Doesn't Just Offer a Premium Quality Product...

- ✓ Full Line of Cab Shock Absorbers, Universal Steering Dampeners, & Shock Absorbers
- ✓ Electronic Cataloging & Custom PDF Catalogs
- ✓ Fleet Testing Program
- ✓ Sales Support & Training
- ✓ Marketing & Promotional Support
- ✓ Technical & Product Support Hotline
- ✓ Highly Responsive Customer Service



BULLDOG HD™ Covers these Brands and More!



*Brands are representative of application coverage

**FRONT****REAR**

Acterra			
2003-2010			HD1215-0018 With FAS II Airliner Suspension; Shocks are 1.75in Bore
2003-2008	HD1115-0073	OE Interchange: 1012388000; With 6,000-9,000lb Front Axle	
Acterra 5500			
2001-2007			HD1215-0018 With FAS II Airliner Suspension; Shocks are 1.75in Bore
Acterra 6500			
2004-2007			HD1215-0018 With FAS II Airliner Suspension; Shocks are 1.75in Bore
Acterra 7500			
2007-2007			HD1215-0018 With FAS II Airliner Suspension; Shocks are 1.75in Bore
American Lafrance Alf Eagle			
2012-2012	HD1215-0159	OE Interchange: 1012594000; Shocks are 1.75in Bore	
1997-2009	HD1215-0159	OE Interchange: 1012594000; Shocks are 1.75in Bore	
Autocar ACL			
1988-1988			HD1215-0049 OE Interchange: 359013201; Shocks are 1.75in Bore
1988-1988			HD1215-0044 OE Interchange: 8026658; With Air Suspension; Shocks are 1.75in Bore
1988-1988			HD1215-0124 OE Interchange: 8071524; With Air Suspension; Shocks are 1.75in Bore
Blue Bird All American FE			
1989-2020	HD1215-0168	OE Interchange: 1750785; With Ridewell Air Suspension; Shocks are 1.75 in Bore	HD1214-0542 OE Interchange: 1526417; With Neway Air Suspension; Shocks are 1.38in Bore
1989-2016	HD1215-0162	OE Interchange: 00110808; With Hendrickson Airtex Front Suspension; Shocks are 1.75 in Bore	
1989-2016	HD1214-0605	School Bus; Cab Forward; OE Interchange: 2021459; With 3/4 Inch Mounting Pins; Shocks are 1.38in Bore	HD1116-0047 School Bus; Cab Forward; OE Interchange: 614974, 0823054; With Rockwell or Spicer Axle
1989-2016	HD1215-0070	School Bus; Cab Forward; OE Interchange: 1658525; With Parabolic Leaf Spring; Shocks are 1.75in Bore	
1989-2016	HD1215-0079	School Bus; Cab Forward; OE Interchange: 00040015; With Hendrickson Parasteer Suspension; Shocks are 1.75in Bore	HD1215-0122 School Bus; Cab Forward; OE Interchange: 0088035, 471700000464; With Leaf Spring Suspension; Shocks are 1.75in Bore



FRONT



REAR

Blue Bird All American FE

1989-2016	HD1215-0060	School Bus; Cab Forward; OE Interchange: 00106303; With Hendrickson Softek Suspension; Shocks are 1.75in Bore		
1989-2016	HD1116-0044	School Bus; Cab Forward; OE Interchange: 614966; With Rockwell Axle; With 1 inch Mounting Pins		

Blue Bird All American RE

1989-2020	HD1215-0162	OE Interchange: 00110808; With Hendrickson Airtek Front Suspension; Shocks are 1.75 in Bore	HD1214-0542	OE Interchange: 1526417; With Neway Air Suspension; Shocks are 1.38in Bore
1989-2016			HD1116-0047	School Bus; Cab Forward; OE Interchange: 614974, 0823054; With Rockwell or Spicer Axle
1989-2016			HD1215-0122	School Bus; Cab Forward; OE Interchange: 0088035, 471700000464; With Leaf Spring Suspension; Shocks are 1.75in Bore
1989-2016		School Bus; Cab Forward; OE Interchange: 2021459; With 3/4 Inch Mounting Pins; Shocks are 1.38in Bore	HD1214-0605	
1989-2016	HD1215-0070	School Bus; Cab Forward; OE Interchange: 1658525; With Parabolic Leaf Spring; Shocks are 1.75in Bore	HD1116-0044	OE Interchange: 614966; With Rockwell or Spicer Axle
1989-2016	HD1215-0079	School Bus; Cab Forward; OE Interchange: 00040015; With Hendrickson Parasteer Suspension; Shocks are 1.75in Bore	HD1215-0057	School Bus; Cab Forward; OE Interchange: 60998003, 00085991; With Hendrickson Air Suspension; Shocks are 1.75in Bore
1989-2016	HD1215-0060	School Bus; Cab Forward; OE Interchange: 00106303; With Hendrickson Softek Suspension; Shocks are 1.75in Bore	HD1215-0113	OE Interchange: 0823047; With Spicer Axle; Shocks are 1.75in Bore

Blue Bird TC2000

1989-2004			HD1215-0169	OE Interchange: 90045050; With Neway Air Suspension; Shocks are 1.75 in Bore
1989-2004	HD1215-0091	OE Interchange: 1668722, 1722214; With Reyco Air Suspension; Shocks are 1.75in Bore	HD1215-0045	OE Interchange: 1668730; With Reyco Air Suspension; Shocks are 1.75in Bore
1989-2004	HD1215-0096	OE Interchange: 1317767; With Leaf Spring Suspension; 1.75in Bore	HD1215-0111	OE Interchange 1746163; With Leaf Springs; Shocks are 1.75in Bore
1989-2004	HD1215-0070	OE Interchange: 1658525; With Parabolic Leaf Spring; Shocks are 1.75in Bore	HD1214-0532	OE Interchange: 1316546; With Leaf Spring Suspension; Shocks are 1.38in Bore
1989-2004	HD1215-0151	With 3 Inch or 4 Inch Parabolic Leaf Spring; Shocks are 1.75in Bore	HD1215-0151	OE Interchange 1658533; With 3 Inch Parabolic Leaf Spring; Shocks are 1.75in Bore

APPLICATIONS



FRONT



REAR

APPLICATIONS

Chevrolet B7				
1997-2002	HD1215-0081	OE Interchange: 15123676, 15174898, 15887728; Shocks are 1.75in Bore		
1993-1998	HD1214-0556	OE Interchange: 22064230; Shocks are 1.38in Bore	HD1214-0561	OE Interchange: 22064232; With 15,000 to 21,000lb Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1993-1996			HD1215-0156	OE Interchange: 22064233; With 19,000 to 21,000 kb Taper Leaf Springs; Shocks are 1.75in Bore

Chevrolet C4500 Kodiak				
2004-2008			HD1215-0158	With Conventional Cab; Low Profile Vehicle; With 12,000 to 19,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore
2003-2009	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682, 15174298, 15192385, 15588554, 15887728; With Conventional Cab; Steering Axle; Shocks are 1.75in Bore	HD1215-0112	OE Interchange: 15782915, 15185643, 15185644; With Conventional Cab; Drive Axle; With Hendrickson RS-460 Suspension; With 12,000 to 15,000lb Axle with Leaf Springs; Shocks are 1.75in Bore
2003-2009			HD1215-0120	OE Interchange: 88963409; With Conventional Cab; Low Profile Vehicle; With 12,000 to 18,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore

Chevrolet C50				
1990-1990			HD1215-0156	OE Interchange: 22064233; With 19,000 to 21,000 kb Taper Leaf Springs; With Conventional Cab; Shocks are 1.75in Bore
1990-1990			HD1214-0561	OE Interchange: 22064232; Conventional Cab; With 15,000 to 21,000lb Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1990-1990		OE Interchange: 15123676, 15174898, 88982682, 15174298, 15192385, 15588554, 15887728; With Conventional Cab; Steering Axle; Shocks are 1.75in Bore	HD1215-0044	OE Interchange: 22064402; With Conventional Cab; Low Profile Vehicle; With 21,000lb Axle; Taper Leaf Springs Suspension; Shocks are 1.75in Bore
1976-1989	HD1214-0578	OE Interchange: 22002294, 22007752; With 97" Bumper to Back of Cab; With Conventional Cab; Shocks are 1.38in Bore		
1976-1989	HD1215-0089	With Conventional Cab; Shocks are 1.75in Bore	HD1214-0539	OE Interchange: 22012095, 22012166, 4940606; With Conventional Cab; With 97" Bumper to Back of Cab; With 20,800lb or 23,000lb Axle; Shocks are 1.38in Bore
1977-1980	HD1214-0533	OE Interchange: 4975467, 4975494, 22007750; With Conventional Cab; With 5,000 to 7,000lb Axle; Shocks are 1.38in Bore		



FRONT



REAR

APPLICATIONS

Chevrolet C50				
1975-1989	HD1214-0608	OE Interchange: 4975511; With Conventional Cab; With 9,000 to 12,000lb Axle; Shocks are 1.38in Bore		
1975-1980	HD1214-0579	OE Interchange: 22012096, 3192892; Excludes Tilt Cab; With Forward Control Chassis; With 9,000 to 11,000lb Axle; Shocks are 1.38in Bore		
1973-1981	HD1214-0640	OE Interchange: 4940614, 4963854, 4984526; With Conventional Cab; 92" Bumper to Back of Cab; Shocks are 1.38in Bore		
1973-1980	HD1215-0113	OE Interchange: 5552451, 22012090; With Rear Engine; Shocks are 1.75in Bore		
1973-1975	HD1214-0533	OE Interchange: 4975467, 4975494, 22007750; With Conventional Cab; With 5,000 to 7,000lb Axle; Shocks are 1.38in Bore		
1971-1980	HD1214-0539	OE Interchange: 3192890, 4940606, 4940662, 4975497, 22002293, 22007701, 22007751, 22012095; With Conventional or Tilt Cab; With 5,000 or 7,000lb Axle; Shocks are 1.38in Bore	HD1214-0539	OE Interchange: 22012095, 22012166, 4940606; With Conventional Cab; With 97" Bumper to Back of Cab; With 20,800lb or 23,000lb Axle; Shocks are 1.38in Bore
1968-1972	HD1214-0579	OE Interchange: 22012096, 3192892; Excludes Tilt Cab; With Forward Control Chassis; With 9,000 to 11,000lb Axle; Shocks are 1.38in Bore		
1963-1970	HD1214-0539	OE Interchange: 3192890, 4940606, 4940662, 4975497, 22002293, 22007701, 22007751, 22012095; With Conventional or Tilt Cab; With 5,000 or 7,000lb Axle; Shocks are 1.38in Bore		
1960-1989			HD1214-0579	OE Interchange: 3192892, 22012096; 72" Bumper to Back of Cab; With 17201 and 17221 Axle; Shocks are 1.38in Bore

Chevrolet C5500 Kodiak				
2004-2008			HD1215-0158	With Conventional Cab; Low Profile Vehicle; With 12,000 to 19,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore
2003-2009	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682, 15174298, 15192385, 15588554, 15887728; With Conventional Cab; Steering Axle; Shocks are 1.75in Bore	HD1215-0112	OE Interchange: 15185643, 15185644; With Conventional Cab; Drive Axle; 11,000 to 15,000lb Axle with Leaf Spring Suspension; Shocks are 1.75in Bore
2003-2009			HD1215-0120	OE Interchange: 88963409; With Conventional Cab; Low Profile Vehicle; With 12,000 to 18,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Chevrolet C5500 Kodiak

1990-1991	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682, 15174298, 15192385, 15588554, 15887728; With Conventional Cab; Steering Axle; Shocks are 1.75in Bore	HD1214-0561	OE Interchange: 22064232; Conventional Cab; With 15,000 to 21,000lb Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1990-1991	HD1214-0556	OE Interchange: 15588554, 22064230; Steering Axle; Shocks are 1.38in Bore	HD1215-0044	OE Interchange: 22064402; With Conventional Cab; Low Profile Vehicle; With 21,000lb Axle; Taper Leaf Springs Suspension; Shocks are 1.75in Bore
1990-1990			HD1215-0156	OE Interchange: 22064233; With 19,000 to 21,000 kb Taper Leaf Springs; With Conventional Cab; Shocks are 1.75in Bore

Chevrolet C60

1990-1990			HD1215-0156	OE Interchange: 22064233; With 19,000 to 21,000 kb Taper Leaf Springs; With Conventional Cab; Shocks are 1.75in Bore
1990-1990	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682, 15174298, 15192385, 15588554, 15887728; With Conventional Cab; Steering Axle; Shocks are 1.75in Bore	HD1214-0561	OE Interchange: 22064232; Conventional Cab; With 15,000 to 21,000lb Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1990-1990	HD1214-0556	OE Interchange: 15588554, 22064230; Steering Axle; Shocks are 1.38in Bore	HD1215-0044	OE Interchange: 22064402; With Conventional Cab; Low Profile Vehicle; With 21,000lb Axle; Taper Leaf Springs Suspension; Shocks are 1.75in Bore
1980-1989	HD1214-0578	OE Interchange: 22002294, 22007752; With 97" Bumper to Back of Cab; With Conventional Cab; Shocks are 1.38in Bore	HD1214-0579	Shocks are 1.38in Bore
1980-1989	HD1214-0608	OE Interchange: 22002295, 22017530, 22017531, 22007753; With Conventional Cab; With 9,000 to 12,000lb Axle; With 97" Bumper to Back of Cab; Shocks are 1.38in Bore		
1980-1989	HD1215-0089	With Conventional Cab; Shocks are 1.75in Bore	HD1214-0539	OE Interchange: 22012095, 22012166, 4940606; With Conventional Cab; With 97" Bumper to Back of Cab; With 20,800lb or 23,000lb Axle; Shocks are 1.38in Bore
1975-1980	HD1214-0579	OE Interchange: 3192892, 22012096; With Cowl Cab; Excludes School Bus Models; Shocks are 1.38in Bore		
1975-1976	HD1214-0608	OE Interchange: 4975511; With Conventional Cab; With 9,000 to 12,000lb Axle; Shocks are 1.38in Bore		
1973-1980	HD1215-0113	OE Interchange: 5552451, 22012090; With Rear Engine; Shocks are 1.75in Bore	HD1214-0579	Shocks are 1.38in Bore



FRONT



REAR

APPLICATIONS

Chevrolet C60				
1973-1980	HD1214-0533	OE Interchange: 4975467, 4975494, 22007750; With Conventional Cab; With 5,000 to 7,000lb Axle; Shocks are 1.38in Bore	HD1214-0539	OE Interchange: 22012095, 22012166, 4940606; With Conventional Cab; With 97" Bumper to Back of Cab; With 20,800lb or 23,000lb Axle; Shocks are 1.38in Bore
1966-1981	HD1214-0640	OE Interchange: 4940614, 4963854, 4984526; With Conventional Cab; 92" Bumper to Back of Cab; Shocks are 1.38in Bore		
1968-1972	HD1214-0579	OE Interchange: 3192892, 22012096; With Cowl Cab; Excludes School Bus Models; Shocks are 1.38in Bore		
1963-1980	HD1214-0539	OE Interchange: 3192890, 4940606, 4940662, 4975497, 22002293, 22007701, 22007751, 22012095; With Conventional or Tilt Cab; With 5,000 or 7,000lb Axle; Shocks are 1.38in Bore		
1960-1972			HD1214-0579	Shocks are 1.38in Bore

Chevrolet C60 Kodiak				
1990-1996			HD1215-0156	OE Interchange: 22064233; With 19,000 to 21,000 lb Taper Leaf Springs; With Conventional Cab; Shocks are 1.75in Bore
1990-1996	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682, 15174298, 15192385, 15588554, 15887728; With Conventional Cab; Steering Axle; Shocks are 1.75in Bore	HD1214-0561	OE Interchange: 22064232; Conventional Cab; With 15,000 to 21,000lb Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1990-1996	HD1214-0556	OE Interchange: 15588554, 22064230; Steering Axle; Shocks are 1.38in Bore	HD1215-0044	OE Interchange: 22064402; With Conventional Cab; Low Profile Vehicle; With 21,000lb Axle; Taper Leaf Springs Suspension; Shocks are 1.75in Bore

Chevrolet C6500 Kodiak				
2004-2008			HD1215-0158	With Conventional Cab; Low Profile Vehicle; With 12,000 to 19,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore
2003-2009	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682, 15174298, 15192385, 15588554, 15887728; With Conventional Cab; Steering Axle; Shocks are 1.75in Bore	HD1215-0112	OE Interchange: 15782915, 15185643, 15185644; With Conventional Cab; Drive Axle; With Hendrickson RS-460 Suspension; With 12,000 to 15,000lb Axle with Leaf Springs; Shocks are 1.75in Bore
2003-2009			HD1215-0120	OE Interchange: 88963409; With Conventional Cab; Low Profile Vehicle; With 12,000 to 18,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Chevrolet C6500 Kodiak				
1997-2002	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682, 15174298, 15192385, 15588554, 15887728; With Conventional Cab; Steering Axle; Shocks are 1.75in Bore	HD1214-0561	OE Interchange: 22064232; Conventional Cab; With 15,000 to 21,000lb Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1997-2002	HD1214-0556	OE Interchange: 15588554, 22064230; Steering Axle; Shocks are 1.38in Bore	HD1215-0045	OE Interchange: 12474917, 15740554; With Conventional Cab; Drive Axle; With Hendrickson Air Suspension; Shocks are 1.75in Bore
1997-2002			HD1215-0156	OE Interchange: 22064233; With Conventional Cab; Drive Axle; With 23,000lb Axle; Taper Leaf Spring; Shocks are 1.75in Bore
1997-2002			HD1215-0133	OE Interchange: 12474915, 15963161; Drive Axle; With Conventional Cab; With Hendrickson Air Suspension; With 21,000 to 23,000lb Axle; Shocks are 1.75in Bore

Chevrolet C70				
1990-1990	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682, 15174298, 15192385, 15588554, 15887728; With Conventional Cab; Steering Axle; Shocks are 1.75in Bore	HD1214-0561	OE Interchange: 22064232; Conventional Cab; With 15,000 to 21,000lb Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1990-1990	HD1214-0556	OE Interchange: 15588554, 22064230; Steering Axle; Shocks are 1.38in Bore	HD1215-0044	OE Interchange: 22064402; With Conventional Cab; Low Profile Vehicle; With 21,000lb Axle; Taper Leaf Springs Suspension; Shocks are 1.75in Bore
1990-1990			HD1215-0156	OE Interchange: 22064233; With Conventional Cab; With 19,000 to 21,000lb Axle; Taper Leaf Springs; Shocks are 1.75in Bore
1980-1989	HD1214-0608	OE Interchange: 22002295, 22017530, 22017531, 22007753; With Conventional Cab; With 9,000 to 12,000lb Axle; With 97" Bumper to Back of Cab; Shocks are 1.38in Bore		
1980-1980	HD1214-0533	OE Interchange: 4975467, 4975494, 22007750; With Conventional Cab; With 5,000 to 7,000lb Axle; Shocks are 1.38in Bore		
1979-1989	HD1214-0578	OE Interchange: 22002294, 22007752; With 97" Bumper to Back of Cab; With Conventional Cab; Shocks are 1.38in Bore	HD1214-0539	OE Interchange: 22012095, 22012166, 4940606; With Conventional Cab; With 97" Bumper to Back of Cab; With 20,800lb or 23,000lb Axle; Shocks are 1.38in Bore
1979-1989	HD1215-0089	With Conventional Cab; Shocks are 1.75in Bore	HD1214-0579	OE Interchange: 22012096, 22012169, 3192892; With Conventional Cab; Excludes 20,800 and 23,000 Rear Axle; Shocks are 1.38in Bore



FRONT



REAR

APPLICATIONS

Chevrolet C70			
1979-1981	HD1214-0640	OE Interchange: 4940614, 4963854, 4984526; With Conventional Cab; 92" Bumper to Back of Cab; Shocks are 1.38in Bore	
1979-1980	HD1215-0113	OE Interchange: 5552451, 22012090; With Rear Engine; Shocks are 1.75in Bore	
1979-1980	HD1214-0579	OE Interchange: 4975467, 4975494, 22007750, 4975510; With Conventional Cab; Shocks are 1.38in Bore	
1979-1980	HD1214-0539	OE Interchange: 3192890, 4940606, 4940662, 4975497, 22002293, 22007701, 22007751, 22012095; With Conventional or Tilt Cab; With 5,000 or 7,000lb Axle; Shocks are 1.38in Bore	
1960-1961			HD1214-0579 2 Ton; Shocks are 1.38in Bore

Chevrolet C70 Kodiak			
1990-1996	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682, 15174298, 15192385, 15588554, 15887728; With Conventional Cab; Steering Axle; Shocks are 1.75in Bore	HD1214-0561 OE Interchange: 22064232; Conventional Cab; With 15,000 to 21,000lb Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1990-1996	HD1214-0556	OE Interchange: 15588554, 22064230; Steering Axle; Shocks are 1.38in Bore	HD1215-0044 OE Interchange: 22064402; With Conventional Cab; Low Profile Vehicle; With 21,000lb Axle; Taper Leaf Springs Suspension; Shocks are 1.75in Bore
1990-1996			HD1215-0156 OE Interchange: 22064233; With Conventional Cab; With 19,000 to 21,000lb Axle; Taper Leaf Springs; Shocks are 1.75in Bore

Chevrolet C7500 Kodiak			
2004-2008			HD1215-0158 With Conventional Cab; Low Profile Vehicle; With 12,000 to 19,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore
2003-2009	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682, 15174298, 15192385, 15588554, 15887728; With Conventional Cab; Steering Axle; Shocks are 1.75in Bore	HD1215-0112 OE Interchange: 15782915, 15185643, 15185644; With Conventional Cab; Drive Axle; With Hendrickson RS-460 Suspension; With 12,000 to 15,000lb Axle with Leaf Springs; Shocks are 1.75in Bore
2003-2009			HD1215-0120 OE Interchange: 88963409; With Conventional Cab; Low Profile Vehicle; With 12,000 to 18,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore
1997-2002	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682, 15174298, 15192385, 15588554, 15887728; With Conventional Cab; Steering Axle; Shocks are 1.75in Bore	HD1214-0561 OE Interchange: 22064232; Conventional Cab; Drive Axle; 15,000 to 23,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore



FRONT



REAR

APPLICATIONS

Chevrolet C7500 Kodiak

1997-2002	HD1214-0556	OE Interchange: 15588554, 22064230; Steering Axle; Shocks are 1.38in Bore	HD1215-0045	OE Interchange: 12474917, 15740554; With Conventional Cab; Drive Axle; With Hendrickson Air Suspension; Shocks are 1.75in Bore
1997-2002			HD1215-0133	OE Interchange: 12474915, 15963161; Drive Axle; With Conventional Cab; With Hendrickson Air Suspension; With 21,000 to 23,000lb Axle; Shocks are 1.75in Bore
1997-2002			HD1215-0156	OE Interchange: 22064233; With Conventional Cab; Drive Axle; With 23,000lb Axle; Taper Leaf Spring; Shocks are 1.75in Bore

Chevrolet C8500

2004-2008			HD1215-0158	With Conventional Cab; Low Profile Vehicle; With 12,000 to 19,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore
2003-2009	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682, 15174298, 15192385, 15588554, 15887728; With Conventional Cab; Steering Axle; Shocks are 1.75in Bore	HD1215-0112	OE Interchange: 15782915, 15185643, 15185644; With Conventional Cab; Drive Axle; With Hendrickson RS-460 Suspension; With 12,000 to 15,000lb Axle with Leaf Springs; Shocks are 1.75in Bore
2003-2009			HD1215-0120	OE Interchange: 88963409; With Conventional Cab; Low Profile Vehicle; With 12,000 to 18,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore

Chevrolet Express 3500

1996-2002			HD1294-0001	With Dual Rear Wheels
-----------	--	--	-------------	-----------------------

Chevrolet G30

1993-1996	HD1214-0555	With Recreational Package		
1979-1996			HD1214-0594	Cutaway Van; Drive Axle; With Recreational Package
1978-1991			HD1214-0606	Drive Axle; Excludes Cutaway Van; With Recreational Package
1975-1992	HD1214-0555	With Recreational Package	HD1214-0551	OE Interchange: 90044769, 90044770; Tag Axle; With Neway Tag Axle TA-3-CA; Shocks are 1.38in Bore

Chevrolet G30 Van

1970-1970	HD1214-0555	All Models		
-----------	-------------	------------	--	--



FRONT



REAR

Chevrolet P30				
1985-1985			HD1214-0594	Stripped Chassis; With Monobeam Front Suspension
1975-1999	HD1215-0116	(Stripped Chassis) Excludes Monobeam Front Suspension	HD1215-0098	(Stripped Chassis) Drive Axle

Chevrolet P30 Van				
1973-1974	HD1215-0116	Excludes Monobeam Front Suspension	HD1215-0098	All Models

Chevrolet S7				
1987-1989	HD1214-0608	(S7 To 42) OE Interchange: 22017531, 22002295, 22017530; Shocks are 1.38in Bore	HD1214-0539	(S7 to 42) OE Interchange: 22012095, 22012166, 4940606; With Conventional Cab; With 97" Bumper to Back of Cab; With 20,800lb or 23,000lb Axle; Shocks are 1.38in Bore
1987-1989	HD1214-0579	Shocks are 1.38in Bore	HD1214-0579	OE Interchange: 22012096, 22012169, 3192892; Excludes 20,800 and 23,000lb Rear Axle; Shocks are 1.38in Bore

Chevrolet T6500				
2006-2009			HD1215-0158	With 15,000 to 23,000lb Axle; Shocks are 1.75in Bore
2004-2007	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682; Steering Axle; Shocks are 1.75in Bore		
1997-2002	HD1215-0156	OE Interchange: 22064804, 22165187; With Tilt Cab; Steering Axle; FL1 8,000lb Axle; Shocks are 1.75in Bore	HD1215-0156	OE Interchange: 22064233; With Tilt Cab; Drive Axle; With 23,000lb Axle; Taper Leaf Spring; Shocks are 1.75in Bore
1997-2002	HD1215-0156	OE Interchange: 22064804, 22165187; With Tilt Cab; Steering Axle; FL1 8,000lb Axle; Shocks are 1.75in Bore	HD1215-0045	OE Interchange: 12474917, 15740554; With Conventional or Tilt Cab; Drive Axle; With Hendrickson Air Suspension; Shocks are 1.75in Bore
1997-2002	HD1215-0031	Steering Axle; Excludes Low Profile Option; OE Interchange: 22064805 and 22165188; Shocks are 1.75in Bore	HD1214-0561	OE Interchange: 22064232; With Tilt Cab; Drive Axle; 15,000 to 23,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1997-2002			HD1215-0133	OE Interchange: 12474915, 15963161; Drive Axle; With Tilt Cab; With Hendrickson Air Suspension; Shocks are 1.75in Bore

Chevrolet T7500				
2006-2009			HD1215-0158	With 15,000 to 23,000lb Axle; Shocks are 1.75in Bore
2004-2007	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682; Steering Axle; Shocks are 1.75in Bore		

APPLICATIONS



FRONT



REAR

APPLICATIONS

Chevrolet T7500				
1997-2002	HD1215-0156	OE Interchange: 22064804, 22165187; With Tilt Cab; Steering Axle; FL1 8,000lb Axle; Shocks are 1.75in Bore	HD1215-0156	OE Interchange: 22064233; With Tilt Cab; Drive Axle; Taper Leaf Spring; Shocks are 1.75in Bore
1997-2002			HD1215-0045	OE Interchange: 12474917, 15740554; With Conventional or Tilt Cab; Drive Axle; With Hendrickson Air Suspension; Shocks are 1.75in Bore
1997-2002	HD1215-0031	Steering Axle; Excludes Low Profile Option; OE Interchange: 22064805 and 22165188; Shocks are 1.75in Bore	HD1214-0561	OE Interchange: 22064232; With Tilt Cab; Drive Axle; 15,000 to 23,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1997-2002			HD1215-0133	OE Interchange: 12474915, 15963161; Drive Axle; With Tilt Cab; With Hendrickson Air Suspension; Shocks are 1.75in Bore

Chevrolet T8500				
2006-2009			HD1215-0158	With 15,000 to 23,000lb Axle; Shocks are 1.75in Bore
2004-2007	HD1215-0081	OE Interchange: 15123676, 15174898, 88982682; Steering Axle; Shocks are 1.75in Bore		

Chevrolet W4500 Tiltmaster				
1992-2002	HD1214-0604	OE Interchange: 1516302000; Steering Axle; Shocks are 1.38in Bore		
1992-1995	HD1214-0540	OE Interchange: 8970830290, 97083029; Steering Axle; With 13,000lb Axle; Shocks are 1.38in Bore	HD1214-0571	OE Interchange: 9516306662, 94033786; Steering Axle; Shocks are 1.38in Bore

Chevrolet W5500 Tiltmaster				
2003-2003	HD1213-0734	OE Interchange: 1516302191; Shocks are 1.38 in Bore		
1990-2001	HD1213-0734	OE Interchange: 1516302191; Shocks are 1.38 in Bore		

Chevrolet W6500 Tiltmaster				
1987-1996			HD1214-0526	OE Interchange: 1516301670; Drive Axle; Shocks are 1.38in Bore

Crane Carrier Centurion				
1989-2009	HD1215-0171	OE Interchange: 277A1, 277A9; Shocks are 1.75in Bore		
1989-2009	HD1215-0113	OE Interchange: 277A8, 680091; Shocks are 1.75in Bore		
1987-1987	HD1215-0171	OE Interchange: 277A1, 277A9; Shocks are 1.75in Bore		



FRONT



REAR

APPLICATIONS

Crane Carrier Centurion

1987-1987	HD1215-0113	OE Interchange: 277A8, 680091; Shocks are 1.75in Bore		
-----------	-------------	---	--	--

Crane Carrier Century II

1987-1999	HD1215-0171	OE Interchange: 277A1, 277A9; Shocks are 1.75in Bore		
1987-1999	HD1215-0113	OE Interchange: 277A8, 680091; Shocks are 1.75in Bore		

Dodge B300

1975-1980	HD1214-0548	With Recreational Package	HD1214-0551	OE Interchange: 90044769, 90044770; Tag Axle; With Neway Tag Axle TA-3-CA; Shocks are 1.38in Bore
1975-1980			HD1214-0606	Drive Axle; With Recreational Package

Dodge B300 Van

1971-1974	HD1214-0548	With Recreational Package	HD1214-0551	OE Interchange: 90044769, 90044770; Tag Axle; With Neway Tag Axle TA-3-CA; Shocks are 1.38in Bore
1971-1974			HD1214-0606	Drive Axle; With Recreational Package

Dodge B350

1993-1994	HD1214-0548	With Recreational Package		
1981-1994			HD1214-0606	Drive Axle; With Recreational Package
1981-1992	HD1214-0548	With Recreational Package	HD1214-0551	OE Interchange: 90044769, 90044770; Tag Axle; With Neway Tag Axle TA-3-CA; Shocks are 1.38in Bore

Dodge D400

1978-1981	HD1214-0643	Shocks are 1.38in Bore		
-----------	-------------	------------------------	--	--

Dodge M300

1973-1974	HD1214-0645	OE Interchange: 4036892, 3638631		
-----------	-------------	----------------------------------	--	--

Dodge M350

1974-1974	HD1214-0645	OE Interchange: 4036892, 3638631		
-----------	-------------	----------------------------------	--	--

Dodge P300 Van

1966-1974	HD1214-0662	Shocks are 1.38in Bore	HD1214-0575	Shocks are 1.38in Bore
1960-1964	HD1214-0662	Shocks are 1.38in Bore	HD1214-0575	Shocks are 1.38in Bore

Dodge P400 Series

1957-1957	HD1214-0643	Shocks are 1.38in Bore		
-----------	-------------	------------------------	--	--



FRONT



REAR

APPLICATIONS

Dodge P410 Series

1958-1959	HD1214-0643	Shocks are 1.38in Bore		
-----------	-------------	------------------------	--	--

Dodge P420 Series

1958-1959	HD1214-0643	Shocks are 1.38in Bore		
-----------	-------------	------------------------	--	--

Dodge P450 Series

1959-1959	HD1214-0643	Shocks are 1.38in Bore		
-----------	-------------	------------------------	--	--

Dodge Ram 2500

1994-2002	HD1214-0653	(4WD) With 8,800lb GVW	HD1214-0652	(4WD) With 8,800lb GVW
-----------	-------------	------------------------	-------------	------------------------

Dodge Ram 3500

1994-2002	HD1214-0653	(4WD) Cab & Chassis and Standard Cab Models; (RWD) Cab and Chassis With Solid Front Axle	HD1214-0652	(4WD) All Models; (RWD) Cab and Chassis Models Only
-----------	-------------	--	-------------	---

Dodge Ram 3500 Van

1996-2003	HD1214-0548	With Recreational Package	HD1214-0606	Drive Axle; With Recreational Package
-----------	-------------	---------------------------	-------------	---------------------------------------

Dodge Ram 4500

2008-2010			HD1215-0105	OE Interchange: 52014061AA; Shocks are 1.75in Bore
2008-2008			HD1215-0092	OE Interchange: 52014077AB; Shocks are 1.75in Bore

Dodge Ram 5500

2008-2010			HD1215-0105	OE Interchange: 52014061AA; Shocks are 1.75in Bore
2008-2008			HD1215-0092	OE Interchange: 52014077AB; Shocks are 1.75in Bore

Dodge Sprinter 2500

2007-2009			HD1214-0648	With Dual Rear Wheels; Shocks are 1.38in Bore
2003-2009			HD1214-0659	With Single Rear Wheels; Shocks are 1.38in Bore
2003-2006			HD1214-0596	With Dual Rear Wheels; Shocks are 1.38in Bore

Dodge Sprinter 3500

2007-2009			HD1214-0648	With Dual Rear Wheels; Shocks are 1.38in Bore
2003-2009			HD1214-0659	With Single Rear Wheels; Shocks are 1.38in Bore



FRONT



REAR

Dodge Sprinter 3500			
2003-2006		HD1214-0596	With Dual Rear Wheels; Shocks are 1.38in Bore

Ford AT9513				
1996-1998	HD1215-0128	OE Interchange: F6HT18045AC, F6HT18045HB, F6HT18045HC; With 113" or 122" BBC; With 8,500 to 12,000lb Axle; 54" Taper Leaf Springs; Shocks are 1.75in Bore	HD1215-0045	OE Interchange: 4790228, F6HT18080FC; 113" & 122" BBC; With Hendrickson HA-120 & HA-230 Air Suspension; Shocks are 1.75in Bore
1996-1998	HD1214-0562	OE Interchange: F6HT18045CC; 113" & 122" BBC; With 14,600 to 16,000lb Axle; With 54" Multi Leaf Spring Suspension; Shocks are 1.38in Bore	HD1215-0042	OE Interchange: 90045099, F6HT18080EA; 113" & 122" BBC; With Neway AD123 Air Suspension; 1.75in Bore
1996-1998	HD1213-0707	(Cab Shock) OE Interchange: F6HT5K-407AB, F7HT5K407BA; With 113" and 122" BBC	HD1215-0067	OE Interchange: 572412, F6HT18080DA, and F6H218125B; 113" or 122" BBC; With Hendrickson HAS-40LH Air Suspension; 1.75in Bore
1996-1998	HD1214-0658	OE Interchange: F6HT18045BC; 113" & 122" BBC; With 12,000 - 13,200lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
1996-1998	HD1215-0157	OE Interchange: F6HT18045EB, F6HT18045EC, F6HT18045GB, F6HT-18045GC; With 12,000 to 14,600lb Axle; With 54" or 60" Taper Springs; Shocks are 1.75in Bore	HD1215-0036	OE Interchange: F4HT18080BA, F6HT18080JA; With 21,000 or 23,000lb Axle; Shocks are 1.75in Bore
1996-1998			HD1215-0029	OE Interchange: F4HT18080AB, F6HT18080CA; With 113" or 112" BBC; With 17,500, 19,000, or 23,000lb Axle; Shocks are 1.75in Bore

Ford AT9522				
1997-1998	HD1215-0128	OE Interchange: F6HT18045AC, F6HT18045HB, F6HT18045HC; With 113" or 122" BBC; With 8,500 to 12,000lb Axle; 54" Taper Leaf Springs; Shocks are 1.75in Bore	HD1215-0045	OE Interchange: 4790228, F6HT18080FC; 113" & 122" BBC; With Hendrickson HA-120 & HA-230 Air Suspension; Shocks are 1.75in Bore
1997-1998	HD1214-0562	OE Interchange: F6HT18045CC; 113" & 122" BBC; With 14,600 to 16,000lb Axle; With 54" Multi Leaf Spring Suspension; Shocks are 1.38in Bore	HD1215-0042	OE Interchange: 90045099, F6HT18080EA; 113" & 122" BBC; With Neway AD123 Air Suspension; 1.75in Bore
1997-1998	HD1213-0707	(Cab Shock) OE Interchange: F6HT5K-407AB, F7HT5K407BA; With 113" and 122" BBC	HD1215-0067	OE Interchange: 572412, F6HT18080DA, and F6H218125B; 113" or 122" BBC; With Hendrickson HAS-40LH Air Suspension; 1.75in Bore
1997-1998	HD1214-0658	OE Interchange: F6HT18045BC; 113" & 122" BBC; With 12,000 - 13,200lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore

APPLICATIONS



FRONT



REAR

APPLICATIONS

Ford AT9522

1997-1998	HD1215-0157	OE Interchange: F6HT18045EB, F6HT18045EC, F6HT18045GB, F6HT-18045GC; With 12,000 to 14,600lb Axle; With 54" or 60" Taper Springs; Shocks are 1.75in Bore	HD1215-0036	OE Interchange: F4HT18080BA, F6HT18080JA; With 21,000 or 23,000lb Axle; Shocks are 1.75in Bore
1997-1998			HD1215-0029	OE Interchange: F4HT18080AB, F6HT18080CA; With 113" or 112" BBC; With 17,500, 19,000, or 23,000lb Axle; Shocks are 1.75in Bore

Ford B600

1991-1994	HD1214-0559	OE Interchange: E0HT18045AA; Shocks are 1.38in Bore		
1986- 1990			HD1215-0107	(Rear Forward) OE Interchange: E0HT18080AA; Shocks are 1.75in Bore;
1980-1990	HD1214-0559	OE Interchange: E0HT18045AA; Shocks are 1.38in Bore	HD1214-0563	OE Interchange: D7HT18080DA; Shocks are 1.38in Bore

Ford B700

1994-1994	HD1214-0660	School Bus; Cab Forward; OE Interchange: F4HT18045CB; With 52 Inch Multi Leaf Spring; Shocks are 1.38in Bore		
1994-1994	HD1215-0068	OE Interchange: F4HT18045EA; School Bus- Cab Forward; With 14,600lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0036	OE Interchange: F4HT18080BA; With 21,000lb Taper Leaf Spring; Shocks are 1.75in Bore; Bus (School) -Cab Forward
1991-1994	HD1214-0559	OE Interchange: F1HT18045AA; Shocks are 1.38in Bore		
1986-1990			HD1215-0107	OE Interchange: E0HT18080AA; Shocks are 1.75in Bore;
1980-1990	HD1214-0559	OE Interchange: F1HT18045AA; Shocks are 1.38in Bore	HD1214-0563	OE Interchange: D7HT18080DA; Shocks are 1.38in Bore

Ford B7000

1983-1987	HD1214-0559	OE Interchange: E0HT18045AA; Shocks are 1.38in Bore	HD1214-0563	OE Interchange: D7HT18080DA; Shocks are 1.38in Bore
-----------	-------------	---	-------------	---

Ford B800

1995-1997	HD1214-0660	School Bus; Cab Forward; OE Interchange: F4HT18045CB; With 52 Inch Multi Leaf Spring; Shocks are 1.38in Bore		
1995-1997	HD1215-0068	OE Interchange: F4HT18045EA; With 14,600lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0036	OE Interchange: F4HT18080BA; With 21,000lb Taper Leaf Spring; Shocks are 1.75in Bore



FRONT



REAR

Ford C600			
1980-1986	HD1214-0595	OE Interchange: D7HT18045JA; With 31,000lb Springs; With 7,000lb Axle; Shocks are 1.38in Bore	
1980-1986	HD1214-0564	OE Interchange: D2EF18045AA; With 4,040 to 12,000lb Axle; Shocks are 1.38in Bore	
Ford C700			
1980-1986	HD1214-0595	OE Interchange: D7HT18045JA; With 31,000lb Springs; With 7,000lb Axle; Shocks are 1.38in Bore	
1980-1986	HD1214-0564	OE Interchange: D2EF18045AA; With 4,040 to 12,000lb Axle; Shocks are 1.38in Bore	
Ford C7000			
1980-1986	HD1214-0595	OE Interchange: D7HT18045JA; With 31,000lb Springs; With 7,000lb Axle; Shocks are 1.38in Bore	
1980-1986	HD1214-0564	OE Interchange: D2EF18045AA; With 4,040 to 12,000lb Axle; Shocks are 1.38in Bore	
Ford C800			
1980-1989	HD1214-0595	OE Interchange: D7HT18045JA; With 31,000lb Springs; With 7,000lb Axle; Shocks are 1.38in Bore	
1980-1989	HD1214-0564	OE Interchange: D2EF18045AA; With 4,040 to 12,000lb Axle; Shocks are 1.38in Bore	
Ford C8000			
1988-1990	HD1214-0595	OE Interchange: D7HT18045JA; With 31,000lb Springs; With 7,000lb Axle; Shocks are 1.38in Bore	
1981-1986	HD1214-0595	OE Interchange: D7HT18045JA; With 31,000lb Springs; With 7,000lb Axle; Shocks are 1.38in Bore	
Ford CF6000			
1986-1990	HD1215-0135	OE Interchange: E5HT18045AA; Brazil Built; Shocks are 1.75in Bore	
Ford CF7000			
1992-1994	HD1213-0705	(Cab Shock) OE Interchange: F2HT-5K407AA	
1986-1997	HD1215-0135	OE Interchange: 87H1118045AA, E5HT18045AA; Brazil Built; Shocks are 1.75in Bore	

APPLICATIONS



FRONT



REAR

APPLICATIONS

Ford CF8000

1992-1997	HD1215-0135	OE Interchange: F2HT18045CA, F2HT-18045BA; Shocks are 1.75in Bore		
-----------	-------------	---	--	--

Ford CL9000

1990-1991			HD1215-0133	OE Interchange: 4790213; With Hendrickson Air Suspension; Shocks are 1.75in Bore
1981-1991	HD1215-0135	OE Interchange: D7HT18045NA; Shocks are 1.75in Bore		
1981-1989			HD1214-0530	OE Interchange: D7HA18080AA; With Tandem Rear Axle; With Neway Air Suspension; Shocks are 1.38in Bore

Ford CLT9000

1981-1991	HD1215-0135	OE Interchange: F1HT18045NA, D7HT-18045NA; Shocks are 1.75in Bore		
1990-1991			HD1215-0133	OE Interchange: 4790213; With Hendrickson Air Suspension; Shocks are 1.75in Bore
1981-1989			HD1214-0530	OE Interchange: D7HA18080AA; With Tandem Rear Axle; With Neway Air Suspension; Shocks are 1.38in Bore

Ford E-150

2008-2014	HD1214-0638	All Models	HD1214-0601	All Models
-----------	-------------	------------	-------------	------------

Ford E-150 Econoline

2008-2008	HD1214-0638	All Models	HD1214-0601	All Models
-----------	-------------	------------	-------------	------------

Ford E-250

2003-2014	HD1214-0638	All Models	HD1214-0601	All Models
2003-2004	HD5113-0017	With Original Equipment Steering Damper		

Ford E-250 Econoline

1996-2002	HD5113-0017	With Original Equipment Steering Damper		
1992-2002	HD1214-0638	All Models	HD1214-0601	All Models

Ford E-350 Club Wagon

2003-2005	HD5113-0017	With Original Equipment Steering Damper		
2002-2005	HD1214-0529	With Ambulance or Recreational Package	HD1214-0527	With Ambulance or Recreational Package
2002-2005	HD1214-0638	All Models	HD1294-0003	Load adjusting; For Severe Service Units; For Towing and Hauling
2002-2005			HD1214-0601	All Models



FRONT



REAR

APPLICATIONS

Ford E-350 Econoline

1992-2000		With Ambulance or Recreational Package	HD1214-0527	With Ambulance or Recreational Package
1992-2000	HD1214-0638	All Models	HD1294-0003	Load adjusting; For Severe Service Units; For Towing and Hauling
1992-2000			HD1214-0601	All Models
1992-1998	HD5113-0017	With Original Equipment Steering Damper		
1975-1991	HD1214-0598	With Recreational Package; With Ambulance Package	HD1214-0551	OE Interchange: 90044769, 90044770; Tag Axle; With Neway Tag Axle TA-3-CA; Shocks are 1.38in Bore
1975-1991	HD1294-0004	Drive Axle	HD1214-0646	Drive Axle; With Recreational Package; With Ambulance Package

Ford E-350 Econoline Club Wagon

1992-2002		With Ambulance or Recreational Package	HD1214-0527	With Ambulance or Recreational Package
1992-2002	HD1214-0638	All Models	HD1294-0003	Load adjusting; For Severe Service Units; For Towing and Hauling
1992-2002	HD5113-0017	With Original Equipment Steering Damper	HD1214-0601	All Models
1977-1991	HD1214-0598	With Recreational Package; With Ambulance Package	HD1214-0551	OE Interchange: 90044769, 90044770; Tag Axle; With Neway Tag Axle TA-3-CA; Shocks are 1.38in Bore
1977-1991	HD1294-0004	Drive Axle	HD1214-0646	Drive Axle; With Recreational Package; With Ambulance Package

Ford E-350 Super Duty

1999-2019	HD5113-0017	With Original Equipment Steering Damper		
1999-2018	HD1214-0638	All Models	HD1294-0003	Load adjusting; For Severe Service Units; For Towing and Hauling
1999-2018			HD1214-0601	Excludes Ambulance Package
1999-2017		With Ambulance or Recreational Package	HD1214-0527	With Ambulance or Recreational Package

Ford E-450 Econoline Super Duty

2000-2002	HD5113-0017	With Original Equipment Steering Damper	HD1214-0527	All Models
2000-2002	HD1214-0638	All Models	HD1294-0003	Load adjusting; For Severe Service Units; For Towing and Hauling
2000-2002			HD1214-0601	All Models

Ford E-450 Super Duty

2007-2017			HD1215-0008	With Crew Cab or Extended Cab Models; Severe Duty; Shocks are 1.75in Bore
2003-2019	HD5113-0017	With Original Equipment Steering Damper		
2003-2017		All Models	HD1214-0527	All Models



FRONT



REAR

APPLICATIONS

Ford E-450 Super Duty

2003-2017			HD1294-0003	Load adjusting; For Severe Service Units; For Towing and Hauling
2003-2016	HD1214-0638	All Models	HD1214-0601	All Models

Ford Econoline Super Duty

1996-1999	HD1214-0529	With Ambulance or Recreational Package	HD1214-0527	With Ambulance or Recreational Package
1996-1999	HD5113-0017	With Original Equipment Steering Damper	HD1294-0003	Load adjusting; For Severe Service Units; For Towing and Hauling
1996-1999	HD1214-0638	All Models	HD1214-0601	Excludes Ambulance Package

Ford Excursion

2005-2005	HD5113-0017	(RWD) With Original Equipment Steering Damper		
-----------	--------------------	---	--	--

Ford F-250

1992-1996	HD5113-0117	(RWD) With Original Equipment Steering Damper		
-----------	--------------------	---	--	--

Ford F-250 Super Duty

2017-2018	HD1214-0649	(4WD)		
2005-2016	HD1214-0649	(4WD)	HD1214-0651	(4WD)
1999-2010	HD5113-0017	(RWD) With Original Equipment Steering Damper		
1999-2004			HD1214-0650	(4WD)

Ford F-350

1992-1997	HD5113-0017	(RWD) With Original Equipment Steering Damper		
-----------	--------------------	---	--	--

Ford F-350 Super Duty

2008-2018	HD1214-0649	(4WD)		
2005-2007	HD1214-0649	(4WD)	HD1214-0651	(4WD) With Dual Rear Wheels; Excludes Cab & Chassis Models
1999-2010	HD5113-0017	(RWD) With Original Equipment Steering Damper		
1999-2004			HD1214-0650	(4WD)

Ford F-450 Super Duty

2005-2019	HD1215-0006	Shocks are 1.75in Bore		
2007-2017			HD1214-0651	Excludes Cab & Chassis Models
2005-2016			HD1215-0050	Severe Duty; Shocks are 1.75in Bore
1999-2004			HD1214-0650	All Models



FRONT



REAR

Ford F-550 Super Duty

2005-2019	HD1215-0006	Shocks are 1.75in Bore		
2005-2016			HD1215-0050	Severe Duty; Shocks are 1.75in Bore
1999-2004			HD1214-0650	All Models

Ford F500

1975-1977	HD1214-0595	Shocks are 1.38in Bore	HD1214-0568	Shocks are 1.38in Bore
-----------	-------------	------------------------	-------------	------------------------

Ford F53

2011-2017	HD1215-0093	All Models	HD1215-0101	All Models
2006-2009	HD1215-0093	All Models	HD1215-0101	All Models
1999-2004	HD5113-0015	All Models		
1999-2004	HD1215-0093	All Models	HD1215-0101	All Models
1992-1997	HD5113-0015	All Models		
1988-1997	HD1215-0093	All Models	HD1215-0130	Drive Axle

Ford F59

1992-1997	HD5113-0015	All Models		
1988-1997	HD1215-0093	All Models	HD1215-0130	Drive Axle

Ford F600

1990-1990	HD1214-0550	OE Interchange: D2HF18045AA; D7HT-18045CA; 9,000 to 12,000lb Axle; With Heavy Duty Suspension; Shocks are 1.38in Bore	HD1215-0029	OE Interchange: E6HT18080AA; Shocks are 1.75in Bore
1989-1994	HD1215-0078	OE Interchange: E9HS18045AA; Low Profile Vehicle; Shocks are 1.75in Bore		
1988-1990			HD1215-0121	OE Interchange: E8HS18080AA; Shocks are 1.75in Bore
1986-1989	HD1215-0088	OE Interchange: F6HT18045MA; Low Profile Vehicle; Shocks are 1.75in Bore	HD1215-0029	OE Interchange: E6HT18080AA; Shocks are 1.75in Bore
1983-1989	HD1214-0550	OE Interchange: D2HF18045AA; D7HT-18045CA; 9,000 to 12,000lb Axle; With Heavy Duty Suspension; Shocks are 1.38in Bore		
1980-1990			HD1214-0563	OE Interchange: D7HT18080DA, D7HF18080AA; 17,000 to 18,000lb Rear Axle; Shocks are 1.38in Bore
1980-1990			HD1214-0568	OE Interchange: C7PF18077A, D2TF18080HA, D7HT18080BA; With 13,000 to 15,000lb Axle; Shocks are 1.38in Bore

APPLICATIONS



FRONT



REAR

Ford F600				
1970-1979	HD1214-0595	OE Interchange: D2HT18045GA, D2T-F18045GA; With 5,500 to 9,000lb Axle; Shocks are 1.38in Bore		

Ford F650					
APPLICATIONS	2016-2019			HD1215-0083	
	2016-2019			HD1215-0170	OE Interchange: FC4Z18125A; With 13,500, 15,500, or 19,000lb multi Leaf Springs; Shocks are 1.75in Bore
	2016-2017	HD1215-0148	OE Interchange: FC4Z18124A, FC-4C18124B; Shocks are 1.75in Bore		
	2015-2015	HD1215-0022	OE Interchange: 4C4Z18124RA; With 12,000-13,200lb Front Suspension; Shocks are 1.75in Bore		
	2015-2015	HD1215-0095	OE Interchange: 3584117C2, 4C4Z18124P, AA615, 3584116C1, 3584116C2, 4C4Z18124QA1 AA616; Shocks are 1.75in Bore		
	2010-2013	HD1215-0095	OE Interchange: 3584117C2, 4C4Z18124P, AA615, 3584116C1, 3584116C2, 4C4Z18124QA1 AA616; Shocks are 1.75in Bore		
	2010-2011			HD1215-0055	OE Interchange: 3578858C1, 3578858C2, and 4C4Z18125DA; Shocks are 1.75in Bore
	2005-2007	HD1215-0147	OE Interchange: 3553628C1, 3553628C2; Shocks are 1.75in Bore		
	2004-2011			HD1215-0063	OE Interchange: 501906C92, 4C4Z18125B, 4C4018080BA; Shocks are 1.38in Bore
	2004-2009			HD1215-0073	OE Interchange: 4C4Z18125CA, ASH1105, 606753; Shocks are 1.75in Bore
	2004-2009	HD1215-0095	OE Interchange: 3584117C2, 4C4Z18124P, AA615, 3584116C1, 3584116C2, 4C4Z18124QA1 AA616; Shocks are 1.75in Bore	HD1215-0055	OE Interchange: 3578858C1, 3578858C2, and 4C4Z18125DA; Shocks are 1.75in Bore
	2000-2013	HD1215-0022	OE Interchange: 4C4Z18124RA; With 12,000-13,200lb Front Suspension; Shocks are 1.75in Bore		
	2000-2003	HD1215-0123	OE Interchange: F81A18045PD, XC3518045AD, XC3518045JA; Shocks are 1.75in Bore		
2000-2003	HD1215-0095	OE Interchange: 3584117C2, 4C4Z18124P, AA615, 3584116C1, 3584116C2, 4C4Z18124QA1 AA616; Shocks are 1.75in Bore			



FRONT



REAR

Ford F650			
2000-2003	HD1215-0089	OE Interchange: F81A18080ZC; With 12,000lb Axle; Shocks are 1.75in Bore	HD1215-0059
			OE Interchange: 1C4418080AA; With Hendrickson HAS-190 Air Suspension; Shocks are 1.75in Bore

Ford F700			
1996-1997	HD1215-0128	OE Interchange: F6HT18045AA; With Multi-Leaf Spring Suspension; Shocks are 1.75in Bore	
1994-1997	HD1214-0660	OE Interchange: F4HT18045CB; With Multi Leaf Spring; With 4,500 to 13,200lb Axle; Shocks are 1.38in Bore	
1994-1997	HD1215-0043	OE Interchange: F4HT18045AB, F4HT18045AC; With 2700, 3300, 3800, 4000, 6000, 7000, 8500, and 9000lb Axle; Shocks are 1.75in Bore	HD1215-0029
1994-1997	HD1215-0088	OE Interchange: F2HT18045DA; Low Profile Vehicle; Shocks are 1.75in Bore	
1991-1994	HD1215-0078	OE Interchange: E9HS18045AA; Low Profile Vehicle; Shocks are 1.75in Bore	HD1215-0029
1990-1990	HD1214-0550	OE Interchange: D2HF18045AA; D7HT-18045CA; 9,000 to 12,000lb Axle; With Heavy Duty Suspension; Shocks are 1.38in Bore	HD1215-0029
1989-1989	HD1215-0078	OE Interchange: E9HS18045AA; Low Profile Vehicle; Shocks are 1.75in Bore	HD1215-0029
1988-1990			HD1215-0121
1986-1988			HD1215-0029
1983-1989	HD1214-0550	OE Interchange: D2HF18045AA; D7HT-18045CA; 9,000 to 12,000lb Axle; With Heavy Duty Suspension; Shocks are 1.38in Bore	
1980-1990			HD1214-0563
1973-1990			HD1214-0568
1973-1979	HD1214-0595	OE Interchange: D2HT18045GA, D2T-F18045GA, 52HF18045CA; With 5,500 to 9,000lb Axle; Shocks are 1.38in Bore	

APPLICATIONS



FRONT



REAR

APPLICATIONS

Ford F700				
1973-1979	HD1214-0564	OE Interchange: D2EF18045AA, B2HT-18045BA, D2TF18045AA; With 9,000lb Axle; Shocks are 1.38in Bore		
1970-1970	HD1214-0595	OE Interchange: D2HT18045GA, D2T-F18045GA, 52HF18045CA; With 5,500 to 9,000lb Axle; Shocks are 1.38in Bore	HD1214-0568	OE Interchange: C7PF18077A, D2TF18080HA, D7HT18080BA; Shocks are 1.38in Bore

Ford F750				
2016-2019			HD1215-0083	OE Interchange: FC4Z18125D; with Rear Air Suspension; With 19,000-23,000lb Axle; Shocks are 1.75in Bore
2016-2019			HD1215-0170	OE Interchange: FC4Z18125A; With 13,500, 15,500, or 19,000lb multi Leaf Springs; Shocks are 1.75in Bore
2016-2017	HD1215-0148	OE Interchange: FC4Z18124A, FC-4C18124B; Shocks are 1.75in Bore		
2015-2015	HD1215-0022	OE Interchange: 4C4Z18124RA; With 12,000-13,200lb Front Suspension; Shocks are 1.75in Bore		
2015-2015	HD1215-0095	OE Interchange: 3584117C2, 4C4Z18124P, AA615, 3584116C1, 3584116C2, 4C4Z18124QA1 AA616; Shocks are 1.75in Bore		
2010-2013	HD1215-0095	OE Interchange: 3584117C2, 4C4Z18124P, AA615, 3584116C1, 3584116C2, 4C4Z18124QA1 AA616; Shocks are 1.75in Bore		
2005-2007	HD1215-0147	OE Interchange: 3553628C1, 3553628C2; Shocks are 1.75in Bore		
2004-2011			HD1215-0063	OE Interchange: 501906C92, 4C4Z18125B, 4C4018080BA; Shocks are 1.38in Bore
2004-2009	HD1215-0095	OE Interchange: 3584117C2, 4C4Z18124P, AA615, 3584116C1, 3584116C2, 4C4Z18124QA1 AA616; Shocks are 1.75in Bore	HD1215-0073	OE Interchange: 4C4Z18125CA, ASH1105, 606753; Shocks are 1.75in Bore
2000-2013	HD1215-0022	OE Interchange: 4C4Z18124RA; With 12,000-13,200lb Front Suspension; Shocks are 1.75in Bore		
2000-2003	HD1215-0095	OE Interchange: 3584117C2, 4C4Z18124P, AA615, 3584116C1, 3584116C2, 4C4Z18124QA1 AA616; Shocks are 1.75in Bore		
2000-2003	HD1215-0123	OE Interchange: F81A18045PD, XC3518045AD, XC3518045JA; Shocks are 1.75in Bore		



FRONT



REAR

Ford F750				
2000-2003	HD1215-0089	OE Interchange: F81A18080ZC; With 12,000lb Axle; Shocks are 1.75in Bore	HD1215-0059	OE Interchange: 1C4418080AA; With Hendrickson HAS-190 Air Suspension; Shocks are 1.75in Bore

Ford F800				
1994-1997	HD1214-0660	OE Interchange: F4HT18045CB; With Multi Leaf Spring; With 4,500 to 13,200lb Axle; Shocks are 1.38in Bore		
1994-1997	HD1215-0088	OE Interchange: F2HT18045DA; Low Profile Vehicle; Shocks are 1.75in Bore		
1994-1997	HD1215-0043	OE Interchange: F4HT18045AB, F4HT18045AC; With 2700, 3300, 3800, 4000, 6000, 7000, 8500, and 9000lb Axle; Shocks are 1.75in Bore		
1990-1990	HD1215-0078	OE Interchange: F1HT18045AA; Shocks are 1.75in Bore		
1988-1990			HD1215-0121	OE Interchange: E8HS18080AA; Shocks are 1.75in Bore
1986-1997			HD1215-0029	OE Interchange: F4HT18080AA, F4HT18080AB, and E6HT18080AA; With Taper Leaf Spring; Shocks are 1.75in Bore
1983-1990	HD1214-0550	OE Interchange: D2HF18045AA; D7HT-18045CA; 9,000 to 12,000lb Axle; With Heavy Duty Suspension; Shocks are 1.38in Bore	HD1214-0563	OE Interchange: D7HT18080DA, D7HF18080AA; 17,000 to 18,000lb Rear Axle; Shocks are 1.38in Bore
1981-1990			HD1214-0568	OE Interchange: D7HT18080BA; With 13,000 to 15,000lb Axle; Shocks are 1.38in Bore
1980-1982			HD1214-0563	OE Interchange: D7HT18080DA, D7HF18080AA; 17,000 to 18,000lb Rear Axle; Shocks are 1.38in Bore

Ford FT900				
1996-1997	HD1215-0128	OE Interchange: F6HT18045AA; With Multi-Leaf Spring Suspension; Shocks are 1.75in Bore		
1994-1995	HD1214-0660	OE Interchange: F4HT18045CB; With Multi Leaf Spring; With 4,500 to 13,200lb Axle; Shocks are 1.38in Bore		
1994-1997	HD1215-0068	OE Interchange: F4HT18045EA; With 14,600lb Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
1994-1997	HD1215-0043	OE Interchange: F4HT18045AB; With 6000, 7000, 8500, and 9000lb Axle; Shocks are 1.75in Bore	HD1215-0029	OE Interchange: F4HT18080AA; With 15,000lb Taper Leaf Spring; Or 19,000lb Leaf Springs; Shocks are 1.75in Bore

APPLICATIONS



FRONT



REAR

APPLICATIONS

Ford FT900				
1994-1997	HD1215-0088	Low Profile Vehicle; Shocks are 1.75in Bore	HD1215-0036	OE Interchange: F4HT18080BA; With 21,000lb Axle; Shocks are 1.75in Bore
1990-1993	HD1215-0078	OE Interchange: E9HS18045AA, F1HT18045AA; Low Profile Vehicle; Shocks are 1.75in Bore		

Ford L800				
1981-1984	HD1214-0564	OE Interchange: D0HA18045E, D2HF18045DA, D7HT18045EA, D2HT18045BA, D2EF18045AA, D2K-F18045AA; With 7,000 to 12,000lb Axle; Shocks are 1.38in Bore		
1981-1984	HD1214-0559	OE Interchange: D2HF18045BA, D7HT-18045DA; With 7,000 to 16,000lb Axle; Shocks are 1.38in Bore		
1981-1984	HD1214-0550	OE Interchange: D2HF18045AA; With 7,000 to 16,000lb Axle; Shocks are 1.38in Bore		

Ford L8000				
1981-1988	HD1214-0564	OE Interchange: D2KF18045AA; With 7,000 to 12,000lb Axle; Shocks are 1.38in Bore	HD1215-0133	OE Interchange: D7HT18045BA; With Hendrickson Air Suspension; Shocks are 1.75in Bore
1981-1985	HD1214-0550	OE Interchange: D2HF18045AA; With 7,000 to 16,000lb Axle; Shocks are 1.38in Bore		

Ford L8000F				
1994-1997			HD1215-0036	OE Interchange: F4HT18080BA; With 21,000lb Axle; With 46" Taper Leaf Spring; Shocks are 1.75in Bore
1991-1997	HD1215-0134	OE Interchange: F1HT18045RA, F1HT18045RB; With 58" Parabolic Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
1991-1997	HD1214-0564	OE Interchange: F1HT18045DA, F1HT-18045DB; 4,500 to 16,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore	HD1215-0133	OE Interchange: D7HT18045BA; With Hendrickson Air Suspension; Shocks are 1.75in Bore

Ford L8501				
1997-1997	HD1215-0157	OE Interchange: F6HT18045EB, F6HT18045EC, F6HT18045GB, F6HT-18045GC; With 12,000 to 14,600lb Axle; With 54" or 60" Taper Springs; 101", 113", or 122" BBC; Shocks are 1.75in Bore	HD1215-0045	OE Interchange: 4790228, F6HT18080FC; 113" & 122" BBC; With Hendrickson HA-120 & HA-230 Air Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Ford L8501				
1997-1997	HD1214-0562	OE Interchange: F6HT18045CC; 101", 113", or 122" BBC; With 14,600 or 16,000lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0042	OE Interchange: 90045099, F6HT18080EA; With Neway AD123 Air Suspension; Shocks are 1.75in Bore
1997-1997	HD1214-0658	OE Interchange: F6HT18045BC; 101", 113", & 122" BBC; With 12,000 - 13,200lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0067	OE Interchange: 572412, F6HT18080DA, and F6H218125B; 101", 113" or 122" BBC; With Hendrickson HAS-40LH Air Suspension; 1.75in Bore
1997-1997			HD1215-0029	OE Interchange: F4HT18080AB, F6HT18080CA, and XC4518080AA; With 101", 113", or 122" BBC; With 15,000, 17,500, 19,000, or 23,000lb Axle; Shocks are 1.75in Bore
1997-1997	HD1215-0128	OE Interchange: F6HT18045HB, F6HT18045HC; With 101", 113", and 122" BBC; With 8,500 to 9,000lb Axle; 54" Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0036	OE Interchange: F4HT18080BA, F6HT18080JA; With 101", 113", or 122" BBC; With 21,000 or 23,000lb Axle; With 46" or 52" Taper Leaf Spring; Shocks are 1.75in Bore

Ford L8511				
1998-1998			HD1215-0042	OE Interchange: 90045099, F6HT18080EA; With Neway AD123 Air Suspension; Shocks are 1.75in Bore

Ford L8513				
1996-1998			HD1215-0042	OE Interchange: 90045099, F6HT18080EA; With Neway AD123 Air Suspension; Shocks are 1.75in Bore

Ford L900				
1981-1981	HD1214-0564	OE Interchange: D2KF18045AA; With 7,000 to 12,000lb Axle; Shocks are 1.38in Bore		
1981-1981	HD1214-0550	OE Interchange: D2HF18045AA; With 7,000 to 16,000lb Axle; Shocks are 1.38in Bore		
1981-1981	HD1214-0559	OE Interchange: D2HF18045BA, D7HT-18045DA; With 7,000 to 16,000lb Axle; Shocks are 1.38in Bore		

Ford L9000				
1994-1997			HD1215-0036	OE Interchange: F4HT18080BA; With 21,000lb Axle; With 46" Taper Leaf Spring; Shocks are 1.75in Bore
1991-1997	HD1214-0595	OE Interchange: F1HT18045DB; With 4,500 to 16,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore		



FRONT

REAR



APPLICATIONS

Ford L9000				
1991-1997	HD1215-0134	OE Interchange: F1HT18045RA, F1HT18045RB; With 58" Parabolic Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
1981-1990	HD1214-0550	OE Interchange: D2HF18045AA; With 7,000 to 16,000lb Axle; Shocks are 1.38in Bore		

Ford L9501				
1997-1997	HD1215-0128	OE Interchange: F6HT18045HB, F6HT18045HC; With 101", 113", and 122" BBC; With 8,500 to 9,000lb Axle; 54" Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0045	OE Interchange: 4790228, F6HT18080FC; 113" & 122" BBC; With Hendrickson HA-120 & HA-230 Air Suspension; Shocks are 1.75in Bore
1997-1997	HD1214-0562	OE Interchange: F6HT18045CC; 101", 113", or 122" BBC; With 14,600 or 16,000lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0042	OE Interchange: 90045099, F6HT18080EA; With Neway AD123 Air Suspension; Shocks are 1.75in Bore
1997-1997	HD1214-0658	OE Interchange: F6HT18045BC; 113" & 122" BBC; With 12,000 - 13,200lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0067	OE Interchange: 572412, F6HT18080DA, and F6H218125B; 101", 113" or 122" BBC; With Hendrickson HAS-40LH Air Suspension; 1.75in Bore
1997-1997	HD1215-0157	OE Interchange: F6HT18045EB, F6HT18045EC, F6HT18045GB, F6HT-18045GC; With 12,000 to 14,600lb Axle; With 54" or 60" Taper Springs; 101", 113", or 122" BBC; Shocks are 1.75in Bore	HD1215-0029	OE Interchange: F4HT18080AB, F6HT18080CA, and XC4518080AA; With 101", 113", or 122" BBC; With 15,000, 17,500, 19,000, or 23,000lb Axle; Shocks are 1.75in Bore
1997-1997			HD1215-0036	OE Interchange: F4HT18080BA, F6HT18080JA; With 101", 113", or 122" BBC; With 21,000 or 23,000lb Axle; With 46" or 52" Taper Leaf Spring; Shocks are 1.75in Bore

Ford L9513				
1996-1997	HD1215-0128	OE Interchange: F6HT18045HB, F6HT18045HC; With 101", 113", and 122" BBC; With 8,500 to 9,000lb Axle; 54" Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0045	OE Interchange: 4790228, F6HT18080FC; 113" & 122" BBC; With Hendrickson HA-120 & HA-230 Air Suspension; Shocks are 1.75in Bore
1996-1997	HD1214-0562	OE Interchange: F6HT18045CC; 101", 113", or 122" BBC; With 14,600 or 16,000lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0042	OE Interchange: 90045099, F6HT18080EA; With Neway AD123 Air Suspension; Shocks are 1.75in Bore
1996-1997	HD1214-0658	OE Interchange: F6HT18045BC; 113" & 122" BBC; With 12,000 - 13,200lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0067	OE Interchange: 572412, F6HT18080DA, and F6H218125B; 101", 113" or 122" BBC; With Hendrickson HAS-40LH Air Suspension; 1.75in Bore



FRONT



REAR

APPLICATIONS

Ford L9513

1996-1997	HD1215-0157	OE Interchange: F6HT18045EB, F6HT18045EC, F6HT18045GB, F6HT-18045GC; With 12,000 to 14,600lb Axle; With 54" or 60" Taper Springs; 101", 113", or 122" BBC; Shocks are 1.75in Bore	HD1215-0029	OE Interchange: F4HT18080AB, F6HT18080CA, and XC4518080AA; With 101", 113", or 122" BBC; With 15,000, 17,500, 19,000, or 23,000lb Axle; Shocks are 1.75in Bore
1996-1997			HD1215-0036	OE Interchange: F4HT18080BA, F6HT18080JA; With 101", 113", or 122" BBC; With 21,000 or 23,000lb Axle; With 46" or 52" Taper Leaf Spring; Shocks are 1.75in Bore

Ford L9522

1998-1998			HD1215-0042	OE Interchange: 90045099, F6HT18080EA; With Neway AD123 Air Suspension; Shocks are 1.75in Bore
-----------	--	--	-------------	--

Ford LA8000F

1991-1997	HD1215-0134	OE Interchange: F1HT18045EA, F1HT18045EB; With 52" Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0045	OE Interchange: 4790228; With Hendrickson Air Suspension; Shocks are 1.75in Bore
1991-1997	HD1213-0679	(Cab Shock)OE Interchange: 12010012; With Link Cab Suspension		
1991-1997	HD1215-0126	OE Interchange: F6HT18045LA; With 12,000 to 13,000lb Axle; Shocks are 1.75in Bore		
1991-1997	HD1214-0595	OE Interchange: F1HT18045CA; With 4,500 to 10,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore		

Ford LA9000

1988-1997	HD1214-0595	OE Interchange: F1HT18045CA; With 4,500 to 10,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore	HD1215-0045	OE Interchange: 4790228; With Hendrickson Air Suspension; Shocks are 1.75in Bore
-----------	-------------	---	-------------	--

Ford LL9000

1994-1996	HD1214-0595	OE Interchange: F1HT18045DB; With 4,500 to 12,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore		
1994-1996	HD1215-0088	OE Interchange: F1HT18045KB; With 16,000lb Axle; Shocks are 1.75in Bore		
1991-1992	HD1214-0595	OE Interchange: F1HT18045DB; With 4,500 to 12,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore		
1991-1992	HD1215-0088	OE Interchange: F1HT18045KB; With 16,000lb Axle; Shocks are 1.75in Bore		



FRONT

REAR



APPLICATIONS

Ford LLA9000

1992-1994	HD1214-0595	OE Interchange: F1HT18045CA; With 4,500 to 10,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore	HD1215-0045	OE Interchange: 4790228; With Hendrickson Air Suspension; Shocks are 1.75in Bore
------------------	--------------------	---	--------------------	--

Ford LN600

1980-1985	HD1214-0595	OE Interchange: D7HT18045GA; With 3,000 to 7,000lb Axle; Shocks are 1.38in Bore		
1980-1985	HD1214-0564	OE Interchange: D2EF18045AA, D7HT-18045BA; With 4,400 to 9,000lb Axle; Shocks are 1.38in Bore	HD1214-0568	OE Interchange: D7HT18080BA; With 11,000 to 17,000lb Axle; Shocks are 1.38in Bore

Ford LN700

1980-1986	HD1214-0595	OE Interchange: D7HT18045GA; With 3,000 to 7,000lb Axle; Shocks are 1.38in Bore		
1980-1986	HD1214-0564	OE Interchange: D2EF18045AA, D7HT-18045BA, C1TT18045C; With 4,400 to 9,000lb Axle; Shocks are 1.38in Bore	HD1214-0568	OE Interchange: D7HT18080BA; With 11,000 to 17,000lb Axle; Shocks are 1.38in Bore

Ford LN7000

1994-1997	HD1215-0088	OE Interchange: F1HT18045GA; With 52" Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0036	OE Interchange: F4HT18080BA; With 21,000 or 23,000lb Axle; With 46" Taper Leaf Spring; Shocks are 1.75in Bore
1991-1997	HD1215-0134	OE Interchange: F1HT18045RA, F1HT18045RB; With 58" Parabolic Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
1991-1993	HD1215-0088	OE Interchange: F1HT18045GA; With 52" Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
1981-1997	HD1214-0595	OE Interchange: D7HT18045GA; With 3,000 to 7,000lb Axle; Shocks are 1.38in Bore		
1981-1997	HD1214-0564	OE Interchange: D2EF18045AA; With 4,400 to 9,000lb Axle; Shocks are 1.38in Bore	HD1215-0133	OE Interchange: 4790213; With Hendrickson Air Suspension; Shocks are 1.75in Bore

Ford LN800

1981-1984	HD1214-0559	OE Interchange: D2HF18045BA, D7HT-18045DA; With 6,000 to 16,000lb Axle; Shocks are 1.38in Bore		
1980-1984	HD1214-0595	OE Interchange: D7HT18045GA; With 3,000 to 7,000lb Axle; Shocks are 1.38in Bore		
1980-1984	HD1214-0564	OE Interchange: D2EF18045AA, D7HT-18045BA, D2KF18045AA; With 4,400 to 9,000lb Axle; Shocks are 1.38in Bore		
1980-1981	HD1214-0550	OE Interchange: D2HF18045AA; Shocks are 1.38in Bore		



FRONT



REAR

Ford LN8000				
1994-1997	HD1215-0088	OE Interchange: F1HT18045GA; With 52" Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0036	OE Interchange: F4HT18080BA; With 21,000 or 23,000lb Axle; With 46" Taper Leaf Spring; Shocks are 1.75in Bore
1991-1997	HD1215-0134	OE Interchange: F1HT18045RA, F1HT18045RB; With 58" Parabolic Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
1991-1993	HD1215-0088	OE Interchange: F1HT18045GA; With 52" Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
1981-1997	HD1214-0564	OE Interchange: F1HT18045DA; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore	HD1215-0133	OE Interchange: 4790213; With Hendrickson Air Suspension; Shocks are 1.75in Bore
1981-1997	HD1214-0595	OE Interchange: F1HT18045DB; 4,500 to 16,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore		
1981-1997	HD1214-0559	OE Interchange: D2HF18045BA, D7HT-18045DA; With 6,000 to 16,000lb Axle; Shocks are 1.38in Bore		
1981-1981	HD1214-0550	OE Interchange: D2HF18045AA; Shocks are 1.38in Bore		

Ford LN900				
1981-1981	HD1214-0559	OE Interchange: D2HF18045BA, D7HT-18045DA; With 6,000 to 16,000lb Axle; Shocks are 1.38in Bore		
1981-1981	HD1214-0550	OE Interchange: D2HF18045AA; Shocks are 1.38in Bore		

Ford LN9000				
1991-1997	HD1214-0564	OE Interchange: F1HT18045DA; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore		
1991-1997	HD1215-0088	OE Interchange: F1HT18045GA; With 52" Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
1991-1997	HD1215-0134	OE Interchange: F1HT18045RA, F1HT18045RB; With 58" Parabolic Taper Leaf Spring Suspension; Shocks are 1.75in Bore		

Ford LNT800				
1981-1983	HD1214-0595	OE Interchange: D7HT18045GA; With 3,000 to 7,000lb Axle; Shocks are 1.38in Bore		
1981-1983	HD1214-0564	OE Interchange: D2KF18045AA; With 7,000 to 12,000lb Axle; Shocks are 1.38in Bore		

APPLICATIONS



FRONT



REAR

APPLICATIONS

Ford LNT800				
1981-1983	HD1214-0559	OE Interchange: D2HF18045BA, D7HT-18045DA; With 6,000 to 16,000lb Axle; Shocks are 1.38in Bore		
1981-1981	HD1214-0550	OE Interchange: D2HF18045AA; Shocks are 1.38in Bore		

Ford LNT8000				
1981-1989	HD1214-0564	OE Interchange: D2EF18045AA; With 4,400 to 9,000lb Axle; Shocks are 1.38in Bore	HD1215-0133	OE Interchange: 4790213; With Hendrickson Air Suspension; Shocks are 1.75in Bore
1981-1989	HD1214-0595	OE Interchange: D7HT18045GA; With 3,000 to 7,000lb Axle; Shocks are 1.38in Bore		
1981-1989	HD1214-0559	OE Interchange: D2HF18045BA, D7HT-18045DA; With 6,000 to 16,000lb Axle; Shocks are 1.38in Bore		
1981-1981	HD1214-0550	OE Interchange: D2HF18045AA; Shocks are 1.38in Bore		

Ford LNT9000				
1991-1997	HD1214-0595	OE Interchange: F1HT18045DB; With 4,500 to 16,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore		
1991-1997	HD1215-0088	OE Interchange: F1HT18045GA; With 52" Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
1991-1997	HD1215-0134	OE Interchange: F1HT18045RA, F1HT18045RB; With 58" Parabolic Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
1981-1997	HD1214-0564	OE Interchange: F1HT18045DA; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore	HD1215-0133	OE Interchange: 4790213; With Hendrickson Air Suspension; Shocks are 1.75in Bore
1981-1997	HD1214-0559	OE Interchange: D2HF18045BA, D7HT-18045DA; With 6,000 to 16,000lb Axle; Shocks are 1.38in Bore		
1981-1981	HD1214-0550	OE Interchange: D2HF18045AA; Shocks are 1.38in Bore		

Ford LS9000				
1990-1997	HD1214-0595	OE Interchange: F1HT18045CA; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore		
1990-1997	HD1215-0134	OE Interchange: F1HT18045EA; With 52" Taper Leaf Spring Suspension; Shocks are 1.75in Bore		



FRONT



REAR

APPLICATIONS

Ford LT800			
1981-1984	HD1214-0564	OE Interchange: D2KF18045AA; With 7,000 to 12,000lb Axle; Shocks are 1.38in Bore	
1981-1983	HD1214-0559	OE Interchange: D2HF18045BA, D7HT-18045DA; With 6,000 to 16,000lb Axle; Shocks are 1.38in Bore	
1981-1983	HD1214-0550	OE Interchange: D2HF18045AA; With 7,000 to 16,000lb Axle; Shocks are 1.38in Bore	

Ford LT8000			
1981-1988	HD1214-0564	OE Interchange: D2KF18045AA; With 7,000 to 12,000lb Axle; Shocks are 1.38in Bore	
1981-1985	HD1214-0550	OE Interchange: D2HF18045AA; With 7,000 to 16,000lb Axle; Shocks are 1.38in Bore	

Ford LT8501			
1997-1997	HD1214-0562	OE Interchange: F6HT18045CC; 101", 113", or 122" BBC; With 14,600 or 16,000lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0042 OE Interchange: 90045099, F6HT18080EA; With Neway AD123 Air Suspension; Shocks are 1.75in Bore
1997-1997	HD1215-0128	OE Interchange: F6HT18045HB, F6HT18045HC; With 101", 113", and 122" BBC; With 8,500 to 12,000lb Axle; 54" Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0067 OE Interchange: 572412, F6HT18080DA, and F6H218125B; 101", 113" or 122" BBC; With Hendrickson HAS-40LH Air Suspension; 1.75in Bore
1997-1997	HD1214-0658	OE Interchange: F6HT18045BC; 113" & 122" BBC; With 12,000 - 13,200lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0029 OE Interchange: F4HT18080AB, F6HT18080CA, and XC4518080AA; With 101", 113", or 122" BBC; With 15,000, 17,500, 19,000, or 23,000lb Axle; Shocks are 1.75in Bore
1997-1997	HD1215-0157	OE Interchange: F6HT18045EB, F6HT18045EC, F6HT18045GB, F6HT-18045GC; With 12,000 to 14,600lb Axle; With 54" or 60" Taper Springs; 101", 113", or 122" BBC; Shocks are 1.75in Bore	HD1215-0036 OE Interchange: F4HT18080BA, F6HT18080JA; With 21,000 or 23,000lb Axle; With 101", 113" or 112" BBC; With 46" or 52" Taper Leaf Spring; Shocks are 1.75in Bore

Ford LT8513			
1996-1997	HD1214-0562	OE Interchange: F6HT18045CC; 101", 113", or 122" BBC; With 14,600 or 16,000lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0042 OE Interchange: 90045099, F6HT18080EA; With Neway AD123 Air Suspension; Shocks are 1.75in Bore
1996-1997	HD1215-0128	OE Interchange: F6HT18045HB, F6HT18045HC; With 101", 113", and 122" BBC; With 8,500 to 12,000lb Axle; 54" Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0067 OE Interchange: 572412, F6HT18080DA, and F6H218125B; 101", 113" or 122" BBC; With Hendrickson HAS-40LH Air Suspension; 1.75in Bore



FRONT



REAR

APPLICATIONS

Ford LT8513				
1996-1997	HD1214-0658	OE Interchange: F6HT18045BC; 113" & 122" BBC; With 12,000 - 13,200lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0029	OE Interchange: F4HT18080AB, F6HT18080CA, and XC4518080AA; With 101", 113", or 122" BBC; With 15,000, 17,500, 19,000, or 23,000lb Axle; Shocks are 1.75in Bore
1996-1997	HD1215-0157	OE Interchange: F6HT18045EB, F6HT18045EC, F6HT18045GB, F6HT-18045GC; With 12,000 to 14,600lb Axle; With 54" or 60" Taper Springs; 101", 113", or 122" BBC; Shocks are 1.75in Bore	HD1215-0036	OE Interchange: F4HT18080BA, F6HT18080JA; With 21,000 or 23,000lb Axle; With 101", 113" or 112" BBC; With 46" or 52" Taper Leaf Spring; Shocks are 1.75in Bore

Ford LT9000				
1994-1997			HD1215-0036	OE Interchange: F4HT18080BA; With 21,000lb Axle; With 46" Taper Leaf Spring; Shocks are 1.75in Bore
1991-1997	HD1215-0134	OE Interchange: F1HT18045EA; With 52" Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
1991-1996	HD1214-0595	OE Interchange: F1HT18045DB; With 4,500 to 16,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore		
1981-1996	HD1214-0564	OE Interchange: F1HT18045DA; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore		
1981-1990	HD1214-0559	OE Interchange: D2HF18045BA, D7HT-18045DA; With 6,000 to 16,000lb Axle; Shocks are 1.38in Bore		
1981-1985	HD1214-0550	OE Interchange: D2HF18045AA; With 7,000 to 16,000lb Axle; Shocks are 1.38in Bore		

Ford LT9501				
1997-1997	HD1215-0128	OE Interchange: F6HT18045HB, F6HT18045HC; With 101", 113", and 122" BBC; With 8,500 to 12,000lb Axle; 54" Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0045	OE Interchange: 4790228, F6HT18080FC; 101", 113", 112" BBC; With Hendrickson HA-219 & HA-230 Air Suspension; Shocks are 1.75in Bore
1997-1997	HD1214-0562	OE Interchange: F6HT18045CC; 101", 113", or 122" BBC; With 14,600 or 16,000lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0042	OE Interchange: 90045099, F6HT18080EA; With Neway AD123 Air Suspension; Shocks are 1.75in Bore
1997-1997	HD1214-0658	OE Interchange: F6HT18045BC; 113" & 122" BBC; With 12,000 - 13,200lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0067	OE Interchange: 572412, F6HT18080DA, and F6H218125B; 101", 113" or 122" BBC; With Hendrickson HAS-40LH Air Suspension; 1.75in Bore



FRONT



REAR

APPLICATIONS

Ford LT9501

1997-1997	HD1215-0157	OE Interchange: F6HT18045EB, F6HT18045EC, F6HT18045GB, F6HT-18045GC; With 12,000 to 14,600lb Axle; With 54" or 60" Taper Springs; 101", 113", or 122" BBC; Shocks are 1.75in Bore	HD1215-0029	OE Interchange: F4HT18080AB, F6HT18080CA, and XC4518080AA; With 101", 113", or 122" BBC; With 15,000, 17,500, 19,000, or 23,000lb Axle; Shocks are 1.75in Bore
1997-1997			HD1215-0036	OE Interchange: F4HT18080BA, F6HT18080JA; With 21,000 or 23,000lb Axle; With 101", 113" or 112" BBC; With 46" or 52" Taper Leaf Spring; Shocks are 1.75in Bore

Ford LT9513

1996-1997	HD1215-0128	OE Interchange: F6HT18045HB, F6HT18045HC; With 101", 113", and 122" BBC; With 8,500 to 12,000lb Axle; 54" Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0045	OE Interchange: 4790228, F6HT18080FC; 101", 113", 112" BBC; With Hendrickson HA-219 & HA-230 Air Suspension; Shocks are 1.75in Bore
1996-1997	HD1214-0562	OE Interchange: F6HT18045CC; 101", 113", or 122" BBC; With 14,600 or 16,000lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0042	OE Interchange: 90045099, F6HT18080EA; With Neway AD123 Air Suspension; Shocks are 1.75in Bore
1996-1997	HD1214-0658	OE Interchange: F6HT18045BC; 113" & 122" BBC; With 12,000 - 13,200lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0067	OE Interchange: 572412, F6HT18080DA, and F6H218125B; 101", 113" or 122" BBC; With Hendrickson HAS-40LH Air Suspension; 1.75in Bore
1996-1997	HD1215-0157	OE Interchange: F6HT18045EB, F6HT18045EC, F6HT18045GB, F6HT-18045GC; With 12,000 to 14,600lb Axle; With 54" or 60" Taper Springs; 101", 113", or 122" BBC; Shocks are 1.75in Bore	HD1215-0029	OE Interchange: F4HT18080AB, F6HT18080CA, and XC4518080AA; With 101", 113", or 122" BBC; With 15,000, 17,500, 19,000, or 23,000lb Axle; Shocks are 1.75in Bore
1996-1997			HD1215-0036	OE Interchange: F4HT18080BA, F6HT18080JA; With 21,000 or 23,000lb Axle; With 101", 113" or 112" BBC; With 46" or 52" Taper Leaf Spring; Shocks are 1.75in Bore

Ford LT9522

1997-1997	HD1214-0658	OE Interchange: F6HT18045BC; 113" & 122" BBC; With 12,000 - 13,200lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0045	OE Interchange: 4790228, F6HT18080FC; 101", 113", 112" BBC; With Hendrickson HA-219 & HA-230 Air Suspension; Shocks are 1.75in Bore
1997-1997	HD1214-0562	OE Interchange: F6HT18045CC; 101", 113", or 122" BBC; With 14,600 or 16,000lb Axle; With 54" Multi Leaf Spring; Shocks are 1.38in Bore	HD1215-0042	OE Interchange: 90045099, F6HT18080EA; With Neway AD123 Air Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Ford LT9522				
1997-1997	HD1215-0128	OE Interchange: F6HT18045HB, F6HT18045HC; With 101", 113", and 122" BBC; With 8,500 to 12,000lb Axle; 54" Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0067	OE Interchange: 572412, F6HT18080DA, and F6H218125B; 101", 113" or 122" BBC; With Hendrickson HAS-40LH Air Suspension; 1.75in Bore
1997-1997	HD1215-0157	OE Interchange: F6HT18045EB, F6HT18045EC, F6HT18045GB, F6HT-18045GC; With 12,000 to 14,600lb Axle; With 54" or 60" Taper Springs; 101", 113", or 122" BBC; Shocks are 1.75in Bore	HD1215-0029	OE Interchange: F4HT18080AB, F6HT18080CA, and XC4518080AA; With 101", 113", or 122" BBC; With 15,000, 17,500, 19,000, or 23,000lb Axle; Shocks are 1.75in Bore
1997-1997			HD1215-0036	OE Interchange: F4HT18080BA, F6HT18080JA; With 21,000 or 23,000lb Axle; With 101", 113" or 112" BBC; With 46" or 52" Taper Leaf Spring; Shocks are 1.75in Bore

Ford LTA9000				
1988-1997	HD1214-0595	OE Interchange: F1HT18045CA; With 4,500 to 10,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore	HD1215-0045	OE Interchange: 4790228; With Hendrickson Air Suspension; Shocks are 1.75in Bore

Ford LTL9000				
1982-1985	HD1214-0550	OE Interchange: D2HF18045AA; With 7,000 to 12,000lb Axle; Shocks are 1.38in Bore		

Ford LTLA9000				
1992-1997	HD1214-0595	OE Interchange: F1HT18045CA; With 4,500 to 10,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore	HD1215-0045	OE Interchange: 4790228; With Hendrickson Air Suspension; Shocks are 1.75in Bore

Ford LTS8000				
1981-1983	HD1214-0550	OE Interchange: D2HF18045AA; With 7,000 to 16,000lb Axle; Shocks are 1.38in Bore		

Ford LTS9000				
1990-1997	HD1214-0595	OE Interchange: F1HT18045CA; With 4,500 to 10,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore		
1990-1997	HD1215-0134	OE Interchange: F1HT18045EA; With 52" Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
1981-1990	HD1214-0564	OE Interchange: D0HA18045E, D2HF-18045DA, D7HT18045EA; With 16,000lb Axle; Shocks are 1.38in Bore		
1981-1985	HD1214-0550	OE Interchange: D2HF18045AA, D2HT-18045CA; With 7,000 to 16,000lb Axle; Shocks are 1.38in Bore		



FRONT



REAR

APPLICATIONS

Ford P-400				
1975-1976	HD1214-0605	With Heavy Duty Springs; Shocks are 1.38in Bore		

Ford P-500				
1975-1976	HD1214-0605	Shocks are 1.38in Bore	HD1214-0568	Shocks are 1.38in Bore

Freightliner 108SD				
2012-2019	HD1215-0025	OE Interchange: 1013684000, 1013809000; With Flat Leaf Spring; Shocks are 1.75in Bore	HD1215-0104	OE Interchange: 1615770000; With Freightliner Turfrac Air Suspension; Shocks are 1.75in Bore
2012-2019			HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
2012-2019			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore

Freightliner 114SD				
2012-2019			HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
2012-2019	HD1215-0025	OE Interchange: 1013684000, 1013809000; With Flat Leaf Spring; Shocks are 1.75in Bore	HD1215-0104	OE Interchange: 1615770000; With Freightliner Turfrac Air Suspension; Shocks are 1.75in Bore
2012-2019			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore

Freightliner 122SD				
2014-2015			HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
2014-2015			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore

Freightliner Argosy				
2013-2015	HD1215-0025	OE Interchange: 101302100, 1012703000, 1012704000; With Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
1999-2015			HD1215-0018	OE Interchange: 1613952000, 1613957000, 1615817000, and 680339; Drive Axle; With FAS II Airliner Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Freightliner Argosy

1999-2015			HD1215-0026	Drive Axle; With Low Profile Air Suspension; OE Interchange: 1614259000 and 1616577000; Shocks are in Bore
-----------	--	--	--------------------	--

Freightliner Business Class M2

2004-2012	HD1215-0024	OE Interchange: 1012388000, 101239000, 1012396000; With 6,000 to 13,000 GVW; Shocks are 1.75in Bore	HD1215-0026	Drive Axle; With Low Profile Air Suspension; OE Interchange: 1614259000 and 1616577000; Shocks are in Bore
2004-2012			HD1214-0611	OE Interchange: 1616486000, 1616442000; Drive Axle; With 52 Inch Spring; With 10,000 to 23,000lb Axle; Shocks are 1.38in Bore

Freightliner Cascadia

2017-2020	HD1214-0845	OE Interchange: 1014193000; Shocks are 1.38 in Bore		
2009-2017	HD1215-0103	OE Interchange: 58913003, 58913012; Steering Axle; With Hendrickson Airtek Suspension; Shocks are 1.75in Bore		
2009-2017	HD1214-0538	(Cab Shock) OE Interchange: 1860764000 and 1841762000		
2008-2020	HD1215-0025	OE Interchange: 1013211000, 1013634000; with 12,000-13,300lb Taper Leaf Springs; Shocks are 1.75in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
2008-2016			HD1215-0018	OE Interchange: 1613952000, 1613957000, 1615817000, and 680339; Drive Axle; With FAS II Airliner Suspension; Shocks are 1.75in Bore

Freightliner Century Class

2001-2011	HD1214-0636	(Cab Shock) OE Interchange: 1841762001		
2001-2011	HD1214-0544	(Cab Shock) OE Interchange: 1830378000, 1832999000	HD1214-0607	OE Interchange: 1614794000; Drive Axle; Shocks are 1.38in Bore
2001-2011	HD1214-0538	(Cab Shock) OE Interchange: 1832999001, 1841762000, and 1841762002	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
2001-2011	HD1215-0021	Steering Axle; With Taper Leaf Spring Suspension; OE Interchange: 1012542000; Shocks are 1.75in Bore	HD1215-0018	OE Interchange: 1613952000, 1613957000, 1615817000, and 680339; Drive Axle; With FAS II Airliner Suspension; Shocks are 1.75in Bore
2001-2011	HD1215-0025	OE Interchange: 1013211000, 1012703000, 1012704000; Shocks are 1.75in Bore	HD1215-0026	Drive Axle; With Low Profile Air Suspension; OE Interchange: 1614259000 and 1616577000; Shocks are in Bore

Freightliner Classic

2001-2011	HD1215-0171	OE Interchange: 680009; Shocks are 1.75in Bore		
-----------	--------------------	--	--	--



FRONT



REAR

APPLICATIONS

Freightliner Classic

2001-2010	HD1214-0535	(Cab Shock) OE Interchange: 1829846000	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
2001-2010	HD1215-0029	OE Interchange: 1012032002; Steering Axle; Shocks are 1.75in Bore	HD1215-0018	OE Interchange: 1613952000, 1613957000, 1615817000, and 680339; Drive Axle; With FAS II Airliner Suspension; Shocks are 1.75in Bore
2008-2010	HD1215-0025	OE Interchange: 1013211000; Steering Axle; With 1.5" Taper Leaf 12000lb Spring; Shocks are 1.75in Bore		
2001-2006	HD1215-0025	OE Interchange: 1013211000; Steering Axle; With 1.5" Taper Leaf 12000lb Spring; Shocks are 1.75in Bore		

Freightliner Classic XL

2001-2009	HD1215-0171	OE Interchange: 680009; Shocks are 1.75in Bore		
2001-2009	HD1215-0029	OE Interchange: 1012032004; Steering Axle; Shocks are 1.75in Bore		
2001-2009	HD1215-0113	OE Interchange: 70029; Steering Axle; Shocks are 1.75in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
2001-2009	HD1215-0025	OE Interchange: 1013211000; Steering Axle; With 1.5" Taper Leaf 12000lb Spring; Shocks are 1.75in Bore		

Freightliner Columbia

2001-2020			HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
2001-2012	HD1214-0535	(Cab Shock) OE Interchange: 1829846000		
2001-2012	HD1214-0538	(Cab Shock) OE Interchange: 1841762000		
2001-2012	HD1215-0025	OE Interchange: 1829846000; Steering Axle; Shocks are 1.75in Bore		

Freightliner Coronado

2010-2016	HD1214-0538	(Cab Shock) OE Interchange: 1841762000 and 1841762002		
2010-2016	HD1214-0636	(Cab Shock) OE Interchange: 1841762001		
2010-2016	HD1215-0025	OE Interchange: 1013211000; Steering Axle; With 1.5" Taper Leaf 12000lb Spring; Shocks are 1.75in Bore		
2004-2020			HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore



FRONT

REAR



APPLICATIONS

Freightliner FC70

1999-2004	HD1215-0068	OE Interchange: 6803230300, 665538; Steering Axle; With 11,000 to 12,000lb Spring; Shocks are 1.75in Bore		
1999-2004	HD1214-0566	OE Interchange: 6803230200, 654654; Steering Axle; 6,000 - 9,000lb Springs; Shocks are 1.38in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore

Freightliner FC80

1999-2007	HD1215-0068	OE Interchange: 6803230300, 665538; Steering Axle; With 11,000 to 12,000lb Spring; Shocks are 1.75in Bore		
1999-2007	HD1214-0566	OE Interchange: 6803230200, 654654; Steering Axle; 6,000 - 9,000lb Springs; Shocks are 1.38in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore

Freightliner FL50

1995-2005	HD1215-0068	OE Interchange: 6803230300, 665538; Steering Axle; With 9,000, 11,000, and 12,000lb Axle; Shocks are 1.75in Bore	HD1214-0568	OE Interchange: 161113300; Drive Axle; With FAS Airliner Suspension; Shocks are 1.38in Bore
1995-2005	HD1214-0566	OE Interchange: 6803230200, 654654; Steering Axle; 6,000 - 9,000lb Springs; Shocks are 1.38in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
1995-2005			HD1214-0593	OE Interchange: 6803260000; Drive Axle; With 15,000lb Springs; Shocks are 1.38in Bore

Freightliner FL60

1991-2004	HD1215-0068	OE Interchange: 6803230300, 665538; Steering Axle; With 9,000, 11,000, and 12,000lb Axle; Shocks are 1.75in Bore	HD1214-0593	OE Interchange: 6803260000; Drive Axle; With 15,000lb Springs; Shocks are 1.38in Bore
1991-2004	HD1214-0566	OE Interchange: 6803230200, 654654; Steering Axle; 6,000 - 9,000lb Springs; Shocks are 1.38in Bore		
1991-2004	HD1213-0651	(Cab Shock) OE Interchange: 12020054		
1991-2004	HD1214-0544	(Cab Shock) OE Interchange: 1830378, 1830378000	HD1214-0568	OE Interchange: 161113300; Drive Axle; With FAS Airliner Suspension; Shocks are 1.38in Bore
1991-2004	HD1214-0535	(Cab Shock) OE Interchange: 1829846000	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore

Freightliner FL70

1991-2005	HD1215-0068	OE Interchange: 6803230300, 665538; Steering Axle; With 9,000, 11,000, and 12,000lb Axle; Shocks are 1.75in Bore	HD1214-0593	OE Interchange: 6803260000; Drive Axle; With 15,000lb Springs; Shocks are 1.38in Bore
-----------	--------------------	--	--------------------	---



FRONT



REAR

APPLICATIONS

Freightliner FL70				
1991-2005	HD1214-0566	OE Interchange: 6803230200, 654654; Steering Axle; 6,000 - 9,000lb Springs; Shocks are 1.38in Bore		
1991-2005	HD1213-0651	(Cab Shock) OE Interchange: 12020054		
1991-2005	HD1214-0544	(Cab Shock) OE Interchange: 1830378, 1830378000	HD1214-0568	OE Interchange: 161113300; Drive Axle; With FAS Airliner Suspension; Shocks are 1.38in Bore
1991-2005	HD1214-0535	(Cab Shock) OE Interchange: 1829846000	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore

Freightliner FL80				
1991-2005	HD1214-0566	OE Interchange: 6803230200, 654654; Steering Axle; 6,000 - 9,000lb Springs; Shocks are 1.38in Bore	HD1214-0568	OE Interchange: 161113300; Drive Axle; With FAS Airliner Suspension; Shocks are 1.38in Bore
1991-2005	HD1215-0068	OE Interchange: 6803230300, 665538; Steering Axle; With 9,000, 11,000, and 12,000lb Axle; Shocks are 1.75in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
1991-2005			HD1214-0593	OE Interchange: 6803260000; Drive Axle; With 15,000lb Springs; Shocks are 1.38in Bore

Freightliner FLB				
2002-2002	HD1213-0651	(Cab Shock) OE Interchange: 12020054	HD1215-0064	OE Interchange: 1613947000, 6813260400; Drive Axle; With Airliner Rolling Lobe Spring Air Suspension; Shocks are 1.75in Bore
2002-2002	HD1215-0029	OE Interchange: 1012030002, 1012032000, 1012032001, 1012032002, 1012032003, 1012032004, 70042, 535228, 680009; Steering Axle; Shocks are 1.75in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
2002-2002			HD1214-0568	OE Interchange: 16106880, 535227, 650224, 665236; Drive Axle; With Rear Air Suspension; Shocks are 1.38in Bore
2002-2002			HD1215-0113	OE Interchange: 1612117000; Drive Axle; With Convoluted Spring Air Suspension; Shocks are 1.75in Bore
2002-2002			HD1214-0508	OE Interchange: 90044162; Tag Axle With Neway Air Suspension; Shocks are 1.38in Bore
2002-2002	HD1213-0680	(Cab Shock) OE Interchange: 6818910205	HD1214-0568	OE Interchange: 16106880, 535227, 650224, 665236; Drive Axle; With Rear Air Suspension; Shocks are 1.38in Bore
1994-1999	HD1213-0651	(Cab Shock) OE Interchange: 12020054	HD1215-0064	OE Interchange: 1613947000, 6813260400; Drive Axle; With Airliner Rolling Lobe Spring Air Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Freightliner FLB				
1994-1999	HD1215-0029	OE Interchange: 1012030002, 1012032000, 1012032001, 1012032002, 1012032003, 1012032004, 70042, 535228, 680009; Steering Axle; Shocks are 1.75in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
1994-1999	HD1213-0680	(Cab Shock) OE Interchange: 6818910205	HD1214-0508	OE Interchange: 90044162; Tag Axle With Neway Air Suspension; Shocks are 1.38in Bore
1994-1999			HD1215-0113	OE Interchange: 1612117000; Drive Axle; With Convoluted Spring Air Suspension; Shocks are 1.75in Bore

Freightliner FLC112				
1992-2001	HD1214-0636	(Cab Shock) OE Interchange: 1841762001		
1992-2001	HD1213-0679	(Cab Shock) OE Interchange: 12010012, 12020012; With Link Cab Suspension		
1992-2001			HD1214-0568	OE Interchange: 16106880, 535227, 650224, 665236; Drive Axle; With Rear Air Suspension; Shocks are 1.38in Bore
1992-2001	HD1214-0573	(Cab Shock) OE Interchange: 1860765000, 12011043, 12021043, 12011044, 12021044; With Link Cab Suspension	HD1215-0113	OE Interchange: 1612117000; Drive Axle; With Convoluted Spring Air Suspension; Shocks are 1.75in Bore
1992-2001			HD1215-0064	OE Interchange: 1613947000, 6813260400; Drive Axle; With Airliner Rolling Lobe Spring Air Suspension; Shocks are 1.75in Bore
1992-2001	HD1215-0029	OE Interchange: 1012030002, 1012032000, 1012032001, 1012032002, 1012032003, 1012032004, 70042, 535228, 680009; Steering Axle; Shocks are 1.75in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
1992-2001	HD1215-0025	OE Interchange: 101302100; Steering Axle; With Low Profile Air Suspension; Shocks are 1.75in Bore	HD1214-0508	OE Interchange: 90044162; Tag Axle With Neway Air Suspension; Shocks are 1.38in Bore
1992-2001	HD1214-0535	(Cab Shock) OE Interchange: 1829846000	HD1215-0026	Drive Axle; With Low Profile Air Suspension; OE Interchange: 1614259000 and 1616577000; Shocks are in Bore

Freightliner FLC120				
1998-1998	HD1214-0636	(Cab Shock) OE Interchange: 1841762001		
1998-1998	HD1214-0573	(Cab Shock) OE Interchange: 186076500, 12021043	HD1214-0568	OE Interchange: 16106880, 535227, 650224, 665236; Drive Axle; With Rear Air Suspension; Shocks are 1.38in Bore
1998-1998			HD1215-0113	OE Interchange: 1612117000; Drive Axle; With Convoluted Spring Air Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Freightliner FLC120

1998-1998	HD1214-0535	(Cab Shock) OE Interchange: 1829846000	HD1215-0064	OE Interchange: 1613947000, 6813260400; Drive Axle; With Airliner Rolling Lobe Spring Air Suspension; Shocks are 1.75in Bore
1998-1998	HD1215-0029	OE Interchange: 1012030002, 1012032000, 1012032001, 1012032002, 1012032003, 1012032004, 70042, 535228, 680009; Steering Axle; Shocks are 1.75in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
1998-1998	HD1215-0025	OE Interchange: 101302100; Steering Axle; With Low Profile Air Suspension; Shocks are 1.75in Bore	HD1214-0508	OE Interchange: 90044162; Tag Axle With Neway Air Suspension; Shocks are 1.38in Bore

Freightliner FLD112

1992-2002	HD1214-0636	(Cab Shock) OE Interchange: 1841762001		
1992-2002	HD1213-0679	(Cab Shock) OE Interchange: 12010012, 12020012; With Link Cab Suspension		
1992-2002	HD1214-0573	(Cab Shock) OE Interchange: 186076500, 12021043	HD1215-0113	OE Interchange: 1612117000; Drive Axle; With Convoluted Spring Air Suspension; Shocks are 1.75in Bore
1992-2002			HD1215-0064	OE Interchange: 1613947000, 6813260400; Drive Axle; With Airliner Rolling Lobe Spring Air Suspension; Shocks are 1.75in Bore
1992-2002	HD1215-0029	OE Interchange: 1012030002, 1012032000, 1012032001, 1012032002, 1012032003, 1012032004, 70042, 535228, 680009; Steering Axle; Shocks are 1.75in Bore	HD1215-0018	OE Interchange: 1613952000, 1613957000, 1615817000, and 680339; Drive Axle; With FAS II Airliner Suspension; Shocks are 1.75in Bore
1992-2002	HD1215-0025	OE Interchange: 101302100; Steering Axle; With Low Profile Air Suspension; Shocks are 1.75in Bore	HD1214-0508	OE Interchange: 90044162; Tag Axle With Neway Air Suspension; Shocks are 1.38in Bore
1992-2002	HD1214-0535	(Cab Shock) OE Interchange: 1829846000	HD1215-0026	Drive Axle; With Low Profile Air Suspension; OE Interchange: 1614259000 and 1616577000; Shocks are in Bore

Freightliner FLD120

1992-2002	HD1214-0636	(Cab Shock) OE Interchange: 1841762001		
1992-2002			HD1215-0113	OE Interchange: 1612117000; Drive Axle; With Convoluted Spring Air Suspension; Shocks are 1.75in Bore
1992-2002			HD1215-0064	OE Interchange: 1613947000, 6813260400; Drive Axle; With Airliner Rolling Lobe Spring Air Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Freightliner FLD120

1992-2002	HD1215-0029	OE Interchange: 1012030002, 1012032000, 1012032001, 1012032002, 1012032003, 1012032004, 70042, 535228, 680009; Steering Axle; Shocks are 1.75in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
1992-2002	HD1215-0025	OE Interchange: 101302100; Steering Axle; With Low Profile Air Suspension; Shocks are 1.75in Bore	HD1214-0508	OE Interchange: 90044162; Tag Axle With Neway Air Suspension; Shocks are 1.38in Bore
1992-2002	HD1214-0535	(Cab Shock) OE Interchange: 1829846000	HD1215-0026	Drive Axle; With Low Profile Air Suspension; OE Interchange: 1614259000 and 1616577000; Shocks are in Bore

Freightliner FS65

1996-2008	HD1215-0068	OE Interchange: 6803230300; Steering Axle; With Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1214-0593	OE Interchange: 6803230300; Drive Axle; With Taper Leaf Spring Suspension; Shocks are 1.38in Bore
-----------	-------------	--	-------------	---

Freightliner M2 106

2001-2008	HD1115-0073	OE Interchange: 1012390000; With 10,000-12,000lb Taper Leaf Spring Suspension		
2001-2008	HD1115-0073	OE Interchange: 1012388000; With 6,000-9,000lb Front Axle		

Freightliner M2 112

2003-2010	HD1214-0573	(Cab Shock) OE Interchange: 12011044, 12021044		
2003-2010	HD1215-0021	Steering Axle; With P2 Chassis; OE Interchange 1012542000; Shocks are 1.75in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
2003-2010	HD1215-0025	OE Interchange: 1013021000; Steering Axle; Shocks are 1.75in Bore		
2003-2010	HD1215-0064	OE Interchange: 1613947000; Steering Axle; With PE Chassis; Shocks are 1.75in Bore		

Freightliner MB Line

1998-2009	HD1214-0528	OE Interchange: 1617684000; Steering Axle; Shocks are 1.38in Bore		
-----------	-------------	---	--	--

Freightliner MB60

1992-1995	HD1215-0068	OE Interchange: 6803230300, 665538; Steering Axle; With 9,000, 11,000, and 12,000lb Axle; Shocks are 1.75in Bore	HD1214-0568	OE Interchange: 1611133000; With FAS Airliner Suspension; Drive Axle; Shocks are 1.38in Bore
1992-1995	HD1214-0566	OE Interchange: 6803230200, 654654; Steering Axle; 6,000 - 9,000lb Springs; Shocks are 1.38in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Freightliner MB60

1992-1995			HD1214-0593	OE Interchange: 680326000; Drive Axle; With 15,000lb Springs; Shocks are 1.38in Bore
1992-1994	HD1214-0645	With Front Axle Stabilizer Bar Rearward of Axle		

Freightliner MB70

1992-1995	HD1215-0068	OE Interchange: 6803230300, 665538; Steering Axle; With 9,000, 11,000, and 12,000lb Axle; Shocks are 1.75in Bore	HD1214-0568	OE Interchange: 1611133000; With FAS Airliner Suspension; Drive Axle; Shocks are 1.38in Bore
1992-1995	HD1214-0566	OE Interchange: 6803230200, 654654; Steering Axle; 6,000 - 9,000lb Springs; Shocks are 1.38in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
1992-1995			HD1214-0593	OE Interchange: 680326000; Drive Axle; With 15,000lb Springs; Shocks are 1.38in Bore
1992-1994	HD1214-0645	With Front Axle Stabilizer Bar Rearward of Axle		

Freightliner MT35

1997-1998	HD1214-0645	With Front Axle Stabilizer Bar Rearward of Axle; With Leaf Spring Suspension		
-----------	--------------------	--	--	--

Freightliner MT45

1998-2016	HD1214-0657	OE Interchange: 1615089000; Steering Axle; With 38" Front Springs; Shocks are 1.38in Bore		
1998-1998	HD1214-0645	With Front Axle Stabilizer Bar Rearward of Axle; With Leaf Spring Suspension		

Freightliner MT55

1999-2016	HD1214-0657	OE Interchange: 1615089000; Steering Axle; With 38" Front Springs; Shocks are 1.38in Bore	HD1214-0607	OE Interchange: 1614794000; Drive Axle; Shocks are 1.38in Bore
1999-2016			HD1214-0602	OE Interchange: 1615705000, 1615934000, 1616262000; Drive Axle; Shocks are 1.38in Bore

Freightliner Sprinter 2500

2007-2009			HD1214-0648	With Dual Rear Wheels; Shocks are 1.38in Bore
2002-2009			HD1214-0659	With Single Rear Wheels; Shocks are 1.38in Bore
2002-2006			HD1214-0596	With Dual Rear Wheels; Shocks are 1.38in Bore



FRONT



REAR

APPLICATIONS

Freightliner Sprinter 3500

2007-2015			HD1214-0648	With Dual Rear Wheels; Shocks are 1.38in Bore
2002-2009			HD1214-0659	With Single Rear Wheels; Shocks are 1.38in Bore
2002-2006			HD1214-0596	With Dual Rear Wheels; Shocks are 1.38in Bore

Freightliner XC

2002-2005	HD1215-0118	OE Interchange: B46-2545-M100, B46-2556-M100; IFS114 Independent Front Suspension; 23,000 GVW & Up; Shocks are 1.75in Bore	HD1215-0150	OE Interchange: 16-16736-000, 16-14668-000, B46-2147-M100, B46-2546-M100; 23,000 GVW & Up; With AD160, AD200 or ADL200 Rear Suspension
2002-2002	HD1215-0152	23,000 GVW & Up; AS120, AS140 Beam Front Suspension; With 3/4 x 1-3/4 Uppers Sleeve Mount		
2002-2002	HD1215-0062	OE Interchange: B46-2556-M100, 90045083; With 2300 GVW or Higher; With IFS114 Ind. Suspension; Shocks are 1.75in Bore		

Gillig School Bus

1989-1993	HD1116-0047	School Bus; Cab Forward; OE Interchange: 200171; With 1 Inch Mounting Pins	HD1116-0047	School Bus; Cab Forward; OE Interchange: 200171; With 1 Inch Mounting Pins
1989-1993	HD1214-0640	OE Interchange: 57131; With 3/4 Inch Mounting Pins; Shocks are 1.38in Bore		
1989-1993	HD1214-0568	OE Interchange: 53176; With 1 Inch Mounting Pins; Shocks are 1.38in Bore	HD1214-0568	OE Interchange: 53176; With 1 Inch Mounting Pins; Shocks are 1.38in Bore
1989-1993	HD1116-0044	OE Interchange: 70034, 680009; With 1 Inch Mounting Pins		OE Interchange: 70034, 680009; With 1 Inch Mounting Pins
1989-1993	HD1214-0605	OE Interchange: 57113; With 3/4 Inch Mounting Pins; Shocks are 1.38in Bore		

GMC 3000

1960-1966	HD1213-0674	OE Interchange: 676081; Shocks are 1.38in Bore		
-----------	--------------------	--	--	--

GMC 3500

1960-1962			HD1214-0579	Shocks are 1.38in Bore
-----------	--	--	--------------------	------------------------

GMC B7

1993-1998	HD1215-0081	OE Interchange: 22064230; Bus Chassis; Shocks are 1.75in Bore	HD1214-0561	OE Interchange: 22064232; Bus Chassis; With 15,000 to 21,000 Multi Leaf Spring Suspension; Shocks are 1.38in Bore
-----------	--------------------	---	--------------------	---



FRONT



REAR

GMC C4500 Topkick

2008-2009			HD1215-0112	OE Interchange: 15782915, 15185643, 15185644; With Conventional Cab; Drive Axle; With Hendrickson RS-460 Suspension; With 12,000 to 15,000lb Axle with Leaf Springs; Shocks are 1.75in Bore
2003-2009			HD1215-0120	OE Interchange: 88963409; With Conventional Cab; Low Profile Vehicle; With 12,000 to 18,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore
2003-2007	HD1215-0081	OE Interchange: 15123676, 15174898, 15887728, 15588554, 15174298, 15192385, 88982682, 22064230; Steering Axle; Shocks are 1.75in Bore	HD1215-0112	OE Interchange: 15782915, 15185643, 15185644; With Conventional Cab; Drive Axle; With Hendrickson RS-460 Suspension; With 12,000 to 15,000lb Axle with Leaf Springs; Shocks are 1.75in Bore

APPLICATIONS

GMC C5000

1990-1990			HD1215-0156	OE Interchange: 20064233; Drive Axle; With Conventional Cab; With 23,000lb Axle; Taper Leaf Spring; Shocks are 1.75in Bore
1990-1990			HD1215-0133	OE Interchange: 12474915, 15963161; Drive Axle; With Hendrickson Air Suspension; With 21,000 to 23,000lb Axle; With Conventional Cab; Shocks are 1.75in Bore
1990-1990			HD1215-0045	OE Interchange: 12474917, 15740554; Drive Axle; With Hendrickson Air Suspension; With Conventional Cab; Shocks are 1.75in Shocks
1990-1990			HD1214-0561	OE Interchange: 22064232; Bus Chassis; With 15,000 to 21,000 Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1990-1990	HD1214-0556	OE Interchange: 15588554, 22064230; Steering Axle; Shocks are 1.38in Bore	HD1215-0044	OE Interchange: 22064402; With Conventional Cab; Low Profile Vehicle; With 21,000lb Axle; Taper Leaf Springs Suspension; Shocks are 1.75in Bore
1990-1990			HD1215-0108	OE Interchange: 22064432; Conventional Cab; With 15,000 to 21,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore
1981-1989			HD1214-0539	OE Interchange: 22012095, 22012166, 4940606; With Conventional Cab; With 97" Bumper to Back of Cab; With 20,800lb or 23,000lb Axle; Shocks are 1.38in Bore
1980-1989	HD1214-0608	OE Interchange: 22002295, 22007753, 22017530, 22017531; Conventional Cab; Shocks are 1.38in Bore	HD1214-0579	OE Interchange: 3192892, 22012096, 22012169; With Conventional Cab; Excludes 18,500, 20,800, and 23,000lb Rear Axles; Shocks are 1.38in Bore



FRONT



REAR

APPLICATIONS

GMC C5000			
1980-1981	HD1214-0640	OE Interchange: 4940614, 4963854, 4984526; With Conventional Cab; 92" Bumper to Back of Cab; Shocks are 1.38in Bore	
1980-1980	HD1214-0539	OE Interchange: 3192890, 4940606, 4940662, 4975497, 22002293, 22007701, 22007751, 22012095; With Conventional or Tilt Cab; With 5,000 or 7,000lb Axle; Shocks are 1.38in Bore	HD1214-0539 OE Interchange: 22012095, 22012166, 4940606; With Conventional Cab; With 97" Bumper to Back of Cab; With 20,800lb or 23,000lb Axle; Shocks are 1.38in Bore

GMC C5000 Topkick			
1990-1991			HD1215-0156 OE Interchange: 20064233; Drive Axle; With Conventional Cab; With 23,000lb Axle; Taper Leaf Spring; Shocks are 1.75in Bore
1990-1991			HD1215-0133 OE Interchange: 12474915, 15963161; Drive Axle; With Hendrickson Air Suspension; With 21,000 to 23,000lb Axle; With Conventional Cab; Shocks are 1.75in Bore
1990-1991			HD1215-0045 OE Interchange: 12474917, 15740554; Drive Axle; With Hendrickson Air Suspension; With Conventional Cab; Shocks are 1.75in Shocks
1990-1991			HD1214-0561 OE Interchange: 22064232; Bus Chassis; With 15,000 to 21,000 Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1990-1991	HD1214-0556	OE Interchange: 15588554, 22064230; Steering Axle; Shocks are 1.38in Bore	HD1215-0044 OE Interchange: 22064402; With Conventional Cab; Low Profile Vehicle; With 21,000lb Axle; Taper Leaf Springs Suspension; Shocks are 1.75in Bore
1990-1991			HD1215-0108 OE Interchange: 22064432; Conventional Cab; With 15,000 to 21,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore

GMC C5500 Topkick			
2008-2009			HD1215-0112 OE Interchange: 15782915, 15185643, 15185644; With Conventional Cab; Drive Axle; With Hendrickson RS-460 Suspension; With 12,000 to 15,000lb Axle with Leaf Springs; Shocks are 1.75in Bore
2003-2009			HD1215-0120 OE Interchange: 88963409; With Conventional Cab; Low Profile Vehicle; With 12,000 to 18,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore



FRONT



REAR

GMC C5500 Topkick				
2003-2007	HD1215-0081	OE Interchange: 15123676, 15174898, 15887728, 15588554, 15174298, 15192385, 88982682, 22064230; Steering Axle; Shocks are 1.75in Bore	HD1215-0112	OE Interchange: 15782915, 15185643, 15185644; With Conventional Cab; Drive Axle; With Hendrickson RS-460 Suspension; With 12,000 to 15,000lb Axle with Leaf Springs; Shocks are 1.75in Bore
GMC C6000				
1990-1990			HD1215-0156	OE Interchange: 22064233; Drive Axle; With Conventional Cab; With 23,000lb Axle; Taper Leaf Spring; Shocks are 1.75in Bore
1990-1990			HD1215-0133	OE Interchange: 12474915, 15963161; Drive Axle; With Hendrickson Air Suspension; With 21,000 to 23,000lb Axle; With Conventional Cab; Shocks are 1.75in Bore
1990-1990			HD1215-0045	OE Interchange: 12474917, 15740554; Drive Axle; With Hendrickson Air Suspension; With Conventional Cab; Shocks are 1.75in Shocks
1990-1990			HD1214-0561	OE Interchange: 22064232; Bus Chassis; With 15,000 to 21,000 Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1990-1990	HD1214-0556	OE Interchange: 15588554, 22064230; With Conventional Cab; Shocks are 1.38in Bore	HD1215-0044	OE Interchange: 22064402; With Conventional Cab; Low Profile Vehicle; With 21,000lb Axle; Taper Leaf Springs Suspension; Shocks are 1.75in Bore
1981-1989			HD1214-0539	OE Interchange: 22012095, 22012166, 4940606; With Conventional Cab; With 97" Bumper to Back of Cab; With 20,800lb or 23,000lb Axle; Shocks are 1.38in Bore
1980-1981	HD1214-0640	OE Interchange: 4940614, 4963854, 4984526; With Conventional Cab; 92" Bumper to Back of Cab; Shocks are 1.38in Bore		
1980-1989	HD1214-0608	OE Interchange: 22002295, 22007753, 22017530, 22017531; Conventional Cab; Shocks are 1.38in Bore	HD1214-0579	OE Interchange: 3192892, 22012096, 22012169; With Conventional Cab; Excludes 18,500, 20,800, and 23,000lb Rear Axles; Shocks are 1.38in Bore
1980-1980	HD1214-0539	OE Interchange: 3192890, 4940606, 4940662, 4975497, 22002293, 22007701, 22007751, 22012095; With Conventional or Tilt Cab; With 5,000 or 7,000lb Axle; Shocks are 1.38in Bore	HD1214-0539	OE Interchange: 22012095, 22012166, 4940606; With Conventional Cab; With 97" Bumper to Back of Cab; With 20,800lb or 23,000lb Axle; Shocks are 1.38in Bore

APPLICATIONS



FRONT



REAR

APPLICATIONS

GMC C6000 Topkick				
1991-1996			HD1215-0108	OE Interchange: 22064432; Conventional Cab; With 15,000 to 21,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore
1990-1996			HD1215-0156	OE Interchange: 22064233; Drive Axle; With Conventional Cab; With 15,000lb to 23,000lb Axle; With Multi-Leaf Spring; Shocks are 1.38in Bore
1990-1996			HD1215-0133	OE Interchange: 12474915, 15963161; Drive Axle; With Hendrickson Air Suspension; With 21,000 to 23,000lb Axle; With Conventional Cab; Shocks are 1.75in Bore
1990-1996			HD1215-0045	OE Interchange: 12474917, 15740554; Drive Axle; With Hendrickson Air Suspension; With Conventional Cab; Shocks are 1.75in Shocks
1990-1996			HD1214-0561	OE Interchange: 22064232; Bus Chassis; With 15,000 to 21,000 Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1990-1996	HD1214-0556	OE Interchange: 15588554, 22064230; With Conventional Cab; Shocks are 1.38in Bore	HD1215-0044	OE Interchange: 22064402; With Conventional Cab; Low Profile Vehicle; With 21,000lb Axle; Taper Leaf Springs Suspension; Shocks are 1.75in Bore

GMC C6500 Topkick				
2003-2009			HD1215-0112	OE Interchange: 15782915, 15185643, 15185644; With Conventional Cab; Drive Axle; With Hendrickson RS-460 Suspension; With 12,000 to 15,000lb Axle with Leaf Springs; Shocks are 1.75in Bore
2003-2009			HD1215-0120	OE Interchange: 88963409; With Conventional Cab; Low Profile Vehicle; With 12,000 to 18,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore
2000-2007	HD1215-0081	OE Interchange: 15123676, 15174898, 15887728, 15588554, 15174298, 15192385, 88982682, 22064230; Steering Axle; Shocks are 1.75in Bore		
1997-2002			HD1215-0156	OE Interchange: 22064233; Drive Axle; With Conventional Cab; With 23,000lb Axle; Taper Leaf Spring; Shocks are 1.75in Bore
1997-2002			HD1215-0133	OE Interchange: 12474915, 15963161; Drive Axle; With Hendrickson Air Suspension; With 21,000 to 23,000lb Axle; With Conventional Cab; Shocks are 1.75in Bore



FRONT



REAR

GMC C6500 Topkick				
1997-2002			HD1215-0045	OE Interchange: 12474917, 15740554; Drive Axle; With Hendrickson Air Suspension; With Conventional Cab; Shocks are 1.75in Shocks
1997-2002			HD1214-0561	OE Interchange: 22064232; Bus Chassis; With 15,000 to 21,000 Multi Leaf Spring Suspension; Shocks are 1.38in Bore
GMC C7000				
1990-1990			HD1215-0156	OE Interchange: 22064233; Drive Axle; With Conventional Cab; With 23,000lb Axle; Taper Leaf Spring; Shocks are 1.75in Bore
1990-1990			HD1215-0133	OE Interchange: 12474915, 15963161; Drive Axle; With Hendrickson Air Suspension; With 21,000 to 23,000lb Axle; With Conventional Cab; Shocks are 1.75in Bore
1990-1990			HD1215-0045	OE Interchange: 12474917, 15740554; Drive Axle; With Hendrickson Air Suspension; With Conventional Cab; Shocks are 1.75in Shocks
1990-1990			HD1214-0561	OE Interchange: 22064232; Bus Chassis; With 15,000 to 21,000 Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1990-1990	HD1214-0556	OE Interchange: 15588554, 22064230; With Conventional Cab; Shocks are 1.38in Bore	HD1215-0044	OE Interchange: 22064402; With Conventional Cab; Low Profile Vehicle; With 21,000lb Axle; Taper Leaf Springs Suspension; Shocks are 1.75in Bore
1990-1990			HD1215-0108	OE Interchange: 22064432; Conventional Cab; With 15,000 to 21,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore
1981-1989			HD1214-0539	OE Interchange: 22012095, 22012166, 4940606; With Conventional Cab; With 97" Bumper to Back of Cab; With 20,800lb or 23,000lb Axle; Shocks are 1.38in Bore
1980-1981	HD1214-0640	OE Interchange: 4940614, 4963854, 4984526; With Conventional Cab; 92" Bumper to Back of Cab; Shocks are 1.38in Bore		
1980-1989	HD1214-0608	OE Interchange: 22002295, 22007753, 22017530, 22017531; Conventional Cab; Shocks are 1.38in Bore	HD1214-0579	OE Interchange: 3192892, 22012096, 22012169; With Conventional Cab; Excludes 18,500, 20,800, and 23,000lb Rear Axles; Shocks are 1.38in Bore

APPLICATIONS



FRONT



REAR

APPLICATIONS

GMC C7000

1980-1980	HD1214-0539	OE Interchange: 3192890, 4940606, 4940662, 4975497, 22002293, 22007701, 22007751, 22012095; With Conventional or Tilt Cab; With 5,000 or 7,000lb Axle; Shocks are 1.38in Bore	HD1214-0539	OE Interchange: 22012095, 22012166, 4940606; With Conventional Cab; With 97" Bumper to Back of Cab; With 20,800lb or 23,000lb Axle; Shocks are 1.38in Bore
------------------	--------------------	---	--------------------	--

GMC C7000 Topkick

1990-1996			HD1215-0156	OE Interchange: 22064233; Drive Axle; With Conventional Cab; With 23,000lb Axle; Taper Leaf Spring; Shocks are 1.75in Bore
1990-1996			HD1215-0133	OE Interchange: 12474915, 15963161; Drive Axle; With Hendrickson Air Suspension; With 21,000 to 23,000lb Axle; With Conventional Cab; Shocks are 1.75in Bore
1990-1996			HD1215-0045	OE Interchange: 12474917, 15740554; Drive Axle; With Hendrickson Air Suspension; With Conventional Cab; Shocks are 1.75in Shocks
1990-1996			HD1214-0561	OE Interchange: 22064232; Bus Chassis; With 15,000 to 21,000 Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1990-1996	HD1214-0556	OE Interchange: 15588554, 22064230; With Conventional Cab; Shocks are 1.38in Bore	HD1215-0044	OE Interchange: 22064402; With Conventional Cab; Low Profile Vehicle; With 21,000lb Axle; Taper Leaf Springs Suspension; Shocks are 1.75in Bore
1990-1996			HD1215-0108	OE Interchange: 22064432; Conventional Cab; With 15,000 to 21,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore

GMC C7500 Topkick

2003-2009			HD1215-0112	OE Interchange: 15782915, 15185643, 15185644; With Conventional Cab; Drive Axle; With Hendrickson RS-460 Suspension; With 12,000 to 15,000lb Axle with Leaf Springs; Shocks are 1.75in Bore
2003-2009			HD1215-0120	OE Interchange: 88963409; With Conventional Cab; Low Profile Vehicle; With 12,000 to 18,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore
2000-2007	HD1215-0081	OE Interchange: 15123676, 15174898, 15887728, 15588554, 15174298, 15192385, 88982682, 22064230; Steering Axle; Shocks are 1.75in Bore		



FRONT



REAR

APPLICATIONS

GMC C7500 Topkick				
1997-2002			HD1215-0156	OE Interchange: 22064233; Drive Axle; With Conventional Cab; With 23,000lb Axle; Taper Leaf Spring; Shocks are 1.75in Bore
1997-2002			HD1215-0133	OE Interchange: 12474915, 15963161; Drive Axle; With Hendrickson Air Suspension; With 21,000 to 23,000lb Axle; With Conventional Cab; Shocks are 1.75in Bore
1997-2002			HD1215-0045	OE Interchange: 12474917, 15740554; Drive Axle; With Hendrickson Air Suspension; With Conventional Cab; Shocks are 1.75in Shocks
1997-2002	HD1214-0556	OE Interchange: 15588554, 22064230; With Conventional Cab; Shocks are 1.38in Bore	HD1214-0561	OE Interchange: 22064232; Bus Chassis; With 15,000 to 21,000 Multi Leaf Spring Suspension; Shocks are 1.38in Bore

GMC C8500 Topkick				
2003-2009			HD1215-0112	OE Interchange: 15782915, 15185643, 15185644; With Conventional Cab; Drive Axle; With Hendrickson RS-460 Suspension; With 12,000 to 15,000lb Axle with Leaf Springs; Shocks are 1.75in Bore
2003-2009			HD1215-0120	OE Interchange: 88963409; With Conventional Cab; Low Profile Vehicle; With 12,000 to 18,000lb Axle; With Leaf Spring Suspension; Shocks are 1.75in Bore
2003-2007	HD1215-0081	OE Interchange: 15123676, 15174898, 15887728, 15588554, 15174298, 15192385, 88982682, 22064230; Steering Axle; Shocks are 1.75in Bore		

GMC G35				
1978-1978			HD1214-0606	Drive Axle; With Recreational Package; Standard Cab Only
1975-1978	HD1214-0555	With Recreational Package	HD1214-0534	(Cutaway Van) OE Interchange: 90044769, 90044770; With Recreation Package; With Neway Tag Axle TA-3-CA; Shocks are 1.38in Bore

GMC G35/G3500 Van				
1970-1974	HD1214-0555	With Recreational Package		

GMC G3500				
1993-1996	HD1214-0555	With Recreational Package		



FRONT



REAR

APPLICATIONS

GMC G3500

1979-1992	HD1214-0555	With Recreational Package	HD1214-0534	(Cutaway Van) OE Interchange: 90044769, 90044770; With Recreation Package; With Neway Tag Axle TA-3-CA; Shocks are 1.38in Bore
1979-1996			HD1214-0594	(Cutaway Van) Drive Axle; With Recreational Package
1979-1991			HD1214-0606	Drive Axle; With Recreational Package; Standard Cab Only

GMC P35

1975-1978	HD1215-0116	(Stripped Chassis) Excludes Monobeam Front Suspension	HD1215-0098	(Stripped Chassis) All Models
-----------	-------------	---	-------------	-------------------------------

GMC P35/P3500 Van

1973-1974	HD1215-0116	With Motorhome Chassis; Excludes Monobeam Front Suspension	HD1215-0098	With Motorhome Chassis
-----------	-------------	--	-------------	------------------------

GMC P3500

1985-1985			HD1214-0594	(Stripped Chassis) With Monobeam Front Suspension
1979-1999	HD1215-0116	(Stripped Chassis) Excludes Monobeam Front Suspension	HD1215-0098	(Stripped Chassis) Drive Axle

GMC Savana 3500

1996-2002			HD1294-0001	With Dual Rear Wheels
-----------	--	--	-------------	-----------------------

GMC T6500

2004-2007	HD1215-0081	OE Interchange: 15125676, 88982682; Steering Axle; Shocks are 1.75in Bore		
1997-2002	HD1215-0156	OE Interchange: 22064804, 22165187; Steering Axle; Low Profile; FL1 8,000lb Axle; Shocks are 1.75in Bore	HD1215-0156	OE Interchange: 22064233; Drive Axle; With Tilt Cab; With 23,000lb Axle; Taper Leaf Spring; Shocks are 1.75in Bore
1997-2002			HD1215-0133	OE Interchange: 12474915, 15963161; Drive Axle; With Tilt Cab; With Hendrickson Air Suspension; With 23,000lb Axle; Shocks are 1.75in Bore
1997-2002			HD1215-0045	OE Interchange: 12474917, 15963161; With Hendrickson Air Suspension; Drive Axle; Shocks are 1.75in Bore
1997-2002			HD1214-0561	OE Interchange: 22064232; With Tilt Cab; Drive Axle; 15,000 to 23,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1997-2002	HD1215-0031	Steering Axle; Excludes Low Profile Option; OE Interchange: 22064805 and 22165188; Shocks are 1.75in Bore	HD1215-0039	With 16,900lb Drive Axle; With Taper Leaf Spring; OE Interchange 22064489; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

GMC T7500

2004-2007	HD1215-0081	OE Interchange: 15125676, 88982682; Steering Axle; Shocks are 1.75in Bore		
1997-2002	HD1215-0156	OE Interchange: 22064804, 22165187; Steering Axle; Low Profile; FL1 8,000lb Axle; Shocks are 1.75in Bore	HD1215-0156	OE Interchange: 22064233; Drive Axle; With Tilt Cab; With 23,000lb Axle; Taper Leaf Spring; Shocks are 1.75in Bore
1997-2002			HD1215-0133	OE Interchange: 12474915, 15963161; Drive Axle; With Tilt Cab; With Hendrickson Air Suspension; With 23,000lb Axle; Shocks are 1.75in Bore
1997-2002			HD1215-0045	OE Interchange: 12474917, 15963161; With Hendrickson Air Suspension; Drive Axle; Shocks are 1.75in Bore
1997-2002			HD1214-0561	OE Interchange: 22064232; With Tilt Cab; Drive Axle; 15,000 to 23,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1997-2002	HD1215-0031	Steering Axle; Excludes Low Profile Option; OE Interchange: 22064805 and 22165188; Shocks are 1.75in Bore	HD1215-0039	With 16,900lb Drive Axle; With Taper Leaf Spring; OE Interchange 22064489; Shocks are 1.75in Bore

GMC W4500 Forward

2003-2008		OE Interchange: 8972536210; Shocks are 1.38in Bore	HD1214-0540	
2000-2009	HD1214-0540	OE Interchange: 8972536200; Shocks are 1.38in Bore		
1992-2009			HD1214-0571	OE Interchange: 8972536510; Shocks are 1.38in Bore
1992-1999	HD1214-0604	OE Interchange: 1516302000; Steering Axle; Shocks are 1.38in Bore		

GMC W5500 Forward

2003-2008			HD1214-0540	OE Interchange: 8972536210; Shocks are 1.38in Bore
2000-2009	HD1214-0540	OE Interchange: 8972536200; Shocks are 1.38in Bore	HD1214-0571	OE Interchange: 8972536510; Shocks are 1.38in Bore
1988-1993	HD1214-0604	OE Interchange: 1516302000; Steering Axle; Shocks are 1.38in Bore		
1988-1989	HD1213-0734	OE Interchange: 1516302191; Shocks are 1.38 in Bore	HD1214-0571	OE Interchange: 8972536510; Shocks are 1.38in Bore

GMC W7500 Forward

1986-1996	HD1214-0604	OE Interchange: 1516302000; Steering Axle; Shocks are 1.38in Bore		
-----------	-------------	---	--	--



FRONT

REAR



APPLICATIONS

Hino 145			
2005-2010	HD1215-0071	OE Interchange: 485003710A, 485003710, S485003710; Shocks are 1.78in Bore	
Hino 165			
2005-2010	HD1215-0071	OE Interchange: 485003710A, 485003710, S485003710; Shocks are 1.78in Bore	
Hino 185			
2005-2010	HD1215-0071	OE Interchange: 485003710A, 485003710, S485003710; Shocks are 1.78in Bore	
Hino FD17			
1989-1991	HD1214-0641	OE Interchange: 485001801; Shocks are 1.38in Bore	HD1215-0107 OE Interchange: 485301880; Shocks are 1.75in Bore
Hino FD20			
1992-1992	HD1214-0641	OE Interchange: 485001801; Shocks are 1.38in Bore	
Hino FD2218			
1993-1997	HD1214-0641	OE Interchange: 485001801; Shocks are 1.38in Bore	HD1215-0107 OE Interchange: 485301880; Shocks are 1.75in Bore
Hino FD2218LP			
1993-1997	HD1214-0641	OE Interchange: 485001801; Shocks are 1.38in Bore	HD1215-0107 OE Interchange: 485301880; Shocks are 1.75in Bore
Hino FD2220			
1998-2002	HD1214-0641	OE Interchange: 485001801; Shocks are 1.38in Bore	HD1215-0107 OE Interchange: 485301880; Shocks are 1.75in Bore
Hino FD2320			
2003-2004	HD1214-0641	OE Interchange: 485001801; Shocks are 1.38in Bore	
Hino FE17			
1984-1991	HD1214-0640	OE Interchange: 485001541; Shocks are 1.38in Bore	
Hino FE19			
1985-1991	HD1214-0640	OE Interchange: 485001541; Shocks are 1.38in Bore	
Hino FE20			
1992-1992	HD1214-0640	OE Interchange: 485001541; Shocks are 1.38in Bore	



FRONT



REAR

APPLICATIONS

Hino FE2618			
1993-1997	HD1214-0560	OE Interchange: 485001940, 485001941; Shocks are 1.38in Bore	
Hino FE2620			
1998-2004	HD1214-0560	OE Interchange: 485001940, 485001941; Shocks are 1.38in Bore	
Hino FF17			
1984-1991	HD1214-0560	OE Interchange: 485001940, 485001941; Shocks are 1.38in Bore	
Hino FF19			
1984-1991	HD1214-0560	OE Interchange: 485001940, 485001941; Shocks are 1.38in Bore	
Hino FF20			
1992-1992	HD1214-0560	OE Interchange: 485001940, 485001941; Shocks are 1.38in Bore	
Hino FF23			
1992-1992	HD1214-0560	OE Interchange: 485001940, 485001941; Shocks are 1.38in Bore	
Hino FF3018			
1993-1997	HD1214-0560	OE Interchange: 485001940, 485001941; Shocks are 1.38in Bore	
Hino FF3020			
1993-1998	HD1214-0560	OE Interchange: 485001940, 485001941; Shocks are 1.38in Bore	
Hino GC17			
1990-1991	HD1214-0641	OE Interchange: 485001801; Shocks are 1.38in Bore	
Hino GC20			
1992-1992	HD1214-0641	OE Interchange: 485001801; Shocks are 1.38in Bore	
IC Corporation BE School Bus			
2008-2015	HD1214-0558	OE Interchange: 3605735C1, 3605735C2; Shocks are 1.38in Bore	
IC Corporation CE School Bus			
2010-2018	HD1215-0084	OE Interchange: 3578105C1, 3578105C2; With 9,000lb or 10,000lb Axle; Shocks are 1.75in Bore	



FRONT



REAR

APPLICATIONS

IC Corporation CE School Bus

2010-2016	HD1214-0572	OE Interchange: 3578105C1; Shocks are 1.38in Bore	HD1215-0063	OE Interchange: 501906C91, 501906C92; Shocks are 1.38in Bore
2003-2004	HD1214-0572	OE Interchange: 3578105C1; Shocks are 1.38in Bore	HD1215-0063	OE Interchange: 501906C91; Shocks are 1.38in Bore
2003-2004	HD1215-0084	OE Interchange: 3578105C1, 3578105C2; With 9,000lb or 10,000lb Axle; Shocks are 1.75in Bore		

IC Corporation RE School Bus

2003-2016	HD1214-0545	OE Interchange: 472412C91; Shocks are 1.38in Bore	HD1214-0530	OE Interchange: 1660846C91, 537524C91; Shocks are 1.38in Bore
2003-2016			HD1214-0557	OE Interchange: 1660846C91; Shocks are 1.38in Bore
2003-2016			HD1215-0028	OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; Shocks are 1.75in Bore
2003-2016	HD1214-0526	OE Interchange: 540395C92; Shocks are 1.38in Bore	HD1215-0063	OE Interchange: 501906C91; Shocks are 1.38in Bore

International 1754

1981-1989	HD1214-0661	OE Interchange: 472367C91; Steering Axle; With Front Axle Codes 02071, 02073, 02101; Shocks are 1.38in Bore		
1981-1989	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1215-0063	OE Interchange: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187; Shocks are 1.38in Bore

International 1452SC

1987-1992	HD1214-0526	OE Interchange: 540395C92; Steering Axle; Shocks are 1.38in Bore	HD1215-0063	OE Interchange: 501906C91; Drive Axle; Shocks are 1.38in Bore
1987-1992	HD1214-0545	OE Interchange: 472412C91, 586724C91; Steering Axle; Shocks are 1.38in Bore	HD1214-0557	OE Interchange: 1660846C91; Drive Axle; Shocks are 1.38in Bore
1987-1992			HD1215-0028	OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore

International 1652SC

1986-1992	HD1214-0545	OE Interchange: 472412C91, 586724C91; Steering Axle; Shocks are 1.38in Bore	HD1214-0557	OE Interchange: 1660846C91; Drive Axle; Shocks are 1.38in Bore
1986-1992	HD1214-0526	OE Interchange: 540395C92; Steering Axle; Shocks are 1.38in Bore	HD1215-0028	OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore



FRONT



REAR

International 1652SC				
1986-1992			HD1215-0063	OE Interchange: 501906C91; Drive Axle; Shocks are 1.38in Bore
International 1654				
1980-1989	HD1214-0661	OE Interchange: 472367C91; Steering Axle; With Front Axle Codes 02071, 02073, 02101; Shocks are 1.38in Bore		
1980-1989	HD1214-0656	OE Interchange: 1663471C1; Low Profile Vehicle; Steering Axle; Shocks are 1.38in Bore	HD1215-0063	OE Interchange: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187; Shocks are 1.38in Bore
1980-1989	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1214-0557	OE Interchange: 1660846C91; Low Profile Vehicle; Steering Axle; Shocks are 1.38in Bore
International 1724				
1980-1984	HD1214-0661	OE Interchange: 472367C91; Steering Axle; With Front Axle Codes 02071, 02073, 02101; Shocks are 1.38in Bore		
1980-1984	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1215-0063	OE Interchange: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187; Shocks are 1.38in Bore
International 1824				
1979-1984	HD1214-0661	OE Interchange: 472367C91; Steering Axle; With Front Axle Codes 02071, 02073, 02101; Shocks are 1.38in Bore	HD1215-0063	OE International: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187
International 1854				
1981-1989	HD1214-0661	OE Interchange: 472367C91; Steering Axle; With Front Axle Codes 02071, 02073, 02101; Shocks are 1.38in Bore	HD1215-0063	OE International: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187
International 1924 S				
1979-1982	HD1214-0661	OE Interchange: 472367C91, 472414C91; Steering Axle; Shocks are 1.38in Bore	HD1215-0063	OE International: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187
International 1925 S				
1979-1982	HD1214-0661	OE Interchange: 472367C91; Steering Axle; With Front Axle Codes 02071, 02073, 02101; Shocks are 1.38in Bore	HD1215-0063	OE International: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187

APPLICATIONS



FRONT



REAR

APPLICATIONS

International 1954			
1979-1989	HD1214-0661	OE Interchange: 472367C91; Steering Axle; With Front Axle Codes 02071, 02073, 02101; Shocks are 1.38in Bore	HD1215-0063
			OE International: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187

International 1955			
1981-1989	HD1214-0661	OE Interchange: 472367C91; Steering Axle; With Front Axle Codes 02071, 02073, 02101; Shocks are 1.38in Bore	HD1215-0063
			OE International: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187

International 2155			
1984-1989	HD1214-0661	OE Interchange: 472367C91; Steering Axle; With Front Axle Codes 02071, 02073, 02101; Shocks are 1.38in Bore	HD1215-0063
			OE International: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187

International 2275			
1981-1989			HD1115-0078
			OE Interchange: 534464C1; With Ridewell Air Suspension; Non-Gas Shock Absorber
1981-1989	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1215-0028
			OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore
1981-1989			HD1214-0580
			OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1981-1989			HD1214-0530
			OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore

International 2554			
1981-2002	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1215-0028
			OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore
1981-2002			HD1115-0078
			OE Interchange: 534464C1; With Ridewell Air Suspension; Non-Gas Shock Absorber
1981-2002			HD1215-0063
			OE Interchange: 501906C91; Drive Axle; With International Vari-Rate Rear Suspension; Shocks are 1.38in Bore
1981-2002			HD1214-0580
			OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1981-2002			HD1214-0530
			OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore



FRONT



REAR

APPLICATIONS

International 2574				
2001-2003			HD1215-0028	OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore
1995-1999			HD1215-0028	OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore
1990-2003			HD1115-0078	OE Interchange: 534464C1; With Ridewell Air Suspension; Non-Gas Shock Absorber
1990-2003			HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore
1990-1993			HD1215-0028	OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore
1990-2003	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1214-0580	OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1984-1986	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1214-0580	OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1984-1986			HD1115-0078	OE Interchange: 534464C1; With Ridewell Air Suspension; Non-Gas Shock Absorber
1984-1986			HD1215-0028	OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore
1981-2003			HD1215-0063	OE Interchange: 501906C91; Drive Axle; With International Vari-Rate Rear Suspension; Shocks are 1.38in Bore

International 2575				
1984-1989			HD1115-0078	OE Interchange: 534464C1; With Ridewell Air Suspension; Non-Gas Shock Absorber
1984-1989	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1214-0580	OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1984-1989			HD1215-0028	OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

International 2575

1984-1989			HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore
-----------	--	--	--------------------	--

International 2654

1999-2000	HD1214-0545	OE Interchange: 472412C91; Steering Axle; Shocks are 1.38in Bore	HD1215-0028	OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore
1989-2002			HD1215-0063	OE Interchange: 501906C91; Drive Axle; With International Vari-Rate Rear Suspension; Shocks are 1.38in Bore

International 2674

1981-2003			HD1215-0063	OE Interchange: 501906C91; Drive Axle; With International Vari-Rate Rear Suspension; Shocks are 1.38in Bore
1981-2003	HD1214-0545	OE Interchange: 472412C91; Steering Axle; Shocks are 1.38in Bore	HD1215-0028	OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore

International 3000

1996-2002	HD1215-0022	OE Interchange: 3533357C1; School Bus Cab Forward; With 10,000-14,000lb Axle; Shocks are 1.75in Bore		
1996-2002	HD1215-0084	OE Interchange: 3533356C1; School Bus Cab Forward; With 6,000 to 8,000lb Axle; Shocks are 1.75in Bore		
1996-2002	HD1214-0572	OE Interchange: 3533356C1; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		

International 3000FE

1997-1999	HD1215-0022	OE Interchange: 3533357C1; With 10,000-14,000lb Axle; Shocks are 1.75in Bore		
1997-1999	HD1215-0084	OE Interchange: 3533356C1; School Bus Cab Forward; With 6,000 to 8,000lb Axle; Shocks are 1.75in Bore		
1997-1999	HD1214-0572	OE Interchange: 3533356C1; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		

International 3000IC

2000-2002	HD1215-0022	OE Interchange: 3533357C1; With 10,000-14,000lb Axle; Shocks are 1.75in Bore		
2000-2002	HD1215-0084	OE Interchange: 3533356C1; School Bus Cab Forward; With 6,000 to 8,000lb Axle; Shocks are 1.75in Bore		



FRONT



REAR

International 3000IC

2000-2002	HD1214-0572	OE Interchange: 3533356C1; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		
------------------	--------------------	---	--	--

International 3000RE

2005-2005	HD1215-0022	OE Interchange: 3533357C1; With 10,000-14,000lb Axle; Shocks are 1.75in Bore		
2005-2005	HD1215-0084	OE Interchange: 3533356C1; School Bus Cab Forward; With 6,000 to 8,000lb Axle; Shocks are 1.75in Bore		
2005-2005	HD1214-0572	OE Interchange: 3533356C1; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		
2002-2002	HD1215-0022	OE Interchange: 3533357C1; With 10,000-14,000lb Axle; Shocks are 1.75in Bore		
2002-2002	HD1215-0084	OE Interchange: 3533356C1; School Bus Cab Forward; With 6,000 to 8,000lb Axle; Shocks are 1.75in Bore		
2002-2002	HD1214-0572	OE Interchange: 3533356C1; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		
1996-2000	HD1215-0022	OE Interchange: 3533357C1; With 10,000-14,000lb Axle; Shocks are 1.75in Bore		
1996-2000	HD1215-0084	OE Interchange: 3533356C1; School Bus Cab Forward; With 6,000 to 8,000lb Axle; Shocks are 1.75in Bore		
1996-2000	HD1214-0572	OE Interchange: 3533356C1; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		

International 3200

2002-2011	HD1214-0572	OE Interchange: 3533356C1; With 8,000lb Axle; Shocks are 1.38in Bore		
2002-2011	HD1215-0084	OE Interchange: 3533357C1; School Bus Cab Forward; With 10,000-14,000lb Axle; Shocks are 1.75in Bore		

International 3400

1996-2002	HD1215-0022	OE Interchange: 3533357C1; School Bus Cab Forward; With 10,000-14,000lb Axle; Shocks are 1.75in Bore		
1996-2002	HD1215-0084	OE Interchange: 3533357C1; School Bus Cab Forward; With 10,000-14,000lb Axle; Shocks are 1.75in Bore		
1996-2002	HD1214-0572	OE Interchange: 3533356C1; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		
1996-2002	HD1214-0526	OE Interchange: 250441901; School Bus Cab Forward; Shocks are 1.38in Bore		

APPLICATIONS



FRONT



REAR

APPLICATIONS

International 3700

1990-1994	HD1214-0526	OE Interchange: 540395C92; School Bus Cab Forward; Shocks are 1.38in Bore	HD1215-0063	(School Bus- Cab Forward) OE Interchange: 501906C91; Shocks are 1.38in Bore
1990-1994	HD1214-0545	OE Interchange: 472412C91; Shocks are 1.38in Bore	HD1214-0557	OE Interchange: 1660846C91; Shocks are 1.38in Bore
1990-1994			HD1215-0028	OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; Bus- Cab Forward; With International Corporate Air Suspension; Shocks are 1.75in Bore
1990-1994			HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore

International 3800

1990-2004	HD1214-0526	OE Interchange: 540395C92; Shocks are 1.38in Bore	HD1215-0063	OE Interchange: 501906C91; Shocks are 1.38in Bore
1990-2004			HD1214-0557	OE Interchange: 1660846C91; Shocks are 1.38in Bore
1990-2004			HD1215-0028	OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; Bus- Cab Forward; With International Corporate Air Suspension; Shocks are 1.75in Bore
1990-2004	HD1214-0545	(School Bus- Cab Forward) OE Interchange: 472412C91; Shocks are 1.38in Bore	HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore
1987-1987	HD1214-0526	OE Interchange: 540395C92; Shocks are 1.38in Bore	HD1215-0063	OE Interchange: 501906C91; Shocks are 1.38in Bore
1987-1987	HD1214-0545	OE Interchange: 472412C91; Shocks are 1.38in Bore	HD1214-0557	OE Interchange: 1660846C91; Shocks are 1.38in Bore
1987-1987			HD1215-0028	OE Interchange: 1590035C1, 1675455C1, 2018987C1, 501553C91; Bus- Cab Forward; With International Corporate Air Suspension; Shocks are 1.75in Bore
1987-1987			HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore

International 3900FC

1996-1996	HD1215-0108	OE Interchange: 1677707C1, 2015557C1; Shocks are 1.75in Bore	HD1215-0028	OE Interchange: 2018987C1; With International Corporate Air Suspension; With Genesis Front Engine; Shocks are 1.75in Bore
1996-1996	HD1214-0568	OE Interchange: 467371C91; Shocks are 1.35in Bore	HD1214-0568	OE Interchange: 467371C91; Shocks are 1.35in Bore
1996-1996			HD1215-0063	OE Interchange: 501906C91; With Pusher Rear Engine; Shocks are 1.38in Bore



FRONT



REAR

APPLICATIONS

International 3900FC

1991-1994	HD1215-0108	OE Interchange: 1677707C1, 2015557C1; Shocks are 1.75in Bore	HD1215-0028	OE Interchange: 2018987C1; With International Corporate Air Suspension; With Genesis Front Engine; Shocks are 1.75in Bore
1991-1994	HD1214-0568	OE Interchange: 467371C91; Shocks are 1.35in Bore	HD1214-0568	OE Interchange: 467371C91; Shocks are 1.35in Bore
1991-1994		OE Interchange: 467371C91; Shocks are 1.35in Bore	HD1215-0063	OE Interchange: 501906C91; With Pusher Rear Engine; Shocks are 1.38in Bore

International 400

1991-1991	HD1213-0734	OE Interchange: 56101Z5008; Shocks are 1.38 in Bore		
-----------	--------------------	---	--	--

International 4200

2002-2008	HD1215-0022	OE Interchange: 3533357C1; With 10,000-14,000lb Axle; Shocks are 1.75in Bore	HD1215-0147	OE Interchange: 3553628C1; Drive Axle; With IAS Suspension; Low Profile; With Tapered Rail; With 5.3" Ride Height; Shocks are 1.75in Bore
2002-2008	HD1215-0084	OE Interchange: 3533356C1; Steering Axle; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		
2002-2008	HD1214-0572	OE Interchange: 3533356C1; Steering Axle; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		

International 4200LP

2003-2008	HD1215-0022	OE Interchange: 3533357C3; With 10,000-14,000lb Axle; Shocks are 1.75in Bore		
2003-2008	HD1214-0572	OE Interchange: 3533356C1; Steering Axle; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		
2003-2008	HD1215-0084	OE Interchange: 3533356C1; Steering Axle; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		

International 4300

2016-2019	HD1215-0022	OE Interchange: 6127714C1; With 11,000-14,000lb Front Suspension; Shocks are 1.75in Bore		
2016-2019	HD1214-0572	OE Interchange: 6127088C1; With 9,000-10,000lb Front Suspension; Shocks are 1.38in Bore		
2016-2019	HD1215-0084	OE Interchange: 6127088C1; With 9,000-10,000lb Front Suspension; Shocks are 1.75in Bore		



FRONT



REAR

APPLICATIONS

International 4300

2002-2008	HD1215-0022	OE Interchange: 3533357C1; With 10,000-14,000lb Axle; Shocks are 1.75in Bore	HD1215-0147	OE Interchange: 3553628C1; Drive Axle; With IAS Suspension; Low Profile; With Tapered Rail; With 5.3" Ride Height; Shocks are 1.75in Bore
2002-2008	HD1215-0084	OE Interchange: 3533356C1; Steering Axle; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		
2002-2008	HD1214-0572	OE Interchange: 3533356C1; Steering Axle; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		

International 4300LP

2002-2008	HD1215-0022	OE Interchange: 3533357C1; With 10,000-14,000lb Axle; Shocks are 1.75in Bore	HD1215-0147	OE Interchange: 3553628C1; Drive Axle; With IAS Suspension; Low Profile; With Tapered Rail; With 5.3" Ride Height; Shocks are 1.75in Bore
2002-2008	HD1215-0084	OE Interchange: 3533356C1; Steering Axle; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		
2002-2008	HD1214-0572	OE Interchange: 3533356C1; Steering Axle; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		

International 4400

2002-2008	HD1215-0022	OE Interchange: 3533357C1; Steering Axle; With 10,000-14,000lb Axle; Shocks are 1.75in Bore	HD1215-0147	OE Interchange: 3553628C1; Drive Axle; With IAS Suspension; Low Profile; With Tapered Rail; With 5.3" Ride Height; Shocks are 1.75in Bore
2002-2008	HD1215-0084	OE Interchange: 3533356C1; Steering Axle; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		
2002-2008	HD1214-0572	OE Interchange: 3533356C1; Steering Axle; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		

International 4400LP

2002-2008	HD1215-0022	OE Interchange: 3533357C1; Steering Axle; With 10,000-14,000lb Axle; Shocks are 1.75in Bore	HD1215-0147	OE Interchange: 3553628C1; Drive Axle; With IAS Suspension; Low Profile; With Tapered Rail; With 5.3" Ride Height; Shocks are 1.75in Bore
2002-2008	HD1215-0084	OE Interchange: 3533356C1; Steering Axle; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		
2002-2008	HD1214-0572	OE Interchange: 3533356C1; Steering Axle; With 6,000 to 8,000lb Axle; Shocks are 1.38in Bore		



FRONT



REAR

APPLICATIONS

International 4600

1990-1994	HD1213-0679	(Cab Shock) OE Interchange: 12011044; With Link Cab Suspension		
1990-1994	HD1214-0545	OE Interchange: 472412C91, 586724C91; Steering Axle; Shocks are 1.38in Bore		
1990-1994	HD1215-0114	OE Interchange: 1667520C1; Steering Axle; Shocks are 1.75in Bore	HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore

International 4600LP

1990-1994	HD1214-0526	OE Interchange: 540395C92; Steering Axle; Shocks are 1.38in Bore	HD1215-0063	OE Interchange: 501906C91; Drive Axle; Shocks are 1.38in Bore
1990-1994			HD1214-0557	OE Interchange: 1660846C91; Drive Axle; With Air Suspension; Shocks are 1.38in Bore

International 4700

1990-2003	HD1213-0679	(Cab Shock) OE Interchange: 12011044; With Link Cab Suspension		
1990-2003	HD1214-0545	OE Interchange: 472412C91, 586724C91; Steering Axle; Shocks are 1.38in Bore		
1990-2003	HD1215-0114	OE Interchange: 1667520C1; Steering Axle; Shocks are 1.75in Bore	HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore

International 4700LP

1990-2002	HD1214-0526	OE Interchange: 540395C92; Steering Axle; Shocks are 1.38in Bore	HD1214-0557	OE Interchange: 1660846C91; Drive Axle; With Air Suspension; Shocks are 1.38in Bore
-----------	-------------	--	-------------	---

International 4800

1990-2003	HD1214-0545	OE Interchange: 472412C91, 586724C91; Steering Axle; Shocks are 1.38in Bore		
1990-2003	HD1215-0114	OE Interchange: 1667520C1; Steering Axle; Shocks are 1.75in Bore	HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore
1990-2003	HD1213-0679	(Cab Shock) OE Interchange: 12011044; With Link Cab Suspension		

International 4900

1990-2003	HD1213-0679	(Cab Shock) OE Interchange: 12011044; With Link Cab Suspension		
1990-2003	HD1215-0052	OE Interchange: 2015556C1; Steering Axle; With Dual Doors; Shocks are 1.75in Bore		



FRONT



REAR

APPLICATIONS

International 4900				
1990-2003	HD1214-0545	OE Interchange: 472412C91, 586724C91; Steering Axle; Shocks are 1.38in Bore		
1990-2003	HD1215-0114	OE Interchange: 1667520C1; Steering Axle; Shocks are 1.75in Bore	HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore
International 500				
1991-1991	HD1213-0708	OE Interchange: 56101Z5011; Shocks are 1.38in Bore		
International 5070				
1981-2000			HD1214-0539	OE Interchange: 2029200C91; Drive Axle; With Neway 14UKY Air Suspension; Shocks are 1.38in Bore
1981-1987	HD1215-0113	OE Interchange: 426744R91, 453576C91, 477132C1; Steering Axle; Shocks are 1.75in Bore		
International 5600i				
2004-2013			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004; With Hendrickson HMX 400 Haulmax Suspension; With Hendrickson HMX 460 Haulmax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
International 7100				
1990-1995	HD1214-0545	OE Interchange: 472412C91, 586724C91; Steering Axle; Shocks are 1.38in Bore	HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore
International 8100				
1990-2003	HD1215-0052	OE Interchange: 1664788C2, 2015556C1, 3571713C1; Steering Axle; 12,000 to 14,000lb Axle; Shocks are 1.75in Bore	HD1215-0063	OE Interchange: 501906C91; Drive Axle; Shocks are 1.38in Bore
1990-2003	HD1215-0114	OE Interchange: 1667520C1; Steering Axle; Shocks are 1.75in Bore	HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore
1990-2003	HD1214-0545	OE Interchange: 472412C91, 3000070C91; Steering Axle; Excludes Axle Codes 02ADD & 2005; Shocks are 1.38in Bore	HD1214-0539	OE Interchange: 2029200C91; Drive Axle; With Neway 14UKY Air Suspension; Shocks are 1.38in Bore



FRONT



REAR

APPLICATIONS

International 8200

1990-1998	HD1215-0052	OE Interchange: 1664788C2, 2015556C1, 3571713C1; Steering Axle; 12,000 to 14,000lb Axle; Shocks are 1.75in Bore	HD1215-0063	OE Interchange: 501906C91; Drive Axle; Shocks are 1.38in Bore
1990-1998	HD1215-0114	OE Interchange: 1667520C1; Steering Axle; With 16,000 to 18,000lb Suspension; Shocks are 1.75in Bore	HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore
1990-1998	HD1214-0545	OE Interchange: 3000070C91; Steering Axle; Shocks are 1.38in Bore	HD1214-0539	OE Interchange: 2029200C91; Drive Axle; With Neway 14UKY Air Suspension; Shocks are 1.38in Bore

International 8300

1989-1994	HD1215-0052	OE Interchange: 1664788C2, 2015556C1, 3571713C1; Steering Axle; 12,000 to 14,000lb Axle; Shocks are 1.75in Bore	HD1215-0063	OE Interchange: 501906C91; Drive Axle; Shocks are 1.38in Bore
1989-1994	HD1215-0114	OE Interchange: 1667520C1; Steering Axle; With 16,000 to 18,000lb Suspension; Shocks are 1.75in Bore	HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore
1989-1994	HD1214-0545	OE Interchange: 3000070C91; Steering Axle; Shocks are 1.38in Bore	HD1214-0539	OE Interchange: 2029200C91; Drive Axle; With Neway 14UKY Air Suspension; Shocks are 1.38in Bore

International 8500 Transtar

2008-2011	HD1215-0022	OE Interchange: 3533357C1, 3588209C1, 3602060C1; Steering Axle; With 10,000 - 14,000lb Axle; Shocks are 1.75in Bore	HD1215-0041	OE Interchange: 3549099C2; Drive Axle With IAS Suspension; With 9.25" or 9.5" Ride Height; Shocks are 1.75in Bore
-----------	--------------------	---	--------------------	---

International 8600 Transtar

2008-2011	HD1215-0022	OE Interchange: 3533357C1, 3588209C1, 3602060C1; Steering Axle; With 10,000 - 14,000lb Axle; Shocks are 1.75in Bore	HD1215-0041	OE Interchange: 3549099C2; Drive Axle With IAS Suspension; With 9.25" or 9.5" Ride Height; Shocks are 1.75in Bore
-----------	--------------------	---	--------------------	---

International 9100 SBA

1998-1999	HD1215-0052	OE Interchange: 1664788C2, 2015556C1, 3571713C1; Steering Axle; 12,000 to 14,000lb Axle; Shocks are 1.75in Bore		
-----------	--------------------	---	--	--

International 9100I SBA

2000-2003	HD1215-0052	OE Interchange: 3571712C1, 3571713C1; With 12,000 to 14,000 Axle; Taper Leaf Spring Suspension; Steering Axle; Shocks are 1.75in Bore	HD1215-0127	OE Interchange: 3601600C1; Drive Axle; With International/Navistar IROS Flat floor; Shocks are 1.75in Bore
2000-2003	HD1214-0570	OE Interchange: 507202C1; Steering Axle; Set Back Axle; 12,000 to 14,000lb Axle; Taper Leaf Spring; Shocks are 1.38in Bore		



FRONT



REAR

International 9200I SBA

2000-2011	HD1214-0570	OE Interchange: 507202C1; Steering Axle; Set Back Axle; 12,000 to 14,000lb Axle; Taper Leaf Spring; Shocks are 1.38in Bore	HD1215-0127	OE Interchange: 3601600C1; Drive Axle; With International/Navistar IROS Flat floor; Shocks are 1.75in Bore
------------------	--------------------	--	--------------------	--

International 9300

1997-1999	HD1214-0570	OE Interchange: 507202C1; Steering Axle; Shocks are 1.38in Bore	HD1215-0066	OE Interchange: 1664149C1; FA231(02231) 16,000lb Drive Axle; Set Back Axle; Shocks are 1.75in Bore
1989-1999	HD1215-0162	OE Interchange: 503610C2; With 10,000-12,000lb Suspension; Shocks are 1.75 in Bore		
1989-1999	HD1215-0052	OE Interchange: 1664788C2, 2015556C1, 2032533C1, 3571713C1; With 12,000 to 14,000 Axle; Shocks are 1.75in Bore	HD1214-0539	OE Interchange: 2029200C91; Drive Axle; With Neway 14UKY Air Suspension; Shocks are 1.38in Bore
1989-1999	HD1214-0614	(Cab Shock) OE Interchange: 2023684C1, 2023685C1	HD1214-0580	OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1989-1999	HD1214-0533	OE Interchange: 503610C2; Steering Axle; Shocks are 1.38in Bore	HD1214-0533	OE Interchange: 503610C2; Drive Axle; With Hendrickson Air Suspension; Shocks are 1.38in Bore
1989-1999	HD1215-0114	OE Interchange: 1667520C1; Steering Axle; With 16,000 to 18,000lb Suspension; Shocks are 1.75in Bore	HD1214-0557	OE Interchange: 1660846C91; Drive Axle; With Air Suspension; Shocks are 1.38in Bore
1989-1995	HD1214-0570	OE Interchange: 507202C1; Steering Axle; Shocks are 1.38 in Bore	HD1215-0066	OE Interchange: 1664149C1; FA231(02231) 16,000lb Drive Axle; Set Back Axle; Shocks are 1.75in Bore

International 9400

1990-1999	HD1215-0162	OE Interchange: 503610C2; Steering Axle; Shocks are 1.75 in Bore		
1990-1999	HD1215-0114	OE Interchange: 1667520C1; Steering Axle; With 16,000 to 18,000lb Suspension; Shocks are 1.75in Bore	HD1214-0580	OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1990-1999	HD1215-0052	OE Interchange: 1664788C2, 2015556C1, 2032533C1, 3571713C1; Steering Axle; With 12,000 to 14,000 Axle; Shocks are 1.75in Bore	HD1214-0539	OE Interchange: 2029200C91; Drive Axle; With Neway 14UKY Air Suspension; Shocks are 1.38in Bore
1990-1999	HD1214-0533	OE Interchange: 503610C2; Steering Axle; Shocks are 1.38in Bore	HD1214-0533	OE Interchange: 503610C2; Drive Axle; With Hendrickson Air Suspension; Shocks are 1.38in Bore
1990-1999	HD1214-0570	OE Interchange: 507202C1; Steering Axle; Shocks are 1.38in Bore	HD1214-0557	OE Interchange: 1660846C91; Drive Axle; With Air Suspension; Shocks are 1.38in Bore
1990-1999	HD1214-0614	(Cab Shock) OE Interchange: 2023684C1, 2023685C1		

APPLICATIONS



FRONT



REAR

APPLICATIONS

International 9400I SBA

2011-2011	HD1215-0027	OE Interchange: 6127705C1, 3581106C1, 3581107C1, 3581109C1, 3581107C2, 3581107C3; With 12,000lb Axle		
2000-2010	HD1214-0570	OE Interchange: 507202C1; Steering Axle; 12,000 to 14,000lb Axle; With Taper Leaf Spring Suspension; Shocks are 1.38in Bore		
2000-2009	HD1215-0027	OE Interchange: 6127705C1, 3581106C1, 3581107C1, 3581109C1, 3581107C2, 3581107C3; With 12,000lb Axle		

International 9600

1989-1996	HD1215-0114	OE Interchange: 1667520C1; Steering Axle; With 16,000 to 18,000lb Suspension; Shocks are 1.75in Bore	HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore
1989-1996	HD1214-0533	OE Interchange: 503610C2; Steering Axle; Shocks are 1.38in Bore	HD1214-0533	OE Interchange: 503610C2; Drive Axle; With Hendrickson Air Suspension; Shocks are 1.38in Bore
1989-1996	HD1214-0570	OE Interchange: 507202C1; Steering Axle; Shocks are 1.38in Bore	HD1214-0580	OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1989-1996	HD1215-0162	OE Interchange: 00110808; With Hendrickson Airtex Front Suspension; Shocks are 1.75 in Bore		
1989-1996	HD1213-0651	(Cab Shock) OE Interchange: 12020054; With Link Cab Suspension		
1989-1996	HD1215-0052	OE Interchange: 1664788C2, 2015556C1, 2032533C1, 3571713C1; Steering Axle; With 12,000 to 14,000 Axle; Shocks are 1.75in Bore		

International 9700

1989-1996	HD1215-0114	OE Interchange: 1667520C1; Steering Axle; With Taper Leaf Spring Suspension; With 16,000 to 18,000lb Axle; Shocks are 1.75in Bore	HD1214-0580	OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1989-1996	HD1214-0533	OE Interchange: 503610C2; Steering Axle; Shocks are 1.38in Bore	HD1214-0533	OE Interchange: 503610C2; Drive Axle; With Hendrickson Air Suspension; Shocks are 1.38in Bore
1989-1996	HD1214-0570	OE Interchange: 507202C1; Steering Axle; Shocks are 1.38in Bore	HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore
1989-1996	HD1213-0651	(Cab Shock) OE Interchange: 12020054; With Link Cab Suspension		
1989-1996	HD1215-0162	OE Interchange: 00110808; With Hendrickson Airtex Front Suspension; Shocks are 1.75 in Bore		



FRONT



REAR

APPLICATIONS

International 9700

1989-1996	HD1215-0052	OE Interchange: 1664788C2, 2015556C1, 2032533C1, 3571713C1; Steering Axle; With 12,000 to 14,000 Axle; Shocks are 1.75in Bore		
-----------	-------------	---	--	--

International 9800 SBA

1996-1999			HD1215-0115	OE Interchange: 2029200C91; With Neway AD-246-10 Air Suspension; With 60 inch Axle spacing; Shocks are 1.75in Bore
-----------	--	--	-------------	--

International 9900I

2011-2015			HD1215-0045	OE Interchange: 47902024; Drive Axle; With Hendrickson HAS-230, HAS-400, or HAS-460 Air Suspension; Shocks are 1.75in Bore
2010-2015	HD1215-0027	OE Interchange: 3581106C1, 3581107C1, 3581109C1, 3584535C1; Steering Axle; With 12,000-14,000lb Axle; With Taper Leaf Spring; Shocks are 1.75in Bore		
2010-2015	HD1215-0153	OE Interchange: 3977759C1; Steering Axle; With 12,000 to 14,000lb Axle; With Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
2010-2015	HD1214-0573	(Cab Shock) OE Interchange: 12011043, 12011047, 12011049, 12021043, 2614014C1; With Cab Suspension		
2010-2015	HD1215-0052	OE Interchange: 3571711C1, 3571713C1; Steering Axle; With 12,000 to 14,000lb Axle; Taper Leaf Spring Suspension; Shocks are 1.75in Bore		
2010-2015	HD1214-0537	(Cab Shock) OE Interchange: 12010254; With Link Cab Suspension		
2010-2015	HD1214-0570	OE Interchange: 507202C1; Steering Axle; 12,000 to 14,000lb Axle; With Taper Leaf Spring Suspension; Shocks are 1.38in Bore	HD1215-0055	OE Interchange: 3549100C1 and 3578858C1; Drive Axle with IAS Suspension; With 9.25" or 9.5" Ride Height; Shocks are 1.75in Bore

International 9900IX

2000-2009	HD1215-0027	OE Interchange: 3581106C1, 3581107C1, 3581109C1, 3584535C1; Steering Axle; With 12,000-14,000lb Axle; With Taper Leaf Spring; Shocks are 1.75in Bore		
2010-2015	HD1214-0537	(Cab Shock) OE Interchange: 12010254		
2000-2009	HD1215-0153	OE Interchange: 3977759C1; Steering Axle; With 12,000 to 14,000lb Axle; With Taper Leaf Spring Suspension; Shocks are 1.75in Bore		



FRONT



REAR

APPLICATIONS

International 9900IX

2000-2009	HD1214-0573	(Cab Shock) OE Interchange: 12011043, 12011047, 12011049, 12021043, 2614014C1; With Cab Suspension	HD1215-0045	OE Interchange: 47902024; Drive Axle; With Hendrickson HAS-230, HAS-400, or HAS-460 Air Suspension; Shocks are 1.75in Bore
2000-2009	HD1214-0570	OE Interchange: 507202C1; Steering Axle; Set Back Axle; 12,000 to 14,000lb Axle; Taper Leaf Spring; Shocks are 1.38in Bore	HD1215-0055	OE Interchange: 3549100C1, 3544768C1, and 3578858C1; Drive Axle with IAS Suspension; With 9.25" or 9.5" Ride Height; Shocks are 1.75in Bore
2000-2009	HD1215-0052	OE Interchange: 3571711C1, 3571713C1; Steering Axle; With 12,000 to 14,000lb Axle; Taper Leaf Spring Suspension; Shocks are 1.75in Bore		

International CO190

1970-1971	HD1214-0568	OE Interchange: 204994R91, 210534R92, 453561C91, 453562C91, 453565C91, 467371C91, 467372C91; Steering Axle; Shocks are 1.38in Bore	HD1215-0097	OE Interchange: 350425C1, 462557C91; With Air Ride Suspension; After Chassis No. G-387453; Shocks are 1.75in Bore
------------------	--------------------	--	--------------------	---

International CO200

1970-1971	HD1214-0568	OE Interchange: 204994R91, 210534R92, 453561C91, 453562C91, 453565C91, 467371C91, 467372C91; Steering Axle; Shocks are 1.38in Bore	HD1215-0097	OE Interchange: 350425C1, 462557C91; With Air Ride Suspension; After Chassis No. G-387453; Shocks are 1.75in Bore
------------------	--------------------	--	--------------------	---

International CO220

1971-1971	HD1214-0568	OE Interchange: 204994R91, 210534R92, 453561C91, 453562C91, 453565C91, 467371C91, 467372C91; Steering Axle; Shocks are 1.38in Bore	HD1215-0097	OE Interchange: 350425C1, 462557C91; With Air Ride Suspension; After Chassis No. G-387453; Shocks are 1.75in Bore
------------------	--------------------	--	--------------------	---

International CXT

2005-2008	HD1215-0161	OE Interchange: 3606770C1; Shocks are 1.75in Bore		
------------------	--------------------	---	--	--

International F1924

1979-1981	HD1214-0661	OE Interchange: 472367C91; Steering Axle; With Front Axle Codes 02071, 02073, 02101; Shocks are 1.38in Bore		
1979-1981	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1215-0063	OE Interchange: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187; Shocks are 1.38in Bore

International F1954

1979-1989	HD1214-0661	OE Interchange: 472367C91; Steering Axle; With Front Axle Codes 02071, 02073, 02101; Shocks are 1.38in Bore		
------------------	--------------------	---	--	--



FRONT



REAR

APPLICATIONS

International F1954

1979-1989	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1215-0063	OE Interchange: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187; Shocks are 1.38in Bore
-----------	-------------	--	-------------	---

International F2275

1979-1989	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1214-0580	OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1979-1989			HD1115-0078	OE Interchange: 534464C1; With Ridewell Air Suspension; Non-Gas Shock Absorber
1979-1989			HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore
1979-1989			HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore

International F2554

1979-1989			HD1115-0078	OE Interchange: 534464C1; With Ridewell Air Suspension; Non-Gas Shock Absorber
1979-1989	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1214-0580	OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1979-1989			HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore
1979-1989			HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore

International F2574

1979-1989	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1214-0580	OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1979-1989			HD1115-0078	OE Interchange: 534464C1; With Ridewell Air Suspension; Non-Gas Shock Absorber
1979-1989			HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore



FRONT



REAR

International F2574

1979-1989			HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore
-----------	--	--	--------------------	--

International F2575

1979-1989	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1214-0580	OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1979-1989			HD1115-0078	OE Interchange: 534464C1; With Ridewell Air Suspension; Non-Gas Shock Absorber
1979-1989			HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore
1979-1989			HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore

APPLICATIONS

International F2654

1980-1989	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1214-0580	OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1980-1989			HD1115-0078	OE Interchange: 534464C1; With Ridewell Air Suspension; Non-Gas Shock Absorber
1980-1989			HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore
1980-1989			HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore

International F2674

1979-1989	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1214-0580	OE Interchange: 790335C91; Drive Axle; With Neway ARD-125/244 Air Suspension; Shocks are 1.38in Bore
1979-1989			HD1115-0078	OE Interchange: 534464C1; With Ridewell Air Suspension; Non-Gas Shock Absorber
1979-1989			HD1215-0028	OE Interchange: 501553C91, 1675455C1, 1690035C1, 2018987C1; Drive Axle; With International Corporate Air Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

International F2674

1979-1989			HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore
-----------	--	--	--------------------	--

International F5070

1981-2001	HD1116-0043	OE Interchange: 426744R91, 426744R92, 453576C91, 477132C1; Non-Gas Shock Absorber		
1981-1987	HD1215-0113	OE Interchange: 426744R91, 453576C91, 477132C1; Steering Axle; Shocks are 1.75in Bore		

International F5070-SF

1981-1987	HD1116-0043	OE Interchange: 426744R91, 426744R92, 453576C91, 477132C1; Non-Gas Shock Absorber		
1981-1987	HD1215-0113	OE Interchange: 426744R91, 453576C91, 477132C1; Steering Axle; Shocks are 1.75in Bore		

International HV507

2019-2020			HD1215-0069	OE Interchange: 60657003; With Hendrickson Primaax 230 or 460 Suspension; Shocks are 1.75in Bore
2019-2020			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore

International HV513

2019-2020			HD1215-0069	OE Interchange: 60657003; With Hendrickson Primaax 230 or 460 Suspension; Shocks are 1.75in Bore
2019-2020			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore

International HV607

2019-2020			HD1215-0069	OE Interchange: 60657003; With Hendrickson Primaax 230 or 460 Suspension; Shocks are 1.75in Bore
-----------	--	--	--------------------	--



FRONT



REAR

APPLICATIONS

International HV607

2019-2020			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
-----------	--	--	--------------------	--

International HV613

2019-2020			HD1215-0069	OE Interchange: 60657003; With Hendrickson Primaax 230 or 460 Suspension; Shocks are 1.75in Bore
2019-2020			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore

International HX515

2017-2019			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
-----------	--	--	--------------------	--

International HX520

2018-2019			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
-----------	--	--	--------------------	--

International HX615

2017-2019			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
-----------	--	--	--------------------	---

International HX620

2017-2019			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
-----------	--	--	--------------------	---



FRONT



REAR

APPLICATIONS

International Lonestar				
2009-2015			HD1215-0041	OE Interchange: 3688615C1, 36886171, 3688614C1; Shocks are 1.75in Bore

International LT625				
2018-2019	HD1215-0080	OE Interchange: 4050443C2, 4050444C2; With 12,000lb Leaf Spring Front Suspension; With 14,000lb Taper Leaf Front Suspension; Shocks are 1.75in Bore	HD1215-0136	OE Interchange: 3684524C1A; With Hendrickson HTB 400LT Air Suspension; Shocks are 1.75in Bore

International M1200				
1966-1972	HD1213-0678			Metro Models M1200 Excludes Frame Code 01000.0962
1966-1972			HD1213-0678	Metro Models M1200 with Code 03204 Auxillary Springs

International M1400				
1966-1969			HD1214-0640	OE Interchange: 308649C91, 453567C91; Shocks are 1.38in Bore
1966-1969			HD1214-0605	OE Interchange: 308669C91, 453556C91; Shocks are 1.38in Bore

International M1400 Metro II				
1987-1990	HD1214-0545	OE Interchange: 472412C91, 586724C91; Steering Axle; Shocks are 1.38in Bore	HD1214-0605	OE Interchange: 308669C91, 453556C91; Shocks are 1.38in Bore

International M1600 Metro II				
1987-1990	HD1214-0661	OE Interchange: 472367C91; Steering Axle; With Front Axle Codes 02071, 02073, 02101; Shocks are 1.38in Bore	HD1214-0640	OE Interchange: 308649C91, 453567C91; Shocks are 1.38in Bore
1987-1990	HD1214-0545	OE Interchange: 472411C91, 472412C91, 586724C91; Steering Axle; With Front Axle Code 02109, 02118, 02309, 02127, 02139, 02329, 02339; Shocks are 1.38in Bore	HD1215-0063	OE Interchange: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187; Shocks are 1.38in Bore
1987-1990	HD1214-0605	OE Interchange: 308668C91, 308669C91, 453556C91, 874695R91; Shocks are 1.38in Bore	HD1214-0640	OE Interchange: 206620R91, 308649C91; Shocks are 1.38in Bore

International MV607				
2019-2019	HD1215-0022	OE Interchange: 6127714C1; With 11,000-14,000lb Front Suspension; Shocks are 1.75in Bore		
2019-2019	HD1214-0572	OE Interchange: 6127088C1; With 9,000-10,000lb Front Suspension; Shocks are 1.38in Bore		
2019-2019	HD1215-0084	OE Interchange: 6127088C1; With 9,000-10,000lb Front Suspension; Shocks are 1.75in Bore		



FRONT



REAR

APPLICATIONS

International Prostar

2010-2016	HD1215-0119	OE Interchange: 3606859C1; With Day Cab; With Leaf Spring Suspension; Shocks are 1.75in Bore		
2010-2016	HD1215-0080	OE Interchange: 3606857C1; Sleeper Cab with Leaf Spring Suspension; Shocks are 1.75in Bore	HD1215-0041	OE Interchange: 3688615C1, 36886171, 3688614C1; Shocks are 1.75in Bore
2010-2016	HD1215-0154	OE Interchange: 3806341C4, 3810581C4; With 113" Sleeper Cab; With Leaf Spring Suspension; With Air Suspension; Shocks are 1.75in Bore		

International S1723

1980-1985	HD1214-0661	OE Interchange: 472367C91; Steering Axle; With Front Axle Codes 02071, 02073, 02101; Shocks are 1.38in Bore		
1980-1985			HD1215-0028	OE Interchange: 1675455C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore
1980-1985			HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore

International S1823

1980-1982	HD1214-0545	OE Interchange: 472412C91, 472411C91; With Front Axle Codes 02109, 02118, 02309, 02127, 02139, 02329, and 02339; Shocks are 1.38in Bore	HD1215-0028	OE Interchange: 1675455C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore
1980-1982			HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore
1980-1982			HD1215-0063	OE Interchange: 501906C91; Drive Axle; Excludes Rear Axle Codes 14029, 14030, and 14187; Shocks are 1.38in Bore

International S1853

1981-1989	HD1214-0568	OE Interchange: 204994R91, 210534R92, 453561C91, 453562C91, 453565C91, 467371C91, 467372C91; Forward Control; Steering Axle; Shocks are 1.38in Bore	HD1214-0568	OE Interchange: 204994R91, 210534R92, 453561C91, 453562C91, 453565C91, 467371C91, 467372C91; Forward Control; Steering Axle; Shocks are 1.38in Bore
1981-1989	HD1214-0545	OE Interchange: 472412C91, 472411C91; With Front Axle Codes 02109, 02118, 02309, 02127, 02139, 02329, and 02339; Shocks are 1.38in Bore	HD1215-0028	OE Interchange: 1675455C1, 501553C91; With International Corporate Air Suspension; Shocks are 1.75in Bore
1981-1989			HD1214-0530	OE Interchange: 537524C91; Drive Axle; With Neway ARD-234 Air Suspension; Shocks are 1.38in Bore



FRONT

REAR



International S1853

1981-1989			HD1214-0640	OE Interchange: 453567C91; Forward Control; With Axle Code 14149; With FD Serial Numbers; Shocks are 1.38in Bore
-----------	--	--	--------------------	--

International Terrastar

2011-2015	HD1214-0642	OE Interchange: 3902993C2, 3902993C3, 3991991C1; Shocks are 1.38in Bore		
2011-2015	HD1214-0543	OE Interchange: 3945165C1, 3977794C2; Shocks are 1.38in Bore		

International Transtar

2015-2019	HD1215-0022	OE Interchange: 3588209C2; With 10,000-12,000lb Front Axle; Shocks are 1.75in Bore		
2015-2019	HD1215-0080	OE Interchange: 3674348C1; Shocks are 1.75in Bore		
2015-2017	HD1215-0113	OE Interchange: 426744R91, 477132C1, 293009C91, 453576C91, 453577C91; Steering Axle; Shocks are 1.75in Bore		

International Workstar 7300

2015-2016	HD1214-0497	(Cab Shock) OE Interchange: 2509222C91, 2509224C91, 3557165C1, 3557167C3, and 3560705C2		
2015-2016	HD1214-0573	(Cab Shock) OE Interchange: 12011049, 12011043; With Link Cab Suspension		
2015-2016	HD1215-0100	OE Interchange: 3558089C2; Steering Axle; With 16,000 to 20,000lb Axle; With Multi-Leaf Spring; Standard Duty; Shocks 1.75in Bore	HD1215-0045	OE Interchange: 47902024; Drive Axle; With Hendrickson HAS-230, HAS-400, or HAS-460 Air Suspension; Shocks are 1.75in Bore
2015-2016	HD1215-0161	OE Interchange: 3541456C1; Steering Axle; Severe Service; With 16,000 to 20,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.75in Bore		

International Workstar 7400

2015-2016	HD1214-0497	(Cab Shock) OE Interchange: 2509222C91, 2509224C91, 3557165C1, 3557167C3, and 3560705C2		
2015-2016	HD1214-0573	(Cab Shock) OE Interchange: 12011049, 12011043; With Link Cab Suspension		
2015-2016	HD1215-0100	OE Interchange: 3558089C2; Steering Axle; With 16,000 to 20,000lb Axle; With Multi-Leaf Spring; Standard Duty; Shocks 1.75in Bore		

APPLICATIONS



FRONT

REAR



APPLICATIONS

International Workstar 7400

2015-2016	HD1215-0161	OE Interchange: 3541456C1; Steering Axle; Severe Service; With 16,000 to 20,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.75in Bore		
-----------	-------------	---	--	--

International Workstar 7600

2010-2016	HD1215-0100	OE Interchange: 3558089C2; Steering Axle; With 16,000 to 20,000lb Axle; With Multi-Leaf Spring; Standard Duty; Shocks 1.75in Bore	HD1215-0045	OE Interchange: 47902024; Drive Axle; With Hendrickson HAS-230, HAS-400, or HAS-460 Air Suspension; Shocks are 1.75in Bore
2010-2015	HD1214-0497	(Cab Shock) OE Interchange: 2509222C91, 2509224C91, 3557165C1, 3557167C3, and 3560705C2		
2010-2016	HD1214-0573	(Cab Shock) OE Interchange: 12011049, 12011043; With Link Cab Suspension		
2010-2016	HD1215-0161	OE Interchange: 3541456C1; Steering Axle; Severe Service; With 16,000 to 20,000lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.75in Bore		

Isuzu FRR

2000-2004	HD1213-0734	OE Interchange: 1516302191; Shocks are 1.38 in Bore		
1995-1998	HD1213-0734	OE Interchange: 1516302191; Shocks are 1.38 in Bore		

Isuzu FSR

1997-2002	HD1215-0156	OE Interchange: 8220648040; Steering Axle; FL1 8,100lb Axle; Low Profile; Shocks are 1.75in Bore	HD1215-0156	OE Interchange: 22064233; Drive Axle; With Tilt Cab; With 23,000lb Axle; Taper Leaf Spring; Shocks are 1.75in Bore
1997-2002			HD1214-0561	OE Interchange: 8220642320; Drive Axle; 15,000 to 23,500lb Axle; With Multi Leaf Spring Suspension; Shocks are 1.38in Bore
1989-1996			HD1214-0526	OE Interchange: 1516301670; Drive Axle; Shocks are 1.38in Bore

Isuzu FTR

2005-2009	HD1215-0081	OE Interchange: 15123676, 88982682; Shocks are 1.75in Bore	HD1214-0561	OE Interchange: 15174902, 88982686; Shocks are 1.38in Bore
-----------	-------------	--	-------------	--

Isuzu NPR

1988-1989	HD1213-0734	OE Interchange: 1516302191; From Production Date 06/1988; Shocks are 1.38 in Bore		
1986-2010	HD1214-0540	OE Interchange: 8972536200, 8972536210; Shocks are 1.38in Bore	HD1214-0571	OE Interchange: 8972536640, 8972536510; Drive Axle; Shocks are 1.38in Bore



FRONT



REAR

APPLICATIONS

Isuzu NPR				
1986-2010	HD1214-0604	OE Interchange: 1516302000; Steering Axle; Shocks are 1.38in Bore		

Isuzu NQR				
2011-2016	HD1214-0540	OE Interchange: 8982326720, 8982326721; Shocks are 1.38in Bore	HD1214-0571	OE Interchange: 8980980591, 8983162280; Shocks are 1.38in Bore
2008-2010			HD1214-0571	OE Interchange: 8980980591, 8983162280; Shocks are 1.38in Bore
2000-2007	HD1214-0540	OE Interchange: 8972536200, 8973070240; Shocks are 1.38in Bore	HD1214-0571	OE Interchange: 8980980591, 8983162280; Shocks are 1.38in Bore

Isuzu NRR				
2005-2016	HD1214-0540	OE Interchange: 8982326720, 8982326721; Shocks are 1.38in Bore	HD1214-0571	OE Interchange: 8980980591, 8983162280; Shocks are 1.38in Bore
1988-1988	HD1213-0734	OE Interchange: 1516302191; With Build Date Before 05/31/1988; Shocks are 1.38 in Bore		

Kenworth C500				
2010-2016			HD1215-0077	OE Interchange: 665944; With Air Glide 200 Suspension; with 40,000lb GVW; 4 Units Required; Shocks are 1.75in Bore
2010-2016			HD1115-0075	OE Interchange: K37432; With Air Glide 100 Rear Suspension; With 8 Air Springs; Non-gas Shock Absorber
1981-2016			HD1215-0085	OE Interchange: K37429; With Air Glide 100 Rear Suspension; Shocks are 1.75in Bore
1981-2016			HD1214-0609	OE Interchange: K37429; With Air Glide 100 Rear Suspension; Shocks are 1.38in Bore

Kenworth K100				
1981-1985			HD1215-0177	OE Interchange: K37428; With Torsion Bar Bogey Suspension; Shocks are 1.75 in Bore
1981-1985			HD1115-0075	OE Interchange: K37432; With Air Glide 100 Rear Suspension; With 8 Air Springs; Non-gas Shock Absorber
1981-1985			HD1215-0077	OE Interchange: 665944; With Air Glide 200 Suspension; with 40,000lb GVW; 4 Units Required; Shocks are 1.75in Bore
1981-1985			HD1215-0085	OE Interchange: K37429; With Air Glide 100 Rear Suspension; With 8 Air Springs; Shocks are 1.75in Bore



FRONT



REAR

Kenworth K100				
1981-1985	HD1213-0652	(Cab Shock); OE Interchange: 12021164; With link Cab Suspension	HD1214-0609	OE Interchange: K37429; With Air Glide 100 Rear Suspension; With 8 Air Springs; Shocks are 1.38in Bore

Kenworth K100E				
2005-2006			HD1215-0077	OE Interchange: 665944; With Air Glide 200 Suspension; with 40,000lb GVW; 4 Units Required; Shocks are 1.75in Bore
2005-2006			HD1115-0075	OE Interchange: K37432; With Air Glide 100 Rear Suspension; Non-gas Shock Absorber
2005-2006			HD1215-0177	OE Interchange: K37428; With Torsion Bar Bogey Suspension; Shocks are 1.75 in Bore
2005-2006			HD1214-0609	OE Interchange: K37429; With Air Glide 100 Rear Suspension; Shocks are 1.38in Bore
2005-2006	HD1213-0652	(Cab Shock); OE Interchange: 12021164; With link Cab Suspension	HD1215-0085	OE Interchange: K37429; With Air Glide 100 Rear Suspension; Shocks are 1.75in Bore
1985-2003			HD1215-0177	OE Interchange: K37428; With Torsion Bar Bogey Suspension; Shocks are 1.75 in Bore
1985-2003			HD1215-0077	OE Interchange: 665944; With Air Glide 200 Suspension; with 40,000lb GVW; 4 Units Required; Shocks are 1.75in Bore
1985-2003			HD1115-0075	OE Interchange: K37432; With Air Glide 100 Rear Suspension; Non-gas Shock Absorber
1985-2003			HD1215-0085	OE Interchange: K37429; With Air Glide 100 Rear Suspension; Shocks are 1.75in Bore
1985-2003	HD1213-0652	(Cab Shock); OE Interchange: 12021164; With link Cab Suspension	HD1214-0609	OE Interchange: K37429; With Air Glide 100 Rear Suspension; Shocks are 1.38in Bore

APPLICATIONS

Kenworth K300				
1993-2005			HD1215-0077	OE Interchange: 665944; With Air Glide 200 Suspension; with 40,000lb GVW; 8 Air Springs; 4 Units Required; Shocks are 1.75in Bore
1993-2005			HD1215-0085	OE Interchange: K37432; With Air Glide 100 Rear Suspension; With 8 Air Springs; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Kenworth K300

1993-2005	HD1214-0567	OE Interchange: 665565; Shocks are 1.38in Bore	HD1214-0609	OE Interchange: K37432; With Air Glide 100 Rear Suspension; With 8 Air Springs; Shocks are 1.38in Bore
1993-2005	HD1215-0023	OE Interchange: B711000, 665617; With 12,000lb Taper Leaf Suspension; Shocks are 1.75in Bore		

Kenworth T170

2008-2019	HD1215-0023	OE Interchange: B711000, 665617; With 12,000lb Taper Leaf Suspension; Shocks are 1.75in Bore		
-----------	-------------	--	--	--

Kenworth T2000

2002-2011			HD1115-0075	OE Interchange: K37432; With Air Glide 100 Rear Suspension; Non-gas Shock Absorber
1997-2011			HD1215-0086	With Air Glide 400 Rear Suspension; Shocks are 1.75in Bore
1997-2011	HD1213-0652	(Cab Shock); OE Interchange: R711005; With Link Cabmate KWT000-A Air Suspension	HD1215-0085	OE Interchange: K37432; With Air Glide 100 Rear Suspension; With 8 Air Springs; Shocks are 1.75in Bore
1997-2011	HD1215-0020	OE Interchange: B711001, 665858; With 13,000lb Front Axle; Shocks are 1.75in Bore	HD1214-0609	OE Interchange: 665945; With Air Glide 200 Suspension; With 46,000 GVW; With 8 Air Springs; Shocks are 1.38in Bore

Kenworth T270

2015-2019	HD1215-0048	OE Interchange: B716019; With 10,000-14,600lb Taper Leaf Suspension; With Set Back Axle; Shocks are 1.75in Bore		
2010-2014	HD1215-0048	OE Interchange: B716004; With 8,000lb Front Axle; Shocks are 1.75in Bore		
2008-2010	HD1215-0023	OE Interchange: 665617; With 12,000lb Front Axle; Shocks are 1.75in Bore	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore

Kenworth T300

2016-2019	HD1215-0048	OE Interchange: B716019; With 10,000-14,600lb Taper Leaf Suspension; With Set Back Axle; Shocks are 1.75in Bore		
1995-2008			HD1115-0075	OE Interchange: K37432; With Air Glide 100 Rear Suspension; With 8 Air Springs; Non-gas Shock Absorber



FRONT



REAR

APPLICATIONS

Kenworth T300

1995-2008			HD1215-0077	OE Interchange: 665944; With 40,000lb GVW; With Air Glide 200 Suspension; Shocks are 1.75in Bore
1995-2008			HD1215-0085	OE Interchange: K37432; With Air Glide 100 Rear Suspension; With 8 Air Springs; Shocks are 1.75in Bore
1995-2008			HD1214-0609	OE Interchange: K37432; With Air Glide 100 Rear Suspension; Shocks are 1.38in Bore

Kenworth T370

2015-2019	HD1215-0048	OE Interchange: B716019; With 10,000-14,600lb Taper Leaf Suspension; With Set Back Axle; Shocks are 1.75in Bore		
2010-2014	HD1215-0048	OE Interchange: B716004; With 8,000lb Front Axle; Shocks are 1.75in Bore		
2008-2010	HD1215-0023	OE Interchange: 665617; With 12,000lb Front Axle; Shocks are 1.75in Bore	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore

Kenworth T400

2012-2020	HD1215-0020	OE Interchange: B711001, 665858; With 12,000-20,000lb Front Axle; Shocks are 1.75in Bore		
2010-2020			HD1215-0086	With Air Glide 400 Rear Suspension; Shocks are 1.75in Bore
2010-2020			HD1215-0085	OE Interchange: 60657003; With Hendrickson Primaax EX 232, 462, or 692 Suspension; Shocks are 1.75in Bore
2010-2020			HD1215-0129	OE Interchange: 60665011; With Hendrickson Primaax EX262S or EX522S Suspension; Shocks are 1.75in Bore
2010-2020			HD1215-0155	OE Interchange: 90045068; With Neway AD123 Rear Suspension; With Neway AD246 Rear Suspension; Shocks are 1.75in Bore
2010-2020			HD1215-0042	OE Interchange: 90045099; With Neway AD123 Rear Suspension; With Neway AD246 Rear Suspension; Shocks are 1.75in Bore
2010-2020			HD1215-0054	OE Interchange: 90045132; With Neway AD-123 Rear Suspension; With Neway AD-246 Rear Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Kenworth T400			
2010-2020		HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
1998-1999		HD1215-0177	OE Interchange: K3744, K37428; With Kenworth Air Ride Suspension; With 4 Air Springs; With Torsion Bar Bogey Suspension; Shocks are 1.75 in Bore
1998-1999		HD1115-0075	OE Interchange: K37432; With Air Glide 100 Rear Suspension; With 8 Air Springs; Non-gas Shock Absorber
1989-1999		HD1215-0077	OE Interchange: 665944; With 40,000lb GVW; With Air Glide 200 Suspension; Shocks are 1.75in Bore
1989-1999		HD1215-0085	OE Interchange: K374C7; With Air Glide 100 Rear Suspension; Shocks are 1.75in Bore
1989-1999		HD1214-0609	OE Interchange: K3747, K3749, K37429, K37487, K374C7; With Air Glide 100 Suspension; Shocks are 1.38in Bore
1984-1984		HD1215-0077	OE Interchange: 665944; With 40,000lb GVW; With Air Glide 200 Suspension; Shocks are 1.75in Bore
1984-1984		HD1215-0085	OE Interchange: K374C7; With Air Glide 100 Rear Suspension; Shocks are 1.75in Bore
1984-1984		HD1215-0177	OE Interchange: K73428; With Kenworth Air Ride Suspension; With 4 Air Springs; Shocks are 1.75 in Bore
1984-1984		HD1214-0609	OE Interchange: K37487; With Air Glide 100 Suspension; Shocks are 1.38in Bore
1982-1982		HD1215-0077	OE Interchange: 665944; With 40,000lb GVW; With Air Glide 200 Suspension; Shocks are 1.75in Bore
1982-1982		HD1215-0177	OE Interchange: K37428; With Kenworth Air Ride Suspension; Shocks are 1.75 in Bore
1982-1982		HD1215-0085	OE Interchange: K374C7; With Air Glide 100 Rear Suspension; Shocks are 1.75in Bore
1982-1982		HD1214-0609	OE Interchange: K37487; With Air Glide 100 Suspension; Shocks are 1.38in Bore



FRONT



REAR

APPLICATIONS

Kenworth T600A				
2007-2007			HD1215-0086	With Air Glide 400 Rear Suspension; Shocks are 1.75in Bore
2007-2007			HD1215-0077	OE Interchange: 665944; With Air Glide 200 Suspension; With 40,000lb GVW; 8 Air Springs; 4 Units Required; Shocks are 1.75in Bore
2007-2007	HD1215-0020	OE Interchange: 665858; Steering Axle; Shocks are 1.75in Bore	HD1214-0609	OE Interchange: K37487; With Air Glide 100 Suspension; With 8 Air Springs; Shocks are 1.38in Bore
1986-2007			HD1115-0075	OE Interchange: K37432; With Air Glide 100 Rear Suspension; With 8 Air Springs; Non-gas Shock Absorber
1986-2007			HD1215-0085	OE Interchange: K37487; With Air Glide 100 Rear Suspension; With 8 Air Springs; Shocks are 1.75in Bore
1986-1992			HD1215-0086	With Air Glide 400 Rear Suspension; Shocks are 1.75in Bore
1986-1992			HD1215-0077	OE Interchange: 665944; With Air Glide 200 Suspension; With 40,000lb GVW; 8 Air Springs; 4 Units Required; Shocks are 1.75in Bore
1986-1992			HD1214-0609	OE Interchange: K37487; With Air Glide 100 Suspension; With 8 Air Springs; Shocks are 1.38in Bore

Kenworth T660				
2008-2019	HD1215-0167	With AG130 Suspension; Shocks are 1.75 in Bore		
2008-2019	HD1213-0652	(Cab Shock); OE Interchange: 12021065; With Link Cab Suspension		
2008-2019	HD1215-0020	OE Interchange: B711001, 665858; With 12,000-13,200lb Front Suspension; Shocks are 1.75in Bore	HD1215-0086	With Air Glide 400 Rear Suspension; Shocks are 1.75in Bore

Kenworth T680				
2013-2020	HD1215-0167	With AG130 Suspension; Shocks are 1.75 in Bore	HD1215-0086	With Air Glide 400 Rear Suspension; Shocks are 1.75in Bore
2013-2020			HD1215-0069	With Hendrickson Primaax EX462 Suspension; With 8.5-10.5 ride Height; Shocks are 1.75in Bore
2013-2020			HD1215-0129	OE Interchange: 60665011; With Hendrickson Primaax EX462 Suspension; With 12.5-15.5 inch Ride Height



FRONT



REAR

APPLICATIONS

Kenworth T680				
2013-2020	HD1215-0048	OE Interchange: B716019, B716020, B716005; With 10,000-20,000lb Taper Leaf Front Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
2015-2016			HD1215-0086	OE Interchange: C711014; With AG 380 Rear Air Suspension; Shocks are 1.75in Bore
2015-2016	HD1215-0048	OE Interchange: B716019; Shocks are 1.75in Bore	HD1215-0076	OE Interchange: C711017; With AG 400L Rear Air Suspension; Shocks are 1.75in Bore
2013-2014			HD1215-0065	OE Interchange: 671963; With AG 460 Rear Air Suspension; Shocks are 1.75in Bore
2013-2014			HD1215-0086	OE Interchange: 671962; With AG 400 Rear Air Suspension; Shocks are 1.75in Bore
2013-2014	HD1215-0048	OE Interchange: B716019; Shocks are 1.75in Bore	HD1215-0034	OE Interchange: C711002; With AG 380 Rear Air Suspension; Shocks are 1.75in Bore

Kenworth T700				
2011-2015	HD1215-0020	OE Interchange: B711001; With 12,000-22,000lb Front Axle; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0086	With Air Glide 400 Rear Suspension; Shocks are 1.75in Bore

Kenworth T800				
2011-2016	HD1215-0167	With AG130 Suspension; Shocks are 1.75 in Bore		
2005-2019	HD1215-0020	OE Interchange: B711001; With 12,000-20,000lb Front Axle; With Set Back Axle; Shocks are 1.75in Bore		
1987-2020			HD1215-0177	OE Interchange: K37428; Shocks are 1.75 in Bore
1987-2020			HD1215-0077	OE Interchange: 665944; With Air Glide 200 Suspension; With 40,000lb GVW; 8 Air Springs; 4 Units Required; Shocks are 1.75in Bore
1987-2020			HD1215-0054	OE Interchange: 90045132; With Neway Air Suspension; Shocks are 1.75in Bore
1987-2020			HD1215-0085	OE Interchange: K37487; With Air Glide 100 Rear Suspension; With 8 Air Springs; Shocks are 1.75in Bore
1987-2020			HD1214-0609	OE Interchange: K37487; With Air Glide 100 Suspension; With 8 Air Springs; Shocks are 1.38in Bore



FRONT



REAR

APPLICATIONS

Kenworth T800

1987-2015			HD1115-0075	OE Interchange: K37432; With Air Glide 100 Rear Suspension; With 8 Air Springs; Non-gas Shock Absorber
-----------	--	--	--------------------	--

Kenworth T880

2014-2020			HD1215-0086	With Air Glide 400 Rear Suspension; Shocks are 1.75in Bore
2014-2020	HD1215-0167	With AG130 Suspension; Shocks are 1.75 in Bore	HD1215-0069	With Hendrickson Primaax EX462 Suspension; With 8.5-10.5 ride Height; Shocks are 1.75in Bore
2014-2020	HD1214-0507	OE Interchange: 11418; Tag Axle; With Watson and Chalin SL Series steerable lift Axles	HD1215-0129	OE Interchange: 60665011; With Hendrickson Primaax EX462 Suspension; With 12.5-15.5 inch Ride Height
2014-2020	HD1215-0048	OE Interchange: B716019, B716020; With 10,000-20,000lb Taper Leaf Front Suspension; Shocks are 1.75in Bore	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore

Kenworth W900

1982-2020			HD1215-0177	OE Interchange: K37428; Shocks are 1.75 in Bore
1982-2020			HD1215-0054	OE Interchange: 90045132; With Neway Air Suspension; Shocks are 1.75in Bore
1981-2020			HD1215-0077	OE Interchange: 665944; With Air Glide 200 Suspension; With 40,000lb GVW; 8 Air Springs; 4 Units Required; Shocks are 1.75in Bore
1981-2020			HD1215-0085	OE Interchange: K37432; With Air Glide 100 Rear Suspension; With 8 Air Springs; Shocks are 1.75in Bore
1981-2020			HD1214-0609	OE Interchange: K37432; With Air Glide 100 Rear Suspension; With 8 Air Springs; Shocks are 1.38in Bore

Kenworth W990

2019-2020	HD1215-0056	OE Interchange: B716013; With 12,000-14,6000lb Taper Leaf Springs; Shocks are 1.75in Bore		
-----------	--------------------	---	--	--

Mack Anthem

2018-2020			HD1215-0083	OE Interchange: 60675001; With Hendrickson HAS 400 or 460 Suspension; Shocks are 1.75in Bore
2018-2020			HD1215-0030	OE Interchange: 22202559, 471700009647, 22202560; With 40,000lb Air Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Mack Anthem

2018-2020	HD1215-0074	OE Interchange: 21436096; With 13,200lb Front Axle; Shocks are 1.75in Bore	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
-----------	-------------	--	-------------	---

Mack CH

1989-2005			HD1215-0054	OE Interchange: 25624351; With Neway AD Air Suspension; Shocks are 1.75in Bore
1989-2005			HD1214-0565	OE Interchange: 14QK413M4, 572414; With Hendrickson HAS-40LH Air Suspension; Shocks are 1.38in Bore
1989-2005	HD1214-0496	(Cab Shock); OE Interchange: 14QK391BM2	HD1215-0042	OE Interchange: 14QK414M, 90045099; With Neway AD Air Suspension; Shocks are 1.75in Bore

Mack CHN

2004-2007	HD1215-0074	OE Interchange: 20973993, 14QK3107M; With 12,000lb Front Axle; Shocks are 1.75in Bore	HD1215-0030	OE Interchange: 14QK3101M; With Mack Corporate Air Suspension, Shocks are 1.75in Bore
2004-2007	HD1215-0042	OE Interchange: 20998401; With 14,600lb Axle; Shocks are 1.75in Bore		

Mack CHU

2011-2019			HD1215-0030	OE Interchange: 22202559, 22202560; With 40,000lb Air Suspension; Shocks are 1.75in Bore
2008-2019	HD1214-0553	(Cab Shock); OE Interchange: 25625636, 25625635, 20874147, 14QK3103M, 14QK303M		
2008-2019	HD1215-0042	OE Interchange: 20625775, 20998401, 14QK434M; Shocks are 1.75in Bore	HD1215-0083	OE Interchange: 60675001; With Hendrickson HAS 400 or 460 Suspension; Shocks are 1.75in Bore

Mack CL

1991-2007			HD1215-0054	OE Interchange: 25624351; With Neway AD Air Suspension; Shock with extended length 24.3 inches; Shocks are 1.75in Bore
1991-2007	HD1214-0496	(Cab Shock); OE Interchange: 14QK391BM2	HD1215-0042	OE Interchange: 14QK393AM, 479029; With Hendrickson Air Suspension; Shocks are 1.75in Bore

Mack CT

2005-2007	HD1214-0553	(Cab Shock); OE Interchange: 14QK427M, 14QK428M, 14QK432M		
-----------	-------------	---	--	--



FRONT



REAR

APPLICATIONS

Mack CX				
1998-2005	HD1215-0054	OE Interchange: 14QK392BM3; With 12,000lb Taper Leaf Front Suspension; Shocks are 1.75in Bore	HD1215-0054	OE Interchange: 25624351; With Neway AD Air Suspension; Shock with extended length 24.3 inches; Shocks are 1.75in Bore
1998-2005	HD1214-0553	(Cab Shock); OE Interchange: 14QK399M2, 14QK399M3; With 70 or 80 inch Sleeper Cab		
1998-2005	HD1215-0074	OE Interchange: 20513881, 141700000373, 14QK431M; Shocks are 1.75in Bore	HD1215-0042	OE Interchange: 14QK414M, 90045099; With Neway AD Air Suspension; Shock with extended length 21.7 inches; Shocks are 1.75in Bore
Mack CXN				
2004-2008	HD1215-0053	OE Interchange: 20485633; With Hendrickson Airtex Front Suspension; Shocks are 1.75in Bore	HD1215-0030	OE Interchange: 14QK3101M; With Mack Corporate Air Suspension, Shocks are 1.75in Bore
2004-2008			HD1214-0597	OE Interchange: 14QK3101M; With Mack Corporate Air Suspension, Shocks are 1.38in Bore
Mack CXP				
2006-2007	HD1215-0074	OE Interchange: 20973993, 14QK3114M; With 12,000lb Front Axle; Shocks are 1.75in Bore	HD1215-0030	OE Interchange: 14QK2136M, 471700002626, 20897198; With 40,000lb Air Suspension; Shocks are 1.75in Bore
Mack CXU				
2008-2019	HD1214-0553	(Cab Shock); OE Interchange: 20874147, 14QK3103M, 14QK303M, 25625635, 25625636; With Sleeper Cab		
2008-2019	HD1215-0074	OE Interchange: 21436096, 20973993, 14QK3114M; With 12,000-14,600lb Front Axle; Shocks are 1.75in Bore	HD1215-0030	OE Interchange: 20897198, 14QK2136M, 22202559, 22202560, 21462382; With 40,000lb Air Suspension; Shocks are 1.75in Bore
Mack F				
1981-1982	HD1215-0177	With Standard Suspension; Shocks are 1.75 in Bore		
Mack Granite				
2018-2019			HD1215-0109	OE Interchange: 21979343; With 46,000lb Mack MRide Suspension; Shocks are 1.75in Bore
2015-2018	HD1214-0553	(Cab Shock); OE Interchange: 20873442, 14QK423M	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Mack Granite				
2015-2017	HD1215-0042	OE Interchange: 20625775, 20998401, 14QK434M; Shocks are 1.75in Bore		
Mack GU4				
2012-2019	HD1215-0042	OE Interchange: 20625775, 20998401, 14QK434M; Shocks are 1.75in Bore	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
2012-2018			HD1215-0083	OE Interchange: 60675001; With Hendrickson HAS 400 or 460 Suspension; Shocks are 1.75in Bore
Mack GU5				
2012-2018			HD1215-0083	OE Interchange: 60675001; With Hendrickson HAS 400 or 460 Suspension; Shocks are 1.75in Bore
2012-2017	HD1215-0042	OE Interchange: 20625775, 20998401, 14QK434M; Shocks are 1.75in Bore	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
Mack GU7				
2008-2019	HD1214-0553	(Cab Shock); OE Interchange: 20873442, 14QK423M	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
2008-2018			HD1215-0083	OE Interchange: 60675001; With Hendrickson HAS 400 or 460 Suspension; Shocks are 1.75in Bore
2008-2010	HD1215-0125	OE Interchange: 25626048, 20863239, 14QK427M, 14QK3108M; With 20,000lb Front Axle; Shocks are 1.75in Bore		
Mack GU8				
2008-2019	HD1214-0553	(Cab Shock); OE Interchange: 20873442, 14QK423M	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore



FRONT



REAR

Mack GU8				
2008-2018			HD1215-0083	OE Interchange: 60675001; With Hendrickson HAS 400 or 460 Suspension; Shocks are 1.75in Bore
2008-2010	HD1215-0125	OE Interchange: 25626048, 20863239, 14QK427M, 14QK3108M; With 20,000lb Front Axle; Shocks are 1.75in Bore		
Mack LE				
2010-2010			HD1116-0046	OE Interchange: 1252607B000; With Ridewell RD-202S HD Tandem Suspension; Non-Gas Shock Absorber
Mack LEU				
2010-2016	HD1215-0090	OE Interchange: 21002497; With 20,000lb Front Axle; Shocks are 1.75in Bore	HD1116-0046	OE Interchange: 1252607B000; With Ridewell RD-202S HD Tandem Suspension; Non-Gas Shock Absorber
Mack MH				
1983-1994	HD1215-0177	OE Interchange: 14QK378M; Shocks are 1.75 in Bore		
Mack RD				
2007-2007	HD1215-0177	OE Interchange: 14QK2110P1		
2007-2007	HD1214-0541	(Cab Shock); OE Interchange: 14QK2111P4; With Cab Air Suspension		
1981-1984	HD1215-0177	OE Interchange: 14QK2110P1		
1981-1984	HD1214-0541	(Cab Shock); OE Interchange: 14QK2111P4; With Cab Air Suspension		
Mack RW				
1985-1993	HD1215-0177	OE Interchange: 14QK378M; Shocks are 1.75 in Bore		
Mack TD700				
2010-2017			HD1215-0083	OE Interchange: 60675001; With Hendrickson HAS 400 or 460 Suspension; Shocks are 1.75in Bore
2010-2017			HD1215-0069	OE Interchange: 20782199; With Hendrickson 40,000lb Primaax or Firemaax EX Suspension; Shocks are 1.75in Bore
Mack U				
1981-1989	HD1215-0177	OE Interchange: 14QK2115; Shocks are 1.75 in Bore		



FRONT



REAR

APPLICATIONS

Mercedes-Benz Sprinter 3500

2010-2017			HD1214-0648	(RWD) Shocks are 1.38in Bore
-----------	--	--	--------------------	------------------------------

Motor Coach Industries 102DL3

1993-2007			HD1116-0049	OE Interchange: 12L589; Drive Axle; Non-Gas Shock Absorber
1993-2007			HD1116-0052	OE Interchange: 12L5100, 12L5114, 85727; With Tag Axle; Non-Gas Shock Absorber

Motor Coach Industries D4005

2013-2017			HD1116-0049	OE Interchange: 12L589; Drive Axle; Non-Gas Shock Absorber
2011-2011			HD1116-0049	OE Interchange: 12L589; Drive Axle; Non-Gas Shock Absorber
2005-2009			HD1116-0049	OE Interchange: 12L589; Drive Axle; Non-Gas Shock Absorber

Motor Coach Industries D4505

2006-2019			HD1116-0049	OE Interchange: 12L589; Drive Axle; Non-Gas Shock Absorber
-----------	--	--	--------------------	--

Motor Coach Industries J4500

2009-2019			HD1116-0051	OE Interchange: 12055445; With Tag Axle; Non-Gas Shock Absorber
2007-2007			HD1116-0051	OE Interchange: 12055445; With Tag Axle; Non-Gas Shock Absorber
2001-2003			HD1116-0051	OE Interchange: 12055445; With Tag Axle; Non-Gas Shock Absorber
2009-2019	HD1116-0048	OE Interchange: 12051150; Non-Gas Shock Absorber	HD1116-0050	OE Interchange: 12501188; Non-Gas Shock Absorber; Drive Axle
2007-2007	HD1116-0048	OE Interchange: 12051150; Non-Gas Shock Absorber	HD1116-0050	OE Interchange: 12501188; Non-Gas Shock Absorber; Drive Axle
2001-2003	HD1116-0048	OE Interchange: 12051150; Non-Gas Shock Absorber	HD1116-0050	OE Interchange: 12501188; Non-Gas Shock Absorber; Drive Axle

Nova Bus Corporation RTS

2001-2002	HD1116-0033	OE Interchange: G1201338, G1011823, and 22024673	HD1116-0046	OE Interchange: 22052014, G1011822, G1201339, G1203223; Non-Gas Shock Absorber
-----------	--------------------	--	--------------------	--

Peterbilt 220

2010-2010	HD1215-0056	OE Interchange: 0202738; With 12,000lb Axle; Shocks are 1.75in Bore		
2007-2007	HD1215-0056			



FRONT



REAR

Peterbilt 270				
2001-2001	HD1215-0038	OE Interchange: ACHF113; Shocks are 1.75in Bore		

Peterbilt 320				
2001-2018			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
1987-2018	HD1215-0032	With split progressive Spring Suspension; Shocks are 1.75in Bore	HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore

Peterbilt 325				
2008-2018	HD1215-0056	OE Interchange: 0202738; Shocks are 1.75in Bore		

Peterbilt 330				
2016-2020	HD1215-0048	OE Interchange: B716019; With 10,000-14,600lb Taper Leaf Suspension; With Set Back Axle; Shocks are 1.75in Bore		
2011-2015			HD1214-0612	OE Interchange: 0307423; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
2007-2020	HD1215-0117	OE Interchange: 0203020; Shocks are 1.75in Bore	HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore
2007-2016	HD1215-0056	OE Interchange: 0202738; With 12,000lb Axle; With Set Back Axle; Shocks are 1.75in Bore		
2007-2009			HD1214-0612	OE Interchange: 0307423; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1995-2002			HD1215-0037	OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore
1995-2005	HD1215-0056	OE Interchange: 0202738; With 12,000lb Axle; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore
1995-2005	HD1215-0117	OE Interchange: 0203020; Shocks are 1.75in Bore	HD1214-0612	OE Interchange: 0307423; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore

Peterbilt 335				
2005-2010	HD1214-0536	(Cab Shock); OE Interchange: R716005	HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore

APPLICATIONS



FRONT



REAR

APPLICATIONS

Peterbilt 337

2010-2020	HD1215-0048	OE Interchange: B716019; With 10,000-14,600lb Taper Leaf Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore
------------------	--------------------	---	--------------------	--

Peterbilt 340

2007-2010			HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore
------------------	--	--	--------------------	--

Peterbilt 348

2014-2018	HD1215-0048	OE Interchange: B716019; With 10,000-14,600lb Taper Leaf Suspension; With Set Back Axle; Shocks are 1.75in Bore		
2010-2018	HD1215-0167	OE Interchange: B716012; Shocks are 1.75 in Bore	HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore
2010-2018	HD1214-0536	(Cab Shock); OE Interchange: R716005; With Day Cab	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
2010-2012	HD1215-0048	OE Interchange: B716005; With 10,000-12,000lb Front Axle; Shocks are 1.75in Bore		

Peterbilt 357

2002-2008			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
1997-2007			HD1214-0612	OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1991-2008			HD1215-0149	OE Interchange: 0304176; With Air Leaf Suspension; Shocks are 1.75in Bore
1992-1994			HD1214-0612	OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1990-2007	HD1215-0061	OE Interchange: 0201890; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore		
1990-2007	HD1214-0546	(Cab Shock); OE Interchange: R716007; With Unibuilt Cab		



FRONT



REAR

APPLICATIONS

Peterbilt 357			
1990-1990			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1986-2008			HD1215-0033 OE Interchange: 0304629; With Air Leaf Suspension; Shocks are 1.75in Bore
1986-2008			HD1215-0037 OE Interchange: 0305384; With Low Air Leaf Spring; Shocks are 1.75in Bore
1986-2008	HD1215-0032	OE Interchange: 0202742; With 12,000-14,600lb Taper Leaf Springs; With Set forward Axle; Shocks are 1.75in Bore	HD1115-0078 OE Interchange: 90044011; With Neway ARD 125/244-8 Series Air Suspension; Non-Gas Shock Absorber
1986-2008	HD1215-0056	OE Interchange: 0202738; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0082 With Air Trac Suspension; Shocks are 1.75in Bore
1986-1989			HD1215-0149 OE Interchange: 0304176; With Air Leaf Suspension; Shocks are 1.75in Bore

Peterbilt 359			
1981-1988			HD1215-0082 With Air Trac Suspension; Shocks are 1.75in Bore

Peterbilt 362			
2001-2001			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1990-2005	HD1215-0061	OE Interchange: 0201890; With progressive Spring; Shocks are 1.75in Bore	
1990-1999			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1983-2006			HD1215-0033 OE Interchange: 0304629; With Air trac Suspension; Shocks are 1.75in Bore
1981-2006			HD1215-0037 OE Interchange: 665633; With Low Air Leaf Springs; Shocks are 1.75in Bore
1981-2006			HD1215-0082 With Air Trac Suspension; Shocks are 1.75in Bore
1981-2006	HD1215-0056	OE Interchange: 0202738; With progressive Spring Suspension; Shocks are 1.75in Bore	HD1214-0612 OE Interchange: 0305384, 0306084,0307423,665633; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1981-1983			HD1215-0149 OE Interchange: 0304176; With Air trac Suspension; Old Style; Shocks are 1.75in Bore

Peterbilt 365			
2014-2018			HD1215-0082 With Air Trac Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Peterbilt 365				
2008-2020	HD1214-0536	(Cab Shock); OE Interchange: R716005; With Day Cab	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore
2008-2018	HD1215-0032	With 12,000-23,000lb Taper Leaf Springs; With Set forward Axle; Shocks are 1.75in Bore		
2008-2012			HD1215-0085	OE Interchange 0307420; With Quadraflex 4 Spring Suspension; Shocks are 1.75in Bore
2008-2012			HD1214-0609	OE Interchange: 0307420; With Quadraflex 4 Spring Suspension; Shocks are 1.38in Bore

Peterbilt 367				
2008-2018			HD1215-0167	OE Interchange: 90045605; With Neway ADZ Suspension; Shocks are 1.75 in Bore
2008-2018			HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore
2008-2018	HD1215-0032	With 12,000-23,000lb Taper Leaf Springs; With Set forward Axle; Shocks are 1.75in Bore	HD1215-0085	OE Interchange 0307420; With Quadraflex 4 Spring Suspension; Shocks are 1.75in Bore
2008-2018	HD1214-0536	(Cab Shock); OE Interchange: R716005; With Day Cab	HD1214-0609	OE Interchange: 0307420; With Quadraflex 4 Spring Suspension; Shocks are 1.38in Bore
2008-2018	HD1214-0546	(Cab Shock); OE Interchange: R716007; With 70 inch Sleeper Cab	HD1215-0094	OE Interchange: 60680005, 6068005L, H60680005; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 17.5 in. Saddle Height; With 18.5 in. Saddle Height; Shocks are 1.75in Bore
2008-2018			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore

Peterbilt 372				
1997-1997			HD1215-0033	OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
1997-1997			HD1215-0037	OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Peterbilt 372			
1997-1997			HD1115-0078 OE Interchange: 90044011; With Neway ARD 125/244-8 Series Air Suspension; Non-Gas Shock Absorber
1997-1997	HD1215-0061	OE Interchange: 0201890; With Spring Suspension; Shocks are 1.75in Bore	HD1214-0612 OE Interchange: 0305384, 0306084,0307423,665633; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1993-1994			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1990-1995			HD1215-0033 OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
1990-1991			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1989-1995			HD1215-0037 OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore
1989-1995			HD1115-0078 OE Interchange: 90044011; With Neway ARD 125/244-8 Series Air Suspension; Non-Gas Shock Absorber
1989-1995	HD1215-0061	OE Interchange: 0201890; With Spring Suspension; Shocks are 1.75in Bore	HD1214-0612 OE Interchange: 0305384, 0306084,0307423,665633; With Low Air Leaf Suspension; Shocks are 1.38in Bore

Peterbilt 375			
1994-1996			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1992-1992			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1990-1996			HD1215-0033 OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
1990-1996	HD1215-0061	OE Interchange: 0201890; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1987-1996			HD1215-0037 OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore
1987-1996	HD1215-0032	With 12,000-23,000lb Taper Leaf Springs; With Set forward Axle; Shocks are 1.75in Bore	HD1115-0078 OE Interchange: 90044011; With Neway ARD 125/244-8 Series Air Suspension; Non-Gas Shock Absorber
1987-1996	HD1214-0546	(Cab Shock); OE Interchange: 2902455; With Unibuilt Cab	HD1215-0082 With Air Trac Suspension; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Peterbilt 376				
1999-1999	HD1215-0032	OE Interchange: 0202742; With Spring Suspension; With Set forward Axle; Shocks are 1.75in Bore	HD1215-0033	OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
1999-1999	HD1215-0061	OE Interchange: 0201890; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0037	OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore
1999-1999	HD1215-0056	OE Interchange: 0202738; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1115-0078	OE Interchange: 90044011; With Neway ARD 125/244-8 Series Air Suspension; Non-Gas Shock Absorber
1999-1999	HD1214-0546	(Cab Shock); OE Interchange: 2902455; With Unibuilt Cab	HD1214-0612	OE Interchange: 0307423, 665633; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1994-1996	HD1215-0061	OE Interchange: 0201890; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0037	OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore
1994-1996	HD1215-0056	OE Interchange: 0202738; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1115-0078	OE Interchange: 90044011; With Neway ARD 125/244-8 Series Air Suspension; Non-Gas Shock Absorber
1994-1996	HD1214-0546	(Cab Shock); OE Interchange: 2902455; With Unibuilt Cab	HD1214-0612	OE Interchange: 0307423, 665633; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1994-1996	HD1215-0032	OE Interchange: 0202742; With Spring Suspension; With Set forward Axle; Shocks are 1.75in Bore	HD1215-0033	OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
1990-1992			HD1215-0149	OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1988-1992	HD1215-0032	OE Interchange: 0202742; With Spring Suspension; With Set forward Axle; Shocks are 1.75in Bore	HD1215-0033	OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
1988-1992	HD1214-0546	(Cab Shock); OE Interchange: 2902455; With Unibuilt Cab	HD1214-0612	OE Interchange: 0307423, 665633; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1988-1992	HD1215-0061	OE Interchange: 0201890; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1115-0078	OE Interchange: 90044011; With Neway ARD 125/244-8 Series Air Suspension; Non-Gas Shock Absorber
1988-1992	HD1215-0056	OE Interchange: 0202738; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0037	OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore

Peterbilt 377				
1999-2001			HD1215-0149	OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Peterbilt 377			
1997-1998			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1992-1993			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1990-2001	HD1215-0061	OE Interchange: 0201890; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0033 OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
1990-1997			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1987-2001			HD1215-0037 OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore
1987-2001	HD1215-0032	OE Interchange: 0202742; With Taper Leaf Spring; With Set forward Axle; Shocks are 1.75in Bore	HD1115-0078 OE Interchange: 90044011; With Neway ARD 125/244-8 Series Air Suspension; Non-Gas Shock Absorber
1987-2001	HD1214-0546	(Cab Shock); OE Interchange R716007; With Unibuilt Cab	HD1215-0082 With Air Trac Suspension; Shocks are 1.75in Bore

Peterbilt 378			
2002-2007			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1996-2000			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1990-2007	HD1214-0546	(Cab Shock); OE Interchange: 2902455; With Unibuilt Cab	
1990-2007	HD1215-0061	OE Interchange: 0201890; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	
1990-2007	HD1215-0056	OE Interchange: 0202738; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	
1990-1997			HD1215-0033 OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
1990-1997			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore



FRONT



REAR

APPLICATIONS

Peterbilt 378			
1990-1992			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1988-2007			HD1215-0037 OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore
1988-2007			HD1115-0078 OE Interchange: 90044011; With Neway ARD 125/244-8 Series Air Suspension; Non-Gas Shock Absorber
1988-2007	HD1215-0032	OE Interchange: 0202742; With Spring Suspension; With Set forward Axle; Shocks are 1.75in Bore	HD1215-0082 With Air Trac Suspension; Shocks are 1.75in Bore

Peterbilt 379			
2003-2006			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1999-2007			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1999-2001			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1994-1996			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1991-1997			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1990-2007	HD1214-0536	(Cab Shock); OE Interchange: 2016775	
1990-2007	HD1215-0061	OE Interchange: 0201890; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	
1990-2007	HD1215-0056	OE Interchange: 0202738; With Spring Suspension; Steering Axle; With Set Back Axle; Shocks are 1.75in Bore	
1990-2007	HD1214-0546	(Cab Shock); OE Interchange: R716007, 2902455; With Unibuilt Cab	HD1215-0033 OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
1990-1992			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore



FRONT



REAR

APPLICATIONS

Peterbilt 379				
1986-2007	HD1215-0032	OE Interchange: 0202742; With Spring Suspension; With Set forward Axle; Shocks are 1.75in Bore	HD1215-0037	OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore
1986-2007			HD1115-0078	OE Interchange: 90044011; With Neway ARD 125/244-8 Series Air Suspension; Non-Gas Shock Absorber
1986-2007			HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore

Peterbilt 384				
2014-2015	HD1214-0569	(Cab Shock); OE Interchange: 2906005	HD1215-0033	OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
2012-2014			HD1215-0149	OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
2011-2013			HD1214-0612	OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
2010-2010			HD1215-0149	OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
2008-2016	HD1215-0167	OE Interchange: B716000; With Peterbilt Front Air Leaf Suspension; Shocks are 1.75 in Bore	HD1215-0037	OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore
2008-2016	HD1215-0032	OE Interchange: 0202742; With Spring Suspension; With Set forward Axle; Shocks are 1.75in Bore	HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore
2008-2016	HD1215-0056	OE Interchange: 0202738; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0085	OE Interchange: 0307420; With Quadraflex 4 Spring Suspension; Shocks are 1.75in Bore
2008-2016	HD1215-0061	OE Interchange: 0201890; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1214-0609	OE Interchange: 0307420; With Quadraflex 4 Spring Suspension; Shocks are 1.38in Bore
2008-2012	HD1214-0569	(Cab Shock); OE Interchange: 2906005	HD1215-0033	OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore

Peterbilt 385				
2006-2007			HD1214-0612	OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
2004-2007	HD1215-0020	OE Interchange: 665858; Steering Axle; With Composite Spring; Shocks are 1.75in Bore		



FRONT



REAR

APPLICATIONS

Peterbilt 385			
2001-2007			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1999-1999			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
1999-1999			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
1996-2007			HD1115-0075 OE Interchange: 0307420; With Quadrafles 4 Spring Suspension; Non-gas Shock Absorber
1996-2007	HD1215-0032	OE Interchange: 0202742; With Spring Suspension; With Set forward Axle; Shocks are 1.75in Bore	HD1215-0033 OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
1996-2007	HD1215-0061	OE Interchange: 0201890; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0037 OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore
1996-2007	HD1215-0056	OE Interchange: 0202738; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0085 OE Interchange: 0307420; With Quadraflex 4 Spring Suspension; Shocks are 1.75in Bore
1996-2007	HD1214-0569	(Cab Shock); OE Interchange: 2906005	HD1214-0609 OE Interchange: 0307420; With Quadraflex 4 Spring Suspension; Shocks are 1.38in Bore

Peterbilt 386			
2014-2015			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
2006-2016	HD1215-0032	OE Interchange: 0202742; With Spring Suspension; With Set forward Axle; Shocks are 1.75in Bore	
2006-2016	HD1214-0536	(Cab Shock); OE Interchange: R716005; With Day Cab	HD1215-0033 OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
2006-2016	HD1215-0061	OE Interchange: 0201890; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0037 OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore
2006-2016	HD1214-0546	(Cab Shock); OE Interchange: R716007; With 70 inch Sleeper Cab	HD1215-0085 OE Interchange: 0307420; With Quadraflex 4 Spring Suspension; Shocks are 1.75in Bore
2006-2016	HD1214-0569	(Cab Shock); OE Interchange: 2906005	HD1214-0609 OE Interchange: 0307420; With Quadraflex 4 Spring Suspension; Shocks are 1.38in Bore



FRONT



REAR

Peterbilt 386			
2006-2013			HD1215-0082 With Air Trac Suspension; Shocks are 1.75in Bore
2009-2009			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
2006-2008			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
2006-2006	HD1215-0056	OE Interchange: 0204010; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore

Peterbilt 387			
2009-2010			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
2007-2007			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
2005-2005			HD1214-0612 OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
2003-2004			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
2000-2011	HD1215-0032	With 12,000-23,000lb Taper Leaf Springs; With Set forward Axle; Shocks are 1.75in Bore	
2000-2011	HD1215-0056	OE Interchange: 0204010; With Spring Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1115-0075 OE Interchange: 0307420; With Quadraflex 4 Spring Suspension; Non-gas Shock Absorber
2000-2011	HD1214-0569	(Cab Shock); OE Interchange: 2906032, 2906005, R716008; With 70 inch Sleeper Cab	HD1215-0033 OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
2000-2003			HD1215-0037 OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore
2000-2003			HD1214-0612 OE Interchange: 0307423, 665633; With Low Air Leaf Suspension; Shocks are 1.38in Bore
2000-2001			HD1215-0149 OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore

APPLICATIONS



FRONT



REAR

APPLICATIONS

Peterbilt 389

2008-2018	HD1215-0032	With 12,000-23,000lb Taper Leaf Springs; With Set forward Axle; Shocks are 1.75in Bore	HD1215-0177	OE Interchange: 800781; With Low Mount Type; With Chalmers 40,000lb Rear Suspension
2008-2018	HD1214-0546	(Cab Shock); OE Interchange: R716007; With 70 inch Sleeper Cab	HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore
2008-2018	HD1214-0637	(Cab Shock); OE Interchange: 2019140, R716006; With Day Cab	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore

Peterbilt 520

2017-2020			HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore
2017-2020			HD1215-0054	With Neway AD+252-10 Tandem Axle; Shocks are 1.75in Bore
2017-2020	HD1215-0032	With 18,000-23,000lb Taper Leaf Springs; With Set forward Axle; Shocks are 1.75in Bore	HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore

Peterbilt 567

2014-2020	HD1215-0032	With 12,000-23,000lb Taper Leaf Springs; With Set forward Axle; Shocks are 1.75in Bore		
2014-2020	HD1215-0048	OE Interchange: B716019; With 10,000-14,600lb Taper Leaf Suspension; With Set Back Axle; Shocks are 1.75in Bore	HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore
2014-2018			HD1215-0132	OE Interchange: 60680004, 60680004L, H60680004, 641780001; With Hendrickson HMX 400 Haulmaax Suspension; With Hendrickson HMX 460 Haulmaax Suspension; With 16.5 in Saddle Height; Shocks are 1.75in Bore

Peterbilt 579

2017-2020	HD1215-0048	OE Interchange: B716019; With 12,000-14,600lb Taper Leaf Suspension; With Set Back Axle; Shocks are 1.75in Bore		
2013-2020	HD1215-0167	With Peterbilt Front Air Leaf Suspension; Shocks are 1.75 in Bore		
2013-2020	HD1215-0032	With 12,000-14,600lb Taper Leaf Springs; With Set forward Axle; Shocks are 1.75in Bore		



FRONT



REAR

Peterbilt 579				
2013-2016	HD1215-0048	OE Interchange: B716005; With 10,000-12,000lb Front Axle; With Day Cab; Shocks are 1.75in Bore		

Peterbilt 587				
2018-2018			HD1215-0085	OE Interchange: 0307420; With Quadraflex 4 Spring Suspension; Shocks are 1.75in Bore
2011-2018	HD1214-0569	(Cab Shock); OE Interchange: 2906032, 2906005, R716008; With 70 inch Sleeper Cab	HD1215-0082	With Air Trac Suspension; Shocks are 1.75in Bore
2014-2015			HD1215-0149	OE Interchange: 0304176; Drive Axle; With Air Leaf Suspension; Old Style; Shocks are 1.75in Bore
2014-2014			HD1214-0612	OE Interchange: 0305384, 0306084, 0307423, 85033, 665633; Drive Axle; With Low Air Leaf Suspension; Shocks are 1.38in Bore
2011-2018	HD1215-0167	With Peterbilt Front Air Leaf Suspension; Shocks are 1.75 in Bore		
2011-2018	HD1215-0032	With 12,000-14,6000lb Taper Leaf Springs; With Set forward Axle; Shocks are 1.75in Bore		
2011-2016			HD1215-0085	OE Interchange: 0307420; With Quadraflex 4 Spring Suspension; Shocks are 1.75in Bore
2011-2016			HD1214-0609	OE Interchange: 0307420; With Quadraflex 4 Spring Suspension; Shocks are 1.38in Bore
2011-2015			HD1215-0033	OE Interchange: 0304629; New Style; With Air Leaf Suspension; Shocks are 1.75in Bore
2011-2015	HD1215-0020	OE Interchange: 665858; Steering Axle; With Composite Spring; Shocks are 1.75in Bore	HD1215-0037	OE Interchange: 0307423; With Low Air Leaf Suspension; Shocks are 1.75in Bore

APPLICATIONS

Prevost X3 Coach				
2007-2019			HD1116-0043	OE Interchange: 630001; Non-Gas Shock Absorber

Prevost XL II				
1999-2003		OE Interchange: 4817000999386, 650407, 630127; Drive and Tag Axle shock	HD1116-0036	

Ram 4500				
2011-2018			HD1215-0105	Shocks are 1.75in Bore



FRONT



REAR

APPLICATIONS

Ram 5500			
2011-2018			HD1215-0105 Shocks are 1.75in Bore
Ram Promaster 2500			
2014-2018			HD1214-0552 Shocks are 1.38in Bore
Ram Promaster 3500			
2014-2018			HD1214-0552 Shocks are 1.38in Bore
Sterling Truck AT9500			
1999-2008			HD1215-0018 HD1215-0018
1999-2008			HD1215-0042 OE Interchange: 90045099, F6HT18080EA; With Neway AD123 Air Suspension; Shocks are 1.75in Bore
Sterling Truck AT9513			
1999-2001	HD1215-0025	OE Interchange: 10103684000; Shocks are 1.75in Bore	
Sterling Truck Bullet 45			
2008-2010			HD1215-0105 Shocks are 1.75in Bore
2008-2010			HD1215-0092 Shocks are 1.75in Bore
Sterling Truck Bullet 55			
2008-2010			HD1215-0105 Shocks are 1.75in Bore
2008-2010			HD1215-0092 Shocks are 1.75in Bore
Sterling Truck LT8500			
1999-2008			HD1215-0042 OE Interchange: 90045099, F6HT18080EA; With Neway AD123 Air Suspension; Shocks are 1.75in Bore
1999-2008	HD1215-0126	OE Interchange: F6HT18045LA; Shocks are 1.75in Bore	HD1215-0018 With FAS II Airliner Suspension; Shocks are 1.75in Bore
Sterling Truck LT9500			
1999-2008	HD1215-0126	OE Interchange: F6HT18045LA; Shocks are 1.75in Bore	HD1215-0018 With FAS II Airliner Suspension; Shocks are 1.75in Bore
Sterling Truck SC7000 Cargo			
2006-2006	HD1215-0126	OE Interchange: F6HT18045LA; Shocks are 1.75in Bore	
2003-2003	HD1215-0126	OE Interchange: F6HT18045LA; Shocks are 1.75in Bore	



FRONT



REAR

Sterling Truck SC8000 Cargo

1999-2007	HD1215-0126	OE Interchange: F6HT18045LA; Shocks are 1.75in Bore		
-----------	-------------	---	--	--

Thomas Saf-T-Liner

1996-2003			HD1215-0113	(MVP Model) OE Interchange: 87002, 728802, 61310101; Pusher; Shocks are 1.75in Bore
1991-2016	HD1215-0024	MVP Models; OE Interchange: 61300224; Shocks are 1.75in Bore	HD1215-0108	OE Interchange: 61310107, 61310119; Shocks are 1.75in Bore

Thomas School Bus

2006-2006	HD1116-0047	OE Interchange: 680010		
2006-2006	HD1214-0545	OE Interchange: 651442, 61300285; Shocks are 1.38in Bore		
2006-2006	HD1215-0024	With Freightliner M2 Chassis; OE Interchange: 101239000, 1012396000, 1012388000; Shocks are 1.75in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
2006-2006	HD1215-0114	OE Interchange: 1619138000; Shocks are 1.75in Bore	HD1116-0043	OE Interchange: 630001; Non-Gas Shock Absorber
2006-2006	HD1215-0068	OE Interchange: 6803230300, GBL665538; Steering Axle; With Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1214-0593	OE Interchange: 6803260000, GBL654725; Drive Axle; With Taper Leaf Spring Suspension; Shocks are 1.38in Bore
2000-2000	HD1116-0047	OE Interchange: 680010		
2000-2000	HD1214-0545	OE Interchange: 651442, 61300285; Shocks are 1.38in Bore		
2000-2000	HD1215-0024	With Freightliner M2 Chassis; OE Interchange: 101239000, 1012396000, 1012388000; Shocks are 1.75in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
2000-2000	HD1215-0114	OE Interchange: 1619138000; Shocks are 1.75in Bore	HD1116-0043	OE Interchange: 630001; Non-Gas Shock Absorber
2000-2000	HD1215-0068	OE Interchange: 6803230300, GBL665538; Steering Axle; With Taper Leaf Spring Suspension; Shocks are 1.75in Bore	HD1214-0593	OE Interchange: 6803260000, GBL654725; Drive Axle; With Taper Leaf Spring Suspension; Shocks are 1.38in Bore
1988-1991	HD1116-0047	OE Interchange: 680010	HD1116-0043	OE Interchange: 630001; Non-Gas Shock Absorber
1988-1991	HD1214-0545	OE Interchange: 651442, 61300285; Shocks are 1.38in Bore	HD1214-0593	OE Interchange: 6803260000, GBL654725; Drive Axle; With Taper Leaf Spring Suspension; Shocks are 1.38in Bore
1988-1991	HD1215-0024	With Freightliner M2 Chassis; OE Interchange: 101239000, 1012396000, 1012388000; Shocks are 1.75in Bore	HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore
1988-1991	HD1215-0114	OE Interchange: 1619138000; Shocks are 1.75in Bore		

APPLICATIONS



FRONT

REAR



APPLICATIONS

Thomas School Bus			
1988-1991	HD1215-0068	OE Interchange: 6803230300, GBL665538; Steering Axle; With Taper Leaf Spring Suspension; Shocks are 1.75in Bore	
UD 1200			
1999-2004	HD1214-0540	OE Interchange: 561000T825, E61000T825; Shocks are 1.38in Bore	
UD 1300			
2005-2007	HD1214-0540	OE Interchange: 561000T825, E61000T825; Shocks are 1.38in Bore	
UD 1400			
1994-2010	HD1214-0540	OE Interchange: 561000T825, E61000T825; Shocks are 1.38in Bore	
UD 1800			
2011-2013	HD1213-0708	OE Interchange: 5610130Z01; Shocks are 1.38in Bore	
1995-1998	HD1213-0708	OE Interchange: 5610130Z01; Shocks are 1.38in Bore	
1989-1994	HD1213-0734	Shocks are 1.38 in Bore	
UD 1800CS			
2005-2010	HD1213-0708	OE Interchange: 5610130Z01; Shocks are 1.38in Bore	
1999-2004	HD1213-0734	Shocks are 1.38 in Bore	
UD 1800HD			
2005-2010	HD1213-0708	OE Interchange: 5610130Z01; Shocks are 1.38in Bore	
UD 2000			
1998-2013	HD1213-0708	OE Interchange: 5610130Z01; Shocks are 1.38in Bore	
UD 2300DH			
2005-2013	HD1213-0708	OE Interchange: 5610130Z01; Shocks are 1.38in Bore	
UD 2300LP			
2005-2013	HD1213-0708	OE Interchange: 5610130Z01; Shocks are 1.38in Bore	



FRONT



REAR

Volvo FE				
1992-1998	HD1214-0677	OE Interchange: 6876828; Shocks are 1.38 in Bore	HD1214-0567	OE Interchange: 6790756; With Parabolic Leaf Spring; Shocks are 1.38in Bore

Volvo VAH				
2011-2018	HD1215-0074	OE Interchange: 21436086; Shocks are 1.75in Bore	HD1215-0083	With Hendrickson HAS 400 or 460 Suspension; Shocks are 1.75in Bore
2011-2018	HD1214-0554	(Cab Shock); OE Interchange: 20721254, 22662224		

Volvo VHD				
2001-2017	HD1215-0051	OE Interchange: 20434880; With 12,000-22,000lb Front Axle; Shocks are 1.75in Bore	HD1215-0069	With Hendrickson 40,000lb Primaax or Firemaax EX Suspension; Shocks are 1.75in Bore
2001-2017	HD1215-0125	OE Interchange: 20433426; With 12,000-20,000lb Front Axle; Shocks are 1.75in Bore	HD1215-0109	OE Interchange: 20433427, 8073212; With T-Ride Suspension; Shocks are 1.75in Bore
2001-2009	HD1214-0554	(Cab Shock); OE Interchange: 20721254, 22662224		

Volvo VN				
2004-2004	HD1215-0074	OE Interchange: 8078195, 20513881, 20433424; Shocks are 1.75in Bore		
1998-1999	HD1215-0074	OE Interchange: 8078195, 20513881, 20433424; Shocks are 1.75in Bore	HD1215-0030	OE Interchange: 8086651, 20433425, 20551628; Shocks are 1.75in Bore
2004-2004	HD1215-0053	OE Interchange: 20485633; Shocks are 1.75in Bore	HD1215-0030	OE Interchange: 8086651, 20433425, 20551628; Shocks are 1.75in Bore
2004-2004	HD1214-0576	(Cab Shock); Oe Interchange: 8078547, 8078546, 20496217, 20624917	HD1214-0597	OE Interchange: 8086651, 20433425, 20551628; Shocks are 1.38in Bore
1998-1999	HD1215-0053	OE Interchange: 20485633; Shocks are 1.75in Bore		
1998-1999	HD1214-0576		HD1214-0597	OE Interchange: 8086651, 20433425, 20551628; Shocks are 1.38in Bore

Volvo VNL				
2011-2020	HD1215-0074	OE Interchange: 21436086, 20433424; with 12,000-13,200lb Front Axle; Shocks are 1.75in Bore		
2000-2020	HD1215-0053	With Hendrickson Airtek Front Suspension; Shocks are 1.75in Bore	HD1215-0030	OE Interchange: 21462378, 20433425, 20551628, 21462380; With 40,000lb Air Suspension; Shocks are 1.75in Bore
2000-2020			HD1214-0597	OE Interchange: 21462378, 20433425, 20551628, 21462380; With 40,000lb Air Suspension; Shocks are 1.38in Bore
2000-2018			HD1215-0069	With Hendrickson 40,000lb Primaax or Firemaax EX Suspension; Shocks are 1.75in Bore

APPLICATIONS

**FRONT****REAR**

Volvo VNM					
2011-2016			HD1215-0053	OE Interchange: 20485633; Excludes Model 780; With 12,000-12,500lb Axle; Shocks are 1.75in Bore	
2000-2018			HD1215-0030	OE Interchange: 21462378, 21462380; With 38,000lb Air Suspension; Shocks are 1.75in Bore	
2000-2018	HD1215-0074	OE Interchange: 21436086; With 12,000-12,500lb Front Axle; Shocks are 1.75in Bore	HD1214-0597	OE Interchange: 21462378, 21462380; With 38,000lb Air Suspension; Shocks are 1.38in Bore	
Volvo VNR					
2018-2020	HD1215-0053	With Hendrickson Airtex Front Suspension; Shocks are 1.75in Bore	HD1215-0030	OE Interchange: 21462380; With 38,000lb Air Suspension; Shocks are 1.75in Bore	
2018-2020	HD1215-0074	OE Interchange: 21436086; With 12,000-12,500lb Front Axle; Shocks are 1.75in Bore	HD1214-0597	OE Interchange: 21462380; With 38,000lb Air Suspension; Shocks are 1.38in Bore	
Volvo VT					
2006-2010	HD1213-0735	OE Interchange: 027005976; With Dual Shocks; Shocks are 1.75 in Bore			
2006-2010	HD1215-0051	OE Interchange: 373010021; With Dual Shocks; Shocks are 1.75in Bore			
Volvo WG					
1996-2001	HD1215-0051	OE Interchange: 8065787; Shocks are 1.75in Bore			
Volvo WH					
1996-1997	HD1215-0051	OE Interchange: 373010021; With Dual Shocks; Shocks are 1.75in Bore			
Western Star 3800					
1999-2001			HD1215-0110	OE Interchange: 4790213, 479028; With Hendrickson Air Suspension; Shocks are 1.75in Bore	
1999-2001	HD1215-0058	OE Interchanges: 373904402, 373904403; Shocks are 1.75in Bore	HD1214-0644	OE Interchange: 90044907; With Neway Air Suspension; Shocks are 1.38in Bore	
1989-1997	HD1215-0058	OE Interchanges: 373904402, 373904403; Shocks are 1.75in Bore	HD1215-0110	OE Interchange: 4790213, 479028; With Hendrickson Air Suspension; Shocks are 1.75in Bore	
1989-1997			HD1214-0644	OE Interchange: 90044907; With Neway Air Suspension; Shocks are 1.38in Bore	
Western Star 4700SB					
2012-2018			HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore	



FRONT



REAR

APPLICATIONS

Western Star 4700SF				
2012-2018			HD1215-0018	With FAS II Airliner Suspension; Shocks are 1.75in Bore

Western Star 4800				
1981-2002	HD1214-0610	(Cab Shock); OE Interchange: 660103406	HD1214-0644	OE Interchange: 90044907; With Neway Air Suspension; Shocks are 1.38in Bore
1981-2002	HD1214-0613	(Cab Shock); OE Interchange: 660103402, 660103403, 660103404; With Link Cab Suspension	HD1215-0163	OE Interchange: 359014403; With Chalmers Air Beam Suspension; Shocks are 1.75 in Bore

Western Star 4900				
1981-2002	HD1214-0613	(Cab Shock); OE Interchange: 660103402, 660103403, 660103404; With Link Cab Suspension	HD1215-0163	OE Interchange: 359014403; With Chalmers Air Beam Suspension; Shocks are 1.75 in Bore
1981-2002	HD1214-0610	(Cab Shock); OE Interchange: 660103406	HD1214-0644	OE Interchange: 90044907; With Neway Air Suspension; Shocks are 1.38in Bore

Western Star 5800				
1997-2002	HD1214-0613	(Cab Shock); OE Interchange: 660103402, 660103403, 660103404; With Link Cab Suspension	HD1215-0163	OE Interchange: 359014403; With Chalmers Air Beam Suspension; Shocks are 1.75 in Bore
1997-2002	HD1214-0610	(Cab Shock); OE Interchange: 660103406	HD1214-0644	OE Interchange: 90044907; With Neway Air Suspension; Shocks are 1.38in Bore

Western Star 5900				
1989-2001			HD1215-0163	OE Interchange: 359014403; With Chalmers Air Beam Suspension; Shocks are 1.75 in Bore
1989-2001	HD1214-0613	(Cab Shock); OE Interchange: 660103402, 660103403, 660103404; With Link Cab Suspension	HD1214-0644	OE Interchange: 90044907; With Neway Air Suspension; Shocks are 1.38in Bore

Western Star 6900				
1989-2001			HD1215-0163	OE Interchange: 359014403; With Chalmers Air Beam Suspension; Shocks are 1.75 in Bore
1989-2001	HD1214-0613	(Cab Shock); OE Interchange: 660103402, 660103403, 660103404; With Link Cab Suspension	HD1214-0644	OE Interchange: 90044907; With Neway Air Suspension; Shocks are 1.38in Bore

White/GMC WCA				
1988-1995	HD1215-0051	OE Interchange: 373010021; With Dual Shocks; Shocks are 1.75in Bore		

White/GMC WIA				
1988-1995	HD1214-0536	(Cab Shock); OE Interchange: 8168617		



FRONT



REAR

APPLICATIONS

White/GMC WIA

1988-1995	HD1215-0051	OE Interchange: 373010021; With Dual Shocks; Shocks are 1.75in Bore		
1988-1995	HD1214-0639	(Cab Shock); OE Interchange: 660100008, 8162662		

White/GMC WX

1988-1995	HD1214-0574	OE Interchange: 373010004; With Single Shock Absorber; Shocks are 1.38in Bore		
-----------	--------------------	---	--	--

Workhorse P30

2000-2003	HD1215-0116	OE Interchange: B46-1173	HD1215-0098	OE Interchange: B46-1587
-----------	--------------------	--------------------------	--------------------	--------------------------

Workhorse W22

2001-2004	HD1215-0160	OE Interchange: S1978	HD1215-0131	OE Interchange: S1981
-----------	--------------------	-----------------------	--------------------	-----------------------

ENGINEERED FOR FLEET SATISFACTION



The piston rod is chrome plated and micro-polished for low friction and extended life.

Specially designed STOP control to prevent rod punctures and valve damage.

Square groove PTFE piston seal for low friction. Competitors use a round rubber O-ring or no seal at all.

Heavy Duty robotic welding with the highest breakpoint rating in the industry.

Highest rated salt/spray surface corrosion resistance, 42 micron surface finish, in the industry.

A seamless inner working tube for superior concentricity. This provides the best quality seal and strength. The inner tube wall is 40% thicker than the competition.

Upper valve package is 100% disk technology.

A fully functioning lower valve package with 100% disk technology.

In-house bushing manufacturing using proprietary rubber formulations make our bushings superior to the competition.

Interchanges

INTERCHANGE

BULLDOG HD Interchanges	
OE	BULLDOG HD
40015	HD1215-0079
53176	HD1214-0568
57113	HD1214-0605
57131	HD1214-0640
66884	HD1214-0532
70029	HD1215-0113
70034	HD1116-0044
70042	HD1215-0029
85991	HD1215-0057
87002	HD1215-0113
88035	HD1215-0122
106303	HD1215-0060
200171	HD1116-0047
535227	HD1214-0568
535228	HD1215-0029
572412	HD1215-0067
606753	HD1215-0073
614966	HD1116-0044
614974	HD1116-0047
650224	HD1214-0568
654654	HD1214-0566
665236	HD1214-0568
665538	HD1215-0068
671962	HD1215-0086
671963	HD1215-0065
676081	HD1213-0674
680009	HD1116-0044
680009	HD1215-0029
680010	HD1116-0047
680091	HD1215-0113
680339	HD1215-0021
728802	HD1215-0113
823047	HD1215-0113
823054	HD1116-0047
1317767	HD1215-0096
1658525	HD1215-0070
1658533	HD1215-0151
1668722	HD1215-0091
1668730	HD1215-0045
1722214	HD1215-0091
1746163	HD1215-0111

BULLDOG HD Interchanges	
OE	BULLDOG HD
1830378	HD1214-0544
2021459	HD1214-0605
3192890	HD1214-0539
3192892	HD1214-0579
3638631	HD1214-0645
4036892	HD1214-0645
4790213	HD1215-0133
4790228	HD1215-0045
4940606	HD1214-0539
4940614	HD1214-0640
4940662	HD1214-0539
4963854	HD1214-0640
4975467	HD1214-0533
4975467	HD1214-0579
4975494	HD1214-0533
4975494	HD1214-0579
4975497	HD1214-0539
4975510	HD1214-0579
4975511	HD1214-0608
4984526	HD1214-0640
4984838	HD5113-0014
5552451	HD1215-0113
8026658	HD1215-0044
8071524	HD1215-0124
12010012	HD1213-0679
12010254	HD1214-0537
12011043	HD1214-0573
12011044	HD1213-0679
12011044	HD1214-0573
12011049	HD1214-0573
12020012	HD1213-0679
12020054	HD1213-0651
12021043	HD1214-0573
12021044	HD1214-0573
12474915	HD1215-0133
12474917	HD1215-0045
15123676	HD1215-0081
15174298	HD1215-0081
15174898	HD1215-0081
15174902	HD1214-0561
15185643	HD1215-0112

BULLDOG HD Interchanges	
OE	BULLDOG HD
15185644	HD1215-0112
15192385	HD1215-0081
15588554	HD1214-0556
15588554	HD1215-0081
15740554	HD1215-0045
15782915	HD1215-0112
15887728	HD1215-0081
15963161	HD1215-0133
16106880	HD1214-0568
22002293	HD1214-0539
22002294	HD1214-0578
22002295	HD1214-0608
22007701	HD1214-0539
22007750	HD1214-0533
22007750	HD1214-0579
22007751	HD1214-0539
22007752	HD1214-0578
22007753	HD1214-0608
22011982	HD5113-0014
22012090	HD1215-0113
22012095	HD1214-0539
22012096	HD1214-0579
22012166	HD1214-0539
22012169	HD1214-0579
22017530	HD1214-0608
22017531	HD1214-0608
22024673	HD1116-0033
22064230	HD1214-0556
22064230	HD1215-0081
22064232	HD1214-0561
22064233	HD1215-0156
22064402	HD1215-0044
22064432	HD1215-0108
22064489	HD1215-0039
22064804	HD1215-0156
22064805	HD1215-0031
22165187	HD1215-0156
22165188	HD1215-0031
36886171	HD1215-0041
58913003	HD1215-0103
58913012	HD1215-0103

Interchanges

BULLDOG HD Interchanges	
OE	BULLDOG HD
60998003	HD1215-0057
61300224	HD1215-0024
61310101	HD1215-0113
61310107	HD1215-0108
61310119	HD1215-0108
61310434	HD1215-0022
61310478	HD1215-0023
88963409	HD1215-0120
88982682	HD1215-0081
88982686	HD1214-0561
90044162	HD1214-0508
90044769	HD1214-0534
90044769	HD1214-0551
90044770	HD1214-0534
90044770	HD1214-0551
90045083	HD1215-0062
90045099	HD1215-0042
94033786	HD1214-0571
97083029	HD1214-0540
101239000	HD1215-0024
250441901	HD1214-0526
359013201	HD1215-0049
485001541	HD1214-0640
485001801	HD1214-0641
485001940	HD1214-0560
485001941	HD1214-0560
485003710	HD1215-0071
485301880	HD1215-0107
683260400	HD1215-0064
1012030002	HD1215-0029
1012032002	HD1215-0029
1012032004	HD1215-0029
1012388000	HD1215-0024
1012388000	HD1215-0024
1012396000	HD1215-0024
1012542000	HD1215-0021
1012542000	HD1215-0021
1012703000	HD1215-0025
1012704000	HD1215-0025
1013021000	HD1215-0025
1013211000	HD1215-0025

BULLDOG HD Interchanges	
OE	BULLDOG HD
1516301670	HD1214-0526
1516302000	HD1214-0604
1611133000	HD1214-0568
1612117000	HD1215-0113
1613947000	HD1215-0064
1613952000	HD1215-0019
1613957000	HD1215-0020
1614259000	HD1215-0026
1614794000	HD1214-0607
1615089000	HD1214-0657
1615436000	HD1214-0607
1615705000	HD1214-0602
1615817000	HD1215-0018
1615934000	HD1214-0602
1616262000	HD1214-0602
1616442000	HD1214-0611
1616486000	HD1214-0611
1616542000	HD1214-0607
1616577000	HD1215-0026
1617684000	HD1214-0528
1619138000	HD1215-0114
1829846000	HD1214-0535
1829846000	HD1215-0025
1830378000	HD1214-0544
1832999000	HD1214-0544
1832999001	HD1214-0538
1841762000	HD1214-0538
1841762001	HD1214-0636
1841762002	HD1214-0538
1860764000	HD1214-0538
1860765000	HD1214-0573
6803230200	HD1214-0566
6803230300	HD1214-0593
6803230300	HD1215-0068
6803260000	HD1214-0593
6818910205	HD1213-0680
8220642320	HD1214-0561
8970830290	HD1214-0540
8972536200	HD1214-0540
8972536210	HD1214-0540
8972536510	HD1214-0571

BULLDOG HD Interchanges	
OE	BULLDOG HD
8972536640	HD1214-0571
8980980591	HD1214-0571
8983162280	HD1214-0571
9516306662	HD1214-0571
472000000000	HD1215-0122
15900351	HD1215-0028
1614668000	HD1215-0150
1616736000	HD1215-0150
166084691	HD1214-0530
166084691	HD1214-0557
16634711	HD1214-0656
16641491	HD1215-0066
16647882	HD1215-0052
16675201	HD1215-0114
16754551	HD1215-0028
16777071	HD1215-0108
16900351	HD1215-0028
14418080	HD1215-0059
20155561	HD1215-0052
20155571	HD1215-0108
20189871	HD1215-0028
20236841	HD1214-0614
20236851	HD1214-0614
202920091	HD1214-0539
20325331	HD1215-0052
20499491	HD1214-0568
21053492	HD1214-0568
250922291	HD1214-0497
250922491	HD1214-0497
26140141	HD1214-0573
2778	HD1215-0113
29300991	HD1215-0113
300007091	HD1214-0545
30866891	HD1214-0605
30866991	HD1214-0605
3504251	HD1215-0097
35057352	HD1214-0558
35333561	HD1214-0572
35333561	HD1215-0084
35333571	HD1212-0022
35414561	HD1214-0161

INTERCHANGE

Interchanges

INTERCHANGE

BULLDOG HD Interchanges	
OE	BULLDOG HD
35447681	HD1215-0055
35490992	HD1215-0041
35491001	HD1215-0055
35536281	HD1215-0147
35536282	HD1215-0147
35571651	HD1214-0497
35571673	HD1214-0497
35580892	HD1215-0100
35607052	HD1214-0497
35717111	HD1215-0052
35717121	HD1215-0052
35717131	HD1215-0052
35781051	HD1214-0572
35781051	HD1215-0084
35781052	HD1215-0084
35788581	HD1215-0055
35788582	HD1215-0055
358411161	HD1215-0095
35841162	HD1215-0095
35841172	HD1215-0095
35841182	HD1212-0022
35882091	HD1212-0022
36020601	HD1212-0022
36057351	HD1214-0558
36067701	HD1215-0161
36068571	HD1215-0080
36068591	HD1215-0119
36886141	HD1215-0041
36886151	HD1215-0041
38063414	HD1215-0154
38105814	HD1215-0154
39029932	HD1214-0642
39029933	HD1214-0642
39451651	HD1214-0543
39777591	HD1215-0153
39777942	HD1214-0543
39919911	HD1214-0642
42674491	HD1215-0113
45355691	HD1214-0605
45356191	HD1214-0568
45356291	HD1214-0568

BULLDOG HD Interchanges	
OE	BULLDOG HD
45356591	HD1214-0568
45357691	HD1215-0113
45357791	HD1215-0113
46255791	HD1215-0097
46737191	HD1214-0568
46737191	HD1214-0568
46737291	HD1214-0568
47236791	HD1214-0661
47241191	HD1214-0545
47241291	HD1214-0545
47241291	HD1214-0545
47241491	HD1214-0661
4771321	HD1215-0113
485003710	HD1215-0071
44018080	HD1215-0063
44218124	HD1212-0022
4418124	HD1215-0095
4418124	HD1215-0095
4418125	HD1215-0063
4418125	HD1215-0073
4418125	HD1215-0055
50155391	HD1215-0028
50190691	HD1215-0063
50190692	HD1215-0063
5036102	HD1214-0533
5072021	HD1214-0570
520104077	HD1215-0092
52014061	HD1215-0105
53752491	HD1214-0530
54039592	HD1214-0526
561000825	HD1214-0540
561013001	HD1213-0708
561015011	HD1213-0708
58672491	HD1214-0545
58672491	HD1214-0545
79033591	HD1214-0580
87469591	HD1214-0605
8718045	HD1215-0135
615	HD1215-0095
616	HD1215-0095
617	HD1212-0022

BULLDOG HD Interchanges	
OE	BULLDOG HD
113	HD1215-0038
1105	HD1215-0073
461173	HD1215-0116
461587	HD1215-0098
462147100	HD1215-0150
462545100	HD1215-0118
462546100	HD1215-0150
462556100	HD1215-0062
462556100	HD1215-0118
716019	HD1215-0048
118045	HD1214-0564
711002	HD1215-0034
711014	HD1215-0086
711017	HD1215-0076
718077	HD1214-0568
18045	HD1214-0564
18045	HD1214-0564
218045	HD1214-0564
218045	HD1214-0550
218045	HD1214-0559
218045	HD1214-0595
218045	HD1214-0564
218045	HD1214-0564
218045	HD1214-0595
218045	HD1214-0564
218045	HD1214-0595
218045	HD1214-0564
218045	HD1214-0595
218080	HD1214-0568
718080	HD1214-0530
718080	HD1214-0563
718045	HD1214-0564
718045	HD1215-0133
718045	HD1214-0550
718045	HD1214-0559
718045	HD1214-0564
718045	HD1214-0595
718045	HD1214-0595
718045	HD1215-0135
718080	HD1214-0568
718080	HD1214-0563
18045	HD1214-0559
18080	HD1215-0107

Interchanges

BULLDOG HD Interchanges	
OE	BULLDOG HD
518045	HD1215-0135
61000825	HD1214-0540
618080	HD1215-0029
818080	HD1215-0121
918045	HD1215-0078
118045	HD1214-0559
118045	HD1215-0078
118045	HD1214-0595
118045	HD1214-0564
118045	HD1214-0564
118045	HD1214-0595
118045	HD1215-0134
118045	HD1215-0134
118045	HD1215-0088
118045	HD1215-0088
118045	HD1215-0135
118045	HD1215-0134
118045	HD1215-0134
218045	HD1215-0135
218045	HD1215-0135
218045	HD1215-0088
25407	HD1213-0703
418045	HD1215-0043
418045	HD1215-0043
418045	HD1215-0068
418080	HD1215-0029
418080	HD1215-0029
418080	HD1215-0036
6218125	HD1215-0067
618045	HD1215-0128
618045	HD1215-0128
618045	HD1214-0658
618045	HD1214-0660
618045	HD1214-0562
618045	HD1215-0157
618045	HD1215-0157
618045	HD1215-0157
618045	HD1215-0157
618045	HD1215-0128
618045	HD1215-0128
618045	HD1215-0126

BULLDOG HD Interchanges	
OE	BULLDOG HD
618045	HD1215-0088
618080	HD1215-0029
618080	HD1215-0067
618080	HD1215-0042
618080	HD1215-0045
618080	HD1215-0036
65407	HD1213-0707
75407	HD1213-0707
8118045	HD1215-0123
8118080	HD1215-0089
418124	HD1215-0148
418124	HD1215-0148
1011823	HD1116-0033
1201338	HD1116-0033
654725	HD1214-0593
1978	HD1215-0160
1981	HD1215-0131
485003710	HD1215-0071
3518045	HD1215-0123
3518045	HD1215-0123
4518080	HD1215-0029

Applications by Part Number

BULLDOG HD APPLICATIONS

BULLDOG HD Applications by Part Number	
Part Number	APPLICATION
HD1116-0033	NOVA BUS CORPORATION RTS (2001-2002)
HD1116-0044	Blue Bird All American FE (1989-2016)
HD1116-0044	Blue Bird All American RE (1989-2016)
HD1116-0044	Gillig School Bus (1989-1993)
HD1116-0044	Gillig School Bus (1989-1993)
HD1116-0047	Bluebird All American FE (1989-2016)
HD1116-0047	Bluebird All American RE (1989-2016)
HD1116-0047	Gillig School Bus (1989-1993)
HD1116-0047	Gillig School Bus (1989-1993)
HD1116-0047	Thomas School Bus (1988-2006)
HD1212-0022	Ford F650 (2010-2011)
HD1212-0022	Ford F750 (2010-2011)
HD1212-0022	International 3000 (1996-2002)
HD1212-0022	International 3000FE (1997-1999)
HD1212-0022	International 3000IC (2000-2002)
HD1212-0022	International 3000RE (1996-2005)
HD1212-0022	International 3400 (1996-2002)
HD1212-0022	International 4200 (2002-2008)
HD1212-0022	International 4300 (2002-2008)
HD1212-0022	International 4300LP (2002-2008)
HD1212-0022	International 4400 (2002-2008)
HD1212-0022	International 4400LP (2002-2008)
HD1212-0022	International 8500 Transtar (2008-2011)
HD1212-0022	International 8600 Transtar (2008-2011)
HD1213-0651	Freightliner FL60 (1991-2004)
HD1213-0651	Freightliner FL70 (1991-2005)
HD1213-0651	Freightliner FLB (1994-2002)
HD1213-0651	International 9600 (1989-1996)
HD1213-0651	International 9700 (1989-1996)
HD1213-0674	GMC 3000 (1960-1966)

BULLDOG HD Applications by Part Number	
Part Number	APPLICATION
HD1213-0679	Ford LA8000F (1991-1997)
HD1213-0679	Freightliner FLC112 (1992-2001)
HD1213-0679	Freightliner FLD112 (1992-2002)
HD1213-0679	International 4600 (1990-1994)
HD1213-0679	International 4700 (1990-2003)
HD1213-0679	International 4800 (1990-2003)
HD1213-0679	International 4900 (1990-2003)
HD1213-0680	Freightliner FLB (1994-2002)
HD1213-0703	Ford CF7000 (1992-1994)
HD1213-0707	Ford AT9513 (1996-1998)
HD1213-0707	Ford AT9522 (1997-1998)
HD1213-0708	International 500 (1991-1991)
HD1213-0708	UD 1800 (1995-2013)
HD1213-0708	UD 1800CS (2005-2010)
HD1213-0708	UD 1800HD (2005-2010)
HD1213-0708	UD 2000 (1998-2013)
HD1213-0708	UD 2300DH (2005-2013)
HD1213-0708	UD 2300LP (2005-2013)
HD1214-0004	Ford E-350 Club Wagon (2002-2005)
HD1214-0004	Ford E-350 Econoline (1992-2000)
HD1214-0004	Ford E-350 Econoline Club Wagon (1992-2002)
HD1214-0004	Ford E-350 Super Duty (1999-2018)
HD1214-0004	Ford E-450 Econoline Super Duty (2000-2002)
HD1214-0004	Ford E-450 Super Duty (2003-2017)
HD1214-0004	Ford Econoline Super Duty (1996-1999)
HD1214-0497	International Workstar 7300 (2015-2016)
HD1214-0497	International Workstar 7400 (2015-2016)
HD1214-0497	International Workstar 7600 (2010-2015)
HD1214-0508	Freightliner FLB (1994-2002)

BULLDOG HD Applications by Part Number	
Part Number	APPLICATION
HD1214-0508	Freightliner FLC112 (1992-2001)
HD1214-0508	Freightliner FLC120 (1998-1998)
HD1214-0508	Freightliner FLD112 (1992-2002)
HD1214-0508	Freightliner FLD120 (1992-2002)
HD1214-0526	Chevrolet W6500 Tiltmaster (1987-1996)
HD1214-0526	IC Corporation RE School Bus (2003-2016)
HD1214-0526	International 1452SC (1987-1992)
HD1214-0526	International 1652SC (1986-1992)
HD1214-0526	International 3400 (1996-2002)
HD1214-0526	International 3700 (1990-1994)
HD1214-0526	International 3800 (1987-2004)
HD1214-0526	International 4600LP (1990-1994)
HD1214-0526	International 4700LP (1990-2002)
HD1214-0526	Isuzu FSR (1989-1996)
HD1214-0527	Ford E-350 Club Wagon (2002-2005)
HD1214-0527	Ford E-350 Econoline (1992-2000)
HD1214-0527	Ford E-350 Econoline Club Wagon (1992-2002)
HD1214-0527	Ford E-350 Super Duty (1999-2017)
HD1214-0527	Ford E-450 Econoline Super Duty (2000-2002)
HD1214-0527	Ford E-450 Super Duty (2003-2017)
HD1214-0527	Ford Econoline Super Duty (1996-1999)
HD1214-0528	Freightliner MB Line (1998-2009)
HD1214-0529	Ford E-350 Club Wagon (2002-2005)
HD1214-0529	Ford E-350 Econoline (1992-2000)

Applications by Part Number

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1214-0529	Ford E-350 Econoline Club Wagon (1992-2002)
HD1214-0529	Ford E-350 Super Duty (1999-2017)
HD1214-0529	Ford E-450 Econoline Super Duty (2000-2002)
HD1214-0529	Ford E-450 Super Duty (2003-2017)
HD1214-0529	Ford Econoline Super Duty (1996-1999)

HD1214-0530	Ford CL9000 (1981-1989)
HD1214-0530	Ford CLT9000 (1981-1989)
HD1214-0530	IC Corporation RE School Bus (2003-2016)
HD1214-0530	International 2275 (1981-1989)
HD1214-0530	International 2554 (1981-2002)
HD1214-0530	International 2574 (1990-2003)
HD1214-0530	International 2575 (1984-1989)
HD1214-0530	International 3700 (1990-1994)
HD1214-0530	International 3800 (1987-2004)
HD1214-0530	International 9600 (1989-1996)
HD1214-0530	International 9700 (1989-1996)
HD1214-0530	International F2275 (1979-1989)
HD1214-0530	International F2554 (1979-1989)
HD1214-0530	International F2574 (1979-1989)
HD1214-0530	International F2575 (1979-1989)
HD1214-0530	International F2654 (1980-1989)
HD1214-0530	International F2674 (1979-1989)
HD1214-0530	International S1723 (1980-1985)
HD1214-0530	International S1823 (1980-1982)
HD1214-0530	International S1853 (1981-1989)

HD1214-0532	Blue Bird TC2000 (1989-2004)
--------------------	------------------------------

HD1214-0533	Chevrolet C50 (1973-1980)
HD1214-0533	Chevrolet C60 (1973-1980)
HD1214-0533	Chevrolet C70 (1980-1980)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1214-0533	International 9300 (1989-1999)
HD1214-0533	International 9300 (1989-1999)
HD1214-0533	International 9400 (1990-1999)
HD1214-0533	International 9400 (1990-1999)
HD1214-0533	International 9600 (1989-1996)
HD1214-0533	International 9600 (1989-1996)
HD1214-0533	International 9700 (1989-1996)
HD1214-0533	International 9700 (1989-1996)

HD1214-0534	GMC G35 (1975-1978)
HD1214-0534	GMC G3500 (1979-1992)

HD1214-0535	Freightliner Classic (2001-2010)
HD1214-0535	Freightliner Columbia (2001-2012)
HD1214-0535	Freightliner FL60 (1991-2004)
HD1214-0535	Freightliner FL70 (1991-2005)
HD1214-0535	Freightliner FLC112 (1992-2001)
HD1214-0535	Freightliner FLC120 (1998-1998)
HD1214-0535	Freightliner FLD112 (1992-2002)
HD1214-0535	Freightliner FLD120 (1992-2002)

HD1214-0537	International 9900I (2010-2015)
HD1214-0537	International 9900IX (2000-2009)

HD1214-0538	Freightliner Cascadia (2009-2017)
HD1214-0538	Freightliner Century Class (2001-2011)
HD1214-0538	Freightliner Columbia (2001-2012)
HD1214-0538	Freightliner Coronado (2010-2016)

HD1214-0539	Chevrolet C50 (1963-1990)
HD1214-0539	Chevrolet C50 (1971-1989)
HD1214-0539	Chevrolet C60 (1963-1980)
HD1214-0539	Chevrolet C60 (1973-1989)
HD1214-0539	Chevrolet C70 (1979-1980)
HD1214-0539	Chevrolet C70 (1979-1989)
HD1214-0539	Chevrolet S7 (1987-1989)
HD1214-0539	GMC C5000 (1980-1980)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1214-0539	GMC C5000 (1980-1989)
HD1214-0539	GMC C6000 (1980-1980)
HD1214-0539	GMC C6000 (1980-1989)
HD1214-0539	GMC C7000 (1980-1980)
HD1214-0539	GMC C7000 (1980-1989)
HD1214-0539	International 5070 (1981-2000)
HD1214-0539	International 8100 (1990-2003)
HD1214-0539	International 8200 (1990-1998)
HD1214-0539	International 8300 (1989-1994)
HD1214-0539	International 9300 (1989-1999)
HD1214-0539	International 9400 (1990-1999)

HD1214-0540	Chevrolet W4500 Tiltmaster (1992-1995)
HD1214-0540	GMC W4500 Forward (1992-2009)
HD1214-0540	GMC W4500 Forward (2003-2008)
HD1214-0540	GMC W5500 Forward (2000-2009)
HD1214-0540	GMC W5500 Forward (2003-2008)
HD1214-0540	Isuzu NPR (1986-2010)
HD1214-0540	Isuzu NQR (2000-2016)
HD1214-0540	Isuzu NRR (2005-2016)
HD1214-0540	UD 1200 (1999-2004)
HD1214-0540	UD 1300 (2005-2007)
HD1214-0540	UD 1400 (1994-2010)

HD1214-0543	International Terrastar (2011-2015)
--------------------	-------------------------------------

HD1214-0544	Freightliner Century Class (2001-2011)
HD1214-0544	Freightliner FL60 (1991-2004)
HD1214-0544	Freightliner FL70 (1991-2005)

HD1214-0545	IC Corporation RE School Bus (2003-2016)
HD1214-0545	International 1452SC (1987-1992)
HD1214-0545	International 1652SC (1986-1992)
HD1214-0545	International 1654 (1980-1989)
HD1214-0545	International 1724 (1980-1984)
HD1214-0545	International 1754 (1981-1989)
HD1214-0545	International 2275 (1981-1989)

BULLDOG HD APPLICATIONS

Applications by Part Number

BULLDOG HD APPLICATIONS

BULLDOG HD Applications by Part Number	
Part Number	APPLICATION
HD1214-0545	International 2554 (1981-2002)
HD1214-0545	International 2574 (1984-2002)
HD1214-0545	International 2575 (1984-1989)
HD1214-0545	International 2654 (1999-2000)
HD1214-0545	International 2674 (1981-2003)
HD1214-0545	International 3700 (1990-1994)
HD1214-0545	International 3800 (1987-2004)
HD1214-0545	International 4600 (1990-1994)
HD1214-0545	International 4700 (1990-2003)
HD1214-0545	International 4800 (1990-2003)
HD1214-0545	International 4900 (1990-2003)
HD1214-0545	International 7100 (1990-1995)
HD1214-0545	International 8100 (1990-2003)
HD1214-0545	International 8200 (1990-1998)
HD1214-0545	International 8300 (1989-1994)
HD1214-0545	International F1924 (1979-1981)
HD1214-0545	International F1954 (1979-1989)
HD1214-0545	International F2275 (1979-1989)
HD1214-0545	International F2554 (1979-1989)
HD1214-0545	International F2574 (1979-1989)
HD1214-0545	International F2575 (1979-1989)
HD1214-0545	International F2654 (1980-1989)
HD1214-0545	International F2674 (1979-1989)
HD1214-0545	International M1400 Metro II (1987-1990)
HD1214-0545	International M1600 Metro II (1987-1990)
HD1214-0545	International S1823 (1980-1982)
HD1214-0545	International S1853 (1981-1989)
HD1214-0545	Thomas School Bus (1988-2006)
HD1214-0548	Dodge B300 (1975-1980)
HD1214-0548	Dodge B300 Van (1971-1974)
HD1214-0548	Dodge B350 (1981-1994)

BULLDOG HD Applications by Part Number	
Part Number	APPLICATION
HD1214-0548	Dodge Ram 3500 Van (1996-2003)
HD1214-0550	Ford F600 (1983-1990)
HD1214-0550	Ford F700 (1983-1990)
HD1214-0550	Ford F800 (1983-1990)
HD1214-0550	Ford L800 (1981-1984)
HD1214-0550	Ford L8000 (1981-1985)
HD1214-0550	Ford L900 (1981-1981)
HD1214-0550	Ford L9000 (1981-1990)
HD1214-0550	Ford LN800 (1980-1981)
HD1214-0550	Ford LN8000 (1981-1981)
HD1214-0550	Ford LN900 (1981-1981)
HD1214-0550	Ford LNT800 (1981-1981)
HD1214-0550	Ford LNT8000 (1981-1981)
HD1214-0550	Ford LNT9000 (1981-1981)
HD1214-0550	Ford LT800 (1981-1983)
HD1214-0550	Ford LT8000 (1981-1985)
HD1214-0550	Ford LT9000 (1981-1985)
HD1214-0550	Ford LTL9000 (1982-1985)
HD1214-0550	Ford LTS8000 (1981-1983)
HD1214-0550	Ford LTS9000 (1981-1985)
HD1214-0551	Chevrolet G30 (1975-1992)
HD1214-0551	Dodge B300 (1975-1980)
HD1214-0551	Dodge B300 Van (1971-1974)
HD1214-0551	Dodge B350 (1981-1992)
HD1214-0551	Ford E-350 Econoline (1975-1991)
HD1214-0551	Ford E-350 Econoline Club Wagon (1977-1991)
HD1214-0552	Ram Promaster 2500 (2014-2018)
HD1214-0552	Ram Promaster 3500 (2014-2018)
HD1214-0555	Chevrolet G30 (1975-1996)
HD1214-0555	Chevrolet G30 Van (1970-1970)
HD1214-0555	GMC G35 (1975-1978)
HD1214-0555	GMC G35/G3500 Van (1970-1974)
HD1214-0555	GMC G3500 (1979-1996)
HD1214-0556	Chevrolet B7 (1993-1998)
HD1214-0556	Chevrolet C5500 Kodiak (1990-1991)

BULLDOG HD Applications by Part Number	
Part Number	APPLICATION
HD1214-0556	Chevrolet C60 (1990-1990)
HD1214-0556	Chevrolet C60 Kodiak (1990-1996)
HD1214-0556	Chevrolet C6500 Kodiak (1997-2002)
HD1214-0556	Chevrolet C70 (1990-1990)
HD1214-0556	Chevrolet C70 Kodiak (1990-1996)
HD1214-0556	Chevrolet C7500 Kodiak (1997-2002)
HD1214-0556	GMC C5000 (1990-1990)
HD1214-0556	GMC C5000 Topkick (1990-1991)
HD1214-0556	GMC C6000 (1990-1990)
HD1214-0556	GMC C6000 Topkick (1990-1996)
HD1214-0556	GMC C6500 Topkick (1997-2002)
HD1214-0556	GMC C7000 (1990-1990)
HD1214-0556	GMC C7000 Topkick (1990-1996)
HD1214-0556	GMC C7500 Topkick (1997-2002)
HD1214-0557	IC Corporation RE School Bus (2003-2016)
HD1214-0557	International 1452SC (1987-1992)
HD1214-0557	International 1652SC (1986-1992)
HD1214-0557	International 1654 (1980-1989)
HD1214-0557	International 3700 (1990-1994)
HD1214-0557	International 3800 (1987-2004)
HD1214-0557	International 4600LP (1990-1994)
HD1214-0557	International 4700LP (1990-2002)
HD1214-0557	International 9300 (1989-1999)
HD1214-0557	International 9400 (1990-1999)
HD1214-0558	IC Corporation BE School Bus (2008-2015)
HD1214-0559	Ford B600 (1980-1994)
HD1214-0559	Ford B700 (1980-1994)
HD1214-0559	Ford B7000 (1983-1987)
HD1214-0559	Ford L800 (1981-1984)

Applications by Part Number

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1214-0559	Ford L900 (1981-1981)
HD1214-0559	Ford LN800 (1980-1984)
HD1214-0559	Ford LN8000 (1981-1987)
HD1214-0559	Ford LN900 (1981-1981)
HD1214-0559	Ford LNT800 (1981-1983)
HD1214-0559	Ford LNT8000 (1981-1983)
HD1214-0559	Ford LNT9000 (1981-1997)
HD1214-0559	Ford LT800 (1981-1983)
HD1214-0559	Ford LT9000 (1981-1990)

HD1214-0560	Hino FE2618 (1993-1997)
HD1214-0560	Hino FE2620 (1998-2004)
HD1214-0560	Hino FF17 (1984-1991)
HD1214-0560	Hino FF19 (1984-1991)
HD1214-0560	Hino FF20 (1992-1992)
HD1214-0560	Hino FF23 (1992-1992)
HD1214-0560	Hino FF3018 (1993-1997)
HD1214-0560	Hino FF3020 (1993-1998)

HD1214-0561	Chevrolet B7 (1993-1998)
HD1214-0561	Chevrolet C50 (1990-1990)
HD1214-0561	Chevrolet C5500 Kodiak (1990-1991)
HD1214-0561	Chevrolet C60 (1990-1990)
HD1214-0561	Chevrolet C60 Kodiak (1990-1996)
HD1214-0561	Chevrolet C6500 Kodiak (1997-2002)
HD1214-0561	Chevrolet C70 (1990-1990)
HD1214-0561	Chevrolet C70 Kodiak (1990-1996)
HD1214-0561	Chevrolet C7500 Kodiak (1997-2002)
HD1214-0561	Chevrolet T6500 (1997-2002)
HD1214-0561	Chevrolet T7500 (1997-2002)
HD1214-0561	GMC B7 (1993-1998)
HD1214-0561	GMC C5000 (1990-1990)
HD1214-0561	GMC C5000 Topkick (1990-1991)
HD1214-0561	GMC C6000 (1990-1990)
HD1214-0561	GMC C6000 Topkick (1990-1996)
HD1214-0561	GMC C6500 Topkick (1997-2002)
HD1214-0561	GMC C7000 (1990-1990)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1214-0561	GMC C7000 Topkick (1990-1996)
HD1214-0561	GMC C7500 Topkick (1997-2002)
HD1214-0561	GMC T6500 (1997-2002)
HD1214-0561	GMC T7500 (1997-2002)
HD1214-0561	Isuzu FSR (1997-2002)
HD1214-0561	Isuzu FTR (2005-2009)

HD1214-0562	Ford AT9513 (1996-1998)
HD1214-0562	Ford AT9522 (1997-1998)
HD1214-0562	Ford L8501 (1997-1997)
HD1214-0562	Ford L9501 (1997-1997)
HD1214-0562	Ford L9513 (1996-1997)
HD1214-0562	Ford LT8501 (1997-1997)
HD1214-0562	Ford LT8513 (1996-1997)
HD1214-0562	Ford LT9501 (1997-1997)
HD1214-0562	Ford LT9513 (1996-1997)
HD1214-0562	Ford LT9522 (1997-1997)

HD1214-0563	Ford B600 (1980-1990)
HD1214-0563	Ford B700 (1980-1990)
HD1214-0563	Ford B7000 (1983-1987)
HD1214-0563	Ford F600 (1980-1990)
HD1214-0563	Ford F700 (1980-1990)
HD1214-0563	Ford F800 (1980-1990)

HD1214-0564	Ford C600 (1980-1986)
HD1214-0564	Ford C700 (1980-1986)
HD1214-0564	Ford C7000 (1980-1986)
HD1214-0564	Ford C800 (1980-1989)
HD1214-0564	Ford F700 (1973-1979)
HD1214-0564	Ford L800 (1981-1984)
HD1214-0564	Ford L8000 (1981-1988)
HD1214-0564	Ford L8000F (1991-1997)
HD1214-0564	Ford L900 (1981-1981)
HD1214-0564	Ford LN600 (1980-1985)
HD1214-0564	Ford LN700 (1980-1986)
HD1214-0564	Ford LN7000 (1981-1997)
HD1214-0564	Ford LN800 (1980-1984)
HD1214-0564	Ford LN8000 (1981-1997)
HD1214-0564	Ford LN9000 (1991-1997)
HD1214-0564	Ford LNT800 (1981-1983)
HD1214-0564	Ford LNT8000 (1981-1989)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1214-0564	Ford LNT9000 (1981-1997)
HD1214-0564	Ford LT800 (1981-1984)
HD1214-0564	Ford LT8000 (1981-1988)
HD1214-0564	Ford LT9000 (1981-1996)
HD1214-0564	Ford LTS9000 (1981-1990)

HD1214-0566	Freightliner FC70 (1999-2004)
HD1214-0566	Freightliner FC80 (1999-2007)
HD1214-0566	Freightliner FL50 (1995-2005)
HD1214-0566	Freightliner FL60 (1991-2004)
HD1214-0566	Freightliner FL70 (1991-2005)
HD1214-0566	Freightliner FL80 (1991-2005)
HD1214-0566	Freightliner MB60 (1992-1995)
HD1214-0566	Freightliner MB70 (1992-1995)

HD1214-0568	Ford F-500 (1975-1977)
HD1214-0568	Ford F600 (1970-1990)
HD1214-0568	Ford F700 (1970-1990)
HD1214-0568	Ford F800 (1981-1990)
HD1214-0568	Ford LN600 (1980-1985)
HD1214-0568	Ford LN700 (1980-1986)
HD1214-0568	Ford P-500 (1975-1976)
HD1214-0568	Freightliner FL50 (1995-2005)
HD1214-0568	Freightliner FL60 (1991-2004)
HD1214-0568	Freightliner FL70 (1991-2005)
HD1214-0568	Freightliner FL80 (1991-2005)
HD1214-0568	Freightliner FLB (1994-2002)
HD1214-0568	Freightliner FLC112 (1992-2001)
HD1214-0568	Freightliner FLC120 (1998-1998)
HD1214-0568	Freightliner FLD112 (1992-2002)
HD1214-0568	Freightliner FLD120 (1992-2002)
HD1214-0568	Freightliner MB60 (1992-1995)
HD1214-0568	Freightliner MB70 (1992-1995)
HD1214-0568	Gillig School Bus (1989-1993)
HD1214-0568	Gillig School Bus (1989-1993)
HD1214-0568	International 3900FC (1991-1996)
HD1214-0568	International 3900FC (1991-1996)
HD1214-0568	International CO190 (1970-1971)

BULLDOG HD APPLICATIONS

Applications by Part Number

BULLDOG HD APPLICATIONS

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1214-0568	International CO200 (1970-1971)
HD1214-0568	International CO220 (1971-1971)
HD1214-0568	International S1853 (1981-1989)
HD1214-0568	International S1853 (1981-1989)

HD1214-0570	International 9100I SBA (2000-2003)
HD1214-0570	International 9200I SBA (2000-2010)
HD1214-0570	International 9300 (1989-1999)
HD1214-0570	International 9400 (1990-1999)
HD1214-0570	International 9400I SBA (2000-2010)
HD1214-0570	International 9600 (1989-1996)
HD1214-0570	International 9700 (1989-1996)
HD1214-0570	International 9900I (2010-2015)
HD1214-0570	International 9900IX (2000-2009)

HD1214-0571	Chevrolet W4500 Tiltmaster (1992-1995)
HD1214-0571	GMC W4500 Forward (1992-2009)
HD1214-0571	GMC W5500 Forward (1988-2009)
HD1214-0571	Isuzu NPR (1986-2010)
HD1214-0571	Isuzu NQR (2000-2016)
HD1214-0571	Isuzu NRR (2005-2016)

HD1214-0572	IC Corporation CE School Bus (2003-2016)
HD1214-0572	International 3000 (1996-2002)
HD1214-0572	International 3000FE (1997-1999)
HD1214-0572	International 3000IC (2000-2002)
HD1214-0572	International 3000RE (1996-2005)
HD1214-0572	International 3400 (1996-2002)
HD1214-0572	International 4200 (2002-2008)
HD1214-0572	International 4300 (2002-2008)
HD1214-0572	International 4300LP (2002-2008)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1214-0572	International 4400 (2002-2008)
HD1214-0572	International 4400LP (2002-2008)

HD1214-0573	Freightliner FLC112 (1992-2001)
HD1214-0573	Freightliner FLC120 (1998-1998)
HD1214-0573	Freightliner FLD112 (1992-2002)
HD1214-0573	Freightliner M2 112 (2003-2010)
HD1214-0573	International 9900I (2010-2015)
HD1214-0573	International 9900IX (2000-2009)
HD1214-0573	International Workstar 7300 (2015-2016)
HD1214-0573	International Workstar 7400 (2015-2016)
HD1214-0573	International Workstar 7600 (2010-2016)

HD1214-0575	Dodge P300 Van (1960-1974)
-------------	----------------------------

HD1214-0578	Chevrolet C50 (1976-1989)
HD1214-0578	Chevrolet C60 (1980-1989)
HD1214-0578	Chevrolet C70 (1979-1989)

HD1214-0579	Chevrolet C50 (1960-1989)
HD1214-0579	Chevrolet C50 (1968-1980)
HD1214-0579	Chevrolet C60 (1960-1989)
HD1214-0579	Chevrolet C60 (1968-1980)
HD1214-0579	Chevrolet C70 (1960-1989)
HD1214-0579	Chevrolet C70 (1979-1980)
HD1214-0579	Chevrolet S7 (1987-1989)
HD1214-0579	Chevrolet S7 (1987-1989)
HD1214-0579	GMC 3500 (1960-1962)
HD1214-0579	GMC C5000 (1980-1989)
HD1214-0579	GMC C6000 (1980-1989)
HD1214-0579	GMC C7000 (1980-1989)

HD1214-0580	International 2275 (1981-1989)
HD1214-0580	International 2554 (1981-2002)
HD1214-0580	International 2574 (1984-2003)
HD1214-0580	International 2575 (1984-1989)
HD1214-0580	International 9300 (1989-1999)
HD1214-0580	International 9400 (1990-1999)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1214-0580	International 9600 (1989-1996)
HD1214-0580	International 9700 (1989-1996)
HD1214-0580	International F2275 (1979-1989)
HD1214-0580	International F2554 (1979-1989)
HD1214-0580	International F2574 (1979-1989)
HD1214-0580	International F2575 (1979-1989)
HD1214-0580	International F2654 (1980-1989)
HD1214-0580	International F2674 (1979-1989)

HD1214-0593	Freightliner FL50 (1995-2005)
HD1214-0593	Freightliner FL60 (1991-2004)
HD1214-0593	Freightliner FL70 (1991-2005)
HD1214-0593	Freightliner FL80 (1991-2005)
HD1214-0593	Freightliner FS65 (1996-2008)
HD1214-0593	Freightliner MB60 (1992-1995)
HD1214-0593	Freightliner MB70 (1992-1995)
HD1214-0593	Thomas School Bus (1988-2006)

HD1214-0594	Chevrolet G30 (1979-1996)
HD1214-0594	Chevrolet P30 (1985-1985)
HD1214-0594	GMC G3500 (1979-1996)
HD1214-0594	GMC P3500 (1985-1985)

HD1214-0595	Ford C600 (1980-1986)
HD1214-0595	Ford C700 (1980-1986)
HD1214-0595	Ford C800 (1980-1989)
HD1214-0595	Ford C8000 (1981-1990)
HD1214-0595	Ford CT8000 (1981-1990)
HD1214-0595	Ford F-500 (1975-1977)
HD1214-0595	Ford F600 (1970-1979)
HD1214-0595	Ford F700 (1970-1979)
HD1214-0595	Ford L9000 (1991-1997)
HD1214-0595	Ford LA8000F (1991-1997)
HD1214-0595	Ford LA9000 (1988-1997)
HD1214-0595	Ford LL9000 (1991-1996)
HD1214-0595	Ford LLA9000 (1992-1994)
HD1214-0595	Ford LN600 (1980-1985)
HD1214-0595	Ford LN700 (1980-1986)
HD1214-0595	Ford LN7000 (1981-1997)

Applications by Part Number

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1214-0595	Ford LN800 (1980-1984)
HD1214-0595	Ford LN8000 (1981-1997)
HD1214-0595	Ford LNT800 (1981-1983)
HD1214-0595	Ford LNT8000 (1981-1989)
HD1214-0595	Ford LNT9000 (1991-1997)
HD1214-0595	Ford LS9000 (1990-1997)
HD1214-0595	Ford LT9000 (1991-1996)
HD1214-0595	Ford LTA9000 (1988-1997)
HD1214-0595	Ford LTLA9000 (1992-1997)
HD1214-0595	Ford LTS9000 (1990-1997)

HD1214-0596	Dodge Sprinter 2500 (2003-2006)
HD1214-0596	Dodge Sprinter 3500 (2003-2006)
HD1214-0596	Freightliner Sprinter 2500 (2002-2006)
HD1214-0596	Freightliner Sprinter 3500 (2002-2006)

HD1214-0598	Ford E-350 Econoline (1975-1991)
HD1214-0598	Ford E-350 Econoline Club Wagon (1977-1991)

HD1214-0601	Ford E-150 (2008-2014)
HD1214-0601	Ford E-150 Econoline (2008-2008)
HD1214-0601	Ford E-250 (2003-2014)
HD1214-0601	Ford E-250 Econoline (1992-2002)
HD1214-0601	Ford E-350 Club Wagon (2002-2005)
HD1214-0601	Ford E-350 Econoline (1992-2000)
HD1214-0601	Ford E-350 Econoline Club Wagon (1992-2002)
HD1214-0601	Ford E-350 Super Duty (1999-2018)
HD1214-0601	Ford E-450 Econoline Super Duty (2000-2002)
HD1214-0601	Ford E-450 Super Duty (2003-2016)
HD1214-0601	Ford Econoline Super Duty (1996-1999)

HD1214-0602	Freightliner MT55 (1999-2016)
-------------	-------------------------------

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1214-0604	Chevrolet W4500 Tiltmaster (1992-1995)
HD1214-0604	GMC W4500 Forward (1992-2009)
HD1214-0604	GMC W5500 Forward (1988-1993)
HD1214-0604	GMC W7500 Forward (1986-1996)
HD1214-0604	Isuzu NPR (1986-2010)

HD1214-0605	Blue Bird All American FE (1989-2016)
HD1214-0605	Blue Bird All American RE (1989-2016)
HD1214-0605	Ford P-400 (1975-1976)
HD1214-0605	Ford P-500 (1975-1976)
HD1214-0605	Gillig School Bus (1989-1993)
HD1214-0605	International M1400 (1966-1969)
HD1214-0605	International M1400 Metro II (1987-1990)
HD1214-0605	International M1600 Metro II (1987-1990)

HD1214-0606	Chevrolet G30 (1978-1991)
HD1214-0606	Dodge B300 (1975-1980)
HD1214-0606	Dodge B300 Van (1971-1974)
HD1214-0606	Dodge B350 (1981-1994)
HD1214-0606	Dodge Ram 3500 Van (1996-2003)
HD1214-0606	GMC G35 (1978-1978)
HD1214-0606	GMC G3500 (1979-1991)

HD1214-0607	Freightliner Century Class (2001-2011)
HD1214-0607	Freightliner MT55 (1999-2016)

HD1214-0608	Chevrolet C50 (1975-1989)
HD1214-0608	Chevrolet C60 (1975-1989)
HD1214-0608	Chevrolet C70 (1980-1989)
HD1214-0608	Chevrolet S7 (1987-1989)
HD1214-0608	GMC C5000 (1980-1989)
HD1214-0608	GMC C6000 (1980-1989)
HD1214-0608	GMC C7000 (1980-1989)

HD1214-0611	Freightliner Business Class M2 (2004-2012)
-------------	--

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1214-0614	International 9300 (1989-1999)
HD1214-0614	International 9400 (1990-1999)

HD1214-0636	Freightliner Century Class (2001-2011)
HD1214-0636	Freightliner Coronado (2010-2016)
HD1214-0636	Freightliner FLC112 (1992-2001)
HD1214-0636	Freightliner FLC120 (1998-1998)
HD1214-0636	Freightliner FLD112 (1992-2002)
HD1214-0636	Freightliner FLD120 (1992-2002)

HD1214-0638	Ford E-150 (2008-2014)
HD1214-0638	Ford E-150 Econoline (2008-2008)
HD1214-0638	Ford E-250 (2003-2014)
HD1214-0638	Ford E-250 Econoline (1992-2002)
HD1214-0638	Ford E-350 Club Wagon (2002-2005)

HD1214-0638	Ford E-350 Econoline (1992-2000)
HD1214-0638	Ford E-350 Econoline Club Wagon (1992-2002)
HD1214-0638	Ford E-350 Super Duty (1999-2018)
HD1214-0638	Ford E-450 Econoline Super Duty (2000-2002)
HD1214-0638	Ford E-450 Super Duty (2003-2016)
HD1214-0638	Ford Econoline Super Duty (1996-1999)

HD1214-0640	Chevrolet C50 (1973-1981)
HD1214-0640	Chevrolet C60 (1966-1981)
HD1214-0640	Chevrolet C70 (1979-1981)
HD1214-0640	GMC C5000 (1980-1981)
HD1214-0640	GMC C6000 (1980-1981)
HD1214-0640	GMC C7000 (1980-1981)
HD1214-0640	Gillig School Bus (1989-1993)
HD1214-0640	Hino FE17 (1984-1991)
HD1214-0640	Hino FE19 (1985-1991)
HD1214-0640	Hino FE20 (1992-1992)

BULLDOG HD APPLICATIONS

Applications by Part Number

BULLDOG HD APPLICATIONS

BULLDOG HD Applications by Part Number	
Part Number	APPLICATION
HD1214-0640	International M1400 (1966-1967)
HD1214-0640	International M1400 Metro II (1987-1990)
HD1214-0640	International M1600 Metro II (1987-1990)
HD1214-0640	International S1853 (1981-1989)

HD1214-0641	Hino FD17 (1989-1991)
HD1214-0641	Hino FD20 (1992-1992)
HD1214-0641	Hino FD2218 (1993-1997)
HD1214-0641	Hino FD2218LP (1993-1997)
HD1214-0641	Hino FD2220 (1998-2002)
HD1214-0641	Hino FD2320 (2003-2004)
HD1214-0641	Hino GC17 (1990-1991)
HD1214-0641	Hino GC20 (1992-1992)

HD1214-0642	International Terrastar (2011-2015)
-------------	-------------------------------------

HD1214-0643	Dodge D400 (1978-1981)
HD1214-0643	Dodge P400 Series (1957-1957)

HD1214-0643	Dodge P410 Series (1958-1959)
-------------	-------------------------------

HD1214-0643	Dodge P420 Series (1958-1959)
-------------	-------------------------------

HD1214-0643	Dodge P450 Series (1959-1959)
-------------	-------------------------------

HD1214-0645	Dodge M300 (1973-1974)
-------------	------------------------

HD1214-0645	Dodge M350 (1974-1974)
-------------	------------------------

HD1214-0645	Freightliner MB60 (1992-1994)
-------------	-------------------------------

HD1214-0645	Freightliner MB70 (1992-1994)
-------------	-------------------------------

HD1214-0645	Freightliner MT35 (1997-1998)
-------------	-------------------------------

HD1214-0645	Freightliner MT45 (1998-1998)
-------------	-------------------------------

HD1214-0646	Ford E-350 Econoline (1975-1991)
-------------	----------------------------------

HD1214-0646	Ford E-350 Econoline Club Wagon (1977-1991)
-------------	---

HD1214-0648	Dodge Sprinter 2500 (2007-2009)
-------------	---------------------------------

HD1214-0648	Dodge Sprinter 3500 (2007-2009)
-------------	---------------------------------

HD1214-0648	Freightliner Sprinter 2500 (2007-2009)
-------------	--

BULLDOG HD Applications by Part Number	
Part Number	APPLICATION
HD1214-0648	Freightliner Sprinter 3500 (2007-2015)
HD1214-0648	Mercedes-Benz Sprinter 3500 (2010-2017)

HD1214-0649	Ford F-250 Super Duty (2005-2018)
-------------	-----------------------------------

HD1214-0649	Ford F-350 Super Duty (2005-2018)
-------------	-----------------------------------

HD1214-0650	Ford F-250 Super Duty (1999-2004)
-------------	-----------------------------------

HD1214-0650	Ford F-350 Super Duty (1999-2004)
-------------	-----------------------------------

HD1214-0650	Ford F-450 Super Duty (1999-2004)
-------------	-----------------------------------

HD1214-0650	Ford F-550 Super Duty (1999-2004)
-------------	-----------------------------------

HD1214-0651	Ford F-250 Super Duty (2005-2016)
-------------	-----------------------------------

HD1214-0651	Ford F-350 Super Duty (2005-2007)
-------------	-----------------------------------

HD1214-0651	Ford F-450 Super Duty (2007-2017)
-------------	-----------------------------------

HD1214-0652	Dodge Ram 2500 (1994-2002)
-------------	----------------------------

HD1214-0652	Dodge Ram 3500 (1994-2002)
-------------	----------------------------

HD1214-0653	Dodge Ram 2500 (1994-2002)
-------------	----------------------------

HD1214-0653	Dodge Ram 3500 (1994-2002)
-------------	----------------------------

HD1214-0656	International 1654 (1980-1989)
-------------	--------------------------------

HD1214-0657	Freightliner MT45 (1998-2016)
-------------	-------------------------------

HD1214-0657	Freightliner MT55 (1999-2016)
-------------	-------------------------------

HD1214-0658	Ford AT9513 (1996-1998)
-------------	-------------------------

HD1214-0658	Ford AT9522 (1997-1998)
-------------	-------------------------

HD1214-0658	Ford L8501 (1997-1997)
-------------	------------------------

HD1214-0658	Ford L9501 (1997-1997)
-------------	------------------------

HD1214-0658	Ford L9513 (1996-1997)
-------------	------------------------

HD1214-0658	Ford LT8501 (1997-1997)
-------------	-------------------------

HD1214-0658	Ford LT8513 (1996-1997)
-------------	-------------------------

HD1214-0658	Ford LT9501 (1997-1997)
-------------	-------------------------

HD1214-0658	Ford LT9513 (1996-1997)
-------------	-------------------------

HD1214-0658	Ford LT9522 (1997-1997)
-------------	-------------------------

HD1214-0659	Dodge Sprinter 2500 (2003-2009)
-------------	---------------------------------

BULLDOG HD Applications by Part Number	
Part Number	APPLICATION

HD1214-0659	Dodge Sprinter 3500 (2003-2009)
-------------	---------------------------------

HD1214-0659	Freightliner Sprinter 2500 (2002-2009)
-------------	--

HD1214-0659	Freightliner Sprinter 3500 (2002-2009)
-------------	--

HD1214-0660	Ford B700 (1994-1994)
-------------	-----------------------

HD1214-0660	Ford B800 (1995-1997)
-------------	-----------------------

HD1214-0660	Ford F700 (1994-1997)
-------------	-----------------------

HD1214-0660	Ford F800 (1994-1997)
-------------	-----------------------

HD1214-0660	Ford FT900 (1994-1995)
-------------	------------------------

HD1214-0661	International 1654 (1980-1989)
-------------	--------------------------------

HD1214-0661	International 1724 (1980-1984)
-------------	--------------------------------

HD1214-0661	International 1754 (1981-1989)
-------------	--------------------------------

HD1214-0661	International 1824 (1979-1984)
-------------	--------------------------------

HD1214-0661	International 1854 (1981-1989)
-------------	--------------------------------

HD1214-0661	International 1924 S (1979-1982)
-------------	----------------------------------

HD1214-0661	International 1925 S (1979-1982)
-------------	----------------------------------

HD1214-0661	International 1954 (1979-1989)
-------------	--------------------------------

HD1214-0661	International 1955 (1981-1989)
-------------	--------------------------------

HD1214-0661	International 2155 (1984-1989)
-------------	--------------------------------

HD1214-0661	International F1924 (1979-1981)
-------------	---------------------------------

HD1214-0661	International F1954 (1979-1989)
-------------	---------------------------------

HD1214-0661	International M1600 Metro II (1987-1990)
-------------	--

HD1214-0661	International S1723 (1980-1985)
-------------	---------------------------------

HD1214-0662	Dodge P300 Van (1960-1974)
-------------	----------------------------

HD1215-0008	Ford F-450 Super Duty (2007-2017)
-------------	-----------------------------------

HD1215-0018	Ford AT9513 (1996-1998)
-------------	-------------------------

HD1215-0018	Ford AT9522 (1997-1998)
-------------	-------------------------

HD1215-0018	Freightliner Argosy (1999-2015)
-------------	---------------------------------

HD1215-0018	Freightliner Cascadia (2008-2016)
-------------	-----------------------------------

HD1215-0018	Freightliner Century Class (2001-2011)
-------------	--

HD1215-0018	Freightliner Classic (2001-2010)
-------------	----------------------------------

Applications by Part Number

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1215-0018	Freightliner Classic XL (2001-2009)
HD1215-0018	Freightliner Columbia (2001-2012)
HD1215-0018	Freightliner Coronado (2010-2016)
HD1215-0018	Freightliner FC70 (1999-2004)
HD1215-0018	Freightliner FC80 (1999-2007)
HD1215-0018	Freightliner FL50 (1995-2005)
HD1215-0018	Freightliner FL60 (1991-2004)
HD1215-0018	Freightliner FL70 (1991-2005)
HD1215-0018	Freightliner FL80 (1991-2005)
HD1215-0018	Freightliner FLB (2002-2002)
HD1215-0018	Freightliner FLB (1994-1999)
HD1215-0018	Freightliner FLC112 (1992-2001)
HD1215-0018	Freightliner FLC120 (1998-1998)
HD1215-0018	Freightliner FLD112 (1992-2002)
HD1215-0018	Freightliner FLD120 (1992-2002)
HD1215-0018	Freightliner M2 112 (2003-2010)
HD1215-0018	Freightliner MB60 (1992-1995)
HD1215-0018	Freightliner MB70 (1992-1995)
HD1215-0018	Thomas School Bus (2006-2006)
HD1215-0018	Thomas School Bus (2000-2000)
HD1215-0018	Thomas School Bus (1988-1991)

HD1215-0021	Freightliner Century Class (2001-2011)
HD1215-0021	Freightliner M2 112 (2003-2010)

HD1215-0024	Freightliner Business Class M2 (2004-2012)
HD1215-0024	Thomas SAF-T-LINER (1991-2016)
HD1215-0024	Thomas School Bus (1988-1991)
HD1215-0024	Thomas School Bus (2000-2000)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1215-0024	Thomas School Bus (2006-2006)
HD1215-0025	Freightliner Argosy (2013-2015)
HD1215-0025	Freightliner Century Class (2001-2011)
HD1215-0025	Freightliner Classic (2001-2010)
HD1215-0025	Freightliner Classic XL (2001-2009)
HD1215-0025	Freightliner Columbia (2001-2012)
HD1215-0025	Freightliner Coronado (2010-2016)
HD1215-0025	Freightliner FLC112 (1992-2001)
HD1215-0025	Freightliner FLC120 (1998-1998)
HD1215-0025	Freightliner FLD112 (1992-2002)
HD1215-0025	Freightliner FLD120 (1992-2002)
HD1215-0025	Freightliner M2 112 (2003-2010)

HD1215-0026	Freightliner Argosy (1999-2015)
HD1215-0026	Freightliner Business Class M2 (2004-2012)
HD1215-0026	Freightliner Century Class (2001-2011)
HD1215-0026	Freightliner FLC112 (1992-2001)
HD1215-0026	Freightliner FLD112 (1992-2002)
HD1215-0026	Freightliner FLD120 (1992-2002)

HD1215-0028	IC Corporation RE School Bus (2003-2016)
HD1215-0028	International 1452SC (1987-1992)
HD1215-0028	International 1652SC (1986-1992)
HD1215-0028	International 2275 (1981-1989)
HD1215-0028	International 2554 (1981-2002)
HD1215-0028	International 2574 (1984-2003)
HD1215-0028	International 2575 (1984-1989)
HD1215-0028	International 2654 (1999-2000)
HD1215-0028	International 2674 (1981-2003)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1215-0028	International 3700 (1990-1994)
HD1215-0028	International 3800 (1987-2004)
HD1215-0028	International 3900FC (1991-1996)
HD1215-0028	International 4600 (1990-1994)
HD1215-0028	International 4700 (1990-2003)
HD1215-0028	International 4800 (1990-2003)
HD1215-0028	International 4900 (1990-2003)
HD1215-0028	International 7100 (1990-1995)
HD1215-0028	International 8100 (1990-2003)
HD1215-0028	International 8200 (1990-1998)
HD1215-0028	International 8300 (1989-1994)
HD1215-0028	International F2275 (1979-1989)
HD1215-0028	International F2554 (1979-1989)
HD1215-0028	International F2574 (1979-1989)
HD1215-0028	International F2575 (1979-1989)
HD1215-0028	International F2654 (1980-1989)
HD1215-0028	International F2674 (1979-1989)
HD1215-0028	International S1723 (1980-1985)
HD1215-0028	International S1823 (1980-1982)
HD1215-0028	International S1853 (1981-1989)

HD1215-0029	Ford AT9513 (1996-1998)
HD1215-0029	Ford AT9522 (1997-1998)
HD1215-0029	Ford F600 (1986-1990)
HD1215-0029	Ford F700 (1986-1997)
HD1215-0029	Ford F800 (1986-1997)
HD1215-0029	Ford FT900 (1994-1997)
HD1215-0029	Ford L8501 (1997-1997)
HD1215-0029	Ford L9501 (1997-1997)
HD1215-0029	Ford L9513 (1996-1997)
HD1215-0029	Ford LT8501 (1997-1997)
HD1215-0029	Ford LT8513 (1996-1997)
HD1215-0029	Ford LT9501 (1997-1997)
HD1215-0029	Ford LT9513 (1996-1997)
HD1215-0029	Ford LT9522 (1997-1997)

BULLDOG HD APPLICATIONS

Applications by Part Number

BULLDOG HD APPLICATIONS

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
-------------	-------------

HD1215-0029	Freightliner Classic (2001-2010)
HD1215-0029	Freightliner Classic XL (2001-2009)
HD1215-0029	Freightliner FLB (1994-2002)
HD1215-0029	Freightliner FLC112 (1992-2001)
HD1215-0029	Freightliner FLC120 (1998-1998)
HD1215-0029	Freightliner FLD112 (1992-2002)
HD1215-0029	Freightliner FLD120 (1992-2002)

HD1215-0031	Chevrolet T6500 (1997-2002)
HD1215-0031	Chevrolet T7500 (1997-2002)
HD1215-0031	GMC T6500 (1997-2002)
HD1215-0031	GMC T7500 (1997-2002)

HD1215-0034	Kenworth T680 (2013-2014)
-------------	---------------------------

HD1215-0036	Ford AT9513 (1996-1998)
HD1215-0036	Ford AT9522 (1997-1998)
HD1215-0036	Ford B700 (1994-1994)
HD1215-0036	Ford B800 (1995-1997)
HD1215-0036	Ford FT900 (1994-1997)
HD1215-0036	Ford L8000F (1994-1997)
HD1215-0036	Ford L8501 (1997-1997)
HD1215-0036	Ford L9000 (1994-1997)
HD1215-0036	Ford L9501 (1997-1997)
HD1215-0036	Ford L9513 (1996-1997)
HD1215-0036	Ford LN7000 (1994-1997)
HD1215-0036	Ford LN8000 (1994-1997)
HD1215-0036	Ford LT8501 (1997-1997)
HD1215-0036	Ford LT8513 (1996-1997)
HD1215-0036	Ford LT9000 (1994-1997)
HD1215-0036	Ford LT9501 (1997-1997)
HD1215-0036	Ford LT9513 (1996-1997)
HD1215-0036	Ford LT9522 (1997-1997)

HD1215-0038	Peterbilt 270 (2001-2001)
-------------	---------------------------

HD1215-0039	GMC T6500 (1997-2002)
HD1215-0039	GMC T7500 (1997-2002)

HD1215-0041	International 8500 Transtar (2008-2011)
-------------	---

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
-------------	-------------

HD1215-0041	International 8600 Transtar (2008-2011)
HD1215-0041	International Lonestar (2009-2015)
HD1215-0041	International Prostar (2010-2016)

HD1215-0042	Ford AT9513 (1996-1998)
HD1215-0042	Ford AT9522 (1997-1998)
HD1215-0042	Ford L8501 (1997-1997)
HD1215-0042	Ford L9501 (1997-1997)
HD1215-0042	Ford L9513 (1996-1997)
HD1215-0042	Ford LT8501 (1997-1997)
HD1215-0042	Ford LT8513 (1996-1997)
HD1215-0042	Ford LT9501 (1997-1997)
HD1215-0042	Ford LT9513 (1996-1997)
HD1215-0042	Ford LT9522 (1997-1997)

HD1215-0043	Ford F700 (1994-1997)
HD1215-0043	Ford F800 (1994-1997)
HD1215-0043	Ford FT900 (1994-1997)

HD1215-0044	Autocar ACL (1988-1988)
HD1215-0044	Chevrolet C50 (1990-1990)
HD1215-0044	Chevrolet C5500 Kodiak (1990-1991)
HD1215-0044	Chevrolet C60 (1990-1990)
HD1215-0044	Chevrolet C60 Kodiak (1990-1996)
HD1215-0044	Chevrolet C70 (1990-1990)
HD1215-0044	Chevrolet C70 Kodiak (1990-1996)
HD1215-0044	GMC C5000 (1990-1990)
HD1215-0044	GMC C5000 Topkick (1990-1991)
HD1215-0044	GMC C6000 (1990-1990)
HD1215-0044	GMC C6000 Topkick (1990-1996)
HD1215-0044	GMC C7000 (1990-1990)
HD1215-0044	GMC C7000 Topkick (1990-1996)

HD1215-0045	Blue Bird TC2000 (1989-2004)
HD1215-0045	Chevrolet C6500 Kodiak (1997-2002)
HD1215-0045	Chevrolet C7500 Kodiak (1997-2002)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
-------------	-------------

HD1215-0045	Chevrolet T6500 (1997-2002)
HD1215-0045	Chevrolet T7500 (1997-2002)
HD1215-0045	Ford AT9513 (1996-1998)
HD1215-0045	Ford AT9522 (1997-1998)
HD1215-0045	Ford L8501 (1997-1997)
HD1215-0045	Ford L9501 (1997-1997)
HD1215-0045	Ford L9513 (1996-1997)
HD1215-0045	Ford LA8000F (1991-1997)
HD1215-0045	Ford LA9000 (1988-1997)
HD1215-0045	Ford LLA9000 (1992-1994)
HD1215-0045	Ford LT9501 (1997-1997)
HD1215-0045	Ford LT9513 (1996-1997)
HD1215-0045	Ford LT9522 (1997-1997)
HD1215-0045	Ford LTA9000 (1988-1997)
HD1215-0045	Ford LTLA9000 (1992-1997)
HD1215-0045	GMC C5000 (1990-1990)

HD1215-0045	GMC C5000 Topkick (1990-1991)
HD1215-0045	GMC C6000 (1990-1990)
HD1215-0045	GMC C6000 Topkick (1990-1996)
HD1215-0045	GMC C6500 Topkick (1997-2002)
HD1215-0045	GMC C7000 (1990-1990)
HD1215-0045	GMC C7000 Topkick (1990-1996)
HD1215-0045	GMC C7500 Topkick (1997-2002)

HD1215-0045	GMC T6500 (1997-2002)
HD1215-0045	GMC T7500 (1997-2002)
HD1215-0045	International 9900I (2011-2015)
HD1215-0045	International 9900IX (2000-2009)
HD1215-0045	International Workstar 7300 (2015-2016)
HD1215-0045	International Workstar 7600 (2010-2016)

HD1215-0048	Kenworth T680 (2013-2016)
-------------	---------------------------

HD1215-0049	Autocar ACL (1988-1988)
-------------	-------------------------

HD1215-0052	International 4900 (1990-2003)
HD1215-0052	International 8100 (1990-2003)
HD1215-0052	International 8200 (1990-1998)
HD1215-0052	International 8300 (1989-1994)

Applications by Part Number

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
-------------	-------------

HD1215-0052	International 9100 SBA (1998-1999)
HD1215-0052	International 9100I SBA (2000-2003)
HD1215-0052	International 9300 (1989-1999)
HD1215-0052	International 9400 (1990-1999)
HD1215-0052	International 9600 (1989-1996)
HD1215-0052	International 9700 (1989-1996)
HD1215-0052	International 9900I (2010-2015)
HD1215-0052	International 9900IX (2000-2009)

HD1215-0055	Ford F650 (2004-2011)
HD1215-0055	Ford F750 (2004-2011)
HD1215-0055	International 9900I (2010-2015)
HD1215-0055	International 9900IX (2000-2009)

HD1215-0057	Blue Bird All American RE (1989-2016)
-------------	---------------------------------------

HD1215-0059	Ford F650 (2000-2003)
HD1215-0059	Ford F750 (2000-2003)

HD1215-0060	Blue Bird All American FE (1989-2016)
HD1215-0060	Blue Bird All American RE (1989-2016)

HD1215-0062	Freightliner XC (2002-2002)
-------------	-----------------------------

HD1215-0063	Ford F650 (2004-2011)
HD1215-0063	Ford F750 (2004-2011)
HD1215-0063	IC Corporation CE School Bus (2003-2016)
HD1215-0063	IC Corporation RE School Bus (2003-2016)
HD1215-0063	International 1452SC (1987-1992)
HD1215-0063	International 1652SC (1986-1992)
HD1215-0063	International 1654 (1980-1989)
HD1215-0063	International 1724 (1980-1984)
HD1215-0063	International 1754 (1981-1989)
HD1215-0063	International 1824 (1979-1984)
HD1215-0063	International 1854 (1981-1989)
HD1215-0063	International 1924 S (1979-1982)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
-------------	-------------

HD1215-0063	International 1925 S (1979-1982)
HD1215-0063	International 1954 (1979-1989)
HD1215-0063	International 1955 (1981-1989)
HD1215-0063	International 2155 (1984-1989)
HD1215-0063	International 2554 (1981-2002)
HD1215-0063	International 2574 (1981-2003)
HD1215-0063	International 2654 (1989-2002)
HD1215-0063	International 2674 (1981-2003)
HD1215-0063	International 3700 (1990-1994)
HD1215-0063	International 3800 (1987-2004)
HD1215-0063	International 3900FC (1991-1996)
HD1215-0063	International 4600LP (1990-1994)
HD1215-0063	International 8100 (1990-2003)
HD1215-0063	International 8200 (1990-1998)
HD1215-0063	International 8300 (1989-1994)
HD1215-0063	International F1924 (1979-1981)
HD1215-0063	International F1954 (1979-1989)
HD1215-0063	International M1600 Metro II (1987-1990)
HD1215-0063	International S1823 (1980-1982)

HD1215-0064	Freightliner FLB (1994-2002)
HD1215-0064	Freightliner FLC112 (1992-2001)
HD1215-0064	Freightliner FLC120 (1998-1998)
HD1215-0064	Freightliner FLD112 (1992-2002)
HD1215-0064	Freightliner FLD120 (1992-2002)
HD1215-0064	Freightliner M2 112 (2003-2010)

HD1215-0065	Kenworth T680 (2013-2014)
-------------	---------------------------

HD1215-0066	International 9300 (1989-1995)
HD1215-0066	International 9300 (1997-1999)

HD1215-0067	Ford AT9513 (1996-1998)
HD1215-0067	Ford AT9522 (1997-1998)
HD1215-0067	Ford L8501 (1997-1997)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
-------------	-------------

HD1215-0067	Ford L9501 (1997-1997)
HD1215-0067	Ford L9513 (1996-1997)
HD1215-0067	Ford LT8501 (1997-1997)
HD1215-0067	Ford LT8513 (1996-1997)
HD1215-0067	Ford LT9501 (1997-1997)
HD1215-0067	Ford LT9513 (1996-1997)
HD1215-0067	Ford LT9522 (1997-1997)

HD1215-0068	Ford B700 (1994-1994)
HD1215-0068	Ford B800 (1995-1997)
HD1215-0068	Ford FT900 (1994-1997)
HD1215-0068	Freightliner FC70 (1999-2004)
HD1215-0068	Freightliner FC80 (1999-2007)
HD1215-0068	Freightliner FL50 (1995-2005)
HD1215-0068	Freightliner FL60 (1991-2004)
HD1215-0068	Freightliner FL70 (1991-2005)
HD1215-0068	Freightliner FL80 (1991-2005)
HD1215-0068	Freightliner FS65 (1996-2008)
HD1215-0068	Freightliner MB60 (1992-1995)
HD1215-0068	Freightliner MB70 (1992-1995)
HD1215-0068	Thomas School Bus (1988-2006)

HD1215-0070	Blue Bird All American FE (1989-2016)
HD1215-0070	Blue Bird All American RE (1989-2016)
HD1215-0070	Blue Bird TC2000 (1989-2004)

HD1215-0071	Hino 145 (2005-2010)
HD1215-0071	Hino 165 (2005-2010)
HD1215-0071	Hino 185 (2005-2010)

HD1215-0073	Ford F650 (2004-2009)
HD1215-0073	Ford F750 (2004-2009)

HD1215-0076	Kenworth T680 (2015-2016)
-------------	---------------------------

HD1215-0078	Ford F600 (1989-1994)
HD1215-0078	Ford F700 (1989-1994)
HD1215-0078	Ford F800 (1990-1990)
HD1215-0078	Ford FT900 (1990-1993)

HD1215-0079	Blue Bird All American FE (1989-2016)
HD1215-0079	Blue Bird All American RE (1989-2016)

BULLDOG HD APPLICATIONS

Applications by Part Number

BULLDOG HD APPLICATIONS

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1215-0080	International Prostar (2010-2016)
HD1215-0081	Chevrolet B7 (1997-2002)
HD1215-0081	Chevrolet C4500 Kodiak (2003-2009)
HD1215-0081	Chevrolet C50 (1990-1990)
HD1215-0081	Chevrolet C5500 Kodiak (1990-2009)
HD1215-0081	Chevrolet C60 (1990-1990)
HD1215-0081	Chevrolet C60 Kodiak (1990-1996)
HD1215-0081	Chevrolet C6500 Kodiak (1997-2009)
HD1215-0081	Chevrolet C70 (1990-1990)
HD1215-0081	Chevrolet C70 Kodiak (1990-1996)
HD1215-0081	Chevrolet C7500 Kodiak (1997-2009)
HD1215-0081	Chevrolet C8500 (2003-2009)
HD1215-0081	Chevrolet T6500 (2004-2007)
HD1215-0081	Chevrolet T7500 (2004-2007)
HD1215-0081	Chevrolet T8500 (2004-2007)
HD1215-0081	GMC B7 (1993-1998)
HD1215-0081	GMC C4500 Topkick (2003-2007)
HD1215-0081	GMC C5500 Topkick (2003-2007)
HD1215-0081	GMC C6500 Topkick (2000-2007)
HD1215-0081	GMC C7500 Topkick (2000-2007)
HD1215-0081	GMC C8500 Topkick (2003-2007)
HD1215-0081	GMC T6500 (2004-2007)
HD1215-0081	GMC T7500 (2004-2007)
HD1215-0081	Isuzu FTR (2005-2009)
HD1215-0084	IC Corporation CE School Bus (2003-2018)
HD1215-0084	International 3000 (1996-2002)
HD1215-0084	International 3000FE (1997-1999)
HD1215-0084	International 3000IC (2000-2002)
HD1215-0084	International 3000RE (1996-2005)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1215-0084	International 3400 (1996-2002)
HD1215-0084	International 4200 (2002-2008)
HD1215-0084	International 4300 (2002-2008)
HD1215-0084	International 4300LP (2002-2008)
HD1215-0084	International 4400 (2002-2008)
HD1215-0084	International 4400LP (2002-2008)
HD1215-0086	Kenworth T680 (2013-2016)
HD1215-0088	Ford F600 (1986-1989)
HD1215-0088	Ford F700 (1994-1997)
HD1215-0088	Ford F800 (1994-1997)
HD1215-0088	Ford FT900 (1994-1997)
HD1215-0088	Ford LL9000 (1991-1996)
HD1215-0088	Ford LN7000 (1991-1997)
HD1215-0088	Ford LN8000 (1991-1997)
HD1215-0088	Ford LN9000 (1991-1997)
HD1215-0088	Ford LNT9000 (1991-1997)
HD1215-0089	Chevrolet C50 (1976-1989)
HD1215-0089	Chevrolet C60 (1980-1989)
HD1215-0089	Chevrolet C70 (1979-1989)
HD1215-0089	Ford F650 (2000-2003)
HD1215-0089	Ford F750 (2000-2003)
HD1215-0091	Blue Bird TC2000 (1989-2004)
HD1215-0092	Dodge Ram 4500 (2008-2008)
HD1215-0092	Dodge Ram 5500 (2008-2008)
HD1215-0092	Sterling Truck Bullet 45 (2008-2010)
HD1215-0092	Sterling Truck Bullet 55 (2008-2010)
HD1215-0093	Ford F53 (1988-2017)
HD1215-0093	Ford F59 (1988-1997)
HD1215-0095	Ford F650 (2000-2015)
HD1215-0095	Ford F750 (2000-2015)
HD1215-0096	Blue Bird TC2000 (1989-2004)
HD1215-0097	International CO190 (1970-1971)
HD1215-0097	International CO200 (1970-1971)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1215-0097	International CO220 (1971-1971)
HD1215-0098	Chevrolet P30 (1975-1999)
HD1215-0098	Chevrolet P30 Van (1973-1974)
HD1215-0098	GMC P35 (1975-1978)
HD1215-0098	GMC P35/P3500 Van (1973-1974)
HD1215-0098	GMC P3500 (1979-1999)
HD1215-0098	Workhorse P30 (2000-2003)
HD1215-0100	International Workstar 7300 (2015-2016)
HD1215-0100	International Workstar 7400 (2015-2016)
HD1215-0100	International Workstar 7600 (2010-2016)
HD1215-0101	Ford F53 (1999-2017)
HD1215-0103	Freightliner Cascadia (2009-2017)
HD1215-0105	Dodge Ram 4500 (2008-2010)
HD1215-0105	Dodge Ram 5500 (2008-2010)
HD1215-0105	Ram 4500 (2011-2018)
HD1215-0105	Ram 5500 (2011-2018)
HD1215-0105	Sterling Truck Bullet 45 (2008-2010)
HD1215-0105	Sterling Truck Bullet 55 (2008-2010)
HD1215-0107	Ford B600 (1986-1990)
HD1215-0107	Ford B700 (1986-1990)
HD1215-0107	Hino FD17 (1989-1991)
HD1215-0107	Hino FD2218 (1993-1997)
HD1215-0107	Hino FD2218LP (1993-1997)
HD1215-0107	Hino FD2220 (1998-2002)
HD1215-0108	GMC C5000 (1990-1990)
HD1215-0108	GMC C5000 Topkick (1990-1991)
HD1215-0108	GMC C6000 Topkick (1991-1996)
HD1215-0108	GMC C7000 (1990-1990)
HD1215-0108	GMC C7000 Topkick (1990-1996)
HD1215-0108	International 3900FC (1991-1996)

Applications by Part Number

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
-------------	-------------

HD1215-0108	Thomas SAF-T-LINER (1991-2016)
--------------------	--------------------------------

HD1215-0111	Blue Bird TC2000 (1989-2004)
--------------------	------------------------------

HD1215-0112	Chevrolet C4500 Kodiak (2003-2009)
--------------------	------------------------------------

HD1215-0112	Chevrolet C5500 Kodiak (2003-2009)
--------------------	------------------------------------

HD1215-0112	Chevrolet C6500 Kodiak (2003-2009)
--------------------	------------------------------------

HD1215-0112	Chevrolet C7500 Kodiak (2003-2009)
--------------------	------------------------------------

HD1215-0112	Chevrolet C8500 (2003-2009)
--------------------	-----------------------------

HD1215-0112	GMC C4500 Topkick (2003-2009)
--------------------	-------------------------------

HD1215-0112	GMC C5500 Topkick (2003-2009)
--------------------	-------------------------------

HD1215-0112	GMC C6500 Topkick (2003-2009)
--------------------	-------------------------------

HD1215-0112	GMC C7500 Topkick (2003-2009)
--------------------	-------------------------------

HD1215-0112	GMC C8500 Topkick (2003-2009)
--------------------	-------------------------------

HD1215-0113	Blue Bird All American RE (1989-2016)
--------------------	---------------------------------------

HD1215-0113	Chevrolet C50 (1973-1980)
--------------------	---------------------------

HD1215-0113	Chevrolet C60 (1973-1980)
--------------------	---------------------------

HD1215-0113	Chevrolet C70 (1979-1980)
--------------------	---------------------------

HD1215-0113	Crane Carrier Centurion (1987-2009)
--------------------	-------------------------------------

HD1215-0113	Crane Carrier Century II (1987-1999)
--------------------	--------------------------------------

HD1215-0113	Freightliner Classic XL (2001-2009)
--------------------	-------------------------------------

HD1215-0113	Freightliner FLB (1994-2002)
--------------------	------------------------------

HD1215-0113	Freightliner FLC112 (1992-2001)
--------------------	---------------------------------

HD1215-0113	Freightliner FLC120 (1998-1998)
--------------------	---------------------------------

HD1215-0113	Freightliner FLD112 (1992-2002)
--------------------	---------------------------------

HD1215-0113	Freightliner FLD120 (1992-2002)
--------------------	---------------------------------

HD1215-0113	International 5070 (1981-1987)
--------------------	--------------------------------

HD1215-0113	International F5070 (1981-1987)
--------------------	---------------------------------

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
-------------	-------------

HD1215-0113	International F5070-SF (1981-1987)
--------------------	------------------------------------

HD1215-0113	International Transtar (2015-2017)
--------------------	------------------------------------

HD1215-0113	Thomas SAF-T-LINER (1996-2003)
--------------------	--------------------------------

HD1215-0114	International 4600 (1990-1994)
--------------------	--------------------------------

HD1215-0114	International 4700 (1990-2003)
--------------------	--------------------------------

HD1215-0114	International 4800 (1990-2003)
--------------------	--------------------------------

HD1215-0114	International 4900 (1990-2003)
--------------------	--------------------------------

HD1215-0114	International 8100 (1990-2003)
--------------------	--------------------------------

HD1215-0114	International 8200 (1990-1998)
--------------------	--------------------------------

HD1215-0114	International 8300 (1989-1994)
--------------------	--------------------------------

HD1215-0114	International 9300 (1989-1999)
--------------------	--------------------------------

HD1215-0114	International 9400 (1990-1999)
--------------------	--------------------------------

HD1215-0114	International 9600 (1989-1996)
--------------------	--------------------------------

HD1215-0114	International 9700 (1989-1996)
--------------------	--------------------------------

HD1215-0114	Thomas School Bus (1988-2006)
--------------------	-------------------------------

HD1215-0116	Chevrolet P30 (1975-1999)
--------------------	---------------------------

HD1215-0116	Chevrolet P30 Van (1973-1974)
--------------------	-------------------------------

HD1215-0116	GMC P35 (1975-1978)
--------------------	---------------------

HD1215-0116	GMC P35/P3500 Van (1973-1974)
--------------------	-------------------------------

HD1215-0116	GMC P3500 (1979-1999)
--------------------	-----------------------

HD1215-0116	Workhorse P30 (2000-2003)
--------------------	---------------------------

HD1215-0118	Freightliner XC (2002-2005)
--------------------	-----------------------------

HD1215-0119	International Prostar (2010-2016)
--------------------	-----------------------------------

HD1215-0120	Chevrolet C4500 Kodiak (2003-2009)
--------------------	------------------------------------

HD1215-0120	Chevrolet C5500 Kodiak (2003-2009)
--------------------	------------------------------------

HD1215-0120	Chevrolet C6500 Kodiak (2003-2009)
--------------------	------------------------------------

HD1215-0120	Chevrolet C7500 Kodiak (2003-2009)
--------------------	------------------------------------

HD1215-0120	Chevrolet C8500 (2003-2009)
--------------------	-----------------------------

HD1215-0120	GMC C4500 Topkick (2003-2009)
--------------------	-------------------------------

HD1215-0120	GMC C5500 Topkick (2003-2007)
--------------------	-------------------------------

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
-------------	-------------

HD1215-0120	GMC C6500 Topkick (2003-2009)
--------------------	-------------------------------

HD1215-0120	GMC C7500 Topkick (2003-2009)
--------------------	-------------------------------

HD1215-0120	GMC C8500 Topkick (2003-2009)
--------------------	-------------------------------

HD1215-0121	Ford F600 (1988-1990)
--------------------	-----------------------

HD1215-0121	Ford F700 (1988-1990)
--------------------	-----------------------

HD1215-0121	Ford F800 (1988-1990)
--------------------	-----------------------

HD1215-0122	Blue Bird All American FE (1989-2016)
--------------------	---------------------------------------

HD1215-0122	Blue Bird All American RE (1989-2016)
--------------------	---------------------------------------

HD1215-0123	Ford F650 (2000-2003)
--------------------	-----------------------

HD1215-0123	Ford F750 (2000-2003)
--------------------	-----------------------

HD1215-0124	Autocar ACL (1988-1988)
--------------------	-------------------------

HD1215-0126	Ford LA8000F (1991-1997)
--------------------	--------------------------

HD1215-0128	Ford AT9513 (1996-1998)
--------------------	-------------------------

HD1215-0128	Ford AT9522 (1997-1998)
--------------------	-------------------------

HD1215-0128	Ford F700 (1996-1997)
--------------------	-----------------------

HD1215-0128	Ford FT900 (1996-1997)
--------------------	------------------------

HD1215-0128	Ford L8501 (1997-1997)
--------------------	------------------------

HD1215-0128	Ford L9501 (1997-1997)
--------------------	------------------------

HD1215-0128	Ford L9513 (1996-1997)
--------------------	------------------------

HD1215-0128	Ford LT8501 (1997-1997)
--------------------	-------------------------

HD1215-0128	Ford LT8513 (1996-1997)
--------------------	-------------------------

HD1215-0128	Ford LT9501 (1997-1997)
--------------------	-------------------------

HD1215-0128	Ford LT9513 (1996-1997)
--------------------	-------------------------

HD1215-0128	Ford LT9522 (1997-1997)
--------------------	-------------------------

HD1215-0130	Ford F53 (1988-1997)
--------------------	----------------------

HD1215-0130	Ford F59 (1988-1997)
--------------------	----------------------

HD1215-0131	Workhorse W22 (2001-2004)
--------------------	---------------------------

HD1215-0133	Chevrolet C6500 Kodiak (1997-2002)
--------------------	------------------------------------

HD1215-0133	Chevrolet C7500 Kodiak (1997-2002)
--------------------	------------------------------------

HD1215-0133	Chevrolet T6500 (1997-2002)
--------------------	-----------------------------

HD1215-0133	Chevrolet T7500 (1997-2002)
--------------------	-----------------------------

HD1215-0133	Ford CL9000 (1990-1991)
--------------------	-------------------------

HD1215-0133	Ford CLT9000 (1990-1991)
--------------------	--------------------------

BULLDOG HD APPLICATIONS

Applications by Part Number

BULLDOG HD APPLICATIONS

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1215-0133	Ford L8000 (1981-1988)
HD1215-0133	Ford L8000F (1991-1997)
HD1215-0133	Ford LN7000 (1981-1997)
HD1215-0133	Ford LN8000 (1981-1997)
HD1215-0133	Ford LNT8000 (1981-1989)
HD1215-0133	Ford LNT9000 (1981-1997)
HD1215-0133	Ford LT8000 (1981-1988)
HD1215-0133	Ford LT9000 (1981-1996)
HD1215-0133	GMC C5000 (1990-1990)
HD1215-0133	GMC C5000 Topkick (1990-1991)
HD1215-0133	GMC C6000 (1990-1990)
HD1215-0133	GMC C6000 Topkick (1990-1996)
HD1215-0133	GMC C6500 Topkick (1997-2002)
HD1215-0133	GMC C7000 (1990-1990)
HD1215-0133	GMC C7000 Topkick (1990-1996)
HD1215-0133	GMC C7500 Topkick (1997-2002)
HD1215-0133	GMC T6500 (1997-2002)
HD1215-0133	GMC T7500 (1997-2002)
HD1215-0134	Ford L8000F (1991-1997)
HD1215-0134	Ford L9000 (1991-1997)
HD1215-0134	Ford LA8000F (1991-1997)
HD1215-0134	Ford LN7000 (1991-1997)
HD1215-0134	Ford LN8000 (1991-1997)
HD1215-0134	Ford LN9000 (1991-1997)
HD1215-0134	Ford LNT9000 (1991-1997)
HD1215-0134	Ford LS9000 (1990-1997)
HD1215-0134	Ford LT9000 (1991-1997)
HD1215-0134	Ford LTS9000 (1990-1997)
HD1215-0135	Ford CF6000 (1989-1990)
HD1215-0135	Ford CF7000 (1986-1997)
HD1215-0135	Ford CF8000 (1992-1997)
HD1215-0135	Ford CL9000 (1981-1991)
HD1215-0135	Ford CLT9000 (1981-1991)
HD1215-0147	Ford F650 (2005-2007)
HD1215-0147	Ford F750 (2005-2007)
HD1215-0147	International 4200 (2002-2008)
HD1215-0147	International 4300 (2002-2008)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1215-0147	International 4300LP (2002-2008)
HD1215-0147	International 4400 (2002-2008)
HD1215-0147	International 4400LP (2002-2008)
HD1215-0148	Ford F-650 (2016-2017)
HD1215-0148	Ford F-750 (2016-2017)
HD1215-0150	Freightliner XC (2002-2005)
HD1215-0151	Bluebird TC2000 (1989-2004)
HD1215-0151	Bluebird TC2000 (1989-2004)
HD1215-0152	Freightliner XC (2002-2002)
HD1215-0153	International 9900I (2010-2015)
HD1215-0153	International 9900IX (2000-2009)
HD1215-0154	International Prostar (2010-2016)
HD1215-0156	Chevrolet B7 (1993-1996)
HD1215-0156	Chevrolet C50 (1990-1990)
HD1215-0156	Chevrolet C5500 Kodiak (1990-1990)
HD1215-0156	Chevrolet C60 (1990-1990)
HD1215-0156	Chevrolet C60 Kodiak (1990-1996)
HD1215-0156	Chevrolet C6500 Kodiak (1997-2002)
HD1215-0156	Chevrolet C70 (1990-1990)
HD1215-0156	Chevrolet C70 Kodiak (1990-1996)
HD1215-0156	Chevrolet C7500 Kodiak (1997-2002)
HD1215-0156	Chevrolet T6500 (1997-2002)
HD1215-0156	Chevrolet T6500 (1997-2002)
HD1215-0156	Chevrolet T7500 (1997-2002)
HD1215-0156	Chevrolet T7500 (1997-2002)
HD1215-0156	GMC C5000 (1990-1990)
HD1215-0156	GMC C5000 Topkick (1990-1991)
HD1215-0156	GMC C6000 (1990-1990)
HD1215-0156	GMC C6000 Topkick (1990-1996)
HD1215-0156	GMC C7000 (1990-1990)

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
HD1215-0156	GMC C7000 Topkick (1990-1996)
HD1215-0156	GMC C7500 Topkick (1997-2002)
HD1215-0156	GMC T6500 (1997-2002)
HD1215-0156	GMC T6500 (1997-2002)
HD1215-0156	GMC T7500 (1997-2002)
HD1215-0156	GMC T7500 (1997-2002)
HD1215-0156	Isuzu FSR (1997-2002)
HD1215-0156	Isuzu FSR (1997-2002)
HD1215-0157	Ford AT9513 (1996-1998)
HD1215-0157	Ford AT9522 (1997-1998)
HD1215-0157	Ford L8501 (1997-1997)
HD1215-0157	Ford L9501 (1997-1997)
HD1215-0157	Ford L9513 (1996-1997)
HD1215-0157	Ford LT8501 (1997-1997)
HD1215-0157	Ford LT8513 (1996-1997)
HD1215-0157	Ford LT9501 (1997-1997)
HD1215-0157	Ford LT9513 (1996-1997)
HD1215-0157	Ford LT9522 (1997-1997)
HD1215-0158	Chevrolet C4500 Kodiak (2004-2008)
HD1215-0158	Chevrolet C5500 Kodiak (2004-2008)
HD1215-0158	Chevrolet C6500 Kodiak (2004-2008)
HD1215-0158	Chevrolet C7500 Kodiak (2004-2008)
HD1215-0158	Chevrolet C8500 (2004-2008)
HD1215-0158	Chevrolet T6500 (2006-2009)
HD1215-0158	Chevrolet T7500 (2006-2009)
HD1215-0158	Chevrolet T8500 (2006-2009)
HD1215-0160	Workhorse W22 (2001-2004)
HD1215-0161	International CXT (2005-2008)
HD1215-0161	International Workstar 7300 (2015-2016)
HD1215-0161	International Workstar 7400 (2015-2016)
HD1215-0161	International Workstar 7600 (2010-2016)
HD1294-0001	Chevrolet Express 3500 (1996-2002)

Applications by Part Number

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
-------------	-------------

HD1294-0001	GMC Savana 3500 (1996-2002)
--------------------	-----------------------------

HD1294-0003	Ford E-350 Club Wagon (2002-2005)
--------------------	-----------------------------------

HD1294-0003	Ford E-350 Econoline (1992-2000)
--------------------	----------------------------------

HD1294-0003	Ford E-350 Econoline Club Wagon (1992-2002)
--------------------	---

HD1294-0003	Ford E-350 Super Duty (1999-2018)
--------------------	-----------------------------------

HD1294-0003	Ford E-450 Econoline Super Duty (2000-2002)
--------------------	---

HD1294-0003	Ford E-450 Super Duty (2003-2017)
--------------------	-----------------------------------

HD1294-0003	Ford Econoline Super Duty (1996-1999)
--------------------	---------------------------------------

HD1294-0004	Ford E-350 Econoline (1975-1991)
--------------------	----------------------------------

HD1294-0004	Ford E-350 Econoline Club Wagon (1977-1991)
--------------------	---

HD5113-0014	Chevrolet P30 (1975-1999)
--------------------	---------------------------

HD5113-0014	GMC P35 (1975-1978)
--------------------	---------------------

HD5113-0014	GMC P3500 (1979-1999)
--------------------	-----------------------

HD5113-0014	Workhorse P30 (2000-2003)
--------------------	---------------------------

HD5113-0015	Ford F53 (1992-2004)
--------------------	----------------------

HD5113-0015	Ford F59 (1992-1997)
--------------------	----------------------

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
-------------	-------------

BULLDOG HD Applications by Part Number

Part Number	APPLICATION
-------------	-------------

BULLDOG HD APPLICATIONS



CAB SHOCKS

CAB SHOCKS

Ford AT9513		
1996-1998	HD1213-0707	OE Interchange: F6HT5K407AB, F7HT5K407BA; With 113" and 122" BBC
Ford AT9522		
1997-1998	HD1213-0707	OE Interchange: F6HT5K407AB, F7HT5K407BA; With 113" and 122" BBC
Ford CF7000		
1992-1994	HD1213-0705	OE Interchange: F2HT5K407AA
Ford LA8000F		
1991-1997	HD1213-0679	OE Interchange: 12010012; With Link Cab Suspension
Freightliner Cascadia		
2009-2017	HD1214-0538	OE Interchange: 1860764000 and 1841762000
Freightliner Century Class		
2001-2011	HD1214-0636	OE Interchange: 1841762001
2001-2011	HD1214-0544	OE Interchange: 1830378000, 1832999000
2001-2011	HD1214-0538	OE Interchange: 1832999001, 1841762000, and 1841762002
Freightliner Classic		
2001-2010	HD1214-0535	OE Interchange: 1829846000
Freightliner Columbia		
2001-2012	HD1214-0535	OE Interchange: 1829846000
2001-2012	HD1214-0538	OE Interchange: 1841762000
Freightliner Coronado		
2010-2016	HD1214-0538	OE Interchange: 1841762000 and 1841762002
2010-2016	HD1214-0636	OE Interchange: 1841762001
Freightliner FL60		
1991-2004	HD1213-0651	OE Interchange: 12020054
1991-2004	HD1214-0544	OE Interchange: 1830378, 1830378000
1991-2004	HD1214-0535	OE Interchange: 1829846000
Freightliner FL70		
1991-2005	HD1213-0651	OE Interchange: 12020054
1991-2005	HD1214-0544	OE Interchange: 1830378, 1830378000
1991-2005	HD1214-0535	OE Interchange: 1829846000



CAB SHOCKS

Freightliner FLB

2002-2002	HD1213-0651	OE Interchange: 12020054
2002-2002	HD1213-0680	OE Interchange: 6818910205
1994-1999	HD1213-0651	OE Interchange: 12020054
1994-1999	HD1213-0680	OE Interchange: 6818910205

Freightliner FLC112

1992-2001	HD1214-0636	OE Interchange: 1841762001
1992-2001	HD1213-0679	OE Interchange: 12010012, 12020012; With Link Cab Suspension
1992-2001	HD1214-0573	OE Interchange: 1860765000, 12011043, 12021043, 12011044, 12021044; With Link Cab Suspension
1992-2001	HD1214-0535	OE Interchange: 1829846000

Freightliner FLC120

1998-1998	HD1214-0636	OE Interchange: 1841762001
1998-1998	HD1214-0573	OE Interchange: 1860765000, 12021043
1998-1998	HD1214-0535	OE Interchange: 1829846000

Freightliner FLD112

1992-2002	HD1214-0636	OE Interchange: 1841762001
1992-2002	HD1213-0679	OE Interchange: 12010012, 12020012; With Link Cab Suspension
1992-2002	HD1214-0573	OE Interchange: 1860765000, 12021043
1992-2002	HD1214-0535	OE Interchange: 1829846000

Freightliner FLD120

1992-2002	HD1214-0636	OE Interchange: 1841762001
1992-2002	HD1214-0535	OE Interchange: 1829846000

Freightliner M2 112

2003-2010	HD1214-0573	OE Interchange: 12011044, 12021044
-----------	-------------	------------------------------------

International 4600

1990-1994	HD1213-0679	OE Interchange: 12011044; With Link Cab Suspension
-----------	-------------	--

International 4700

1990-2003	HD1213-0679	OE Interchange: 12011044; With Link Cab Suspension
-----------	-------------	--

International 4800

1990-2003	HD1213-0679	OE Interchange: 12011044; With Link Cab Suspension
-----------	-------------	--

International 4900

1990-2003	HD1213-0679	OE Interchange: 12011044; With Link Cab Suspension
-----------	-------------	--



CAB SHOCKS

CAB SHOCKS

International 9300		
1989-1999	HD1214-0614	OE Interchange: 2023684C1, 2023685C1

International 9400		
1990-1999	HD1214-0614	OE Interchange: 2023684C1, 2023685C1

International 9600		
1989-1996	HD1213-0651	OE Interchange: 12020054; With Link Cab Suspension

International 9700		
1989-1996	HD1213-0651	OE Interchange: 12020054; With Link Cab Suspension

International 9900I		
2010-2015	HD1214-0573	OE Interchange: 12011043, 12011047, 12011049, 12021043, 2614014C1; With Cab Suspension
2010-2015	HD1214-0537	OE Interchange: 12010254; With Link Cab Suspension

International 9900IX		
2010-2015	HD1214-0537	OE Interchange: 12010254
2000-2009	HD1214-0573	OE Interchange: 12011043, 12011047, 12011049, 12021043, 2614014C1; With Cab Suspension

International Workstar 7300		
2015-2016	HD1214-0497	OE Interchange: 2509222C91, 2509224C91, 3557165C1, 3557167C3, and 3560705C2
2015-2016	HD1214-0573	OE Interchange: 12011049, 12011043; With Link Cab Suspension

International Workstar 7400		
2015-2016	HD1214-0497	OE Interchange: 2509222C91, 2509224C91, 3557165C1, 3557167C3, and 3560705C2
2015-2016	HD1214-0573	OE Interchange: 12011049, 12011043; With Link Cab Suspension

International Workstar 7600		
2010-2015	HD1214-0497	OE Interchange: 2509222C91, 2509224C91, 3557165C1, 3557167C3, and 3560705C2
2010-2016	HD1214-0573	OE Interchange: 12011049, 12011043; With Link Cab Suspension

Kenworth K100		
1981-1985	HD1213-0652	OE Interchange: 12021164; With link Cab Suspension

Kenworth K100E		
2005-2006	HD1213-0652	OE Interchange: 12021164; With link Cab Suspension
1985-2003	HD1213-0652	OE Interchange: 12021164; With link Cab Suspension

Kenworth T2000		
1997-2011	HD1213-0652	OE Interchange: R711005; With Link Cabmate KWT000-A Air Suspension



CAB SHOCKS

Kenworth T660		
2008-2019	HD1213-0652	OE Interchange: 12021065; With Link Cab Suspension
Mack CH		
1989-2005	HD1214-0496	OE Interchange: 14QK391BM2
Mack CHU		
2008-2019	HD1214-0553	OE Interchange: 25625636, 25625635, 20874147, 14QK3103M, 14QK303M
Mack CL		
1991-2007	HD1214-0496	OE Interchange: 14QK391BM2
Mack CT		
2005-2007	HD1214-0553	OE Interchange: 14QK427M, 14QK428M, 14QK432M
Mack CX		
1998-2005	HD1214-0553	OE Interchange: 14QK399M2, 14QK399M3; With 70 or 80 inch Sleeper Cab
Mack CXU		
2008-2019	HD1214-0553	OE Interchange: 20874147, 14QK3103M, 14QK303M, 25625635, 25625636; With Sleeper Cab
Mack Granite		
2015-2018	HD1214-0553	OE Interchange: 20873442, 14QK423M
Mack GU7		
2008-2019	HD1214-0553	OE Interchange: 20873442, 14QK423M
Mack GU8		
2008-2019	HD1214-0553	OE Interchange: 20873442, 14QK423M
Mack RD		
2007-2007	HD1214-0541	OE Interchange: 14QK2111P4; With Cab Air Suspension
1981-1984	HD1214-0541	OE Interchange: 14QK2111P4; With Cab Air Suspension
Peterbilt 335		
2005-2010	HD1214-0536	OE Interchange: R716005
Peterbilt 348		
2010-2018	HD1214-0536	OE Interchange: R716005; With Day Cab
Peterbilt 357		
1990-2007	HD1214-0546	OE Interchange: R716007; With Unibuilt Cab



CAB SHOCKS

CAB SHOCKS

Peterbilt 365		
2008-2020	HD1214-0536	OE Interchange: R716005; With Day Cab
Peterbilt 367		
2008-2018	HD1214-0536	OE Interchange: R716005; With Day Cab
2008-2018	HD1214-0546	OE Interchange: R716007; With 70 inch Sleeper Cab
Peterbilt 375		
1987-1996	HD1214-0546	OE Interchange: 2902455; With Unibuilt Cab
Peterbilt 376		
1999-1999	HD1214-0546	OE Interchange: 2902455; With Unibuilt Cab
1994-1996	HD1214-0546	OE Interchange: 2902455; With Unibuilt Cab
1988-1992	HD1214-0546	OE Interchange: 2902455; With Unibuilt Cab
Peterbilt 377		
1987-2001	HD1214-0546	OE Interchange R716007; With Unibuilt Cab
Peterbilt 378		
1990-2007	HD1214-0546	OE Interchange: 2902455; With Unibuilt Cab
Peterbilt 379		
1990-2007	HD1214-0536	OE Interchange: 2016775
1990-2007	HD1214-0546	OE Interchange: R716007, 2902455; With Unibuilt Cab
Peterbilt 384		
2014-2015	HD1214-0569	OE Interchange: 2906005
2008-2012	HD1214-0569	OE Interchange: 2906005
Peterbilt 385		
1996-2007	HD1214-0569	OE Interchange: 2906005
Peterbilt 386		
2006-2016	HD1214-0536	OE Interchange: R716005; With Day Cab
2006-2016	HD1214-0546	OE Interchange: R716007; With 70 inch Sleeper Cab
2006-2016	HD1214-0569	OE Interchange: 2906005
Peterbilt 387		
2000-2011	HD1214-0569	OE Interchange: 2906032, 2906005, R716008; With 70 inch Sleeper Cab
Peterbilt 389		
2008-2018	HD1214-0546	OE Interchange: R716007; With 70 inch Sleeper Cab



CAB SHOCKS

Peterbilt 389		
2008-2018	HD1214-0637	OE Interchange: 2019140, R716006; With Day Cab
Peterbilt 587		
2011-2018	HD1214-0569	OE Interchange: 2906032, 2906005, R716008; With 70 inch Sleeper Cab
Volvo VAH		
2011-2018	HD1214-0554	OE Interchange: 20721254, 22662224
Volvo VHD		
2001-2009	HD1214-0554	OE Interchange: 20721254, 22662224
Volvo VN		
2004-2004	HD1214-0576	Oe Interchange: 8078547, 8078546, 20496217, 20624917
Western Star 4800		
1981-2002	HD1214-0610	OE Interchange: 660103406
1981-2002	HD1214-0613	OE Interchange: 660103402, 660103403, 660103404; With Link Cab Suspension
Western Star 4900		
1981-2002	HD1214-0613	OE Interchange: 660103402, 660103403, 660103404; With Link Cab Suspension
1981-2002	HD1214-0610	OE Interchange: 660103406
Western Star 5800		
1997-2002	HD1214-0613	OE Interchange: 660103402, 660103403, 660103404; With Link Cab Suspension
1997-2002	HD1214-0610	OE Interchange: 660103406
Western Star 5900		
1989-2001	HD1214-0613	OE Interchange: 660103402, 660103403, 660103404; With Link Cab Suspension
Western Star 6900		
1989-2001	HD1214-0613	OE Interchange: 660103402, 660103403, 660103404; With Link Cab Suspension
White/GMC WIA		
1988-1995	HD1214-0536	OE Interchange: 8168617
1988-1995	HD1214-0639	OE Interchange: 660100008, 8162662