

MANIFOLD CLAMP REPAIR KIT

Reduce Installation Time

Easily repair exhaust leaks without removing broken manifold bolts.

Problem

Problem: Broken exhaust manifold bolts near the firewall can't be extracted without removing the cylinder head.

Symptom: Noticeable exhaust fumes in the vehicle and louder than normal exhaust noise.

Cause: Bolts can break during servicing or from thermal expansion during normal engine operation.

Typical Solution: Remove the cylinder head, drill out broken bolts and reinstall manifold.



Close up view of broken exhaust manifold bolt

Solution

Reduce Repair Cost



917-107
GM Full size truck
4.8L, 5.3L, 6.0L
2009-99

Save Time and Money with Dorman's Manifold Repair Kit!

Providing coverage for popular GM Trucks and SUV's **8,700,000 vehicles!**

DORMAN[®]
OE SOLUTIONS[™]

NEW PRODUCTS • NEW SOLUTIONS • NEW OPPORTUNITIES

DORMAN[®]
NEW SINCE 1918