

GB Attention!

In order to ensure correct operation and long working life of this replacement part, the engine coolant must be checked for contamination and replaced if necessary.

