

2009–2014 Ford F–150 Pickup



GLOBAL PARTS DISTRIBUTORS, LLC

Tech Tip

#65



gpd has noticed an issue with 2009–2014 Ford F–150 pickups pertaining to their evaporator. Ford sells the unit as a total assembly but it has been designed to be split and put back together with screws. **The replacement evaporator is gpd #4712009.**



Because the vehicle does not come equipped with a cabin air filter, debris becomes caught in the air flow and is deposited into the evaporator. (as seen to the left)

Expansion valve

For replacement, be sure to keep the retaining clip on the expansion valve to be reused. **The replacement expansion valve is gpd #3411482.**



The deposited debris acts as an insulator to the thermistor probe; giving an incorrect reading.

Debris

Thermistor



This is a zoned evaporator. If you move the thermistor to a different location, the system will not work correctly.

Please refer to the back side for part numbers and references.

Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure or distribution is prohibited. GPD accepts no liability for any damage caused by any virus or other means transmitted by this document.

Discover other replacement A/C and heating parts on our website.