

SECTION 1 – IDENTIFICATION

PRODUCT: **Performance Hydra Jack Oil** DISTRIBUTED BY: Custom Blending
 & Packaging
 Chemical Formula: Proprietary
 Chemical Name: Petroleum Hydrocarbon
 Date: 04/2005

SECTION 2 – INGREDIENTS

CAS #	NAME	PEL/TLV
64742-53-6	Petroleum Hydrocarbon	5mg/M3 (for mist)

** Hazardous ingredient per 29 CFR 1910.1200.

*Subject to reporting requirements of SARA Title III, Section 313.

This product contains no components listed as a carcinogen by NTP, IARC, or OSHA.

SECTION 3 – PHYSICAL DATA

Boiling Point F: less than 500	Melting Point F: NA
Vapor Pressure: NA	Evaporation Rate: NA
Vapor Density: (Air=1) NA	Solubility in Water: Negligible
Specific Gravity (H2O=1): .876	% Volatile by volume: NA
Appearance and Odor: Amber liquid, petroleum odor	

Characteristics**Min/Max**

Gravity, APT @ 60 F	25.5/28.5
Pour Point, F	-59/-64
Flash, CDC, F	325/350
Copper Strip 4hrs/200 F	1B
Aniline Point, F	171/182
Saponification NO., mbkoh/gm	4.4/6.5
Viscosity @ -20 F	1100oP typical/1500cP Max
Viscosity, SUS @ 100 F	65/70
210 F	35/36.2 (Typical)
Viscosity Index	93

SECTION 7 – SPILL OR LEAK PROCEDURES

Steps to be taken in case material is spilled or leaked: Large Spills: Shut off source of leak. Evacuate area and ventilate. Remove ignition sources. Dike and contain. Remove with vacuum trucks or pump to storage vessels. Remaining liquid may be taken up with sand, earth, or other absorbent if necessary. Avoid contamination of ground and surface waters. Do not flush to sewer. Dispose of properly. Small spills: Take up with absorbent material and dispose of properly. **REPORT SPILLS AS REQUIRED TO APPROPRIATE AUTHORITIES.**

Waste Disposal Method: Dispose of in accordance with state, local and federal regulations.

SECTION 8 – CONTROL MEASURES

Respiration Protection: Not normally required. If vapor concentration becomes high use self contained air mask.

Ventilation: Local exhaust is adequate.

Gloves: Neoprene

Eye Protection. Chemical goggles should be worn where eye contact may occur.

Other: none

SECTION 9 – HANDLING AND STORAGE PRECAUTIONS

Precautions to be taken in handling and storage: Keep container tightly closed. Keep from heat and flame sources.

Precautions for use: Do not take internally. Avoid breathing vapor or mist. Wash thoroughly after skin contact.

Notice: This data represents typical values, not product specifications. No guarantee of accuracy or completeness is made. No responsibility is assumed for any kind of loss or damages arising from use of this data.

[View other automotive lifts and stands made by Hein-Werner on our website.](#)