

A/C COMPRESSOR

P/N 199-101 & 199-102

IMPORTANT! LS and similar engines are capable of high RPMs that can damage an A/C compressor's complex moving internal parts. A tach or TPS monitoring RPM switch, such as NOS P/N 15982NOS, should be configured to deactivate the compressor clutch when the engine is above 4000 RPM.

WARNING! Failure to install part 15982NOS or similar will VOID the A/C compressor warranty.

NOTE: See wiring diagram on the next page for 15982NOS installation.

