



70-2103 INSTRUCTIONS

Chevy Malibu 2004-2005

Chevy Cobalt 2005-2006

Pontiac G6 2005-2009

THIS HARNES DOES NOT SUPPLY AN ACCESSORY LEAD. AN ACCESSORY LEAD WILL NEED TO BE OBTAINED FROM ANOTHER SOURCE. ALSO ALL OF THE FACTORY WARNING CHIMES WILL NO LONGER FUNCTION.

Note: The Driver Information Center and radio is one unit. Removal of the radio will prohibit the vehicle owner from programming any of the features of the Driver Information Center. However once the features are programmed the vehicle will retain all the settings.



- Due to the fact that a switched 12 Volt accessory lead does not exist in the factory harness an accessory source must be located.
- Using the separate red wire provided with the fuse tap, locate an accessory power source in the vehicles fuse box.
- Connect this red wire to the after market head unit switched accessory lead.
- Use Metra's standard wiring instructions for the remainder of the installation.