

MOOG® Driveline Couplers

Reduce Vibration and Restore Ride Quality


MOOG driveline couplers are designed to replace worn or deteriorated couplers that can result in increased noise, vibration and harshness (NVH), which reduces ride quality. Serving as the connection point for the transmission and differential, these quality driveline couplers function similar to a universal joint. They are made from premium rubber to provide long service life, like-new NVH reduction and restore ride quality.

- Reduce driveline NVH by isolating driveline vibrations
- Reinforced high-grade nylon 66 wire insures optimal strength and longer coupler life
- Original Equipment replacement

HARDWARE INCLUDED (WHERE APPLICABLE)



REINFORCED HIGH-GRADE NYLON 66 WIRE



PREMIUM RUBBER MATERIAL

MOOG

The Problem Solver®

MOOG® Driveline Couplers

AVAILABLE APPLICATIONS		
PART #	APPLICATION	POSITION
670	Chrysler: 300 (2012-2014), 300C (2011-2014); Dodge: Challenger (2011-2014), Charger (2011-2014)	Rear Driveshaft at Transmission, Rear Driveshaft at Rear Axle
671	Chrysler: 300 (2010), 300C (2005-2011); Dodge: Challenger (2009-2011), Charger (2006-2011), Magnum (2005-2008)	Rear Driveshaft at Rear Axle, Rear Driveshaft at Transmission
673	Ford: Transit 150 <T150> (2015-2018), Transit 250 <T250> (2015-2018), Transit 350 <T350> (2015-2018), Transit 350HD <T350 HD> (2015-2018)	At Transmission
674	BMW: 318Ti (1995-1999), 318i (1992-1998), 318iS (1993-1997), 323Ci (2000), 323i (1999-2000), 325Ci (2001-2006), 325i (1992, 1994-1995, 2001-2005), 325iS (1992-1995), 328i (1996-1998), 328iS (1996-1999), Z3 (1996-2002), Z4 (2003-2005); Chevrolet: Corvette (2001-2013)	Rear Driveshaft at Transmission
675	BMW: 228i (2014-2016), 230i (2017-2018), 320i (2013-2018), 328d (2014-2018), 328i (2013-2016), 330e <F30 LCI> (2016-2018), 330i (2017-2018), 428i (2014-2016), 430i (2017-2019), 528i (2014-2015), X1 (2014-2015), X3 (2014-2017), X4 (2015-2018), X5 (2014-2018), X6 (2015-2016), Z4 (2014-2016)	Rear Driveshaft at Transmission
677	Hyundai: Santa Fe (2001-2006), Tucson (2005-2009); Kia: Sportage (2005-2010)	
678	BMW: 230i (2017-2018), 320iX (2014-2015), 328d (2014-2015), 328i (2014-2016), 330i (2017-2018), 335i (2013-2015), 340i (2016-2018), 428i (2014-2015), 430i (2017-2019), 435i (2014-2016), 440i (2017-2019), 528i (2014-2016), 530e (2018), 535d (2014-2016), 535i (2014-2017), 540i (2017-2018), 550i (2014-2017), 640i (2014-2018), 650i (2014-2018), 740Ld (2014), 740Le (2017-2018), 740Li (2014-2015), 740i (2014-2018), 750Li (2014-2015), 750i (2014-2016), ActiveHybrid 3 (2014-2015), ActiveHybrid 5 (2014-2016), ActiveHybrid 7 (2014-2015), ActiveHybrid 7L (2013-2015), M235i (2014-2016), M240i (2017-2018), M550i (2018), M760Li (2017), M760i (2017-2018), Z4 (2014-2016); BMW Truck: X5 (2014-2018), X6 (2014-2019)	Rear Driveshaft at Rear Axle, Rear Driveshaft at Transmission, At Rear Axle, Rear Driveshaft at Transfer Case, At Transmission
679	BMW: 228i (2014-2016), 320i (2013-2016), 320iX (2014-2015), 328d (2014-2016), 328i (2013-2016), 428i (2014-2016), 528i (2014-2016)	Rear Driveshaft at Rear Axle



The Problem Solver®

Learn more about performance driveline and axles we have.