

BULLETIN: 25950

Difficulty Sourcing All Axle Service Repair Parts

Various GM, Ford, and Dodge Trucks


PROBLEM:

Difficulty in finding parts necessary for complete repair on 60 Series axles

- Difficulty for technicians and fleet repair facilities in finding sources for all of the parts necessary to do a complete repair on 60 Series axles.
- There are no provisions on the existing axle to allow camber angle changes.

SOLUTION:

MOOG® K6652, K992, K8832, K8833



 The K992, eccentric camber-adjusting king pin provides camber alignment adjustments of -1-1/2° to +1-1/2° The kit is easily adjustable for the life of the vehicle.

