

VPW Arbitration Class 2 U1850


Class 2

J1850 Class 2


Symptoms: Video is not displayed on far rear screen.

Reason: We have found that there is a separate video feed for the far rear screen.

Solution: Below is a picture of the connector in which two wires need to be connected for video to be displayed on the far rear screen. For reference the Connector pictured below is purple in color and is located behind the radio and has the rear speaker leads in it as well. This is **NOT** the GMRVD connector.



Pin 4. - DVD Video Signal 2 (+) (Light Green) Pin 12. - DVD Video Signal 2 (-) (White)



Pacific Accessory Corporation MPW Arbitration Plass 2 U1850

(When Replacing the Factory Head Unit See Reverse Side for Instructions) J 1850 Class 2

The GMRVD is a plug and play cable that allows aftermarket monitors and IR headphones to be connected to the factory entertainment system. The GMRVD is connected behind the factory head unit.

• When using an aftermarket monitor, connect the cables labeled "Audio Video output to Overhead LCD" to the aftermarket Monitor video input. If installing aftermarket IR headphones, connect the RED and WHITE RCAs to the audio input of the aftermarket IR headphones. The cables labeled "Audio Video input From Rear Panel" are not used.

