

Technical Notice

TROUBLE CODE FOR THE EVAPORATIVE SYSTEM

ENGLISH

If a diagnostic trouble code for the evaporative system appears after replacing the filler neck, it is important to verify the condition of the filler cap rubber seal.

Replace filler cap if necessary.

- ① Good condition rubber seal.
- ② Bad condition rubber seal.

