

## Technical Notice

### TROUBLE CODE FOR THE EVAPORATIVE SYSTEM

#### ENGLISH

If a diagnostic trouble code for the evaporative system appears after replacing the filler neck, it is important to verify the condition of the filler cap rubber seal.

**Replace filler cap if necessary.**

- ① Good condition rubber seal.
- ② Bad condition rubber seal.

