

Cleaner Air for Passengers Enhanced HVAC Performance Easy Installation, Perfect Fit

TYC #: 800002P

Replacement for OEM 27277-CL025 (FX35/45) 999M1-VS801 (New) 999M1-VP051 (Old)



1. The filter is located behind the glove compartment. Remove plastic panel under the compartment. Remove plastic nut securing the kick panel. Remove two screws under the glove compartment.

03-08 Infiniti FX-35/ FX-45 03-07 Infiniti G35 Coupe 03-06 Infiniti G35 Sedan Estimated Time : 10 min.

02-06 Nissan Altima

04-08 Nissan Maxima 03-07 Nissan Murano 00-06 Nissan Sentra(OP)



3. Remove the filter access door by pushing on the locking tab to release it.



2. Open glove compartment and remove the 4 screws securing the compartment. Remove compartment and set aside.



4. Slide out old filter and <u>install new TYC filter</u>. Ensure that Air Flow arrow is pointing down.

5. Reinstall in reverse order.

Installation guide pictures are from the **BOLD** vehicle model.

*OP = Cabin Air Filter is an OPTION on this application. Some vehicles may not come <u>equipped with a Cabin Air Filter</u>.