



- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

TYC #: 800005P

Estimated Time : 5 min.


Replacement for OEM
LC74-61-P11 (Mazda MPV)
G3210AG000 (Subaru Legacy)
72880XA00A (Subaru B9 Tribeca)
87139-47010-83 (Toyotas)

00-02 Mazda MPV(To Sep-02)
06-08 Subaru B9 Tribeca
05-08 Subaru Legacy Outback

03-09 Toyota 4Runner
07-09 Toyota FJ Cruiser
01-09 Toyota Prius
04-08 Toyota Sienna (CE,LE Model)



1. The filter is located behind the glove compartment. Push in the sides of the glove box to disengage the latches and allow it to swing down. Pull on the retaining arm on the right side of the glove box to release it.



3. Slide out filter frame, remove old filter and replace with new TYC filter.

4. Reinstall in reverse order.



2. Filter access door will be visible after the glove box is swung open. Push on the 2 plastic tabs to release the filter access door .

Installation guide pictures are from the **BOLD** vehicle model.

Discover other A/C and heating parts on our website.