

TYC™

CABIN AIR FILTER

- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

TYC #: 800023P2

Estimated Time : 25 min.

Replacement for OEM
BP4K-61-J6X (Mazda 3)
CC29-61-J6X (Mazda 5)

04-10 Mazda 3
06-10 Mazda 5




1. The filters are located under the glove box. Remove the 2 panels underneath the glove box by unclipping two tabs on the top panel and one clip on the side panel.



2. Remove the junction box by unscrewing the two clips and removing all harnesses connected to the box. Slide out junction box and set aside.



3. Remove 2 x 12mm nuts that hold the junction box bracket and remove bracket.



4. Remove 4 screws on the filter access door and unplug the harness on the filter access door.



5. Slide out the old filters and install new TYC filters. Please see picture for the orientation of the filter. The top piece can be identified by the foam seal.

6. Reinstall in reverse order.

NOTE: Mazda 5 does not have the junction box and only requires the removal of the 2 panels to access the filter door.

Installation guide pictures are from the **BOLD** vehicle model.

Discover other A/C and heating parts on our website.