

- Cleaner Air for Passengers
- Enhanced HVAC Performance
- Easy Installation, Perfect Fit

TYC #: 800024P

Estimated Time: 5 min.

Replacement for OEM GK3J-61-148

03-08 Mazda 6 (w/o Turbo)



1. The filter is located behind the glove compartment. Open glove box and push on the sides while pulling down to disengage the latches.



3. Pull on the 2 retaining tabs on the filter access door. Remove door and set it aside.



2. Unhook the string that is secured on the plastic hook on the right side of the glove box. This allows the glove box to swing down and expose the filter access door behind it.



- 4. Slide out old filter and replace with <u>new TYC filter</u>. Ensure that Air Flow arrow is pointing down.
- 5. Reinstall in reverse order.