

TYC™

CABIN AIR FILTER

- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

TYC #: 800045P

Estimated Time : 25 min.

Replacement for OEM
80291-ST3-515 (NEW)
80291-ST3-E01 (Old)

97-01 Honda CR-V
00-06 Honda Insight




1. The filter is located behind the glove compartment. Push in on the sides while pulling down to disengage the latches. Allow glove box to swing down on its hinges, exposing the filter access door behind it.



3. Slide out the old filter and replace with new TYC filter, making sure Air Flow arrow is pointing to the driver's side.

4. Reinstall in reverse order.



2. Remove the 2 bolts at the bottom securing the metal cross bar . Pull on the top and bottom tabs to release the filter access door. Remove door and set it aside.

Installation guide pictures are from the **BOLD** vehicle model.

Discover other A/C and heating parts on our website.