

TYC™

CABIN AIR FILTER

- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

TYC #: 800046P2

Estimated Time : 10 min.

Replacement for OEM
LDY4-61-J6X

02-06 Mazda MPV (From 9-1-02)
04-10 Mazda RX-8



1. The filters are located behind the glove compartment. To remove the glove box, disengage the hinge on the left side by pulling the glove compartment upwards. After the left hinge is loose, slide the entire box to the left to dislodge the right hinge.



2. After the glove box is removed, the filter access door is visible. Pull on the locking tab on the left to remove the door, exposing the filters inside. Note: This application contains 2 identical filters.



3. Slide out the old filters and install new TYC filters. (TYC filters come in a set of 2) Ensure that the Air Flow arrow is pointing down for both filters.

4. Reinstall in reverse order.

Installation guide pictures are from the **BOLD** vehicle model.

Discover other A/C and heating parts on our website.