

# TYC™

## CABIN AIR FILTER

- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

**TYC #: 800051P**

Estimated Time : 5 min.

Replacement for OEM  
97133-2E250 (old)  
08790-2E200-A (New)

06-09 Hyundai Tucson (w/ Auto AC)



1. The filter is located behind the glove compartment. Push in on the retaining latches to remove them. Remove the retainer string attached to the glove box. Allow glove box to swing down on its hinges.



3. Slide out filter frame, remove old filter and replace with new TYC filter. Ensure that Air Flow arrow is pointing down.

4. Reinstall in reverse order.



2. Filter access door will then be visible. Push on the 2 retaining tabs on the sides to release the door.