



- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit


TYC #: 800066P

Estimated Time : 10 min.

Replacement for OEM
22665802 (05-05)
15781507 (06-07)
95861-78J11 (Suzuki)

05-09 Chevrolet Equinox

02-07 Saturn Vue
07-10 Suzuki XL-7
06-10 PT Torrent



1. The filter is located under the hood, at the passenger side. Locate the 3 retaining pins securing the cowl cover. Remove the pins.



2. Directly below the wiper at the bottom of the windshield, locate the additional 2 retaining pins that secure the cowl cover. Push up cowl cover to expose the filter housing under it.



3. Pull out slightly and slide up the old filter to remove it. Replace with new TYC filter, ensuring that the Air Flow arrow is pointing to the vehicle's cabin.

4. Reinstall in reverse order.

Installation guide pictures are from the **BOLD** vehicle model.

Discover other A/C and heating parts on our website.