

TYC™

CABIN AIR FILTER

- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

TYC #: 800072P2

Estimated Time : 15 min.

Replacement for OEM
27275-2W625

99-03 Infiniti QX-4



1. The filters are located behind the glove compartment. Push in on the sides of the glove box while pulling down to disengage the latches. Remove the retaining string that is attached to the glove box.



3. Remove the clip that holds the filters in place. Slide out both of the old filters. Replace with new TYC filters, ensuring that the Air Flow arrow is pointing to the driver's side for both filters.



2. Allow glove box to swing down on its hinges. Remove the hinges and disconnect the glove box. Set it aside. Locate and remove the 4 screws holding up the glove compartment cover and remove cover.



4. Reinstall in reverse order.