

TYC™

CABIN AIR FILTER

- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

TYC #: 800088P

Estimated Time : 5 min. +

Replacement for OEM
97133-1E000(old)
08790-1E000-A (06-07)
08790-2H000-A (08-10)

07-10 Hyundai Accent Hatchback
06-10 Hyundai Accent Sedan
06-08 Hyundai Elantra Sedan



1. The filter is located behind the glove compartment. Slide out the retainer on each side and push them towards the center of the glove box to remove. Allow glove box to swing down on its hinges.



2. Pinch on the 2 securing tabs together on each side to remove the filter access door. Set access door aside.



3. Reach in and slide out the old filter. Replace with new TYC filter by sliding it into the housing. Ensure that the air flow arrow is pointing down.

4. Reinstall in reverse order.

Installation guide pictures are from the **BOLD** vehicle model.