

# TYC™

## CABIN AIR FILTER

- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

**TYC #: 800154C**

Replacement for OEM  
27277-1ME0B

Estimated Time : 20 min.

11-11 Infiniti M37



1. The filter is located behind the glove compartment. Remove the four screws along the top of the glove box.



4. Slide out old filter from housing; replace with new TYC filter. Ensure that air flow arrow is pointing up.



2. Pull down the entire glove box. Filter access door will now be accessible.

3. Release filter access door by pushing in the 2 tabs on the side.



5. Reinstall in reverse order.